

ASS. REC. BY:

REP:

03/11/19 015923 / NSD30

Special Instruction:

Supervisor:

M42

ASSIGNMENT (Office)

From (Person):

Chin Lee Yiney

of

Mer

Date/Time:

9/9/2019 12:05pm

Estimated Cost:

Bill to:

☒ OD

TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBM 9403U

Insured:

at Workshop, m/s

Bike production

Tel:

6392555

of

G10 Senngoon Ford

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

30/08/2019

CA

☒ REV

/ REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

1:40pm 9/9/19

Person Contacted:

Wendy

Vehicle

☒ IN ☐ OUT

Date/Time

Action/Instruction

Voluntary ✓

FBM 9403U - X

11/9/19

@3pm Mr Kwan will check repair cost and call back

12/09/19

@ 10:45 am revised PA to AEA via me/mr.

12/09/19

@ 10:51 am mandate request authorize repair to AEA via me/mr.

ASS. REQ. BY:

NAZ

REF:

ALG

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

T/A \$300

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

8.5% 9K \$9500

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

(up)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

FBM 94034

Regn:

24 MAY 2018

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

HIND CB 150

cc 149

Colour:

RED

A/C: Insured / Std / NI (NA)

Sp. Reading

39,177

T/Radio: Insured / Std / NI (NA)

Eng/No:

C/No:

MLAKC 2882JS01394

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

110/70 R17

R:

150/60 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

DSSO

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

30/8/19

D.O.I.

9/9/19

Survey held at

BIKE PRODUCTION

Des. of Damages:

Frt / Rear

O/S / N/S

U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	OE Rebate \$6,189.00
12/09/19 @ 18:42pm	mandate approved by Thaddaeus via merimer.
13/09/19 @ 09:11am	informed CIA to Kwan S.H via email.
	Repair limit \$3,300/-
23/09/19	Confirmed 4S \$3,050/- @ 2 days with Naz
	(\$5,526.80 Red - 64%)

RECEIVED 8 SEP 2019

Date/Time, File Pass to?

30/09/19

1) Type

Date/Time, File Return to?

2)

Report Format:

Lump Sum / L.B.E.C

3,050/- 4S

☐

Prel. Report

☒

Final Report

Days Of Repair:

2

Resurvey No. of Trip:

2

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Welding (\$

Survey Fee:

Transportation

5 + RS \$1

Fines

Others

TOTAL

700

11

711

24/9/2019

Your password will expire in 6 days. Click here to change it.

OD CLAIM FBM9403U

From: Chin, Lee-Ying
To: assignments, Admin A
Cc: Fong, Andy-S/Y
Sent: 09/09/2019 12:06:58 PM

Attachments: 20190907_175430.jpg; 20190907_175454.jpg; FBM9403U FBM9403U FBM9403U

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

-----Original Message-----

From: Sbk E [mailto:sbk5643e@yahoo.com]
Sent: Saturday, September 07, 2019 5:57 PM
To: AIG SGP, Claims-Survey
Subject: [EXTERNAL] Re: OD CLAIM FBM9403U

This message is from an external sender; be cautious with links and attachments.

Dear Sir,

Good Day. Please refer to the attached file. Please contact us at 62995177 for pre-repair inspection appointment. Thank you very much for your attention.

Regards,

Kwan S. H.
Director
Bike Production Pte Ltd

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If y

\$3,900/-

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	759J

Vehicle Details

Vehicle No.:	FBM9403U
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Sep 2019
Vehicle Make:	HONDA
Vehicle Model:	CB150R MANUAL
Primary Colour:	Red
Manufacturing Year:	2017
Engine No.:	KC32E0011394
Chassis No.:	MLHKK2882J5011394
Maximum Power Output:	-
Open Market Value:	\$3,744.00
Original Registration Date:	24 May 2018
First Registration Date:	24 May 2018
Transfer Count:	1
Actual ARF Paid:	\$562.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	23 May 2028
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$7,115.00
COE Rebate Amount:	\$6,189.00
Total Rebate Amount:	\$6,189.00

The information contained herein is correct as at 11 Sep 2019

OK

RE: FBM 9403U OD / 9899201255SG - Revise Supplementary

Ng, Thaddaeus-HC <Thaddaeus-HC.Ng@aig.com>

Fri 20/9/2019 9:50 AM

To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>; SUR <sur@lkkauto.com>

Hi Shirley,

Bike Production has raise up Muffler (Exhaust), Rear Tyre & Supplementary Radiator to revise and update.

Has contacted Mr Kwan and agreed.

- Muffler – Repair @ \$190/- (Labour)
- Rear Tyre – Serviceable to remove
- Radiator supplementary – Repair @ \$250/- inclusive R/I

Regards,

Thaddaeus Ng

AIG

Motor Claims Surveyor

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1929 | Fax +(65) 6835 7416 Hp +(65) 8876 5433

Thaddaeus-HC.Ng@AIG.com | www.AIG.com.sg

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Sent: Monday, September 16, 2019 4:05 PM

To: Ng, Thaddaeus-HC <Thaddaeus-HC.Ng@aig.com>

Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>; SUR <sur@lkkauto.com>

Subject: [EXTERNAL] Re: FBM 9403U OD / 9899201255SG

This message is from an external sender; be cautious with links and attachments.

Dear Thaddaeus,

Kindly let us have your supplementary approval.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

RE: EXHAUST AND RADIATOR, Re: SUPPLEMENTARY AND UNCONFIRMED ITEMS AUTHORIZATION, Re: MARKET VALUE, Re: RE: FBM9403U AUTHORIZATION TO REPAIR

Sbk E <sbk5643e@yahoo.com>

Wed 18/9/2019 7:23 AM

To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

4 attachments (5 MB)

fbm9403u aig adm report ows.pdf; 20190907_081634.jpg; 20190907_081636.jpg; 20190907_081650.jpg;

Dear Shirley,

Please refer to the addendum report. It was mentioned that the Insured collided with the front vehicle and rear vehicle hit our Insured vehicle. There were damages to both third party vehicles.

Please also refer to the photos required. I will call you after the radiator is taken out. Thanks.

Regards,

Kwan S. H.

Director

Bike Production Pte Ltd

On Tuesday, September 17, 2019, 5:08:04 PM GMT+8, Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com> wrote:

Hi Kwan S.H,

Refer to our conversation earlier, if remove the radiator & exhaust comp, the L/S figure is \$ 2,800.00 (estimated).

Kindly inform this is not the finalize confirmation.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sbk E <sbk5643e@yahoo.com>

Sent: Saturday, 14 September 2019 12:13 PM

To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

Subject: RE: SUPPLEMENTARY AND UNCONFIRMED ITEMS AUTHORIZATION, Re: MARKET VALUE, Re: RE: FBM9403U AUTHORIZATION TO REPAIR

Dear Shirley,

Good Day. Yesterday, you surveyor came to take photos of the unconfirmed and supplementary items. Please

Re: MARKET VALUE, Re: RE: FBM9403U AUTHORIZATION TO REPAIR

Shirley Hiew (LKK Auto)

Fri 13/9/2019 9:11 AM

To: Sbk E <sbk5643e@yahoo.com>

Cc: SUR <sur@lkkauto.com>

Hi Kwan S.H,

As instructed by our client, please proceed at repair cost not exceeding \$3,300.00 (inclusive supplementary) to repair the insured vehicle **FBM 9403U (Excess \$ 300/-)** on lump sum basis.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sbk E <sbk5643e@yahoo.com>

Sent: Thursday, 12 September 2019 10:45 AM

To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Subject: Re: MARKET VALUE, Re: RE: FBM9403U AUTHORIZATION TO REPAIR

Dear Shirley,

We are agreeable to accept at \$3,300.00 before Excess and GST. Please kindly authorise. Thanks.

Regards,

Kwan S. H.

Director

Bike Production Pte Ltd

On Thursday, September 12, 2019, 10:37:03 AM GMT+8, Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com> wrote:

Dear Wendy,

As spoken, kindly confirm that you are able to undertake the repair cost not exceeding \$ 3,300.00 on lump sum basis.

Re: MARKET VALUE, Re: RE: FBM9403U AUTHORIZATION TO REPAIR

Sbk E <sbk5643e@yahoo.com>

Thu 12/9/2019 10:45 AM

To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Dear Shirley,

We are agreeable to accept at \$3,300.00 before Excess and GST. Please kindly authorise. Thanks.

Regards,

Kwan S. H.

Director

Bike Production Pte Ltd

On Thursday, September 12, 2019, 10:37:03 AM GMT+8, Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com> wrote:

Dear Wendy,

As spoken, kindly confirm that you are able to undertake the repair cost not exceeding \$ 3,300.00 on lump sum basis.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Shir@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sbk E <sbk5643e@yahoo.com>

Sent: Thursday, 12 September 2019 10:06 AM

To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Subject: RE: MARKET VALUE, Re: RE: FBM9403U AUTHORIZATION TO REPAIR

Dear Shirley,

The market value is around \$10,100.00. Therefore, maximum repair limit is \$3,900.00. I will like to highlight that we are not trying to repair to the maximum limit. Thanks.

Regards,

Kwan S. H.

Director

Bike Production Pte Ltd

On Tuesday, September 10, 2019, 8:48:47 AM GMT+8, Sbk E <sbk5643e@yahoo.com> wrote:

Dear Navita,

Please assist to upload the necessary documents. Thanks.

View Sent Message

This mail is associated with :

***FBM9403U (9899201255SG)**
OD
Aug 30 2019 9:05AM
[MUHAMAD YUNUS BIN SHAMSUDIN]
Bike Production Pte Ltd

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 18/09/2019 14:43 PM.
To thaddaeus-hc.ng@aig.com
CC sur@lkkauto.com
Subject Re: Alert - Adj Mandate Maintained - FBM9403U - Claim Handler: Gan, Hunchung

Dear Thaddaeus,

We refer to your below email above matter.

As spoken, exhaust comp. & rear tyre will be removed. Exhaust will be indicated in labour as repair, additional \$ 190.00.

We will re-seek mandate supplementary approval of the radiator after the dismantle photo taken, subject to consistency.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

<-- Original Message -->

From: AIG_SG

To: LKK_HQ

Sent On: 16/09/2019 10:33 PM

Subject: Alert - Adj Mandate Maintained - FBM9403U - Claim Handler: Gan, Hunchung

Maintained: Kindly do not hesitate to arrange photo taking for check and supplementary item. Muffler and Radiator damaged further damaged TBC.
After repair photos require for parts replacement to confirm. Lumpsum acknowledge letter to confirm fo

DOCUMENTS SUMMARY

There are no documents.

\$190 -
Additional \$180/-

Dear Thaddaeus,

As spoken, exhaust comp. & rear tyre will be removed. Exhaust will be indicated in labour as repair.

We will re-seek mandate supplementary approval of the radiator after the dismantle photo taken, Subject

Thank you.

to consistency.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

<-- Original Message -->

From: AIG_SG

To: LKK_HQ

Sent On: 16/09/2019 10:33 PM

Subject: Alert - Adj Mandate Maintained - FBM9403U - Claim Handler: Gan, Hunchung

Maintained: Kindly do not hesitate to arrange photo taking for check and supplementary item. Muffler and Radiator damaged further damaged TBC. After repair photos require for parts replacement to confirm. Lumpsum acknowledge letter to confirm fo

Print Received Message

This mail is associated with :

***FBM9403U (9899201255SG)**

OD

Aug 30 2019 9:05AM

[MUHAMAD YUNUS BIN SHAMSUDIN]

Bike Production Pie Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 16/09/2019 22:33 PM.
To LKK_HQ
Subject Alert - Adj Mandate Maintained - FBM9403U - Claim Handler: Gan, Hunchung

Maintained: Kindly do not hesitate to arrange photo taking for check and supplementary item. Muffler and Radiator damaged further damaged TBC. After repair photos require for parts replacement to confirm. Lumpsum acknowledge letter to confirm fo

View Received Message

This mail is associated with :

***FBM9403U (9899201255SG)**
OD
Aug 30 2019 9:05AM
[MUHAMAD YUNUS BIN SHAMSUDIN]
Bike Production Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 12/09/2019 18:42 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$3300.00) - FBM9403U - Claim Handler: Gan, Hunchung

Approved:3300.00:Kindly do not hesitate to arrange photo taking for check and supplementary item.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Gan, Hunchung

Date: 19 Sep 2019

Preliminary Advice

Vehicle No	: FBM9403U	Accident Date	: 30/08/2019
Make	: HONDA CB150R	Policy No.	: 1900094558
Assignment Date	: 09/09/2019	Excess	: S\$300.00
Date of Inspection	: 09/09/2019	Est. Duration of Repair	: 2 days
Inspection At	: Bike Production Pie Ltd (HQ) 610 SERANGOON ROAD Singapore 218216		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion, o/s body and n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,576.80 (inclusive supp)
Revised Amount	:S\$	4,459.30 (inclusive supp)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,459.30

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	9,500.00
COE / PARF Rebate	:S\$	6,189.00
Salvage Value	:S\$	
Margin for Repair	:S\$	3,311.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Supplementary amount is \$ 511.00

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Gan, Hunchung

Date: 16 Sep 2019

Preliminary Advice

Vehicle No	: FBM9403U	Accident Date	: 30/08/2019
Make	: HONDA CB150R	Policy No.	: 1900094558
Assignment Date	: 09/09/2019	Excess	: S\$300.00
Date of Inspection	: 09/09/2019	Est. Duration of Repair	: 2 days
Inspection At	: Bike Production Pie Ltd (HQ) 610 SERANGOON ROAD Singapore 218216		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion, o/s body and n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,576.80 (inclusive supp)
Revised Amount	:S\$	4,629.30 (inclusive supp)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,629.30

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	9,500.00
COE / PARF Rebate	:S\$	6,189.00
Salvage Value	:S\$	
Margin for Repair	:S\$	3,311.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Supplementary amount is \$ 511.00



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52883356E GST Reg. No. 20-0406911-H



LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 11 Sep 2019

Preliminary Advice

Vehicle No	: FBM9403U	Accident Date	: 30/08/2019
Make	: HONDA CB150R	Policy No.	: 1900094558
Assignment Date	: 09/09/2019	Excess	: S\$0.00
Date of Inspection	: 09/09/2019	Est. Duration of Repair	: 2
Inspection At	: BIKE PRODUCTION PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion, o/s body and n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,910.80
Revised Amount	:S\$	3,821.30
Check Items (Estimated)	:S\$	333.00
Total	:S\$	4,154.30

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	9,500.00
COE / PARF Rebate	:S\$	6,189.00
Salvage Value	:S\$	
Margin for Repair	:S\$	3,311.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Repairer able to undertake the repair cost not exceeding \$ 3,300.00 on lump sum basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/09/2019 16:12
Date Of Accident	30/08/2019 09:05
Exact Location Of Accident	ALONG PIE TOWARDS BKE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBM9403U
Insured/Policyholder	
Name Of Registered Owner	MUHAMAD YUNUS BIN SHAMSUDIN
NRIC No	S9037759J
Email Address	FIEZARAHIM@GMAIL.COM
Mobile Phone No	(LOCAL) +65-87935484
Alternative Phone No	OFFICE-87935484

Vehicle Particulars

Manufacturer	HONDA
Model	CB150R

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	MOTORCYCLE
------------------	------------

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1900094558
Cover Note Number	

Driver

Name of Driver	MUHAMAD YUNUS BIN SHAMSUDIN
NRIC No	S9037759J
Date Of Birth	14/10/1990
Occupation	OUTDOOR
Date Of Driving Pass	11/06/2009
Driving Experience	10 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87935484
Fax Number	
Contact Number	OFFICE-87935484
Email Address	FIEZARAHIM@GMAIL.COM

Address	BLK 332 WOODLANDS AVE 1 #04-425
Postcode	730332
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	WOODLANDS WEST NPC
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	WSS3228
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	MUHAMAD YUNUS BIN SHAMSUDIN
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	FBM9403U
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

PLAN

Refers to police report attached.

I/We declare the foregoing particulars are true in every respect.

Driver's Signature _____
(If driver is not the policyholder)

3/9/17

Sketch Plan Pg. 2

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20190902/2159

Police Station Of Origin:
Woodlands West N.P.C.
1 Woodlands Street 12 SINGAPORE 738622
Tel No: 1800-363 9999

1 of 3

Report No. T/20190902/2159

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 02/09/2019 18:04	Vide Report No.:	Station Diary No.: 614
--	------------------	---------------------------

Informant's Particulars

Name of Informant: MUHAMAD YUNUS BIN SHAMSUDIN			Address: APT BLK 332 WOODLANDS AVENUE 1 #04-425 SINGAPORE 730332		
ID Type / ID No.: NRIC NO / S9037759J			Contact No.: Home/Office: Mobile: 87935484		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 28	Date of Birth: 14/10/1990	Type of Informant: Rider		
Race: Malay			Language:		Institution / School Name:
Occupation: PRODUCTION TECHNICIAN			Driving Licence Information: Class: 2B Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 30/08/2019 09:05	Type of Location: Bend
Location: Along Road 1 PAN ISLAND EXPRESSWAY PIE TOWARDS BKE				
Weather: Drizzling		Road Surface: Wet		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Moving Vehicle Against - Others				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBM9403U	Motorcycle	HONDA	CB150R MANUAL	Red	Slightly Damaged	0
WSS3228	Car				Slightly Damaged	2

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
FBM9403U	AIG ASIA PACIFIC INSURANCE PTE. LTD.	1900094558	28/05/2019	27/05/2020



**SINGAPORE
POLICE FORCE**



T/20190902/2159

2 of 3

Police Station Of Origin:
Woodlands West N.P.C.
1 Woodlands Street 12 SINGAPORE 738622
Tel No: 1800-363 9999

Report No. T/20190902/2159

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	MUHAMAD YUNUS BIN SHAMSUDIN	ID No.	S9037759J
Related Vehicle	FBM9403U (Motorcycle)	Contact No.	87935484
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B Date of Expiry: NIL
Date Treatment	30/08/2019	Date Discharge	30/08/2019
No. of Days granted Medical Leave	14	Degree of Injury	NIL

Brief Details.

On 30/08/2019 at around 0905hrs, I was riding along PIE towards BKE at the bend area, I noticed that there is a Malaysia car (WSS3228) hit onto the divider and had stopped at the most right lane. When I noticed the car, I tried to brake to avoid collision however ended up, I skidded and I was injured. Shortly after, there are police as well as ambulance came to the scene and I was then conveyed to Ng Teng Fong Hospital and subsequently, given 2 weeks of hospitalization leave from 30/08/2019 to 13/09/2019.

I wish to state that after I skidded and fell from my motorbike, the car (SLT2004D) which was behind me hit onto my motorbike however I believed is a slight collision.

The damages observed on my motorcycle is basically on the left side of my motorcycle. My left arm was fractured as well as some abrasion on my right arm.

BT/00



**SINGAPORE
POLICE FORCE**



T/20190902/2159

Police Station Of Origin:
Woodlands West N.P.C.
1 Woodlands Street 12 SINGAPORE 738622
Tel No: 1800-363 9999

3 of 3

Report No. T/20190902/2159

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

L /

Sgt 1 TEO KAI XUN

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

02/09/2019 18:04

Officer In Charge Of Case:

TP / GIT /

Sr Staff Sgt SHAHRUL NIZAM BIN SAMARRI

Contact No.: 65476904

Classification Of Case:

Authentication Stamp

NP158

03/09 2019 5:25PM FAX: 0650 975400

BIKE PRODUCTION PTE LTD

00001/0001

GX-00-10:10:17

BIKE PRODUCTIONS



CERTIFICATE OF INSURANCE

MOTORCYCLE AUTOVANTAGE MOTORCYCLE

Name of Policyholder : MUHAMMAD YUNUS BIN SHAMSUDIN
 Period of Insurance : 28 May 2019 To 27 May 2020
 Engine No. : K0321 0011394
 Chassis No. : MLJHK 2882J8011394

Vehicle No. : FBM9403U
 Policy No. : 1900094558
 Endorsement No. :
 Issued Date : 30 Apr 2019

ABOUT THE COVER

Make/Model : HONDA CB100H
 Engine Capacity/Tonnage : 149 CC
 Driver Restriction : Licensed Driver (Class)
 Person or Class of Persons Permitted to Drive* :
 a) The Policyholder
 b) Any person who is named as a "named driver" under this policy

Sum Insured : Market Value
 Off Peak Car : No

First Year of Registration : 2018
 Insuring with COE/PAF : Yes

Age Condition : Not Applicable

Limitation as to use* :

Use only for personal, domestic and pleasure purposes and for the Policyholder's business.

The Policy does not cover:

- 1) use for hire or reward;
- 2) use for racing, driving test, racing, speed testing, reliability trial or special events;
- 3) use for the carriage of goods (other than carrying in westernized vehicles used in business);
- 4) use for any purpose in watersheds or flood prone areas.

* Limitations imposed in respect of the Motor Vehicle (Third Party Risks and Compensation) Act (Cap. 169) and Section 90 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$300 Third - \$0

Section 2
 Property Damage - \$0

Windstorm : NA

Named Driver and Excess (where applicable)

MUHAMMAD YUNUS BIN SHAMSUDIN - \$300 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

Any accident reports to the Vehicle must be lodged with one of our Authorized Repairers. Within the first 3 years of the first registration of the Vehicle in Singapore, You have the option of having the accident repairs carried out at the Authorized Repairer. For other Approved Reporting Centres/Authorised Repairers, please contact our 24-hour accident emergency hotline at 6738 8300. Alternatively, You may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply scan the QR code with "AIG SG" from App Store or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Financier's Loan: BIKE PRODUCTION PTE LTD

We hereby certify that the policy as shown in Certificate of Insurance is issued in accordance with the provisions of the Motor Vehicle (Third Party Risks and Compensation) Act (Cap. 169), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1996 (Malaysia).

050058016

COWELL - BIKE PRODUCTION

8 BURN ROAD #05-03 TRIVEX

SINGAPORE 389977 ANGEL-NOVINS

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORIZED REPRESENTATIVE

Ty. Jai Lin

Addendum Sheet Pg. 1



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
 6 Raffles Quay #18-00 Singapore 048580
 Tel (65) 6224 0010 Fax (65) 6224 0030
 Operating Hours : Monday to Friday, 09:00 – 17:00
 UEN: S645300206 / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : UCP519116712 Vehicle Registration No: FBM9403U
 Name (as shown in NRIC) : Muhammad Yanus Bin Shamsudin NRIC/FIN/Passport No : S4037759J
 (*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
 Address : _____ Singapore ()
 Contact (Tel) : _____ Mobile No. : 87935484
 Email Address : _____
 Date of Accident : 30/8/2019 Time of Accident : 0905
 Place of Accident : Along PIE towards BKE
 Insurance Company : Ally Insurance.

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

DN 30/08/19 AT AROUND 0905HRS, I WAS RIDING ALONG PIE TOWARDS BKE AT
THE BEND AREA, I NOTICED THAT THERE IS A MULTISIAN CAR (WSS 5228) HIT ONTO
THE ^{DIVIDER} AND HAD STOPPED AT THE MOST RIGHT LANE. WHEN I NOTICE THE CAR, I
TRIED TO BRACE TO AVOID COLLISION HOWEVER ENDED UP, I SKIDDED AND I WAS INJURED
SHORTLY AFTER THERE ARE POLICE & AMBULANCE CAME TO SCENE & I WAS CONVEYED TO
BEG NQ TENG FONG HOSPITAL & I WAS GIVEN 2 WEEKS OF HOSPITALIZATION LEAVE.
I WISH TO STATE THAT AFTER I SKIDDED AND FELL, THE CAR (S4730010)
WHICH WAS BEHIND ME HIT ONTO MY MOTORCYCLE HOWEVER, BELIEVED IS A
SLIGHT COLLISION.

Policyholder / Driver's Signature
 Date: 12/9/19

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:
 Date:

BIKE PRODUCTION PTE LTD
 610, Serangoon Road S(218216)
 Tel: 63922555, 62995177 Fax: 62975400
 ROC/ GST Reg No.: 200007407G

Date: 3 Sept 2019

ASSESSMENT FOR REPAIR: HONDA CB150R MANUAL - FBM9403U

Chassis No.: MLHKC2882J5011304
 Engine No.: KC32ED011304

Qty	Description	Estimate
1 pc	STEERING CLAMP @ 1 ?	
1 pc	Front fender	\$180.00 / SC
1 pc	Front disk brake	\$190.00 X SW
1 pc	Front wheel axle	\$95.00 X SW
1 pc	Front left fork assy	\$480.00 X SW
1 pc	Front right fork assy	\$480.00 X SW
1 pc	Steering stem	\$220.00 X SW
1 pc	Steering bridge	\$195.00 X SW
2 pcs	Steering bearings	\$90.00 X SW
1 pc	Left balancer	\$30.00 / M13
1 pc	Right handle grips	\$40.00
1 pc	Right balancer	\$30.00 / M13
1 pc	Handle bar	\$175.00 / BT
1 pc	Head lamp bracket	\$195.00 / SC
1 pc	Head lamp assy	\$390.00 / SC
1 pc	Brake lever	\$55.00 / BT
1 pc	Fuel tank centre cover emblem	\$30.00 X SW (NEC)
1 pc	IU bracket	\$70.00 X SW (BT)
1 pc	Fuel tank center cover	\$195.00 X SW (SC)
1 pc	Fuel tank centre cover left emblem	\$29.00 X SW (NEC)
1 pc	Fuel tank centre cover right emblem	\$29.00 X SW (NEC)
1 pc	Left silver cover	\$175.00 / SC
1 pc	Left silver cover sticker	\$25.00 / NEC
1 pc	Meter assy	\$390.00 X SW
1 pc	Brake pedal	\$79.00 / BT
1 pc	Right front footrest	\$75.00 / BT
1 pc	Right front footrest holder	\$145.00 / BT
1 pc	Left front footrest	\$75.00 / BT
1 pc	Front left footrest holder	\$145.00 / BT
1 pc	Left rear footrest	\$75.00 X SW (SC)
1 pc	Left rear footrest holder	\$145.00 X SW
1 pc	Side stand	\$95.00 / SC
1 pc	Gear pedal assy	\$155.00 / BT
1 pc	Rear left signal	\$115.00 / SC
1 pc	Rear fender assembly	\$330.00 X SW ?
1 pc	Rear chain adjuster	\$40.00 X SW
1 pc	Rear wheel axle	\$95.00 / SC
1 pc	Exhaust comp	\$750.00 BT / SC
1	CHAIN GUARD	75 / SC
	Less discount 10%	\$6,107.00
		\$610.70
		\$5,496.30
Special nett items		
1 pc	ERP IU	\$157.00 / M13
1 pc	Front number plate	\$20.00 / BT
1 pc	Rear tyre	\$180.00 X SW (SC)
1)	Towing charges	\$100.00 / BT

- 2) Replace, realign and adjust above damaged parts, check wiring and lighting system
- 3) To knock, straighten chassis & body balancing
- 4) To remove/refit, replace (if damage) check and straighten front fork tubes.
- 4) To remove/refit, replace (if damage) check and straighten front sport rims.
- 6) Spray painting

Total Estimate

\$800.00 200
 \$380.00 - 600 X NN
 \$180.00 2.26 X NN
 \$150.00 X NN
 \$380.00 100
 \$7,843.30

Note: The above estimate is subjected to the prevailing GST of 7%

7910.80

NAZ LKX
 9/6/17 1700

L13

2 DAYS

~~CHUCK 1700 PHOTOS~~ CHUCK 1700 PHOTOS
 AFTER REPAIR PHOTOS



For Bike Production Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

BIKE PRODUCTION PTE LTD
 610, Serangoon Road S(218216)
 Tel: 63922555, 62995177 Fax: 62975400
ROC/ GST Reg No.: 200007407G

Date: 3 Sept 2019

ASSESSMENT FOR REPAIR: HONDA CB150R MANUAL - FBM9403U

Chassis No.: MLHKC2882J5011394
 Engine No.: KC32E0011394

Qty	Description	Estimate
> PLS	STEERING CLAMP @ # ?	
1 pc	Front fender	\$180.00 / SC
1 pc	Front disk brake	\$190.00 X SVL
1 pc	Front wheel axle	\$95.00 X SVL
1 pc	Front left fork assy	\$480.00 X SVL
1 pc	Front right fork assy	\$480.00 X SVL
1 pc	Steering stem	\$220.00 X SVL
1 pc	Steering bridge	\$195.00 X SVL
2 pcs	Steering bearings	\$90.00 X SVL
1 pc	Left balancer	\$30.00 / M13
1 pc	Right handle grips	\$40.00
1 pc	Right balancer	\$30.00 / M13
1 pc	Handle bar	\$175.00 / BT
1 pc	Head lamp bracket	\$195.00 / SC
1 pc	Head lamp assy	\$390.00 / SC
1 pc	Brake lever	\$55.00 / BT
1 pc	Fuel tank centre cover amblem	\$30.00 X BT / NEC
1 pc	IU bracket	\$70.00 X BT / BT
1 pc	Fuel tank center cover	\$195.00 X SVL / SC
1 pc	Fuel tank centre cover left amblem	\$29.00 / NEC
1 pc	Fuel tank centre cover right amblem	\$29.00 / NEC
1 pc	Left silver cover	\$175.00 / SC
1 pc	Left silver cover sticker	\$25.00 / NEC
1 pc	Meter assy	\$390.00 X SVL
1 pc	Brake pedal	\$79.00 / BT
1 pc	Right front footrest	\$75.00 / BT
1 pc	Right front footrest holder	\$145.00 / BT
1 pc	Left front footrest	\$75.00 / BT
1 pc	Front left footrest holder	\$145.00 / BT
1 pc	Left rear footrest	\$75.00 X SVL / SC
1 pc	Left rear footrest holder	\$145.00 X SVL
1 pc	Side stand	\$95.00 / SC
1 pc	Gear pedal assy	\$155.00 / BT
1 pc	Rear left signal	\$115.00 / SC
1 pc	Rear fender assembly	\$330.00 X SVL ?
1 pc	Rear chain adjuster	\$40.00 X SVL
1 pc	Rear wheel axle	\$95.00 / SC
1 pc	Exhaust comp	\$750.00 / SC
1	CHAIN GUARD	\$75.00 / SC
	Less discount 10%	\$6,107.00 \$610.70 \$5,496.30
	Special nett items	
1 pc	ERP IU	\$157.00 / BT w/ h/ky
1 pc	Front number plate	\$20.00 / BT
1 pc	Rear tyre	\$180.00 X SVL / SC
1)	Towing charges	\$100.00 / SC

- 2) Replace, realign and adjust above damaged parts, check wiring and lighting system
 - 3) To knock, straighten chassis & body balancing
 - 4) To remove/refit, replace (if damage) check and straighten front fork tubes.
 - 4) To remove/refit, replace (if damage) check and straighten front sport rims.
 - 6) Spray painting
- Total Estimate**

\$800.00 200
 \$380.00 100 XNN
 \$180.00 100 XNN
 \$150.00 XNN
 \$380.00 100
\$7,843.30

Note: The above estimate is subjected to the prevailing GST of 7%

7910.80



For Bike Production Pte Ltd

NAZ LICK
 9/9/19 1700
 LIS

2 DAYS

~~CHECK ITEMS PHOTOS~~ CHECK (ITEMS PHOTOS)
 AFTER REPAIR PHOTOS

consultants hence notify
 of the following:
 before/after spray painting
 any damaged part(s) during resurvey
 prices are subject to confirmation
 any survey is on a "Without Prejudice" basis
 any modification(s) is allowed
 any item(s) must be resurveyed and
 subject to final approval from Insurance Company

acknowledged by Reparer

signature:

Date:

BIKE PRODUCTION PTE LTD
 610, Serangoon Road S(218216)
 Tel: 63922555, 62995177 Fax: 62975400
 ROC/ GST Reg No.: 200007407G

Date: 3 Sept 2019

ASSESSMENT FOR REPAIR: HONDA CB150R MANUAL - FBM9403U

Chassis No.: MLHKC2882J5011394

Engine No.: KC32E0011394


Qty	Description	Estimate
> PLS	• STEERING CLAMP @ 150X	
1 pc	Front fender	\$180.00 / SCL
1 pc	Front disk brake	\$190.00 X SCL
1 pc	Front wheel axle	\$95.00 X SCL
1 pc	Front left fork assy	\$480.00 X SCL
1 pc	Front right fork assy	\$480.00 X SCL
1 pc	Steering stem	\$220.00 X SCL
1 pc	Steering bridge	\$195.00 X SCL
2 pcs	Steering bearings	\$90.00 X SCL
1 pc	Left balancer	\$30.00 / M13
1 pc	• Right handle grips X SCL	\$40.00
1 pc	Right balancer	\$30.00 / M13
1 pc	Handle bar	\$175.00 / BT
1 pc	Head lamp bracket	\$195.00 / SCL
1 pc	Head lamp assy	\$390.00 / SCL
1 pc	Brake lever	\$55.00 / BT
1 pc	Fuel tank centre cover ambler	\$30.00 X BT / NEC
1 pc	IU bracket	\$70.00 X BT / BT
1 pc	Fuel tank center cover	\$195.00 X BT / SCL
1 pc	Fuel tank centre cover left ambler	\$29.00 X BT / NEC
1 pc	Fuel tank centre cover right ambler	\$29.00 X BT / NEC
1 pc	Left silver cover	\$175.00 / SCL
1 pc	Left silver cover sticker	\$25.00 / NEC
1 pc	Meter assy	\$390.00 X SCL
1 pc	Brake pedal	\$79.00 / BT
1 pc	Right front footrest	\$75.00 / BT
1 pc	Right front footrest holder	\$145.00 / BT
1 pc	Left front footrest	\$75.00 / BT
1 pc	Front left footrest holder	\$145.00 / BT
1 pc	Left rear footrest	\$75.00 X BT / SCL
1 pc	Left rear footrest holder	\$145.00 X SCL
1 pc	Side stand	\$95.00 / SCL
1 pc	Gear pedal assy	\$155.00 / BT
1 pc	Rear left signal	\$115.00 / SCL
1 pc	• Rear fender assembly	\$330.00 X BT / BT
1 pc	Rear chain adjuster	\$40.00 X SCL
1 pc	Rear wheel axle	\$95.00 / SCL
1 pc	Exhaust comp	\$750.00 X SCL
1	CHAIN GUARD	75 X SCL 4007
	Less discount 10%	\$6,107.00 \$610.70 \$5,496.30
	Special nett items	
1 pc	ERP IU	\$157.00 / BT
1 pc	Front number plate	\$20.00 / BT
1 pc	Rear tyre X	\$180.00 X SCL
1)	Towing charges	\$100.00 / SCL

- 2)
- 3)
- 4)
- 4)
- 6)

Repair Radiator
 Replace, realign and adjust above
 damaged parts, check wiring and
 lighting system ~~Repair Exhaust~~ \$2007/190
 To knock, straighten chassis & body
 balancing
 To remove/refit, replace (if damage) check and
 straighten front fork tubes.
 To remove/refit, replace (if damage) check and
 straighten front sport rims.
 Spray painting
Total Estimate

\$250 ✓A
~~\$800.00~~
~~\$380.00~~ XNN
~~\$180.00~~ XNN
~~\$150.00~~ XNN
~~\$380.00~~ 100
~~\$7,843.30~~
 8576.30
 4289.3
 X0.8

Note: The above estimate is subjected to the prevailing GST of 7%



For Bike Production Pte Ltd

NAZ LICK
 9/9/19 1700
 LIS
 2 DAYS

~~CHECK ITEMS PHOTOS~~ CITECK (ITEMS PHOTOS)
 AFTER REPAIR PHOTOS

[Signature]
 19/9/19

3431.44
 B4
 SUPPL
 164 300
 EXCESS
 1547
 INCREASE
 UNCONFIRMED

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

8876.00

BIKE PRODUCTION PTE LTD

610, Serangoon Road S(218216)

BIKE PRODUCTION PTE LTD

610, Serangoon Road S(218216)

Tel: 63922555, 62995177 Fax: 62975400

ROC/ GST Reg No.: 200007407G

Date: 3 Sept 2019

ASSESSMENT FOR REPAIR: HONDA CB150R MANUAL - FBM9403U

Chassis No.: MLHKC2882J5011394

Engine No.: KC32E0011394

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Radiator assembly	\$490.00
		\$490.00
	Less discount 10%	\$49.00
		\$441.00
1)	Additional labour	\$70.00
		\$511.00

Note: The above estimate is subjected to the prevailing GST of 7%

SPECIAL NETT

COOLANT

20 / NEC.



For Bike Production Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

19/9/19

Muhamad Yunus Bin Shamsudin
Blk 332 Woodlands Avenue 1
#04-425
Singapore 730332

Date: 3 Sept 2019

To: Mr Kwan Say Hwee
Bike Production Pte Ltd
610, Serangoon Road
Singapore 218216

Dear Sir,


**RE: LETTER OF UNDERTAKING FOR LUMP SUM REPAIR UNDER VEHICLE
NO.: FBM9403U**

I, Muhamad Yunus Bin Shamsudin, NRIC No.: 759J, authorise Bike Production Pte Ltd to repair my motorcycle, Honda CB150R Manual – FBM9403U back to road worthy condition on a lump sum basis.

I understand and acknowledge that a lump sum repair takes into consideration repairs and/or replacements with the use of reconditioned and ex-stock parts wherever possible.

Thank you very much for your attention.

Yours faithfully,



Muhamad Yunus Bin Shamsudin

Muhamad Yunus Bin Shamsudin
Blk 332 Woodlands Avenue 1
#04-425
Singapore 730332

Date: 21 Sept 2019

To: Mr Kwan Say Hwee
Bike Production Pte Ltd
610, Serangoon Road
Singapore 218216

Dear Sir,

**RE: AKNOWLEDGEMENT OF THE ACCIDENT REPAIR AND COLLECTION
OF HONDA CB150R MANUAL VEHICLE NO.: FBM9403U**

I, Muhamad Yunus Bin Shamsudin, NRIC No.: 759J, have inspected the repair done by Bike Production Pte Ltd and the repair is in accordance to the repair quotation and/or surveyor report.

I have collected the above mentioned vehicle on 21/09/19 at 4:30 p.m.

Thank you very much for your attention.

Yours faithfully,


Muhamad Yunus Bin Shamsudin

BIKE PRODUCTION PTE. LTD.

610, Serangoon Road Singapore 218216
Tel: 6392 2555 Fax: 6297 5400

TAX INVOICE

Co. Registration No. 200007407G
GST Reg. No: 200007407G
GST Inclusive

No: 6107

Name : ANG ASIA PACIFIC INSURANCE PTE LTD Date : 24/9/2019
Address : 78 SHENTON WAY #07-16 ANG BUILDING SE 079120
I/C No : _____ Occupation : _____ DOB : _____
Tel : (H) 61493000 (F) 64153723 Driving Licence : _____

Particulars		Amount
Reg. No : <u>FBM9403U</u>	Selling Price	\$2,942.50
Make & Model : <u>HONDA CB150R MANUAL</u>	+ Insurance	\$ 0
Engine No : <u>KC32E0011394</u>	+ Retention	\$ 0
Chassis No : <u>MLH KC 2882 J 5011394</u>	TOTAL PRICE	\$2,942.50
Insurance Type: <input type="checkbox"/> Comprehensive <input type="checkbox"/> Third-Party Fire Theft <input type="checkbox"/> Third-Party Only		
Colour : <u>RED</u>	LUMP SUM REPAIRS Downpayment	\$ 3,050.00
	LESS EXCESS	\$ 300.00
Loan Amount _____	Interest rates _____ p.a.	\$ 2,750.00
Terms : (_____	Monthly Instalments of \$ <u>GST 7%</u>)	192.50
N/R : _____	TEL : _____	\$2,942.50
GTR : _____	TEL : _____	
COE NO : _____	TR	

Note:

- Above prices do not include ERP IU.
- Deposit is not refundable.
- Balance amount must be cleared within 3 days of the invoice date. Deposit will be forfeited if the buyer fails to clear the full balance amount within the stated period.
- Title to the above-mentioned goods will not be handed to the buyer until the full amount and/or changes are paid
- All cheque payments are to be crossed and made payable to **Bike Production Pte Ltd**. If cheque dishonoured, the buyer has to pay **Bike Production Pte Ltd** by cash and a service charge of S\$30.00 plus prevailing GST.
- Bike Production Pte Ltd** will have fullrights to repossess the above-mentioned goods without notice in case of default in payment.
- The buyer shall inspect the above-mentioned goods immediately on notification that goods are due and ready for collection. The buyer shall give notice in writing to the seller of any matter or thing by reason whereof he alleges that the goods are not in acceptable conditions. If the buyer fails to give notice, the above-mentioned goods shall be deemed to be in accordance with the contract and the buyer shall be bound to accept and pay for the same accordingly.
- For hire purchase, no alteration of the hire-purchase agreement and its terms, including down payment and installment period, is allowed once the hire-purchase agreement is made. In the event of cancellation, the buyer shall compensate **Bike Production Pte Ltd** 20% of the total price plus prevailing GST and the deposit shall be forfeited.
- For hire purchase, a Singaporean guarantor between 21 year & 60 year of age and with a different residential address from the buyer is required before the collection of the above-mentioned goods. The guarantor shall not be an undischarged bankrupt and is subject to financial approval.
- I confirm that the information I have provided is my personal data and, where it is not my personal data, that I have the consent of the owner of such personal data to provide such information. By providing this information I understand and give my consent for **Bike Production Pte Ltd** to collect, use, store, transfer and / or disclose personal data about me or us and those whose personal data I or we have provided from sources other than myself or us for the purposes.

For **Bike Production Pte Ltd**

I accept the above terms and conditions

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Sep 2019		09 Sep 2019 15:59 Edit Adj Rpt	S\$3,050.00 Edit Estimates	S\$3,050.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	MUHAMAD YUNUS BIN SHAMSUDIN, ID: S9037759, Tel: +6587935484, Email: FIEZARAHIM@GMAIL.COM	
Vehicle Reg. No.:	FBM9403U	Date of Loss: 30/08/2019 09:00 - :59 [15 Months and 6 Days From LTA Reg Date (Man Yr)]
Claims Type:	OD / 9899201255SG	Policy/Cover Note No.: 1900094558 (Comprehensive)
		Excess: S\$300.00
Repairer:	Bike Production Pie Ltd (HQ) 610 SERANGOON ROAD, 218216 Serangoon - Tel: 63922555	
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Gan, Hunchung] Hunchung.Gan@aig.com	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 18/09/2019]	
Driver/Custodian:	MUHAMAD YUNUS BIN SHAMSUDIN (28 / Male), NRIC: S9037759, Tel: +6587935484 Email: FIEZARAHIM@GMAIL.COM	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
<ul style="list-style-type: none"> AIG_SG (19/09/2019): Alert - Adj Mandate Approved (S\$4459.30) - FBM9403U - Claim Handler: Gan, Hunchu... AIG_SG (16/09/2019): Alert - Adj Mandate Maintained - FBM9403U - Claim Handler: Gan, Hunchung AIG_SG (12/09/2019): Alert - Adj Mandate Approved (S\$3300.00) - FBM9403U - Claim Handler: Gan, Hunchu... AIG_SG (12/09/2019): FBM9403U / OD / 30/08/2019 / Coverage & Excess update 		

ALL ASSOCIATED TASKS		View All	Search Tasks	Create New Task	Complete				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBM9403U (9899201255SG)
OD
Aug 30 2019 9:05AM
[MUHAMAD YUNUS BIN SHAMSUDIN]
Bike Production Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

Upload Video

Upload Audio

View

View in Browser

1 per page

Assessment Reports

No

Finalized On

LKK Auto Consultants Pte Ltd (HQ)

Thumbnail

Print

1

12/09/19 10:49

Adjuster Immediate Advice

Load HTM

2

16/09/19 15:57

Adjuster Immediate Advice

Load HTM

3

19/09/19 14:02

Adjuster Immediate Advice

Load HTM

3 per page

Photos/Images

No

Relabel/Reorder

LKK Auto Consultants Pte Ltd (HQ)

Thumbnail

Print

1

12/09/19 12:32

General View

Load JPG

2

12/09/19 12:32

General View

Load JPG

3

12/09/19 12:32

General View

Load JPG

4

12/09/19 12:32

General View

Load JPG

5

12/09/19 12:32

General View

Load JPG

6

12/09/19 12:32

General View

Load JPG

7

12/09/19 12:32

General View

Load JPG

8

12/09/19 12:32

General View

Load JPG

9

12/09/19 12:32

General View

Load JPG

10

12/09/19 12:32

General View

Load JPG

11

12/09/19 12:32

General View

Load JPG

12

12/09/19 12:32

General View

Load JPG

13

12/09/19 12:32

General View

Load JPG

14

12/09/19 12:32

General View

Load JPG

15

12/09/19 12:32

General View

Load JPG

16

12/09/19 12:32

General View

Load JPG

17

12/09/19 12:32

General View

Load JPG

18

12/09/19 12:32

General View

Load JPG

19

12/09/19 12:32

General View

Load JPG

20

12/09/19 12:32

General View

Load JPG

21

12/09/19 12:32

General View

Load JPG

22

12/09/19 12:32

General View

Load JPG

23

12/09/19 12:32

General View

Load JPG

24

12/09/19 12:32

General View

Load JPG

25

12/09/19 12:32

General View

Load JPG

26

12/09/19 12:32

General View

Load JPG

27

12/09/19 12:32

General View

Load JPG

28

12/09/19 12:32

General View

Load JPG

29

12/09/19 12:32

General View

Load JPG

30

12/09/19 12:32

General View

Load JPG

31

12/09/19 12:32

General View

Load JPG

32

12/09/19 12:32

General View

Load JPG

33

12/09/19 12:32

General View

Load JPG

34

12/09/19 12:32

General View

Load JPG

35

12/09/19 12:32

General View

Load JPG

36

12/09/19 12:32

General View

Load JPG

37

12/09/19 12:32

General View

Load JPG

38

12/09/19 12:32

General View

Load JPG

39

12/09/19 12:32

General View

Load JPG

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
40	12/09/19 12:32	General View		Load JPG	<input checked="" type="checkbox"/>
41	12/09/19 12:32	General View		Load JPG	<input checked="" type="checkbox"/>
42	12/09/19 12:32	General View		Load JPG	<input checked="" type="checkbox"/>
43	12/09/19 12:32	General View		Load JPG	<input checked="" type="checkbox"/>
44	12/09/19 12:32	General View		Load JPG	<input checked="" type="checkbox"/>
45	12/09/19 12:32	General View		Load JPG	<input checked="" type="checkbox"/>
46	12/09/19 12:32	General View		Load JPG	<input checked="" type="checkbox"/>
47	12/09/19 12:32	General View		Load JPG	<input checked="" type="checkbox"/>
48	12/09/19 12:32	General View		Load JPG	<input checked="" type="checkbox"/>
49	12/09/19 12:32	General View		Load JPG	<input checked="" type="checkbox"/>
50	12/09/19 12:32	General View		Load JPG	<input checked="" type="checkbox"/>
51	12/09/19 12:32	General View		Load JPG	<input checked="" type="checkbox"/>
52	12/09/19 12:32	General View		Load JPG	<input checked="" type="checkbox"/>
53	12/09/19 12:32	General View		Load JPG	<input checked="" type="checkbox"/>
54	12/09/19 12:32	General View		Load JPG	<input checked="" type="checkbox"/>
55	12/09/19 12:32	General View		Load JPG	<input checked="" type="checkbox"/>
56	12/09/19 12:32	General View		Load JPG	<input checked="" type="checkbox"/>
57	12/09/19 12:32	General View		Load JPG	<input checked="" type="checkbox"/>
58	12/09/19 12:32	General View		Load JPG	<input checked="" type="checkbox"/>
59	16/09/19 15:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
60	16/09/19 15:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
61	16/09/19 15:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
62	16/09/19 15:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
63	16/09/19 15:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
64	16/09/19 15:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
65	16/09/19 15:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
66	16/09/19 15:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
67	16/09/19 15:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
68	16/09/19 15:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
69	19/09/19 13:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
70	19/09/19 13:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
71	19/09/19 13:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
72	19/09/19 13:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
73	19/09/19 13:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
74	19/09/19 13:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
75	19/09/19 13:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
76	19/09/19 13:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
77	19/09/19 13:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
78	19/09/19 13:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
79	24/09/19 09:48	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
80	24/09/19 09:48	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
81	24/09/19 09:48	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
82	24/09/19 09:48	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
83	24/09/19 09:48	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
84	24/09/19 09:48	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
85	24/09/19 09:48	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
86	24/09/19 09:48	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
87	24/09/19 09:48	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
88	24/09/19 09:48	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
89	24/09/19 09:48	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
90	24/09/19 09:48	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	11/09/19 12:57	Singapore Accident Statement		Load PDF	
2	11/09/19 12:58	Police Report		Load PDF	
3	11/09/19 12:58	Certificate of Insurance		Load PDF	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
4	11/09/19 12:58	MARK ESTIMATE		Load PDF
5	12/09/19 10:48	DRIVING.pdf		Load PDF
6	16/09/19 15:58	ESTIMATE & SUPP MARKED.pdf		Load PDF
7	24/09/19 09:47	ESTIMATE & SUPP MARKED 1.pdf		Load PDF
8	24/09/19 09:58	LUMP SUM LETTER.pdf		Load PDF
9	03/10/19 11:19	Workshop Invoice		Load PDF
10	03/10/19 11:19	Discharge Voucher		Load PDF

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	06/09/19 16:16	Accident Statement		Load HTM
2	12/09/19 16:30	Addendum Sheet		Load TIF
3	12/09/19 16:33	Accident Statement Addm. #1		Load HTM

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	06/09/19 16:13	Accident Photo		Load JPG <input checked="" type="checkbox"/>
2	06/09/19 16:13	Accident Photo		Load JPG <input checked="" type="checkbox"/>
3	06/09/19 16:13	Accident Photo		Load JPG <input checked="" type="checkbox"/>
4	06/09/19 16:13	Accident Photo		Load JPG <input checked="" type="checkbox"/>
5	06/09/19 16:13	Accident Photo		Load JPG <input checked="" type="checkbox"/>
6	06/09/19 16:13	Accident Photo		Load JPG <input checked="" type="checkbox"/>
7	06/09/19 16:13	Accident Photo		Load JPG <input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	06/09/19 16:15	Sketch Plan		Load TIF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CS/AIG19015923/NSD3E2

Date: 03/10/2019

REFERENCE

Insured/Claimant: MUHAMAD YUNUS BIN SHAMSUDIN

Policy No: 1900094558

Date of Loss: 30/08/2019

Nature of Claim: OD

Claim No: 9899201255SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBM9403U

Make & Model: HONDA CB150R, 149cc

Engine No: KC32E0011394

Reg. Date: 24/05/2018 (Man. Year: 2017)

Chassis No: MLHKC2882J5011394

Colour: Red

Odometer: 39177 km

Engine Capacity: 149 cc

Market Value/New Car Price: S\$9,500.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/70 R17

Rear Tyre Size: 150/60 R17

Front Left Side: ROSSO 5 mm

Rear Left Side: ROSSO 5 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,516.80	2,957.30	3,559.50	54.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,310.00	870.00	1,440.00	62.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,826.80	3,827.30	4,999.50	56.64
Approved Total (Overridden) (S\$)		3,050.00		
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	8,526.80	2,750.00	5,776.80	67.75
+ GST 7.00/7.00% (S\$)	596.88	192.50	404.38	67.75
Nett Amount (S\$)	9,123.68	2,942.50	6,181.18	67.75

INSPECTION

Date of Assignment: 09/09/2019

Date Inspected: 09/09/2019 Inspected At:

Bike Production Pte Ltd (HQ)
610 SERANGOON ROAD
Singapore 218216

Estimated Period of Repair: 2.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*STEERING CLAMP	Serviceable	150.00 FL	*- FL
2	1		*FRONT FENDER	Scratched	180.00 FL	*180.00 FL
3	1		*FRONT DISK BRAKE	Serviceable	190.00 FL	*- FL
4	1		*FRONT WHEEL AXLE	Serviceable	95.00 FL	*- FL
5	1		*FRONT LEFT FORK ASSY	Serviceable	480.00 FL	*- FL
6	1		*FRONT RIGHT FORK ASSY	Serviceable	480.00 FL	*- FL
7	1		*STEERING STEM	Serviceable	220.00 FL	*- FL
8	1		*STEERING BRIDGE	Serviceable	195.00 FL	*- FL
9	2		*STEERING BEARINGS	Serviceable	90.00 FL	*- FL
10	1		*LEFT BALANCER	Missing	30.00 FL	*30.00 FL
11	1		*RIGHT HANDLE GRIPS	Serviceable	40.00 FL	*- FL
12	1		*RIGHT BALANCER	Missing	30.00 FL	*30.00 FL
13	1		*HANDLE BAR	Bent	175.00 FL	*175.00 FL
14	1		*HEAD LAMP BRACKET	Scratched	195.00 FL	*195.00 FL
15	1		*HEAD LAMP ASSY	Scratched	390.00 FL	*390.00 FL
16	1		*BRAKE LEVER	Bent	55.00 FL	*55.00 FL
17	1		*FUEL TANK CENTRE COVER EMBLEM	Necessary	30.00 FL	*30.00 FL
18	1		*IU BRACKET	Bent	70.00 FL	*70.00 FL
19	1		*FUEL TANK CENTER COVER	Scratched	195.00 FL	*195.00 FL
20	1		*FUEL TANK CENTRE COVER LEFT EMBLEM	Necessary	29.00 FL	*29.00 FL
21	1		*FUEL TANK CENTRE COVER RIGHT EMBLEM	Necessary	29.00 FL	*29.00 FL
22	1		*LEFT SILVER COVER	Scratched	175.00 FL	*175.00 FL
23	1		*LEFT SILVER COVER STICKER	Necessary	25.00 FL	*25.00 FL
24	1		*METER ASSY	Serviceable	390.00 FL	*- FL
25	1		*BRAKE PEDAL	Bent	79.00 FL	*79.00 FL
26	1		*RIGHT FRONT FOOTREST	Bent	75.00 FL	*75.00 FL
27	1		*RIGHT FRONT FOOTREST HOLDER	Bent	145.00 FL	*145.00 FL
28	1		*LEFT FRONT FOOTREST	Bent	75.00 FL	*75.00 FL
29	1		*FRONT LEFT FOOTREST HOLDER	Bent	145.00 FL	*145.00 FL
30	1		*LEFT REAR FOOTREST	Scratched	75.00 FL	*75.00 FL
31	1		*SIDE STAND	Scratched	95.00 FL	*95.00 FL
32	1		*GEAR PEDAL ASSY	Bent	155.00 FL	*155.00 FL
33	1		*REAR LEFT SIGNAL	Scratched	115.00 FL	*115.00 FL
34	1		*REAR FENDER ASSEMBLY	Bent	330.00 FL	*330.00 FL
35	1		*REAR CHAIN ADJUSTER	Serviceable	40.00 FL	*- FL
36	1		*REAR WHEEL AXLE	Scratched	95.00 FL	*95.00 FL
37	1		*EXHAUST COMP	Serviceable	750.00 FL	*- FL
38	1		*CHAIN GUARD	Scratched	75.00 FL	*75.00 FL
39	1		*ERP IU	Not Working	157.00 FS	*157.00 FS
40	1		*REAR NUMBER PLATE	Bent	20.00 FS	*20.00 FS
41	1		*REAR TYRE	Serviceable	180.00 FS	*- FS
42	1		*RADIATOR ASSEMBLY	Repair	490.00 FL	*- FL
43	1		*COOLANT	Necessary	20.00 FS	*20.00 FS
44	1		*LEFT REAR FOOTREST HOLDER	Serviceable	145.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,199.00	3,264.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	682.20	306.70
Total Parts (\$\$)	6,516.80	2,957.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPAIR RADIATOR	New	250.00	250.00
2	REPLACE, REALIGN AND ADJUST ABOVE DAMAGED PARTS, CHECK WIRING AND LIGHTING SYSTEM	New	800.00	390.00
3	TO KNOCK, STRAIGHTEN CHASSIS & BODY BALANCING	New	380.00	0.00
4	TO REMOVE / REFIT, REPLACE (IF DAMAGE) CHECK AND STRAIGHTEN FRONT FORK TUBES	New	180.00	0.00
5	TO REMOVE / REFIT, REPLACE (IF DAMAGE) CHECK AND STRAIGHTEN FRONT SPORT RIMS	New	150.00	0.00
6	SPRAY PAINTING	New	380.00	100.00
7	ADDITIONAL LABOUR	New	70.00	50.00
8	TOWING CHARGES	New	100.00	80.00
Gross Labour Cost (S\$)			2,310.00	870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >