## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd. From

AIG Building

78 Shenton Way #08-16 Singapore 079120 From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25

Paya Ubi Industrial Park Singapore 408933

Attn: Gan, Hunchung Date: 19 Sep 2019

# **Preliminary Advice**

Vehicle No : FBM9403U **Accident Date** : 30/08/2019 Make : HONDA CB150R Policy No. : 1900094558 **Assignment Date** : 09/09/2019 **Excess** : S\$300.00 Date of Inspection : 09/09/2019 Est. Duration of Repair : 2 days

Inspection At : Bike Production Pie Ltd (HQ) 610 SERANGOON ROAD

Singapore 218216

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion, o/s body and n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,576.80 (inclusive supp)
Revised Amount	:S\$	4,459.30 (inclusive supp)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,459.30

Lump Sum Repair :S\$

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	9,500.00
COE / PARF Rebate	:S\$	6,189.00
Salvage Value	:S\$	
	•	

Margin for Repair :S\$ 3,311.00

#### Remarks

( X )	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
	Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: Supplementary amount is \$511.00