

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building  
78 Shenton Way #08-16  
Singapore 079120

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 11 Sep 2019

**Preliminary Advice**

Vehicle No	: FBM9403U	Accident Date	: 30/08/2019
Make	: HONDA CB150R	Policy No.	: 1900094558
Assignment Date	: 09/09/2019	Excess	: S\$0.00
Date of Inspection	: 09/09/2019	Est. Duration of Repair	: 2
Inspection At	: BIKE PRODUCTION PTE LTD		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion,o/s body and n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,910.80
Revised Amount	:S\$	3,821.30
Check Items (Estimated)	:S\$	333.00
Total	:S\$	4,154.30
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	9,500.00
COE / PARF Rebate	:S\$	6,189.00
Salvage Value	:S\$	
Margin for Repair	:S\$	3,311.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.  
Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Repairer able to undertake the repair cost not exceeding \$ 3,300.00 on lump sum basis.