

Auto Services Pte Ltd

100 Kio Street 63 Singapore 569111

6257 6666 Fax No. : 6257 1330

ST Reg. No. 201019626G

545T

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

06 SEP 2019

561.7+
411.9+
547.8+
1,677.2+
277.7+
82.4+
95.8+
313.1+
745.8=
4,713.4*

4,713.4x
90. %
4,242.06*

0. c

PART

- 1 1 BUMPER COVER REAR
- 2 1 BUMPER LOWER REAR
- 3 1 BUMPER BRACKET CTR REAR
- 4 1 BUMPER BRACKET SIDE RH REAR
- 5 1 BUMPER RETAINER RH REAR
- 6 1 BUMPER REFLECTOR RH
- 7 1 BUMPER BRACKET SIDE LH REAR
- 8 1 BUMPER RETAINER LH REAR
- 9 1 BUMPER REFLECTOR LH
- 10 1 BUMPER BEAM REAR
- 11 1 BUMPER BEAM BRACKET LH REAR
- 12 1 BUMPER BEAM BRACKET RH REAR
- 13 1 BOOT REAR
- 14 1 BOOT FINISHER
- 15 1 BOOT WHEATERSTRIP
- 16 1 BOOT REFLECTOR LAMP LH
- 17 1 BOOT REFLECTOR LAMP RH
- 18 1 BOOT BADGE 'RENAULT'
- 19 1 BOOT BADGE
- 20 1 BOOT STRUT LH
- 21 1 BOOT STRUT RH
- 22 1 BOOT HINGE LH
- 23 1 BOOT HINGE RH
- 24
- 25
- 26
- 27
- 28
- 29

66. +

33. +

66. +

30. +

30. +

5. +

40. =

270. *

0. c

660. +

660. +

60. +

60. +

60. +

60. +

20. =

1,580. *

0. c

4,242.06 +

270. +

1,580. =

6,092.06 *

6,092.06 x

80. %

4,873.648 *

0. c

4/5 4,850. $\diamond$
 $\diamond$