

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 545T**AAD1909-045***Not Authored
C/Sing & 48506*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

06 SEP 2019

SHF 545T

VF1ABL15AUC278386

RENAULT

LATITUDE

5.9.19

CHINA TAIPING

13/6/2014

		PART		LIST	
1	1	BUMPER COVER REAR	\$	Bu 561.70	✓
2	1	BUMPER LOWER REAR	\$	paid 1 411.90	✓
3	1	BUMPER BRACKET CTR REAR	\$	SL 98.10	} X
4	1	BUMPER BRACKET SIDE RH REAR	\$	SL 82.10	
5	1	BUMPER RETAINER RH REAR	\$	SL 59.80	
6	1	BUMPER REFLECTOR RH	\$	SL 16.60	
7	1	BUMPER BRACKET SIDE LH REAR	\$	SL 80.80	
8	1	BUMPER RETAINER LH REAR	\$	SL 54.20	} X
9	1	BUMPER REFLECTOR LH	\$	SL 16.60	
10	1	BUMPER BEAM REAR	\$	Bu 547.80	✓
11	1	BUMPER BEAM BRACKET LH REAR	\$	R 114.50	X
12	1	BUMPER BEAM BRACKET RH REAR	\$	R 100.90	X
13	1	BOOT REAR	\$	Bu 1,677.20	✓
14	1	BOOT FINISHER	\$	SL 344.70	X
15	1	BOOT WHEATERSTRIP	\$	SL 178.20	X
16	1	BOOT REFLECTOR LAMP LH	\$	CM 277.70	✓
17	1	BOOT REFLECTOR LAMP RH	\$	SL 277.70	X
18	1	BOOT BADGE 'RENAULT'	\$	Ru 82.40	✓
19	1	BOOT BADGE	\$	Ru 95.80	✓
20	1	BOOT STRUT LH	\$	SL 145.10	} X
21	1	BOOT STRUT RH	\$	SL 145.10	
22	1	BOOT HINGE LH	\$	R 254.20	
23	1	BOOT HINGE RH	\$	R 253.80	
24	1	BOOT INNER TRIM BOARD	\$	SL 611.00	
25	1	BOOT SWITCH	\$	SL 113.00	
26	1	BOOT LOCK	\$	R 246.60	
27	1	BOOT LOCK CATCH	\$	R 41.70	} X
28	2	LICENCE PLATE LAMP	\$	SL 26.30	
29	2	BOOT RUBBER PLUG	\$	SL 139.30	

Trans-cab Auto Services Pte Ltd**AAD1909-045**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 545T

30	1	TAILLAMP RH	\$	Sn	313.10	X
31	1	TAILLAMP PANEL RH	\$	n	401.40	X
32	1	TAILLAMP LH	\$	ngcm	401.40	✓ 313.10
33	1	TAILLAMP PANEL LH	\$	n	401.40	X
34	1	OUTER PANEL REAR (End Panel)	\$	B	745.80	✓
35	1	OUTER PANEL REAR (End Panel)TRIM	\$	Sn	404.56	X
36	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	n	1,229.40	X
37	1	SPARE WHEEL PANEL TRIM	\$	Sn	612.21	X
38	1	EXHAUST REAR	\$	n	5,263.60	X
39	1	EXHAUST CAP REAR	\$	n	125.40	X
TOTAL			\$		16,953.07	
10%			\$		1,695.31	
			\$		15,257.76	

Special Nett

1	1SET	PARKING AID	\$	Sn	700.00	X
2	1SET	REAR BUMPER CLIP	\$	n	66.00	✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	n	33.00	✓
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	n	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	n	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	n	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	n	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	n	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	n	66.00	✓
10	1	EXHAUST MOUNTING REAR	\$	Sn	16.00	X
11	1SET	BOOT FINISHER CLIP	\$	n	24.20	X
12	1	BOOT STICKER "Trans-cab"	\$	n	30.00	✓
13	1	BOOT STICKER "6555-3333"	\$	n	30.00	✓
14	1	BOOT INNER TRIM CLIP	\$	n	45.00	X
15	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	Sn	385.00	X
16	1	SPARE TYRE	\$	Sn	330.00	X
17	1	TAILLAMP CLIP RH	\$	n	5.00	X
18	2	REAR WINDSCREEN SEALANT	\$	n	80.00	X
19	1	WINDSCREEN MOULDING	\$	n	100.00	X
20	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	n	100.00	X
21	1	TAILLAMP CLIP LH	\$	n	5.00	✓
22	1	Rear Bumper Protector	\$	n	100.00	✓
TOTAL			\$		2,197.20	

Trans-cab Auto Services Pte Ltd**AAD1909-045**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 545T**TOTAL PARTS** \$ **17,454.96****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	7,500.00	6601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	7,500.00	6601
To supply and re-do rear luggage floor panel insulation padding.	\$	nn 380.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	601
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	X
To Rust-Proofing Of The Affected Areas.	\$	170.00	601
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To repair and realign rear exhaust pipe.	\$	nn 170.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	nn 170.00	X

Trans-cab Auto Services Pte Ltd**AAD1909-045**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 545T

To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	~ 380.00	X
To reinstall rear bumper parking sensor.	\$	170.00	601
To Check Electrical Lighting Concerned.	\$	170.00	201
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	~ 380.00	X
TOTAL	\$	18,440.00	
Over All Total	\$	35,894.96	

(LUMP SUM) Repair Days**25 DAYS**

5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: