

ASS. REC. BY:

REF:

CS/SMO19015941/RIT#302

Special Instruction:

Surveyor: RASUASSIGNMENT (Office)From (Person): Gnoh Pau Loong of SMO Date/Time: 09/09/2019

Estimated Cost: _____ Bill to: _____

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SJM 2951E Insured: SGR 3518Bat Workshop m/s Ama Autocare Pte Ltd Tel: _____of 36 Ton Guan Road East #c1-36Policy No: D19MTPV01001347 Claim No: CMTD1904256

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 07/09/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

10/09/2019
H.O.D. Endorsement: _____Date/Time: 09/09/2019 @ 04:46pm Person Contacted: Alvin Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SGR 3518B : NSA/INCD809476/y1 D.O.A: 07/07/2008
	SJM 2951E X \$4300 U/S.
	Lump Sum \$3650. , 8 days.
	Confirm U/S \$4000. , 8 days (Red: 11471.25 : 74%)

Minimum

10/13/19
Surveyor

Form

REF: SMO

2203

WOB XP 1R4-2023/DGE

ASSIGNMENT

From: _____ Date: 10-9-2019

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJM 2951E

at Workshop m/s AMA Autocare

of 36 Toh Guan Road East #01-36

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Veh No: SJM 2951E Yr Regn: 2008 / DGE

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____

Make: Hyundai AVANTE 1.6A c.c. 1591

Colour: BLUE A/C: Insured / Std / NI / NA

Sp. Reading: 192714 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMH0U4BR9U657945

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or _____


Brake: In order / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 185/65R15
R: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 25K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS mp

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or FALKEN

Front	Rear
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm
D.O.A. <u>07/02/19</u>	D.O.I. <u>10/09/19</u>

Survey held at AMA

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
RECEIVED 15 NOV 2019	

Date/Time, File Pass to? : Preli. Report
11511 Typist : Final Report

Date/Time, File Return to? _____

2) _____

Report Format: TP

Lump Sum / I.B.I: (\$ 4000/-)

Days Of Repair: 3

Resurvey No. of Trip: _____

Add Fee: Site Insp (\$)
 Interview (\$)
 Tech. Invs (\$)
 Weekend (\$)

Survey Fee: 490

Transportation: _____ S + RS, SI

Photos _____

Others: 11

TOTAL: 461

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 Sep 2019		09 Sep 2019 16:17 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	DING TEO GOD , ID: S71726641		
Main Claimant:	ANGIEABUY ENTERPRISE , Co. Reg. No.: 53355220J		
Vehicle Reg. No.:	SJM2951E	Date of Loss:	07/09/2019 15:00 - :59
Claim Type:	TP / CMTD1904256	Policy/Cover Note No.:	D19MTPV01001347 (Comprehensive)
Vehicle Reg. No. (Insured):	SGR3518B	Policy No. (Claimant):	
Repairer:	Ama Autocare Pte Ltd (HQ) 36 Toh Guan Road East, #01-36, 608580 Jurong East - Tel:		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 18/09/2019]		
Driver/Custodian (Insured):	EVANGELYN DING XIN YU (), NRIC: T0005758J, Tel: +6598646332 Email:		
Adj Asg. Remarks:	WS: 8778 3636 ALVIN WEE		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									


Denise Tay (LKKAuto)

From: AMA Automotive <ama.claim@gmail.com>
Sent: Thursday, 14 November 2019 12:16 PM
To: Denise Tay (LKKAuto)
Subject: Re: SJM 2951E / TP / DOA: 07/09/2019

Dear Denise

COR lump sum \$4000.00 / 8 Days confirmed.

Thank You and Best Regards



Alvin Wee

AMA Automotive Pte Ltd


36 Toh Guan Road East (Enterprise Hub) #01-36

Singapore 608580

Hp : +65 8778 3636

Tel :+65 6200 0600

www.amaauto.sg



CONFIDENTIAL NOTE: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail.

Data Privacy Policy Notice: AMA Automotive Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf).

On Thu, Nov 14, 2019 at 9:59 AM Denise Tay (LKKAuto) <denisetay@lkkauto.com> wrote:

Dear Victor,

Rasul has re-adjust the marking, lump sum \$4000.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/09/2019 11:20
Date Of Accident	07/09/2019 15:50
Exact Location Of Accident	YISHUN AVE 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJM2951E
Insured/Policyholder	
Name Of Registered Owner	ANGIEABUY ENTERPRISE
Co Reg No	53355220J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96479322
Alternative Phone No	OFFICE-96479322

Vehicle Particulars

Manufacturer	HYUNDAI
Model	AVANTE
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5096499978-01(CLASSIC)
Cover Note Number	

Driver

Name of Driver	PRIMO VINCENT ILAGAN ABUY
NRIC No	S2743789C
Date Of Birth	23/09/1953
Occupation	OUTDOOR
Date Of Driving Pass	10/08/2000
Driving Experience	19 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96479322
Fax Number	
Contact Number	
E Mail Address	NOEMAIL

Address BLK 214 BOON LAY PLACE #06-19
 Postcode
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: : --
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLS REFER ATTACHED ACCIDENT REPORT FROM THE DRIVER.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SGR3518B
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

19 SEP 2019 11:58 AM
Reporting Centre Personnel's Signature (VAC)

Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS DRIVING ALONG YISHUN AVE 1 WITH A FEMALE PASSENGER. IT WAS AROUND 1550 HRS. ON SATURDAY 7 SEPTEMBER. THE WEATHER WAS FINE NO RAIN AND GOOD VISIBILITY. A CYCLIST IN FRONT OF ME SUDDENLY DECIDED TO CHANGE LANES FROM THE EXTREME LEFT TO ~~THE~~ THE RIGHT LANE. I WAS RUNNING AT ABOUT 55-60 KMP HOUR. WHEN THE CYCLIST SWERVED HE DID NOT BOTHER TO CHECK BEHIND HIM SO I HAD TO BRAKE SUDDENLY AND AVOID HIM SO AS NOT TO HIT ~~HIM~~ HIM. THE CAR BEHIND ME COULD NOT BRAKE IN TIME AND SO HIT ME FROM BEHIND IN THE REAR BUMPER CAUSING DAMAGE TO MY REAR THAT THE BUMPER COULD NOT BE CLOSED. SINCE IT WAS DANGEROUS TO STOP AND INSPECT FOR ANY DAMAGE ON THE MAIN ROAD AS IT WAS ON THE CORNER, I DROVE SLOWLY AND FOUND A SAFE PLACE TO INSPECT FOR DAMAGE AND EXCHANGE PARTICULARS WITH THE OTHER DRIVER.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time: 11 58 hrs 9 SEP 2019

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	220J
Vehicle Details	
Vehicle No.:	SJM2951E
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Sep 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	HD AVANTE 1.6 A
Primary Colour:	Blue
Manufacturing Year:	2008
Engine No.:	G4FC8U575123
Chassis No.:	KMHDU41BR9U657945
Maximum Power Output:	89.7 kW (120 bhp)
Open Market Value:	\$11,726.00
Original Registration Date:	29 Dec 2008
First Registration Date:	29 Dec 2008
Transfer Count:	2
Actual ARF Paid:	\$2,073.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	28 Dec 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$13,786.00
COE Rebate Amount:	\$11,836.00
Total Rebate Amount:	\$11,836.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 12 Sep 2019

OK

25,000
 11,836

 13,164
 ==



AMA Autocare Pte Ltd
 Enterprise Hub 36 Toh Guan Road East #01-36
 Singapore (608580)
 E: ama.claim@gmail.com
 T: 87783636

Vehicle No. **SJM2951E HYUNDAI AVANTE 1.6A**

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	ADJUSTMENT
PARTS (LIST ITEMS)				
1	Rear bootlid repair		1649.00	
2	Rear bootlid Hinge @\$107.00 X 3 SVC		214.00	
1	Rear bootlid weatherstrip X 3 SVC		314.00	
1	Rear bootlid HYUNDAI logo emblem new		208.00	32
1	Rear bootlid AVANTE emblem new		152.00	35
	Rear bootlid 'S' emblem new		97.00	31
1	Rear bootlid lock assy SEA		370.00	218
1	Rear bootlid sensor X SVC		378.00	
1	Rear bootlid number plate lamp garnish X 3 SVC		213.00	
2	Rear bootlid number plate lamp @\$78 X 3 SVC		156.00	
2	Rear fender taillamp @\$780.00 X 3 SVC		1560.00	399
2	bootlid taillamp @\$570.00 X 3 SVC		1140.00	
2	Taillamp panel @\$314.50 LH-X/RH-bt (1pc) @ 157.25		629.00	157.25
1	Rear bumper de		1350.00	580
1set	Rear bumper side retainer @\$98.00 /RH-new (1pc) @ 72		196.00	72
1	Rear bumper sponge ca		461.00	129
1	Rear bumper reinforcement ca		738.20	350
2	Rear bumper brackets @\$171.00 new		342.00	113
1	Rear end panel bt		982.00	694
1	Rear end panel top garnish de		216.00	87
1	Rear spare tyre panel repair		960.00	
1	Rear spare tyre top board X SVC		460.00	
2	Rear fender @\$512.50 LH/RH RH-repair /LH-X SVC		1025.00	
2	Rear fender innershield @272.40 LH/RH X SVC		544.80	
			14355.00	0.00
		20% less 25%	3588.75	25% 0.00
			10766.25	0.00
SPECIAL NETT ITEMS				
1set	Rear bumper clips new		80.00	40
1set	Rear End Panel Inner Garnish Clips new		70.00	30
1set	Taillamp clips X nn		70.00	X
1set	Reverse sensor new		220.00	X
1	Rear windscreen sealant X nn		120.00	X
1	Rear end panel sealant new		120.00	60
1	Rear number plate X nn		75.00	X
	TOTAL PARTS		11521.25	0.00

@ 328

2897.25
 20%
 2317.80

350



AMA Autocare Pte Ltd
 Enterprise Hub 36 Toh Guan Road East #01-36
 Singapore (608580)
 E: ama.claim@gmail.com
 T: 87783636

Vehicle No. **SJM2951E HYUNDAI AVANTE 1.6A**

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	1600.00 2000.00	
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1400.00 1000	+100 = 1100
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	190.00 30	
4	To remove and refix/replace rear trims, garnish and fittings so as to facilitate repairs at rear compartment	250.00 80	
5	To remove and replace reverse sensors	180.00 60	
6	To provide anti-rust treatment on affected areas	150.00 60	
7	To remove and refit windscreen	180.00 X	
	Labour Total :	3950.00	
	TOTAL (PARTS & LABOUR):	15471.25	

3330

2317.80

350.00

2330.00

4997.80

202

3998.24

43-4000

8 days

[Signature]
 11/11/19

Resue

Hy 90010068

8 days

4/5

10/09/19 @ 1145

Resue after repair

Require to check mfu

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



AMA Autocare Pte Ltd
 Enterprise Hub 36 Toh Guan Road East #01-36
 Singapore (608580)
 Co. Reg. No. 201735370W E: ama.claim@gmail.com
 T: 87783636

Vehicle No. **SJM2951E HYUNDAI AVANTE 1.6A**

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	ADJUSTMENT
PARTS (LIST ITEMS)				
1	Rear bootlid <i>repair</i>		1649.00	x
1	Rear bootlid Hinge @\$107.00 <i>X^{50%}</i>		214.00	x
1	Rear bootlid weatherstrip <i>X^{50%}</i>		314.00	x
1	Rear bootlid HYUNDAI logo emblem <i>new</i>		208.00	/
1	Rear bootlid AVANTE emblem <i>new</i>		152.00	/
	Rear bootlid 'S' emblem <i>new</i>		97.00	/
1	Rear bootlid lock assy <i>SCA</i>		370.00	/
1	Rear bootlid sensor <i>X^{50%}</i>		378.00	x
1	Rear bootlid number plate lamp garnish <i>X^{50%}</i>		213.00	x
2	Rear bootlid number plate lamp @\$78 <i>X^{50%}</i>		156.00	x
2	Rear fender taillamp @\$780.00 <i>LH X^{50%} / RH-cut (1pc)</i>		1560.00	<i>+780</i>
2	bootlid taillamp @\$570.00 <i>X^{50%}</i>		1140.00	x
2	Taillamp panel @\$314.50 <i>LH X^{50%} / RH-bt (1pc)</i>		629.00	<i>+314.50</i>
1	Rear bumper <i>de</i>		1350.00	/
1set	Rear bumper side retainer @\$98.00 <i>RH-new (1pc)</i>		196.00	/
1	Rear bumper sponge <i>CA</i>		461.00	/
1	Rear bumper reinforcement <i>CA</i>		738.20	/
2	Rear bumper brackets @\$171.00 <i>new</i>		342.00	/
1	Rear end panel <i>bt</i>		982.00	/
1	Rear end panel top garnish <i>de</i>		216.00	/
1	Rear spare tyre panel <i>repair</i>		960.00	x
1	Rear spare tyre top board <i>X^{50%}</i>		460.00	x
2	Rear fender @\$512.50 LH/RH <i>RH-repair / LH-X^{50%}</i>		1025.00	x
2	Rear fender innershield @\$272.40 LH/RH <i>X^{50%}</i>		544.80	x
			14355.00	0.00
		less 25%	3588.75	0.00
		10%	10766.25	0.00
SPECIAL NETT ITEMS				
1set	Rear bumper clips <i>new</i>		88.00 40	
1set	Rear End Panel Inner Garnish Clips <i>new</i>		70.00 30	
1set	Taillamp clips <i>X^{50%}</i>		70.00	x
1set	Reverse sensor <i>new</i>		220.00	/
1	Rear windscreen sealant <i>X^{50%}</i>		120.00	x
1	Rear end panel sealant <i>new</i>		120.00	<i>60</i>
1	Rear number plate <i>X^{50%}</i>		75.00	x
	TOTAL PARTS		11521.25	0.00

6206.70 -
 620.67 - 10%
 5586.03

380



AMA Autocare Pte Ltd
 Enterprise Hub 36 Toh Guan Road East #01-36
 Singapore (608580)
 E: ama.claim@gmail.com
 T: 87783636

Vehicle No. **SJM2951E HYUNDAI AVANTE 1.6A**

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	1600.00 2000.00	
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1400.00 1000	
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	190.00 30	
4	To remove and refix/replace rear trims, garnish and fittings so as to facilitate repairs at rear compartment	250.00 80	
5	To remove and replace reverse sensors	180.00 60	
6	To provide anti-rust treatment on affected areas	150.00 60	
7	To remove and refit windscreen	180.00 X 110	
	Labour Total :	3950.00	
	TOTAL (PARTS & LABOUR):	15471.25	

2470

P - 6206.70 - 10% 5586.03
 S/N - 380
 L - 2470

 8436.03
 1687.21 - 20% 45

 6748.82

Repair
 up 9000.00
 8 days
 45
 10/09/19 @ 1145
 Respray after repair
 Require to check m/p

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 Sep 2019		09 Sep 2019 16:17 Edit Adj Rpt	S\$4,000.00 Edit Estimates	S\$4,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	DING TEO GOD, ID: S7172664I		
Main Claimant:	ANGIEABUY ENTERPRISE, Co. Reg. No.: 53355220J		
Vehicle Reg. No.:	SJM2951E	Date of Loss:	07/09/2019 15:00 - :59 [128 Months and 9 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / CMTD1904256	Policy/Cover Note No.:	D19MTPV01001347 (Comprehensive)
Vehicle Reg. No. (Insured):	SGR3518B	Policy No. (Claimant):	
Repairer:	Ama Autocare Pte Ltd (HQ) 36 Toh Guan Road East, #01-36, 608580 Jurong East - Tel:		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 18/09/2019]		
Driver/Custodian (Insured):	EVANGELYN DING XIN YU (), NRIC: T0005758J, Tel: +6598646332 Email:		
Adj Asg. Remarks:	WS: 8778 3636 ALVIN WEE		

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

***SJM2951E (CMTD1904256)**
[SGR3518B]
 TP
ANGIEABUY ENTERPRISE
 Sep 7 2019 3:00PM
[DING TEO GOD]
 Ama Autocare Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View	View in Browser <input type="button" value="v"/>
Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)		Thumbnail	Print
1	09/09/19 16:16	Accident Statement From:SC - Reg. No: SGR3518B, Claimant: DING TEO GOD		Load HTM	<input type="checkbox"/>
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	15/11/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
2	15/11/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
3	15/11/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
4	15/11/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
5	15/11/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
6	15/11/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
7	15/11/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
8	15/11/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
9	15/11/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
10	15/11/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
11	15/11/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
12	15/11/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
13	15/11/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
14	15/11/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
15	15/11/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
16	15/11/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
17	15/11/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
18	15/11/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
19	15/11/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
20	15/11/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
21	15/11/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
22	15/11/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
23	15/11/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
24	15/11/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
25	15/11/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
26	15/11/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
27	15/11/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
28	15/11/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
29	15/11/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
30	15/11/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
31	15/11/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
32	15/11/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
33	15/11/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
34	15/11/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
35	15/11/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
36	15/11/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
37	15/11/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
38	15/11/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
39	15/11/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)		Thumbnail	Print
40	15/11/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
41	15/11/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
42	15/11/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
43	15/11/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
44	15/11/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
45	15/11/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
46	15/11/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
47	15/11/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
48	15/11/19 11:53	General View		Load JPG	<input checked="" type="checkbox"/>
49	15/11/19 11:53	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
50	15/11/19 11:53	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
51	15/11/19 11:53	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
52	15/11/19 11:53	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
53	15/11/19 11:53	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)		Thumbnail	Print
1	09/09/19 15:30	Pre-Repair Survey		Load PDF	
2	09/09/19 15:30	Pre-Repair Survey - GIA		Load PDF	
3	09/09/19 16:18	Pre-Repair Survey - AGREED LKK		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin: 5px 0;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19015941/R1TF3E2

Date: 19/11/2019

REFERENCE

Handling Insurer:	Sompoo Insurance Singapore Pte. Ltd.	Policy No:	D19MTPV01001347
Claimant Vehicle No :	SJM2951E	Insured Vehicle No :	SGR3518B
Date of Loss:	07/09/2019	Nature of Claim:	TP
		Claim No:	CMTD1904256

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJM2951E	Engine No:	G4FC8U575123
Make & Model:	HYUNDAI AVANTE, 1.6 (A)	Chassis No:	KMHDU41BR9U657945
Reg. Date:	29/12/2008 (Man. Year: 2008)	Odometer:	192714 km
Colour:	Blue		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,239.00	2,667.80	9,571.20	78.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,950.00	2,330.00	1,620.00	41.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,189.00	4,997.80	11,191.20	69.13
Approved Total (Overridden) (S\$)		4,000.00		
Nett Amount (S\$)	16,189.00	4,000.00	12,189.00	75.29

INSPECTION

Date of Assignment:	09/09/2019	
Date Inspected:	10/09/2019	Inspected At:
		Ama Autocare Pte Ltd (HQ) 36 Toh Guan Road East, #01-36 Singapore 608580
Estimated Period of Repair:	8.0 days	

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 19 Nov 2019)
Parts: 143	HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJM2951E)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Repair	1,649.00 FL	*- FL
2	2		*REAR BOOTLID HINGE	Serviceable	214.00 FL	*- FL
3	1		*REAR BOOTLID WEATHERSTRIP	Serviceable	314.00 FL	*- FL
4	1		*REAR BOOTLID HYUNDAI LOGO EMBLEM	Necessary	208.00 FL	*32.00 FL
5	1		*REAR BOOTLID AVANTE EMBLEM	Necessary	152.00 FL	*35.00 FL
6	1		*REAR BOOTLID S EMBLEM	Necessary	97.00 FL	*31.00 FL
7	1		*REAR BOOTLID LOCK ASSY	Scratched	370.00 FL	*218.00 FL
8	1		*REAR BOOTLID SENSOR	Serviceable	378.00 FL	*- FL
9	1		*REAR BOOTLID NUMBER PLATE LAMP GARNISH	Serviceable	213.00 FL	*- FL
10	2		*REAR BOOTLID NUMBER PLATE LAMP	Serviceable	156.00 FL	*- FL
11	1		*REAR FENDER TAILLAMP	O/s Cut/N/s Serviceable	1,560.00 FL	*399.00 FL
12	2		*BOOTLID TAILLAMP	Serviceable	1,140.00 FL	*- FL
13	1		*TAILLAMP PANEL	O/s Bent/N/s Serviceable	629.00 FL	*157.25 FL
14	1		*REAR BUMPER	Deformed	1,350.00 FL	*580.00 FL
15	1		*SET REAR BUMPER SIDE RETAINER	O/s Necessary	196.00 FL	*72.00 FL
16	1		*REAR BUMPER SPONGE	Cracked	461.00 FL	*129.00 FL
17	1		*REAR BUMPER REINFORCEMENT	Cracked	738.20 FL	*350.00 FL
18	2		*REAR BUMPER BRACKETS	Necessary	342.00 FL	*113.00 FL
19	1		*REAR END PANEL	Bent	982.00 FL	*694.00 FL
20	1		*REAR END PANEL TOP GARNISH	Deformed	216.00 FL	*87.00 FL
21	1		*REAR SPARE TYRE PANEL	Repair	960.00 FL	*- FL
22	1		*REAR SPARE TYRE TOP BOARD	Serviceable	460.00 FL	*- FL
23	2		*REAR FENDER LH/RH	N/s Serviceable/O/s Repair	1,025.00 FL	*- FL
24	2		*REAR FENDER INNERSHIELD LH/RH	Serviceable	544.80 FL	*- FL
25	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*40.00 FS
26	1		*SET REAR END PANEL INNER GARNISH CLIPS	Necessary	70.00 FS	*30.00 FS
27	1		*SET TAILLAMP CLIPS	Not Necessary	70.00 FS	*- FS
28	1		*SET REVERSE SENSOR	Not Working	220.00 FS	*220.00 FS
29	1		*REAR WINDSCREEN SEALANT	Not Necessary	120.00 FS	*- FS
30	1		*REAR END PANEL SEALANT	Necessary	120.00 FS	*60.00 FS
31	1		*REAR NUMBER PLATE	Not Necessary	75.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 15,110.00 3,247.25
- List Item Discount on L Items 20.00/20.00% (S\$) 2,871.00 579.45

Total Parts (S\$) 12,239.00 2,667.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; REPLACE DAMAGED PARTS AND COMPONENTS	New	1,600.00	1,000.00
2	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED	New	1,400.00	1,100.00
3	TO REMOVE AND RE-FIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS	New	190.00	30.00
4	TO REMOVE AND REFIX / REPLACE REAR TRIMS, GARNISH AND FITTINGS SO AS TO FACILITATE REPAIRS AT REAR COMPARTMENT	New	250.00	80.00
5	TO REMOVE AND REPLACE REVERSE SENSORS	New	180.00	60.00
6	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS	New	150.00	60.00
7	TO REMOVE AND REFIT WINDSCREEN	New	180.00	0.00
Gross Labour Cost (S\$)			3,950.00	2,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >