

ASS. REC. BY:

REF:

CS/SM019015943/Aqf3

Special Instruction:

Surveyor: Adrian

ASSIGNMENT (Office)

From (Person): Ghoh Pau Loong of SMDDate/Time: 9.9.19 16.20p.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKM 286TInsured: SJ V 8445Mat Workshop m/s Ac AutolutionTel: 68 441184of 13 km Bukit road 4 #03-29Policy No: D19MTPV 01003377Claim No: CMID 190 4257

Sum Insured: _____

Excess: _____

Make of Veh: _____

D.O.A. 8.9.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 9.9.194.47pmPerson Contacted: Jenny

H.O.D. Endorsement: _____

Vehicle IN / OUTDate/Time Action/Instruction (☒) Estimate.

SJ V 8445M - X

SKM 286T - X

10/9/19 @ 5.20pm informed Ghoh Pau Loong, we are pending estimate from repairer.
 06/04/20 @ 1.47pm revised to Ghoh Pau Loong via Messenger,
 LS 6450, 5 days clcd to 5124.64, 537.)

09/11/14

REF: SMO

Surveyor: Adrian

ASSIGNMENT

From: _____ Date: 10.9.2019

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKM 286T

at Workshop m/s Ace Autolubon

of 13 Paki Bukit Road 4 #03-29/30

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKM286T Yr Regn: 2018 March

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel c.c 1496

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 44270 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RU11233004

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: 215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 10/09/19

Survey held at Ace Autolubon

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Sampo

Date/Time, File Pass to?

☐

: Preli. Report

1) 06/4 tuncis

☐

: Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format: MER-TP

Lump Sum / I.B.I. (\$) 4500

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	115J
Vehicle Details	
Vehicle No.:	SKM286T
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Apr 2020
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	Black
Manufacturing Year:	2018
Engine No.:	L15B4433009
Chassis No.:	RU11233004
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$22,421.00
Original Registration Date:	09 Mar 2018
First Registration Date:	09 Mar 2018
Transfer Count:	0
Actual ARF Paid:	\$13,390.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 Mar 2028
PARF Rebate Amount:	\$10,042.00
Intended COE Rebate Details	
COE Expiry Date:	08 Mar 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$36,810.00
COE Rebate Amount:	\$29,161.00
Total Rebate Amount:	\$39,203.00

The information contained herein is correct as at 06 Apr 2020

OK

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompoo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: GNOH PAU LOONG

Date: 06 Apr 2020

Preliminary Advice

Insured Vehicle No	: SJV8445M	Accident Date	: 08/09/2019
TP Vehicle No	: SKM286T	Assignment Date	: 09/09/2019
Make	:	Est. Duration of Repair	: 3.00
Date of Inspection	: 10/09/2019		
Inspection At	: ACE AUTOLUTION PTE LTD (KAKI BUKIT) 13 KAKI BUKIT ROAD 4, #03-29/30 BARTLEY BIZ CENTRE SINGAPORE 417807		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,624.64
Revised Amount	:S\$	5,643.60
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,643.60

Lump Sum Repair	:S\$	4,500.00
-----------------	------	----------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel:6702 4282 Fax:6702 4202

TP Samp0.

Xiao Chen.

Page No. 1

Vehicle No. SKM286T HONDA VEZEL

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR ADJUSTMENT
	PARTS (LIST ITEMS)			
1	TAILGATE <i>Dented</i>		1015.00	✓
1	TAILGATE RUBBER STOPPER LH <i>new</i>		10.00	+
1	TAILGATE " VEZEL " EMBLEM <i>new</i>		71.00	✓
1	TAILGATE LOGO <i>Not new</i>		61.00	+
1	TAILGATE DAMPER @\$300.00 <i>Not new</i>		600.00	+
1	TAILGATE WEATHERSTRIP <i>new</i>		158.00	+
1	TAILGATE INNER TRIM BOARD <i>Not new</i>		211.00	+
1	TAILGATE INNER LOCK <i>Damaged</i>		155.80	✓
1	TAILLAMP LH <i>new</i>		510.00	✓
1	REAR BUMPER <i>Dented</i>		865.00	✓
1	REAR BUMPER SIDE RETAINER LH <i>new</i>		110.00	45
1	REAR BUMPER UNDERDUST <i>new</i>		149.00	✓
1	REAR CORNER PANEL LH <i>new</i>		105.00	✓
1	REAR END PANEL <i>Dented</i>		440.00	✓
1	REAR END PANEL TOP GARNISH <i>new</i>		110.00	✓
1	REAR FENDER LH <i>new</i>		850.00	+
1	REAR ANTENNA SENSOR <i>new</i>		199.00	✓
1	Rear Fender Inner Shield LH <i>new</i>		5580.80	
	Wheel Arch Garnish <i>new</i>		1116.16	20%
	Rear Bumper Reflector		4464.64	
	SPECIAL NETT ITEMS			
1 SET	REVERSE SENSOR <i>Damaged</i>		280.00	200
1	REAR END PANEL SEALANT <i>new</i>		100.00	60
1	REAR END PANEL TOP GARNISH CLIPS <i>new</i>		80.00	+
1 SET	TAILGATE INNER TRIM CLIPS <i>new</i>		60.00	+
1	REAR BUMPER PLATE <i>new</i>		210.00	✓
1	REAR BUMPER BELOW <i>new</i>		320.00	280
1 SET	REAR BUMPER CLIPS <i>new</i>		60.00	30
1	REFLECTOR LAMP LH <i>new</i>		430.00	200
1	REAR WINDSCREEN SEALANT <i>new</i>		80.00	60
	Total Parts		1620.00	



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel:6702 4282 Fax:6702 4202

Page No. 2

Vehicle No. SKM286T HONDA VEZEL

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
	LABOUR		
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	1400.00 800	
2	To supply paint materials, expandable items & putty and respray paint on parts replaced	1200.00 800	
3	To remove and refix wiring at damaged areas	250.00 30	
4	To perform anti rust treatment on affected areas	240.00 80	
5	To remove / refix windscreen	150.00 120	
6	To transfer bootlid mechanism	100.00 80	
7	To tuff kote	80.00 70	
8	To remove and replace reverse sensor	120.00 50	
	Labour Total :	3540.00	1960
	TOTAL (PARTS & LABOUR):	9624.64	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 5619.60

h/s: ASK. ✓

05 Days.

4.5K