



CO. REG. NO: 199402370D
GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

新民通道 (大牌 34 座) 門牌 114 號

Blk 34 Sin Ming Drive, #01-114, Singapore 575708.

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Email: service@kkinhin.com.sg

No. : 26968

Date : 23-May-2015

PAGE : 1

Vehicle Insured : SKS 642 S
Accident Date : 21-May-2015

Our Ref : 150364 (AIG ASIA) / XW

MR MAO FONG CHEE
Singapore

ESTIMATED COST OF REPAIR FOR NISSAN LATIO 1.5L A (2008) SJC2452G

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

300.00 ✓

To putty and respray rear bumper,
rear bumper lower skirting, o/s
rear fender, o/s rear door, o/s
front door & o/s rocker panel lower
skirting.

1,200.00 10 for

Total : S\$ 1,500.00

Singapore Dollars One Thousand Five Hundred Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

Not Authorised

- LKK Auto Consultants Pte Ltd
- Resurvey before/after Spray Painting.
 - Damaged parts to Display when Re-inspection.
 - Parts prices subject to confirmation.
 - Third Party Survey without prejudice.
 - No illegal modification is allowed.