

PITSTOP

WTS Automotive Services Pte Ltd

Ally

**Spare Parts (Appendix A)**

Vehicle No. : GBH6312U

Make & Model : TOYOTA DYNA 150 5MT

Chassis No. : JTFAT35Y10K210940

Submit By :

Year Manufacture :

Engine No. :

IDRAM

2018

1KD2810430

Signature:

Date:

Disposition by Surveyor

Signature:

Date:

Signature:

Date:

Signature:

Date:

Signature:

Date:

Signature:

Date:

Signature:

Date:

Signature:

Date:

Signature:

Date:

Signature:

Date:

Signature:

Date:

Signature:

Date:

Signature:

Date:

Signature:

Date:

Signature:

Date:

Signature:

Date:

Signature:

Date:

Signature:

Date:

Signature:

Date:

Signature:

Date:

Signature:

Date:

Signature:

Date:

Signature:

Date:

Signature:

Date:

Signature:

Date:

Signature:

Date:

Signature:

Date:

Signature:

Date:

Signature:

Date:

Signature:

Date:

Signature:

Date:

Signature:

Date:

Signature:

Date:

Signature:

Date:

Signature:

Date:

Signature:

Date:

Signature:

Date:

Signature:

Date:

Signature:

Date:

Signature:

Date:

S/No.	Part Description	Qty	Price	Disposition by Surveyor
1	RHS REAR SIDE PANEL	1	\$1,200.00	225
2	RHS REAR WHEEL ARCH	1	\$350.00	257
3	FUEL TANK	1	\$620.00	257
4	FUEL TANK BRACKET	1	\$150.00	257
Total on parts			\$2,320.00	
SPECIAL NETT				
1	STICKER - UNION LOGO		\$125.00	100
2	STICKER - UNION ENERGY		\$150.00	100
3	STICKER - 6316 6666		\$150.00	100
Total on S/N			\$425.00	
PAINT MATERIAL AND LABOUR				
1	RHS REAR SIDE PANEL NEW PAINTING	1	\$150.00	✓
2	RHS REAR WHEEL ARCH NEW PAINTING	1	\$50.00	✓
Total on paint material and labour			\$200.00	
LABOUR CHARGE				
1	TO DISMANTLE AND REFIX WHEEL ARCH	1	\$90.00	30
2	TO DISMANTLE AND REFIX FUEL TANK	1	\$160.00	60
3	TO DISMANTLE AND REFIX REAR SIDE PANEL	1	\$250.00	150
4	TO REFIX THE STICKER	1	\$60.00	11X
Total on Labour			\$560.00	
Total on labour			\$560.00	
Total on parts			\$2,320.00	
Total on S/N			\$425.00	
Total on paint material			\$200.00	
Total COR			\$3,505.00	
Repair Discount 20%			\$701.00	
Sub-Total			\$2,804.00	
Gst			\$196.28	
Grand total			\$3,000.28	

Not Allowed  
225  
1/5 #1200  
Hdy.  
Whipht. Atkay.  
17/9/19  
Tel: 62563561

9-995  
257  
746.28  
5.2330.00  
440.00  
1516.28  
202  
1213.

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.