

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 6504H

205/60 R16

DATE 9/9/2019 15:29

Total

MAKE :

Hankook

673681

MODEL :

HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>X Rep.</i>			\$ 553.00
	Rear Bumper Clip 10 pcs <i>X</i>			\$ 22.00
	SUB TOTAL			\$ 575.00
	LESS 20%			\$ 115.00
	DISCOUNTED TOTAL			\$ 460.00
	Labour Charge			
	Panel Beating			\$ 400.00 ¹⁰⁰
	Spray Painting Charge			\$ 300.00 ²⁰⁰
	Wiring Charge			\$ 50.00 ^X
	Remove/Refix Reverse Sensor			\$ 80.00 ^X
	<i>Merina Fee</i>			\$ 11.00
	TOTAL LABOUR			\$ 830.00
	ESTIMATE TOTAL			\$ 1,290.00
<i>Ka hui 10/10/19</i> <i>9/9/19 1620 hr</i> <i>2 Days</i> <i>4/5</i> <i>After Repair photo</i> LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				