

ASS. REC. BY:

REF:

CS100319015993

/T19 d3n2

Special Instruction:

Quoted by: TAU5EH

## ASSIGNMENT (Office)

From (Person):

Jenny Lew

of

UOI

Date/Time:

10/9/19 @ 9.50am

Estimated Cost:

Bill to:

OD ☒ TP WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMM 4752P

Insured:

SKJ 5197B

at Workshop info:

Thuns Eurokars

Tel:

8128 9802

of

27A Tanjong Penjuru

Policy No:

Claim No:

M12D11571909

Sum Insured:

Excess:

Make of Vehicle

(Client's Record)

D.O.A.

5/9/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10.46am 10/9/19

Person Contacted:

JCS

Vehicle IN/OUT

Date/Time

Action/Instruction

Tel: 10101 ✓

SKJ 5197B x

SMM 4752P x

KSS REC BY:

Tanjari

REF: 001

## ASSIGNMENT

From:

Date: 24.9.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMM 4752P

at Workshop m/s Trans Eurokars

at 23 Long Kee Road

Insured

Policy No

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh: 10.000m owner warranty

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value

IDAC Accident Report

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

mp

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMM 4752P

Yr Regn:

2019 June

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda 2

CC

1498

Colour:

S/w

A/C:

Insured / Std / NI / NA

Sp. Reading

1546

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JM6032 HAA 61300413

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/65 R15

R:

N

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

24/9/19 P10a

Survey held at

Transwheels Leycee

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

31/10

Email to Caprine coR. \$4587.26; 6 days  
(Red to 8948.03, 66%)

RECEIVED 01 NOV 2019

Date/Time, File Path to?



Prel. Report

01/11 transw



Final Report

Date/Time, File Path to?

2)

Rep. Form:

7P

Lump Sum / Fee:

4587.26

Days Of Repair:

6

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Insp (\$



Wheel and AS

Survey Fee:

Transportation

S + RS \$1

Photos

Others

TOTAL

3x25:75

250+75

60

80

35

500

## Nivitha (LKK Auto)

---

**From:** LEW JENNY <jennylew@uoi.com.sg>  
**Sent:** Tuesday, 10 September 2019 9:51 AM  
**To:** jess.francis@eurokars.com.sg; SUR; assignments  
**Cc:** ronald.yap@eurokars.com.sg; samuel.ng@eurokars.com.sg;  
jobithomas@eurokars.com.sg; eva.kok@eurokars.com.sg; admin-d@lkkauto.com;  
admin-a@lkkauto.com  
**Subject:** RE: UOI ref - SKJ5197B | Our ref - SMM4752P | Doa Sep 5, 2019 | Requesting for PRI.  
**Attachments:** 3008\_001.zip

WITHOUT PREJUDICE

Dear Jess,

We will appoint LKK as SJE as agreed.

Dear Shiau Chan,

Please arrange to survey the vehicle at Trans Eurokars.

Thank You.

Warmest Regards

Jenny Lew

Claims Division

United Overseas Insurance Limited

3 Anson Road, #28-01 Springleaf Tower, Singapore 079909  
Main • (65) 6222 7733 | DID • (65) 6490 9329 | Fax • (65) 6327 3869 | Email • [jennylew@uoi.com.sg](mailto:jennylew@uoi.com.sg)

### UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

**From:** jess.francis@eurokars.com.sg [mailto:jess.francis@eurokars.com.sg]  
**Sent:** Tuesday, 10 September, 2019 9:35 AM  
**To:** LEW JENNY <jennylew@uoi.com.sg>  
**Cc:** ronald.yap@eurokars.com.sg; samuel.ng@eurokars.com.sg; jobithomas@eurokars.com.sg;  
eva.kok@eurokars.com.sg; admin-d@lkkauto.com; admin-a@lkkauto.com  
**Subject:** RE: UOI ref - SKJ5197B | Our ref - SMM4752P | Doa Sep 5, 2019 | Requesting for PRI.

Dear Ms Jenny,

Referring to your email below.

We will choose LKK Auto for this case.

Kindly do the necessary arrangements before we get in touch with LKK Auto.

word p... Size

Ratio

72 KB 4%

## MOTOR SURVEYORS FOR UOI

1) L&C Auto Consultants Pte Ltd 31 Ubi Avenue 1 #01-20 Payo Ubi Industrial Park Singapore 408032	Tel: 6296 3881 (Shau Chan) Fax: 6296 4315 Email: <a href="mailto:assignment@LCAuto.com">assignment@LCAuto.com</a> <a href="mailto:luc@LCAuto.com">luc@LCAuto.com</a>
2) Priority Services 86 779 Yishun Ave 2 #01-1545 Singapore 760778	Tel: 6293 4922 (Sharon Khoo) Fax: 6293 4867 (Ji Lin)
3) Pioneer Appraisal Services 18 Sin Ming Road #03-02 Singapore 575068	Email: <a href="mailto:pioneer_appraisal@pioneer.sg">pioneer_appraisal@pioneer.sg</a> Tel: 6554 2240 (James Lim) Mobile: 9686 1170 Fax: 6555 1366 (Margaret) Email: <a href="mailto:6554@pioneerappraisal.net">6554@pioneerappraisal.net</a> <a href="mailto:enquiry@pioneerappraisal.net">enquiry@pioneerappraisal.net</a>
4) LTA Inspection Pte Ltd 302 Sin Ming Road Singapore 575027	Tel: 6454 2708 / 8387 3000 (Sui Luen) Fax: 6454 9432 (PC Chong) (Daniel Chan) Email: <a href="mailto:enquiry@ltainspection.com">enquiry@ltainspection.com</a> <a href="mailto:lihuang@ltainspection.com">lihuang@ltainspection.com</a> <a href="mailto:liwendan@ltainspection.com">liwendan@ltainspection.com</a>
5) Automobile Inspection Services Pte Ltd 86 140 Pong Pong Ave 1 #02-145 Singapore 301446	Tel: 6296 0100 / 9665 9530 (Jenny) Fax: 6294 1539 (Terence) Email: <a href="mailto:enquiry@aisinspection.com.sg">enquiry@aisinspection.com.sg</a> <a href="mailto:terence@aisinspection.com.sg">terence@aisinspection.com.sg</a>
6) Autopoint Consultants 86 151A Serangoon North Ave 2 #02-01 Singapore 551151	Tel: 6298 8225 / 9674 9674 (Ray Neo) Fax: 6298 1440 (Liamwei) Email: <a href="mailto:autopoint@autopoint.com.sg">autopoint@autopoint.com.sg</a>
7) Four Team Appraisers Pte Ltd No. 31 Ubi Ave 3 #02-18 Interis Singapore 408068	Tel: 6506 1789 / 9258 9229 (Frankie) Fax: 6506 9221 (Hendy Tan) Email: <a href="mailto:fourteam@fourteam.com.sg">fourteam@fourteam.com.sg</a>
8) L & S Auto Consultants Pte Ltd 86 9 Kampong Park Drive #01-07 Singapore 587025	Tel: 6287 2868 / 6287 6660 Fax: 6287 8749 (Samuel) (Jenny / Grace / Zahirah) Email: <a href="mailto:enquiry@l-s-auto.com">enquiry@l-s-auto.com</a>
9) RT Appraisal Pte Ltd 86 305 Ubi Ave 1 #02-187 Singapore 408005	Tel: 6748 8076 (Rocky Tang) Fax: 6748 2361 (Edison Tang) Email: <a href="mailto:rocky@rt.com.sg">rocky@rt.com.sg</a> <a href="mailto:edison@rt.com.sg">edison@rt.com.sg</a> <a href="mailto:rtappraisal.com.sg">rtappraisal.com.sg</a>

Regards,

Jess Francis Carlos  
Insurance Claims Executive  
Trans Eurokars Pte Ltd  
27A Tanjong Pagar  
Singapore 609042  
Tel no.: 8128 9802

This email, including any attachment, is intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

**From:** LEW JENNY <[jennylew@uoi.com.sg](mailto:jennylew@uoi.com.sg)>

**Sent:** 09 September 2019 5:29 PM

**To:** Jess Francis Amurao Carlos <[jess.francis@eurokars.com.sg](mailto:jess.francis@eurokars.com.sg)>; LEE KATIE <[katielee@uoi.com.sg](mailto:katielee@uoi.com.sg)>

**Cc:** Ronald Yap <[ronald.yap@eurokars.com.sg](mailto:ronald.yap@eurokars.com.sg)>; Samuel Ng <[samuel.ng@eurokars.com.sg](mailto:samuel.ng@eurokars.com.sg)>; Jobi Thomas <[jobithomas@eurokars.com.sg](mailto:jobithomas@eurokars.com.sg)>

**Subject:** RE: UOI ref - SKJ5197B | Our ref - SMM4752P | Doa Sep 5, 2019 | Requesting for PRI.

WITHOUT PREJUDICE

Dear Jess,

Pursuant to the amended Pre-action Protocol for Non-Injury Motor Accident (NIMA), we enclose a list of our Surveyors, for your attention.

In this case, we propose to appoint M/s Priority Services.

Please revert to the undersigned within **two (2) working days** whether you have any objections to the appointment of any of our Surveyors, failing which we shall proceed to carry out the survey of your client's vehicle by our appointed Surveyors.

We reserve all our rights in this matter.

Thank You.

Warmest Regards

Jenny Lew

Claims Division

United Overseas Insurance Limited

3 Anson Road, #28-01 Springleaf Tower, Singapore 079909  
Main • (65) 6222 7733 | DID • (65) 6490 9329 | Fax • (65) 6327 3869 | Email • [jennylew@uoi.com.sg](mailto:jennylew@uoi.com.sg)

**UOB EMAIL DISCLAIMER**

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

**From:** [jess.francis@eurokars.com.sg](mailto:jess.francis@eurokars.com.sg) [mailto:[jess.francis@eurokars.com.sg](mailto:jess.francis@eurokars.com.sg)]  
**Sent:** Monday, 9 September, 2019 5:27 PM  
**To:** LEE KATIE <[katielee@uoi.com.sg](mailto:katielee@uoi.com.sg)>; LEW JENNY <[jennylew@uoi.com.sg](mailto:jennylew@uoi.com.sg)>  
**Cc:** [ronald.yap@eurokars.com.sg](mailto:ronald.yap@eurokars.com.sg); [samuel.ng@eurokars.com.sg](mailto:samuel.ng@eurokars.com.sg); [jobithomas@eurokars.com.sg](mailto:jobithomas@eurokars.com.sg)  
**Subject:** UOI ref - SKJ5197B | Our ref - SMM4752P | Doa Sep 5, 2019 | Requesting for PRI.

To whom it may concern,

Kindly arrange the PRI to our client's vehicle.

Let us know the appointed surveyor for us to arrange.

Regards,

Jess Francis Carlos  
Insurance Claims Executive  
Trans Eurokars Pte Ltd  
27A Tanjong Penuru  
Singapore 609042  
Tel no.: 8128 9802

This email, including any attachment, is intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

**From:** Eurokars Printer Scan <[transeurokars@eurokars.com.sg](mailto:transeurokars@eurokars.com.sg)>  
**Sent:** 09 September 2019 5:18 PM  
**To:** Jess Francis Amurao Carlos <[jess.francis@eurokars.com.sg](mailto:jess.francis@eurokars.com.sg)>  
**Subject:** Attached Image

## Shiau Chan (LKKAUTO)

---

**From:** LEW JENNY <jennylew@uoi.com.sg>  
**Sent:** Friday, 1 November 2019 12:18 PM  
**To:** Shiau Chan (LKKAUTO); Admin-D (LKKAUTO); assignments  
**Cc:** SUR  
**Subject:** RE: UOI ref - SKJ5197B | Our ref - SMM4752P | Doa Sep 5, 2019 | Requesting for PRI.

Dear Shiau Chan,

Claim no : M12D11571909

Warmest Regards

Jenny Lew

Claims Division

United Overseas Insurance Limited

3 Anson Road, #28-01 Springleaf Tower, Singapore 079909  
Main • (65) 6222 7733 | DID • (65) 8490 9329 | Fax • (65) 6327 3869 | Email • [jennylew@uoi.com.sg](mailto:jennylew@uoi.com.sg)

### UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

---

**From:** Shiau Chan (LKKAUTO) [mailto:[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)]  
**Sent:** Friday, 1 November, 2019 11:08 AM  
**To:** Admin-D (LKKAUTO) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>; LEW JENNY <jennylew@uoi.com.sg>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: UOI ref - SKJ5197B | Our ref - SMM4752P | Doa Sep 5, 2019 | Requesting for PRI.

Dear Jenny,

Kindly provide us the claim number of above mentioned.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Sent:** Tuesday, 10 September 2019 10:49 AM  
**To:** 'LEW JENNY' <jennylew@uoi.com.sg>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: UOI ref - SKJ5197B | Our ref - SMM4752P | Doa Sep 5, 2019 | Requesting for PRI.

Dear Sir/Mdm,

Thank you for the assignment.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	07/09/2019 09:31
Date Of Accident	05/09/2019 17:25
Exact Location Of Accident	UPPER THOMSON RD/MARYMOUNT LANE JUNCTION
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMM4752P
<b>Insured/Policyholder</b>	
Name Of Registered Owner	MDM LEE MIN TAY
NRIC No	S0492688I
Email Address	LEEMINTAY@YAHOO.COM
Mobile Phone No	(LOCAL) +65-96498854
Alternative Phone No	OFFICE-96498854

### Vehicle Particulars

Manufacturer	MAZDA
Model	2-1.5 HATCHBACK (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

### Driver

Name of Driver	MDM LEE MIN TAY
NRIC No	S0492688I
Date Of Birth	26/05/1945
Occupation	INDOOR
Date Of Driving Pass	20/02/1968
Driving Experience	51 YEARS AND 6 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96498854
Fax Number	
Contact Number	OFFICE-96498854
Email Address	LEEMINTAY@YAHOO.COM

Address	273B BISHAN STREET 24 #27-112
Postcode	572273
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BISHAN NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 20 BISHAN STREET 23 , POSTCODE: 579757 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-5529999 - FAX NO: 65561905
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

SEE SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO


#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKJ5197B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	GWEE TONG CHEW
NRIC/Passport Number	S1254626B
Contact Number	98249018
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	



No. Of Passenger (Including Driver)

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer Police Report no. T/20190905/2148.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 6/9/19

34/10/19 3:45 PM

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time: 6/9/19

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: [Signature]  
NRIC/FIN No.:



**SINGAPORE  
POLICE FORCE**



T/20190905/2148

1 of 3

Police Station Of Origin:  
Bishan N.P.C  
20 Bishan Street 23 SINGAPORE 579757  
Tel No: 1800-5529999

Report No: T/20190905/2148

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 05/09/2019 21:09	Vide Report No.:	Station Diary No.: 98
--	------------------	--------------------------

**Informant's Particulars**

Name of Informant: LEE MIN TAY			Address: APT BLK 273B BISHAN STREET 24 #27-112 SINGAPORE 572273		
ID Type / ID No.: NRIC NO / S0492688I			Contact No.: Home/Office: Mobile: 96498854		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Female	Age: 74	Date of Birth: 26/05/1945	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: DIRECTOR OF NURSING			Driving Licence Information: Class: 3 Date of Expiry:		

**General Information of the Accident**

Type of Accident:	Non-Injury	Drink Drive: No	Date/Time of Accident: 05/09/2019 17:25	Type of Location: X-Junction
Location: Along Road 1 UPPER THOMSON ROAD				
X-Junction of Marymount Lane				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SKJ5197A	Car					0
SMM4752P	Car	MAZDA	MAZDA2 HATCHBACK K 1.5 AT STANDARD 2WD	Silver		0



**SINGAPORE  
POLICE FORCE**



T/20190905/2148

2 of 3

Report No. T/20190905/2148

Police Station Of Origin:

Bishan N.P.C

20 Bishan Street 23 SINGAPORE 579757

Tel No: 1800-5529999

**CONTINUATION OF REPORT**

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SMM4752P	AIG ASIA PACIFIC INSURANCE PTE. LTD.	1900103536	28/06/2019	27/06/2021

**Brief Details.**

On 05/09/2019 at about 1725hrs, I was traveling along Upper Thomson Road towards Marymount Lane. I was turning right into Marymount Lane. I was waiting for the traffic light to turn green.

Suddenly, I felt an impact from the rear. I alighted and made a check. I realised that one vehicle (SKJ5197A) had hit onto my vehicle's rear. No one was injured at the point of time. No police or ambulance activated. I exchange particular with the driver.

Particulars of the driver:

Gwee Tong Chew, S1254626B

HP: 98249018



**SINGAPORE  
POLICE FORCE**



T/20190905/2148

Police Station Of Origin:  
Bishan N.P.C  
20 Bishan Street 23 SINGAPORE 579757  
Tel No: 1800-5529999

3 of 3

Report No. T/20190905/2148

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan



**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: E / Sgt 2 LIM HWEE JIE, SAMUEL	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 05/09/2019 21:09
Officer In Charge Of Case: TP / GIA / Staff Sgt WONG SIEU LEE Contact No.: 65476151 	Classification Of Case: SN 061
Authentication Stamp NP168 	



TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

UNITED OVERSEAS INSURANCE LTD 3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909 ATTN.: MOTOR CLAIMS FAX:		NAME: Mdm Lee Min Tay ADDRESS: 2738 Bishan Street 24 #27-112 Singapore 572273 TEL: 96498854		WIP: 50809 EXCESS: DATE: 9-Sep-19		
VEH NO:	SMM4752P	DATE IN:		CONTACT PERSON:	Jess 63957874	
CHASSIS NO:	JM6DJ2HAA01300413	MILEAGE:		TYPE OF CLAIM:	THIRD PARTY CLAIM	
MODEL:	MAZDA2	DATE REG.:	28-Jun-19	POLICY NO.:		
<b>NATURE OF WORKS</b>						
<b>Parts Description</b>						
NO	QTY			REVISED	PRICES	
1	REAR BUMPER	1	MDC3R-50-221BBB	de	\$ 893.40 ✓	
2	BRACKET CENTER	1	MKD53-50-251	? ny	\$ 5.40 X	
3	STAY, REAR BUMPER	2	MD09W-50-271A	? X	\$ 22.80 X	
4	CAP CENTER, REAR BUMPER	1	MD09W-50-705	? J	\$ 39.60 X	
5	FASTENER, REAR BUMPER	7	MB45A-56-146A	nh	\$ 21.00 ✓	
6	GROMMET, REAR BUMPER	4	MBHN1-50-021A	nh	\$ 10.80 ✓	
7	GROMMET, REAR BUMPER	2	M9991-00-501	nh	\$ 6.00 ✓	
8	TAPE PROTECTOR, REAR BUMPER	3	MBCKA-50-EM1	nh	\$ 14.10 ✓	
9	LAMP, LICENSE PLATE	2	MD09H-51-270B	X J	\$ 111.60 X	
10	REAR END PANEL	1	MDJYS-70-75Z	X J	\$ 477.10 X	
11	TRIM, END PANEL	1	MD09W-68-89XA02	X J	\$ 77.00 X	
12	FASTENER, TRIM	4	MGJ21-68-885B02	X J	\$ 12.00 X	
13	ORNAMENT, MAZDA	1	MDB2M-51-721	nh	\$ 58.30 ✓	
14	MASCOT, REAR	1	MD09W-51-730	nh	\$ 61.20 ✓	
15	ORNAMENT, SKYACTIVE	1	MD09W-51-771	nh	\$ 68.00 ✓	
16	GASKET LHS, TAILLAMP	1	MDA6A-51-3J8	nh	\$ 54.30 ✓	
17	GASKET RHS, TAILLAMP	1	MDA6A-51-3H8	nh	\$ 54.30 ✓	
18	SILENCER, EXHAUST	1	MP516-40-100B	? J	\$ 1,105.80 X	
19	HANGER, SILENCER	2	MBP47-40-061A	? J	\$ 70.00 X	
20	GASKET, EXHAUST	1	MP549-40-305	? J	\$ 15.40 X	
<b>TOTAL PARTS</b>					\$ 3,178.10	
<b>LESS 10%</b>					\$ 317.81	
<b>TOTAL PARTS COST</b>					\$ 2,860.29	
<b>Labour Description</b>						
1	TO REPLACE REAR BUMPER, REAR END PANEL, TO REPAIR REAR FLOOR PANEL, TAILGATE AND ALL AREAS AFFECTED BY THE ACCIDENT. 660			1320	\$ 3,960.00	
2	MZ-SP-SREAR6	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL, REAR FLOOR PANEL AND TAILGATE. 630			1260	\$ 3,465.00

3	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS. (WITH 1 REVERSE SENSOR)	330 ✓	NETT	\$ 660.00	
4	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	nm	X NETT	\$ 330.00	
5	MZ-BR-PLATE	TO SUPPLY NUMBER PLATE.	nm	X NETT	\$ 70.00	
6	MZ-BR-EXASSY	TO REMOVE & INSTALL REAR EXHAUST ASSY.	photo	nm X	\$ 990.00	X
7	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.		nm 150 X	\$ 250.00	X
8	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		150 ✓	\$ 250.00	
9	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		180 ✓	\$ 350.00	
10		TO SUPPLY BRILA PREMIUM COATING. * To provide sales agreement ?		200 ✓ NETT	\$ 250.00	
11	MZ-BR-SUNDRI	SUNDRIES. ncc	30 ✓	NETT	\$ 100.00	

TOTAL LABOUR	\$ -	\$10,675.00
TOTAL PARTS	\$ -	\$ 2,860.29
TOTAL	\$ -	\$13,535.29
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:  
THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS

TRANS EUROKARS PTE LTD

Authorised Signature

25/9/19  
Tanpin 9749 5949  
WP  
24/9/19 @ 10 am  
\* Resurvey before points  
sur@lkkauto.com.  
o 6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be recovered and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:





# TRANS EUROKARS PTE LTD



## FINALISED COST OF REPAIRS

UNITED OVERSEAS INSURANCE LTD 3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909 ATTN : MOTOR CLAIMS FAX :		NAME : Mdm Lee Min Tay ADDRESS : 273B Bishan Street 24 #27-112 Singapore 572273 TEL : 96498854		WIP : 52968 EXCESS : DATE: 9-Sep-19	
VEH NO :	SMM4752P	DATE IN :		CONTACT PERSON :	Jess 63957874
CHASSIS NO :	JM6DJ2HAA01300413	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA2	DATE REG.:	28-Jun-19	POLICY NO. :	
<b>NATURE OF WORKS</b>					
<b>Parts Description</b>					
NO	QTY			REVISED	PRICES
1	REAR BUMPER	1	MDC3R-50-2218BB	\$ 893.40	\$ 893.40
2	BRACKET CENTER	1	MK053-50-251		\$ 5.40
3	STAY, REAR BUMPER	2	MD09W-50-271A		\$ 22.80
4	CAP CENTER, REAR BUMPER	1	MD09W-50-705		\$ 39.60
5	FASTENER, REAR BUMPER	7	MB45A-56-146A	\$ 21.00	\$ 21.00
6	GROMMET, REAR BUMPER	4	MBHN1-50-021A	\$ 10.80	\$ 10.80
7	GROMMET, REAR BUMPER	2	M9991-00-501	\$ 6.00	\$ 6.00
8	TAPE PROTECTOR, REAR BUMPER	3	MBCKA-50-EM1	\$ 14.10	\$ 14.10
9	LAMP, LICENSE PLATE	2	MD09H-51-2708		\$ 111.60
10	REAR END PANEL	1	MDJYS-70-75Z		\$ 477.10
11	TRIM, END PANEL	1	MD09W-68-89XA02		\$ 77.00
12	FASTENER, TRIM	4	MGJ21-68-885B02		\$ 12.00
13	ORNAMENT, MAZDA	1	MD82M-51-721	\$ 58.30	\$ 58.30
14	MASCOT, REAR	1	MD09W-51-730	\$ 61.20	\$ 61.20
15	ORNAMENT, SKYACTIVE	1	MD09W-51-771	\$ 68.00	\$ 68.00
16	GASKET LHS, TAILLAMP	1	MDA6A-51-3J8	\$ 54.30	\$ 54.30
17	GASKET RHS, TAILLAMP	1	MDA6A-51-3H8	\$ 54.30	\$ 54.30
18	SILENCER, EXHAUST	1	MP516-40-100B		\$ 1,105.80
19	HANGER, SILENCER	2	MBP47-40-061A		\$ 70.00
20	GASKET, EXHAUST	1	MP549-40-305		\$ 15.40
<b>TOTAL PARTS</b>				\$ 1,241.40	\$ 3,178.10
<b>LESS 10%</b>				\$ 124.14	\$ 317.81
<b>TOTAL PARTS COST</b>				\$ 1,117.26	\$ 2,860.29
<b>Labour Description</b>					
1	TO REPLACE REAR BUMPER, REAR END PANEL TO REPAIR REAR FLOOR PANEL, TAILGATE AND ALL AREAS AFFECTED BY THE ACCIDENT.			\$ 1,320.00	\$ 3,960.00
2	MZ-SP-SREAR6	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL, REAR FLOOR PANEL AND TAILGATE.		\$ 1,260.00	\$ 3,465.00

3	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS. (WITH REVERSE SENSOR)	\$ 330.00	\$ 660.00
4	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.		\$ 330.00
5	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE.		\$ 70.00
6	MZ-BR-EXASSY	TO REMOVE & INSTALL REAR EXHAUST ASSY.		\$ 990.00
7	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.		\$ 250.00
8	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 150.00	\$ 250.00
9	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 180.00	\$ 350.00
10		TO SUPPLY BRILA PREMIUM COATING.	\$ 200.00	\$ 250.00
11	MZ-BR-SUNDRI	SUNDRIES.	\$ 30.00	\$ 100.00
			TOTAL LABOUR	\$ 3,470.00 \$ 10,675.00
			TOTAL PARTS	\$ 1,117.26 \$ 2,860.29
			TOTAL	\$ 4,587.26 \$ 13,535.29
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ 4,587.26
			GST 7%	\$ 321.11 \$ -
			GRAND TOTAL	\$ 4,908.37 \$ -

**REMARKS:**

**6 REPAIR DAYS** (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

ID:t05

## INTERNAL INVOICE

CODE: I9104 I04  
CUSTOMER: Mdm Lee Min Tay  
ADDRESS: 273B Bishan Street 24  
#27-112  
Singapore 572273  
MODEL: MAZDA2 IPM3 HB CORE  
CHASSIS NO: JM6DJ2HAA01300413  
ENGINE NO: P520598297  
DESCRIPTION: P.D.I.

PAGE NO: 1  
INVOICE NO: 31017056  
DEPT/POS ID: N / 12  
DATE IN: 25/06/2019  
DATE PRINTED: 29/06/2019  
JOB NO: 44442  
CSO/OP CODE: Calvin Chow  
TEL NO:  
REGN NO: SMM4752P  
REGN DATE:  
MILEAGE: 3  
REQUISITION NO: 30135/CC

MZ-PT M2	PETROL TOPPING	0.00
MZ-PDI M	Std PDI Pkg M2	
	PRE DELIVERY INSPECTION & INSTALL IU	.00
MZ-PV M2	Std PDI Pkg M2	
	POLISH A UNIT OF VEHICLE	0.00
MZ-RP M2	Std PDI Pkg M2	
	SUPPLY 1 SET OF REGN PLATE	0.00
MZ-IU M2	Std PDI Pkg M2	
	SUPPLY 1 UNIT OF IU	0.00
MZ-SF M2	Std PDI Pkg M2	
	SUPPLY & INSTALL M2 SOLAR FILM	.00
SUB	SUBLET 148582	
	SUPPLY BRILA M2 RED LINE BODY COATING	.00
	SUBLET 148585	
MZ-FVC M	INSTALL M2 FRONT & REAR VIDEO CAMERA	.00
MZ-LS M2	SUPPLY & INSTALL M2 HALF LEATHER SEATS(CLASSIC)	.00
	SUBLET 148586	
MZ-RS M2	SUPPLY & INSTALL M2 REVERSE SENSOR(TLW)	.00

COPY DOCUMENT

ID:t05

## INTERNAL INVOICE

CODE: I9104 I04  
CUSTOMER: Mdm Lee Min Tay  
ADDRESS: 273B Bishan Street 24  
#27-112  
Singapore 572273  
SINGAPORE  
MODEL: MAZDA2 IPM3 HB CORE  
CHASSIS NO: JM6DJ2HAA01300413  
ENGINE NO: P520598297

PAGE NO: 2  
INVOICE NO: 31017056  
DEPT/POS ID: N / 12  
DATE: 25/06/2019  
DATE PRINTED: 29/06/2019  
JOB NO: 44442  
CSO/OP CODE: Calvin Chow  
TEL NO:  
REGN NO: SMM4752P  
REGN DATE:  
MILEAGE: 3



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD			Ref : CS/UOI19015997/T1qd3n2	
3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909			Date : 05-11-2019	
			Code : UOI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SKJ 5197B	Veh. Inspected	SMM 4752P
	Policy No.		Coverage (\$)	0.00
	Claim No.	M12D11571909	Excess (\$)	0.00
	Assign From	JENNY LEW	Assign Date	10/09/2019
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	MAZDA 2	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	JM6DJ2HAA01300413	Colour	SILVER
	Odometer	1546	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	185/65 R15	PIRELLI	6 mm
	L/H Front Tyre	185/65 R15	PIRELLI	6 mm
	R/H Rear Tyre	185/65 R15	PIRELLI	6 mm
	L/H Rear Tyre	185/65 R15	PIRELLI	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	05/09/2019	Inspection Date	24/09/2019
	Survey held at	27A TANJONG PENJURU		
	Repairer	TRANS EUROKARS PTE LTD		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>6 Working Days</b>	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMM 4752P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER	DEFORMED	893.40	893.40
1	BRACKET CENTER	NOT NECESSARY	5.40	-
2	STAY,REAR BUMPER	NOT NECESSARY	22.80	-
1	CAP CENTER,REAR BUMPER	NOT NECESSARY	39.60	-
7	FASTENER,REAR BUMPER	NECESSARY	21.00	21.00
4	GROMMET,REAR BUMPER	NECESSARY	10.80	10.80
2	GROMMET,REAR BUMPER	NECESSARY	6.00	6.00
3	TAPE PROTECTOR,REAR BUMPER	NECESSARY	14.10	14.10
2	LAMP,LICENSE PLATE	NOT NECESSARY	111.60	-
1	REAR END PANEL	NOT NECESSARY	477.10	-
1	TRIM END PANEL	NOT NECESSARY	77.00	-
4	FASTENER,TRIM	NOT NECESSARY	12.00	-
1	ORNAMENT,MAZDA	NECESSARY	58.30	58.30
1	MASCOT,REAR	NECESSARY	61.20	61.20
1	ORNAMENT,SKYACTIVE	NECESSARY	68.00	68.00
1	GASKET LHS,TAILLAMP	NECESSARY	54.30	54.30
1	GASKET RHS,TAILLAMP	NECESSARY	54.30	54.30
1	SILENCER,EXHAUST	NOT NECESSARY	1,105.80	-
2	HANGER,SILENCER	NOT NECESSARY	70.00	-
1	GASKET,EXHAUST	NOT NECESSARY	15.40	-
	LESS 10% DISCOUNT		-317.81	-124.14
			2,860.29	1,117.26
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SUNDRIES (SN)	NECESSARY	100.00	30.00
1	NUMBER PLATE (SN)	NOT NECESSARY	70.00	-
			170.00	30.00
<b><u>LABOUR</u></b>				
	TO REPLACE REAR BUMPER,REAR END PANEL,TO REPAIR REAR FLOOR PANEL,TAILGATE AND ALL AREAS AFFECTED BY THE ACCIDENT.		3,960.00	1,320.00
	TO RESPRAY REAR BUMPER,REAR REINFORCEMENT,REAR END PANEL,REAR FLOOR PANEL AND TAILGATE.		3,465.00	1,260.00
	TO TRANSFER REVERSE SENSORS.(WITH REVERSE SENSOR).		660.00	330.00

Report Ref No. CS/UOI19015997/T1qd3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER REVERSE CAMERA.	NOT NECESSARY	330.00	-
	TO REMOVE & INSTALL REAR EXHAUST ASSY.	NOT NECESSARY	990.00	-
	TO CARRY-OUT BODY CAVITY PRESERVATION.	NOT NECESSARY	250.00	-
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		250.00	150.00
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		350.00	180.00
	TO SUPPLY BRILA PREMIUM COATING.		250.00	200.00
			10,505.00	3,440.00
<b>GRAND TOTAL</b>			<b>13,535.29</b>	<b>4,587.26</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>4,587.26</b>

Report Ref No. CS/UOI19015997/T1qd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.