

TH2200

ASS. REC. BY:

REF:

CS3/FWD19016003/And302

Special Instruction:

Surveyor: Adnan

menhman

ASSIGNMENT (Office)

From (Person): Vanessa Chen

of

PWD

Date/Time: 10/09/19 @ 10:31am

Estimated Cost:

Bill to:

OD <sup>①</sup> TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SCH 19U

Insured:

FBS5744C

at Workshop m/s

Eclipse Auto

Tel:

8128 8789

of

155 Kerli Bukit Avenue 1 Level 11

Policy No:

PNMC2019-00002564

Claim No:

1201900026795

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

6/09/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:52am @ 10/9/19

Person Contacted:

Edmund

Vehicle

IN/OUT

Date/Time	Action/Instruction
	13/09/19 (X)
	SCH 19U - CS3/AIG1400173/Rv m3u2
	FBS5744C-X
	Dismantle: 12/9/2019
	After repair: 1/10/2019
23/10/2019	Receive Instruction from Lionel to conduct paper survey
30/10/19	Submit LS \$ Tax (Red 2300, 2419)

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SCH194

Yr Regn: 2017, Jan.

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mercedes Benz E220

c.c. 1,950

Colour:

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

92105

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WDD2130042A120503

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size:

F: 275/40R19.

R: 275/40R19.

BS / DUN / EXNOVA / ☒ GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06 mm

R/Bal.

06 mm

L/Bal.

06 mm

L/Bal.

06 mm

D.O.A.

D.O.L.

10/09/19

Survey held at

Eclipse.

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

TP FWD PRS.

Repair range: \$6.5K - \$7.5K; 06 Days.

MV:

PV:

Nett:

RECEIVED 30 OCT 2019

Date/Time, File Pass to?

☐

Prel. Report

If

☐

Final Report

Date/Time, File Return to?

30/10 - typist

Days Of Repair:

5

Resurvey No. of Trip:

2

Addl Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Recd. Insp (\$

Survey Fee:

Transportation:

3 + PS. \$

Parking:

Fuel:

Total:

PRS &amp; PS

200

50

50+90

11

361

## Nivitha (LKK Auto)

---

**From:** lionel.tan@fwd.com  
**Sent:** Wednesday, 23 October 2019 2:23 PM  
**To:** admin-d@lkkauto.com; assignments@lkkauto.com  
**Cc:** motorclaims.sg@fwd.com  
**Subject:** FW: PRE-REPAIR NOTICE OF ROAD TRAFFIC ACCIDENT ON 06.09.2019 at about 2200 hours along PIE involving SCH 19U and FBJ 5744C (PURSUANT TO PARAGRAPH 2.2 OF THE PRE-ACTION PROTOCOL FOR NIMA CASES)  
**Attachments:** @.dat; SR\_SCH19U.pdf

Claim 1201900026795

Hi

Please assist to prepare paper re-survey report.

Attached TP survey report.

Best Regards,

Lionel Tan  
Senior Executive, Claims



FWD Singapore Pte. Ltd.  
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986  
T (65) 6914 6824  
E [lionel.tan@fwd.com](mailto:lionel.tan@fwd.com)  
W [www.fwd.com.sg](http://www.fwd.com.sg)

---

**From:** Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]  
**Sent:** Tuesday, September 10, 2019 11:43 AM  
**To:** Venessa Chan - SGUser; assignments  
**Cc:** Motor Claims SG - SG Common; Lionel Tan Tian Pei - SGUser; SUR  
**Subject:** RE: PRE-REPAIR NOTICE OF ROAD TRAFFIC ACCIDENT ON 06.09.2019 at about 2200 hours along PIE involving SCH 19U and FBJ 5744C (PURSUANT TO PARAGRAPH 2.2 OF THE PRE-ACTION PROTOCOL FOR NIMA CASES)

**This message has been archived. [View the original item](#)**

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) <<mailto:assignments@lkkauto.com>> | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: [venessa.chan@fwd.com](mailto:venessa.chan@fwd.com) [<mailto:venessa.chan@fwd.com>]

Sent: Tuesday, 10 September 2019 10:31 AM

To: [admin-d@lkkauto.com](mailto:admin-d@lkkauto.com); [admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)

Cc: [motorclaims.sg@fwd.com](mailto:motorclaims.sg@fwd.com); [lionel.tan@fwd.com](mailto:lionel.tan@fwd.com)

Subject: PRE-REPAIR NOTICE OF ROAD TRAFFIC ACCIDENT ON 06.09.2019 at about 2200 hours along PIE involving SCH 19U and FBJ 5744C (PURSUANT TO PARAGRAPH 2.2 OF THE PRE-ACTION PROTOCOL FOR NIMA CASES)

Dear Nivitha,

Please refer to the email below and liaise with TP repairer for PRS.

Please create the case in Merimen & our insured has yet to report.

Thank you.

Best Regards,

Venessa Chan

Administrative Assistant, Clai

**Attachments:**

[image001.png](#)

(9 KB)

[image004.jpg](#)

(8 KB)

[image007.png](#)

(4 KB)

[image008.png](#)

(16 KB)

[image005.emz](#)

(2 KB)

**ATTENTION:**

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Sep 2019 <a href="#">Edit Reg</a>		10 Sep 2019 00:00 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	LEE PECK HWA, ID: S7776026A								
Main Claimant:	SIN HOCK HUAT CONSUTRUCTION, Co, Reg. No.: 52942802D								
Vehicle Reg. No.:	SCH19U	Date of Loss:	06/09/2019 00:00 - :59						
Claim Type:	TP / 1201900026795	Policy/Cover Note No.:	PNMC2019-00002564 (TP, Fire & Theft) Coverage: 16/07/2019 - 15/07/2020						
Vehicle Reg. No. (Insured):	FBJ5744C	Policy No. (Claimant):							
		Excess:							
Repairer:	Eclipse Auto Pte Ltd (HQ) 155 Kaki Bukit Avenue 1, Shun Li Industrial Park #01-01, 416012 Kaki Bukit - Tel:								
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Lionel Tan]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 19/09/2019]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Nivitha (LKK Auto)

---

**From:** venessa.chan@fwd.com  
**Sent:** Tuesday, 10 September 2019 10:31 AM  
**To:** admin-d@lkkauto.com; admin-a@lkkauto.com  
**Cc:** motorclaims.sg@fwd.com; lionel.tan@fwd.com  
**Subject:** PRE-REPAIR NOTICE OF ROAD TRAFFIC ACCIDENT ON 06.09.2019 at about 2200 hours along PIE involving SCH 19U and FBJ 5744C (PURSUANT TO PARAGRAPH 2.2 OF THE PRE-ACTION PROTOCOL FOR NIMA CASES)  
**Attachments:** image001.emz

Dear Nivitha,

Please refer to the email below and liaise with TP repairer for PRS.

Please create the case in Merimen & our insured has yet to report.

Thank you.

Best Regards,

Venessa Chan

Administrative Assistant, Claims




FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

E [venessa.chan@fwd.com](mailto:venessa.chan@fwd.com)

W [www.fwd.com.sg](http://www.fwd.com.sg)



**From:** Prestina [mailto:prestina@jklc.com.sg]

**Sent:** Tuesday, September 10, 2019 10:24 AM

**To:** Venessa Chan - SGUser

**Cc:** General; Motor Claims SG - SG Common; Lionel Tan Tian Pei - SGUser

**Subject:** RE: PRE-REPAIR NOTICE OF ROAD TRAFFIC ACCIDENT ON 06.09.2019 at about 2200 hours along PIE involving SCH 19U and FBJ 5744C (PURSUANT TO PARAGRAPH 2.2 OF THE PRE-ACTION PROTOCOL FOR NIMA CASES)

WITHOUT PREJUDICE  
OUR: JK.19.SCH19U.PD

Dear Sir/Mdm,

We refer to your email of even date whereby parties are not agreeable to each other's list of motor surveyors.

Under the circumstances, no Single Joint has been agreed for this matter.

Please be informed that the said vehicle can be inspected at:

**Venue:** ECLIPSE AUTO PTE LTD

155 Kaki Bukit Avenue 1

Level 1

Singapore 416012

**Contact:** 8128 8789 (Please call before going)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Regards,  
Prestina  
Legal Executive



UEN No. 53394571B  
6A Shenton Way  
#04-02 to 08  
OUE Downtown Gallery  
Singapore 068815

Tel: 6914 2682  
Fax: 6429 1048  
Email: [prestina@jklc.com.sg](mailto:prestina@jklc.com.sg)

**For Surveyor**

Please initial here after completion of pre-repair inspection.  
Thank you.

Name:  
Signature:

Date & Time of Pre-repair Inspection:

**From:** [venessa.chan@fwd.com](mailto:venessa.chan@fwd.com) <[venessa.chan@fwd.com](mailto:venessa.chan@fwd.com)>

**Sent:** Tuesday, September 10, 2019 8:45 AM

**To:** Prestina <[prestina@jklc.com.sg](mailto:prestina@jklc.com.sg)>

**Cc:** General <[general@jklc.com.sg](mailto:general@jklc.com.sg)>; [motorclaims.sg@fwd.com](mailto:motorclaims.sg@fwd.com); [lionel.tan@fwd.com](mailto:lionel.tan@fwd.com)

**Subject:** PRE-REPAIR NOTICE OF ROAD TRAFFIC ACCIDENT ON 06.09.2019 at about 2200 hours along PIE involving SCH 19U and FBJ 5744C (PURSUANT TO PARAGRAPH 2.2 OF THE PRE-ACTION PROTOCOL FOR NIMA CASES)

WITHOUT PREJUDICE

Dear Prestina,

We regret that we are objecting to your proposed list of surveyors.

We will be appointing, M/s **LKK Auto Consultants Pte Ltd**, to conduct the pre-repair survey (PRS) on your client's vehicle, SCH19U. We seek your cooperation to inform your client's workshop to arrange the vehicle readily for dismantling with repair estimates during the pre-repair survey.



If there is a change in your client's workshop, please inform us soon. We reserve our rights for re-inspection.

*\*Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to [motorclaims.sg@fwd.com](mailto:motorclaims.sg@fwd.com).*

Thank you.

Best Regards,

Venessa Chan

Administrative Assistant, Claims




**FWD Singapore Pte. Ltd.**

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

E [venessa.chan@fwd.com](mailto:venessa.chan@fwd.com)

W [www.fwd.com.sg](http://www.fwd.com.sg)



**From:** Prestina [<mailto:prestina@jklc.com.sg>]

**Sent:** Monday, September 9, 2019 4:44 PM

**To:** Venessa Chan - SGUser

**Cc:** General; Motor Claims SG - SG Common; Lionel Tan Tian Pei - SGUser

**Subject:** RE: PRE-REPAIR NOTICE OF ROAD TRAFFIC ACCIDENT ON 06.09.2019 at about 2200 hours along PIE involving SCH 19U and FBJ 5744C (PURSUANT TO PARAGRAPH 2.2 OF THE PRE-ACTION PROTOCOL FOR NIMA CASES)

WITHOUT PREJUDICE

OUR: JK.19.SCH19U.PD

Dear Sir/Mdm,

We refer to your email of even date informing that you wish to conduct a pre-repair survey and your List of Surveyors.

TAKE NOTICE that we object to all your surveyors sated in your said List, for appointment as the Single Joint Expert.

Pursuant to Pre-Action Protocol for NIMA cases, we now propose appointment as Single Joint Expert the following surveyors for your consideration:

1. Alan Cheong
2. Amos Ong

Please reply within 2 working days

Regards,  
Prestina  
Legal Executive



UEN No. 53394571B  
6A Shenton Way  
#04-02 to 08  
OUE Downtown Gallery  
Singapore 068815

Tel: 6914 2682  
Fax: 6429 1048  
Email: [prestina@jklc.com.sg](mailto:prestina@jklc.com.sg)

**From:** [venessa.chan@fwd.com](mailto:venessa.chan@fwd.com) <[venessa.chan@fwd.com](mailto:venessa.chan@fwd.com)>  
**Sent:** Monday, September 9, 2019 3:43 PM  
**To:** Prestina <[prestina@jklc.com.sg](mailto:prestina@jklc.com.sg)>  
**Cc:** General <[general@jklc.com.sg](mailto:general@jklc.com.sg)>; [motorclaims.sg@fwd.com](mailto:motorclaims.sg@fwd.com); [lionel.tan@fwd.com](mailto:lionel.tan@fwd.com)  
**Subject:** PRE-REPAIR NOTICE OF ROAD TRAFFIC ACCIDENT ON 06.09.2019 at about 2200 hours along PIE involving SCH 19U and FBJ 5744C (PURSUANT TO PARAGRAPH 2.2 OF THE PRE-ACTION PROTOCOL FOR NIMA CASES)

WITHOUT PREJUDICE

Dear Prestina,

We refer to your email dated on 09.09.2019 of the PRI Notice of your client's vehicle SCH19U.

Please find our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD
4. RT APPRAISAL PTE LTD

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receiving your reply.

Thank you.

\*Please note that contents of this email should not be construed as any admission of liability on the part of our insured and/ or insurers. We hereby maintain full reservation of rights and all defences available to us.

\*Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to [motorclaims.sg@fwd.com](mailto:motorclaims.sg@fwd.com).

Best Regards,

Venessa Chan




**FWD Singapore Pte. Ltd.**

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

E [venessa.chan@fwd.com](mailto:venessa.chan@fwd.com)

W [www.fwd.com.sg](http://www.fwd.com.sg)



**From:** Prestina [<mailto:prestina@jklc.com.sg>]

**Sent:** Monday, September 9, 2019 3:38 PM

**To:** Motor Claims SG - SG Common

**Cc:** General

**Subject:** PRE-REPAIR NOTICE OF ROAD TRAFFIC ACCIDENT ON 06.09.2019 at about 2200 hours along PIE involving SCH 19U and FBJ 5744C (PURSUANT TO PARAGRAPH 2.2 OF THE PRE-ACTION PROTOCOL FOR NIMA CASES)

WITHOUT PREJUDICE

OUR REF: JK.19.SCH 19U.PD

Dear Sir/Mdm,

We are instructed by **SIN HOCK HUAT CONSTRUCTION** to notify you of a road traffic accident on **06.09.2019 at about 2200 hours along PIE** involving our client's vehicle registration number **SCH 19U** and vehicle registration number **FBJ 5744C** driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not received any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Regards,

Prestina

Legal Executive



UEN No. 53394571B

6A Shenton Way

#04-02 to 08

OUE Downtown Gallery

Singapore 068815

Tel: 6914 2682

Fax: 6429 1048

Email: [prestina@jklc.com.sg](mailto:prestina@jklc.com.sg)

**ATTENTION:**

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

**ATTENTION:**

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

**ATTENTION:**

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Business
Owner ID:	802D
<b>Vehicle Details</b>	
Vehicle No.:	SCH19U
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Sep 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E220D AUTO
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	65492080052244
Chassis No.:	WDD2130042A120503
Maximum Power Output:	143.0 kW (191 bhp)
Open Market Value:	\$55,192.00
Original Registration Date:	11 Jan 2017
First Registration Date:	11 Jan 2017
Transfer Count:	1
Actual ARF Paid:	\$61,346.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Jan 2027
PARF Rebate Amount:	\$46,009.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	10 Jan 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,229.00
COE Rebate Amount:	\$33,901.00
<b>Total Rebate Amount:</b>	<b>\$79,910.00</b>

The information contained herein is correct as at 10 Sep 2019

OK

## AUTOMOBILE ASSESSMENT REPORT

TO: SIN HOCK HUAT CONSTRUCTION  
C/O: ECLIPSE AUTO PTE LTD  
155 KAKI BUKIT AVE 1 #01-00,  
SHUNLI INDUSTRIAL PARK  
SINGAPORE 416012

Our Reference: 919/EA300  
Date: 30-Sep-2019

### ASSESSMENT OF VEHICLE NO. SCH 19 U

DATE OF LOSS: 06-Sep-2019

We have carried out a physical assessment at ECLIPSE AUTO PTE LTD,  
155 Kaki Bukit Ave 1 #01-00 Shunli Industrial Park, Singapore 416012, according to your instruction  
on 10-Sep-2019 and are pleased to submit our report herewith.

### 1. VEHICLE PARTICULARS

Registration No.: SCH 19 U  
Make & Model: MERCEDES BENZ E220D AUTO  
Year of Registration: 2017  
Engine Capacity: 1950  
Chassis No.: WDD2130042A120503  
Engine No.: 65492080052244  
Colour: BLUE  
Mileage (km): 92105

### 2. VEHICLE CONDITION

Body Paint: GOOD  
Steering: SERVICEABLE  
Foot Brake: SERVICEABLE  
Parking Brake: SERVICEABLE  
Modification: NIL

### 3. TYRE PARTICULARS & CONDITION

Front  
RH Make/Size/Thread: FALKEN 245/35 R19 – 70%  
LH Make/Size/Thread: FALKEN 245/35 R19 – 70%


Rear  
RH Make/Size/Thread: GOODYEAR 275/40 R19 – 70%  
LH Make/Size/Thread: GOODYEAR 275/40 R19 – 70%

#### 4. DESCRIPTION OF DAMAGE

At the time of the inspection, the vehicle sustained damages to the REAR portion.

#### 5. REMARKS

Market Value:	Na
Salvage Value:	Na
Repair Limit:	Na
Estimated Amount:	\$16,231.85
Adjusted Amount:	\$14,097.45
Lump Sum:	\$9,500.00
Estimated Repair Days:	8 days



Pursuant to your instruction, we have **NOT AUTHORISED** repair.

The assessment was conducted on a "Without Prejudice" basis.

If we are not notified of anything to the contrary within **14 days** from the date hereof, this report shall be treated as correct.

#### Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by Aeon Auto Consultants LLP for any reliance on this report by any third party.

**ASSESSMENT REPORT FOR VEHICLE NO. SCH 19 U**

**PARTS (LIST ITEMS)**

Qty	Description	Condition	Workshop's Estimate	Our Assessment
1	REAR BOOTLID	Bent	2,293.00	2,293.00 ✓
1	REAR BOOTLID 'E220d' EMBLEM	Necessary	75.00	75.00 ✓
1	REAR BOOTLID 'LOGO' EMBLEM	Necessary	60.00	60.00 ✓
2	REAR BOOTLID HINGES L/R	Repair	290.00	- x
1	REAR BOOTLID INNER PULL HANDLE	Repair	262.00	- x
2	REAR BOOTLID INNER RUBBER SIDE GUIDE STOPPER L/R <i>not new</i>	Bent	66.00	66.00 x
1	REAR BOOTLID LOCK STRIKER <i>not new</i>	Bent	88.00	88.00 x
1	REAR BOOTLID MECHANISM LOCK	Bent	236.00	236.00 ✓
1	REAR BOOTLID MECHANISM LOCK GARNISH	Cut	107.00	107.00 ✓
1	REAR BOOTLID WEATHER STRIP	Cut	238.00	238.00 ✓
1	REAR LH TAILLAMP	Reuse	596.00	- x
1	REAR RH TAILLAMP	Cracked	596.00	596.00 ✓
1	REAR RH TAILLAMP LOWER BRACKET	Bent	116.00	116.00 ✓
1	REAR BUMPER	Cracked	1,950.00	1,950.00 ✓
1	REAR BUMPER CENTER BRACKET	Bent	258.00	258.00 ✓
1	REAR BUMPER REINFORCEMENT	Bent	670.00	670.00 ✓
1	REAR BUMPER ELECTRICAL SENSOR <i>not new</i>	Faulty	310.00	310.00 x
1/2	REAR BUMPER REFLECTOR L/R <i>LH not new</i>	Necessary	340.00	340.00 170.
1	REAR BUMPER LOWER DIFFUSER	Cracked	875.00	875.00 720.
6	REAR BUMPER REVERSE SENSOR <i>1 piece damaged</i>	Faulty	1,404.00	1,404.00 234.
6	REAR BUMPER REVERSE SENSOR 'O' RING	Necessary	108.00	108.00 ✓
6	REAR BUMPER REVERSE SENSOR HOLDER <i>1 piece damaged</i>	Necessary	150.00	150.00 25
2	REAR BUMPER SIDE RETAINER L/R	Bent	62.00	62.00 ✓
1	REAR BUMPER SMART OPENER SENSOR LEAD <i>not new</i>	Faulty	367.50	367.50 x
1	REAR BUMPER SMART OPENER SYSTEM MODULES	Faulty	958.00	958.00 x
1	REAR BUMPER SMART OPENER SYSTEM MODULES GARNISH	Bent	158.00	158.00 ✓
1	REAR BUMPER TOW HOOK COVER	Necessary	79.00	79.00 ✓
1/2	REAR BUMPER EXHAUST CHROME GARNISH L/R <i>RH damaged</i>	Bent	460.00	460.00 230
1	REAR END PANEL INNER TOP GARNISH <i>not new</i>	Cut	156.00	156.00 x
1	REAR END PANEL	Repair	768.00	- x
			14,096.50	12,180.50
Less 10% discount			1,409.65	1,218.05
Parts Total:			12,686.85	10,962.45

8227

7404-30



**ASSESSMENT REPORT FOR VEHICLE NO. SCH 19 U**

**SPECIAL NETT ITEMS**

1	REAR BOOTLID INNER PULL HANDLE CLIPS - SET	Necessary	40.00	40.00 X
1	REAR BOOTLID MECHANISM LOCK GARNISH CLIPS - SET	Necessary	40.00	40.00 X
2	REAR TAILLAMP CLIPS L/R - SET	Necessary	40.00	40.00 20
1	REAR BUMPER CLIPS - SET	Necessary	80.00	80.00 50
1	REAR BUMPER REVERSE SENSOR WIRE HARNESS - SET	Cut	255.00	255.00 +
1	REAR END PANEL INNER TOP GARNISH CLIPS - SET	Necessary	40.00	40.00 X
Special Nett Total :			495.00	495.00

**LABOUR**

S/N	Description	Workshop's Estimate	Our Assessment
1	To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.	120.00	<del>100.00</del> 80
2	To remove, reinstall top trim upholstery, cushion seat, trim garnish, trim liner carpet.	100.00	<del>80.00</del> 60
3	To reset system after repair works.	350.00	<del>300.00</del> 150
4	To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,200.00	<del>1,100.00</del> 500
5	To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1,200.00	<del>1,000.00</del> 750
6	To apply anti-rust chemical on repaired and replaced panel.	80.00	<del>60.00</del> 40
Labour Total :		3,050.00	2,640.00
TOTAL (PARTS & LABOUR) \$		16,231.85	14,097.45

The workshop has agreed to undertake the repair on a Lump Sum basis.

The final adjusted Lump Sum contract amount is

**\$9,500.00**

**(SINGAPORE DOLLARS NINE THOUSAND FIVE HUNDRED ONLY)**



Arrias Ong  
Automobile Assessor

total: 9054.30

h/s: Talc

05 Days

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. This Form must be completed by the Policyholder and/or the Insured.
2. This Form must be completed by the Policyholder and/or the Insured.
3. Information provided must be as truthful and accurate as possible. Any intentional misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and the copies of this report will, for a fee, be made available upon application by interested parties.
7. By this statement, I warrant that I am the owner, driver or person in possession of the vehicle at the time of the accident.

ACCIDENT STATEMENT	
Date Of Report	09/09/2019 13:12
Date Of Accident	08/09/2019 22:00
Exact Location Of Accident	ALONG PIE
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Identification Number	SC1130
Name Of Registered Owner	SIN HOCK HUAT CONSTRUCTION
Co Reg No	-
Email Address	SINHOCKHUAT@SINGNET.COM.SG
Mobile Phone No	-
Alternative Phone No	OFFICE-90079387
Manufacturer	MERCEDES-BENZ
Model	-
Exact Purpose for which vehicle was being used at time of accident	-
Are you covered under your own insurance policy for repair to your vehicle?	NO
If No, which party is liable to be a claim?	THIRD PARTY
Vehicle Category	PRIVATE CAR
INSURANCE INFORMATION	
Name of Insurance Company	ERGO INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPG19000790
Cover time includes	-
DRIVER INFORMATION	
Name of Driver	KENG YEW HUAT
NRIC No	S1795654Z
Date Of Birth	16/08/1967
Occupation	INDOOR
Date Of Driver's Pass	22/04/1988
Driving Experience	11 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90079387
Fax Number	-
Contact Number	-
Email Address	NOEMAIL

Address BUKIT BATOK JURONG WEST ST 81 #03-588  
 Postcode 66659  
 Was driver of the Insured's Company? YES  
 If No, Relationship of the Driver with the Insured  
 Vehicle Registration Number of Driver's Own Vehicle  
 Insurance of Driver's Own Vehicle

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface Dry

Was any other vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident? 2  
 Was any person injured or killed? YES  
 Was any injured person(s) admitted to hospital by ambulance? YES  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/claiming for first claim assistance. NO  
 Number of Passengers (including Driver) 1

Was the accident reported to the police? YES  
 If Yes, Police Station Name BUKIT BATOK NEIGHBOURHOOD POLICE CENTRE  
 Police Station Address ROAD 21 BUKIT BATOK EAST AVE 4 , POSTCODE: 666540 , COUNTRY: SINGAPORE  
 Police Station Contact TEL NO: 1800-6659999 - FAX NO: 66655793  
 Was any physical evidence given? NO  
 If Yes, give details

DETAILS OF OTHER VEHICLE PROPERTY 1  
 PLEASE USE POLICE REPORT

Are policies or info available to applicant? YES  
 Was there any video captured by CCTV Camera? NO  
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number FBJ5744C  
 Vehicle Make/Model/Year  
 Details of Properties  
 Vehicle Category MOTORCYCLE  
 Name of Owner UNKNOWN  
 Motorcyclist's License  
 License Number  
 Address  
 Postcode  
 Insurance Company Name

Nature Of Damage

NA

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

KENG YEW HUAT

Approximate Age

Injury

Injured person in which vehicle?

SCH19U

Were seat belts worn?

YES

Was the injured person taken to hospital by ambulance?

YES

Address

Postcode

DETAILS OF INJURED PERSON 2

Name

UNKNOWN

Approximate Age

Injury

Injured person in which vehicle?

FBJ5744C

Were seat belts worn?

NO

Was the injured person taken to hospital by ambulance?

YES

Address

Postcode

# Accident Sketch Plan

A) 304 19 2  
 B) FBT 5744 C

## FACTS OF THE ACCIDENT

I have seen police report  
 Eclipse Auto Pk Co  
 Eclipse

9/9/2019  
 1:05 PM  
 Reporting Centre Member's Signature  
 Name  
 NRIC/PN No.

# Individual Statement

## SECTION PLAN

### IMPORTANT NOTICE

1. Please report accurately the details of this incident to us for the claim process.
2. This report shall be completed by the Insured and signed by the Insured and/or the Insurer.
3. Information provided must be true and accurate as possible. Any willful misrepresentation or withholding of material facts may constitute a breach of contract and may result in the policy being voided.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false statement may constitute a crime under the Police for Investigation.
6. This report will be forwarded by the Insured to the GSA to the Insurance Centre established by the General Insurance Corporation of Singapore (GIC) for reference and the details of this report will for a while be made available upon application by interested parties.
7. By the date (date of this report) the Insured, you hereby consent to the sharing of this report at the cost of an original of the report being made available to the said.
8. Consent under the Personal Data Protection Act (PDPA)

I, the Insured, acknowledge, agree and consent that:

- (a) All Insurers, my workplace and the Police, Insurance Corporation of Singapore ("ICA") and/or are permitted to collect, use, disclose and/or release my personal data/personal information set out in this form and any other personal information provided by me to the Insurers, my workplace, the Police, the ICA and/or any other "Personal Information" and disclose and transfer such Personal Information to all Insurers who have insured vehicles involved in this accident (all Insurers) who have insured vehicles involved in this accident shall be collectively referred to as the "Insurers"; the Insurers' lawyers/law firms, the Solicitors' Authority, the relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) providing, handling and/or dealing with my claims including those settlement of the claims and any necessary investigations relating to the claims;
  - (ii) to my workplace, Insurers and/or the Police;
  - (iii) handling and/or dealing with my enquiries or responding to any enquiries by me;
  - (iv) collecting, handling and/or dealing with my correspondence, statements, reports or notices to me, including any correspondence or notices relating to my personal data about me to bring about delivery of the claim as well as on the external cover of envelopes/mail packages; and/or
  - (v) handling and/or dealing with my claims including those settlement of the claims and any necessary investigations relating to the claims.
- (b) Insurers and/or my workplace have no liability in this accident and the Insurers' lawyers/law firms, those Insurers permitted to collect, use, disclose and/or process my personal information for one or more of the above purposes; and
- (c) my personal data and/or any other information may be disclosed by any of the Insurers and/or to their third party service providers or agents, including but not limited to, those who may be located outside of Singapore, for one or more of the above purposes;
- (d) my personal data and/or any other information may be used to compile claims history for the purpose of fraud detection, investigation and/or management in present and all future claims;
- (e) my personal data and/or any other information may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing (investigating, handling and/or dealing with) my claims and government agencies as reasonably required for the purposes stated; or
  - (ii) for compliance with any applicable laws or court orders.

Policyholder's Name: [Name]  
Date & Time: [Date & Time]

Insured's Signature  
(Insured's name in the policyholder's)  
Date & Time: [Date & Time]

Reporting Centre Personnel's Signature  
Name: [Name]  
NIC/TPN No.: [NIC/TPN No.]



**SINGAPORE  
POLICE FORCE**



T/20190907/2139

1 of 2

Police Station Of Origin:  
East District S.P.O.  
21 Bukit Batok East Avenue 4 SINGAPORE  
650041  
Tel No: 1900-8659999

Report No: T/20190907/2139

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 07/09/2019 18:40	Video Report No.: G/20190906/0193	Station Diary No.: 147
<b>Informant's Particulars</b>		
Name of Informant: NONG YEW HUAT	Address: APT BLK 859 JURONG WEST STREET 81 #03-588 SINGAPORE 640859	
ID Type / ID No.: NRIC No: / S17836642	Contact No.: Home/Office:	Mobile: 90079387
Nationality: SINGAPORE CITIZEN	Email:	
Sex: Male	Age: 52	Date of Birth: 18/05/1967
Race: Chinese	Type of Informant: Driver	Institution / School Name:
Occupation: CONSTRUCTION MANAGING DIRECTOR	Driving Licence Information: Class: 3	Date of Expiry:

<b>Details of the Accident</b>				
Type of Accident: Injury	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 06/09/2019 22:00	Type of Location: Straight Road
Location: Along Road T PAN ISLAND EXPRESSWAY Along PIE 10.5KM LP478				
Weather: Clear	Road Surface: Dry	Road Speed Limit:		
Traffic Flow: One Way	Traffic Control: Not Controlled	Traffic Volume: Moderate		
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Vehicle No.	Vehicle Type	Make	Model	Color	Condition	No. of Passenger
PS567140	Motorcycle					0
9011801	Car	MERCEDES BENZ	E220D AUTO	Silver	Seriously Damaged	0

<b>Details of Person Involved</b>	
Any Person Involved: No	Use of Pedestrian Crossing: NA





**SINGAPORE  
POLICE FORCE**



T/20190907/2139

2 of 3

Police Station Of Origin:  
Bukit Batok N.P.C  
21 Bukit Batok East Avenue 4 SINGAPORE  
658840  
Tel No: 1900-8352999

Report No. T/20190907/2139

## CONTINUATION OF REPORT

Name	Unknown Rider	ID No.	NIL
Related Vehicle	FBJ5744C (Motorcycle)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Name	KENG YEW HUA?	ID No.	S1795654Z
Related Vehicle	SCH19U (Car)	Contact No.	90079387
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

## Brief Details.

On 26/09/2019 at about 2200hrs, I was driving my vehicle bearing the registration plate SCH19U along PIE towards Changi near Euros. I was at the 2nd lane from the right, slowing coming to a stop as the car in front having braked. I then looked into the rear view mirror and saw a motorcycle bearing the registration plate FBJ5744C riding very fast towards me and it could not stop in time therefore it hit onto the rear of my car. The rider of the motorcycle was on the floor however he was able to stand-up himself. I could not see clearly what was the injuries on him. Subsequently, we stopped at the side and soon after passerby have helped to call the Ambulance and Traffic Police. Traffic police was subsequently at scene. Ambulance was also at scene and the rider was being conveyed to the hospital.

The Police then handed to me a case card ref G/20190906/0193 with the IO incharge Jeya, H: 65476232 and advised me to lodge a Traffic Accident report after they record my statement. The rear bumper, exhaust pipe, car pipe, sensor and headlights of my vehicle were all damaged. I have no idea how much is the cost of repair. I do not have an in car camera. I will go and see a doctor later as my neck is abit pain.





**SINGAPORE  
POLICE FORCE**



T/20190907/2139

3 of 3

Report No. T/20190907/2139

Police Station Of Origin:  
Bukit Batok N.P.C  
21 Bukit Batok East Avenue 4 SINGAPORE  
659640  
Tel No: 1800-8659999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: 21 Sgt 2 YEO YULIN	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 07/09/2019 18:49
Officer In Charge Of Case: TM/GIT/ JAGESH JEYATHESH Call No.: 65476232	Classification Of Case:

Position Stamp

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Sep 2019 <a href="#">Edit Reg</a>		10 Sep 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$7,200.00</b> <a href="#">Edit Estimates</a>	<b>S\$7,200.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<a href="#">Show All</a>
-------------	------------------	----------------------	------------------	--------------------------

**CLAIM SUBFOLDER DETAILS** [Created by adjuster]

Insured:	LEE PECK HWA, ID: 57776026A		
Main Claimant:	SIN HOCK HUAT CONSUTRUCTION, Co. Reg. No.: 52942802D		
Vehicle Reg. No.:	SCH19U	Date of Loss:	06/09/2019 00:00 - :59 [31 Months and 26 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 1201900026795	Policy/Cover Note No.:	PNMC2019-00002564 (TP, Fire & Theft) Coverage: 16/07/2019 - 15/07/2020
Vehicle Reg. No. (Insured):	FBJ5744C	Policy No. (Claimant):	
		Excess:	
Repairer:	Eclipse Auto Pte Ltd (HQ) 155 Kaki Bukit Avenue 1, Shun Li Industrial Park #01-01, 416012 Kaki Bukit - Tel:		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Lionel Tan]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 19/09/2019]		

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

There are no mail for this case.

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SCH19U (1201900026795)  
[FBJ5744C]

TP














SIN HOCK HUAT CONSTRUCTION

Sep 6 2019 12:00AM

[LEE PECK HWA]

Eclipse Auto Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View <div>View in Browser</div>		
Photos/Images									3 per page		<div></div>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	12/09/19 12:01	General View							<div></div> Load JPG	<div></div>	
2	12/09/19 12:01	General View							<div></div> Load JPG	<div></div>	
3	12/09/19 12:01	General View							<div></div> Load JPG	<div></div>	
4	12/09/19 12:01	General View							<div></div> Load JPG	<div></div>	
5	12/09/19 12:01	General View							<div></div> Load JPG	<div></div>	
6	12/09/19 12:01	General View							<div></div> Load JPG	<div></div>	
7	12/09/19 12:01	General View							<div></div> Load JPG	<div></div>	
8	12/09/19 12:01	General View							<div></div> Load JPG	<div></div>	
9	12/09/19 12:01	General View							<div></div> Load JPG	<div></div>	
10	12/09/19 12:01	General View							<div></div> Load JPG	<div></div>	
11	12/09/19 12:01	General View							<div></div> Load JPG	<div></div>	
12	12/09/19 12:01	General View							<div></div> Load JPG	<div></div>	
13	12/09/19 12:01	General View							<div></div> Load JPG	<div></div>	
14	12/09/19 12:01	General View							<div></div> Load JPG	<div></div>	
15	12/09/19 12:01	General View							<div></div> Load JPG	<div></div>	
16	12/09/19 12:01	General View							<div></div> Load JPG	<div></div>	
17	12/09/19 12:01	General View							<div></div> Load JPG	<div></div>	
18	12/09/19 12:01	General View							<div></div> Load JPG	<div></div>	
19	12/09/19 12:01	General View							<div></div> Load JPG	<div></div>	
20	12/09/19 12:01	General View							<div></div> Load JPG	<div></div>	
21	12/09/19 12:01	General View							<div></div> Load JPG	<div></div>	
22	12/09/19 12:01	General View							<div></div> Load JPG	<div></div>	
23	12/09/19 12:01	General View							<div></div> Load JPG	<div></div>	
24	12/09/19 12:01	General View							<div></div> Load JPG	<div></div>	
25	12/09/19 12:01	General View							<div></div> Load JPG	<div></div>	
26	12/09/19 12:01	General View							<div></div> Load JPG	<div></div>	
27	12/09/19 12:01	General View							<div></div> Load JPG	<div></div>	
28	12/09/19 12:01	General View							<div></div> Load JPG	<div></div>	
29	12/09/19 12:01	General View							<div></div> Load JPG	<div></div>	
30	26/09/19 16:52	Photographs of Damaged Parts							<div></div> Load JPG	<div></div>	
31	26/09/19 16:52	Photographs of Damaged Parts							<div></div> Load JPG	<div></div>	
32	26/09/19 16:52	Photographs of Damaged Parts							<div></div> Load JPG	<div></div>	
33	26/09/19 16:52	Photographs of Damaged Parts							<div></div> Load JPG	<div></div>	
34	26/09/19 16:52	Photographs of Damaged Parts							<div></div> Load JPG	<div></div>	
35	26/09/19 16:52	Photographs of Damaged Parts							<div></div> Load JPG	<div></div>	
36	26/09/19 16:52	Photographs of Damaged Parts							<div></div> Load JPG	<div></div>	
37	26/09/19 16:52	Photographs of Damaged Parts							<div></div> Load JPG	<div></div>	
38	26/09/19 16:52	Photographs of Damaged Parts							<div></div> Load JPG	<div></div>	
39	26/09/19 16:52	Photographs of Damaged Parts							<div></div> Load JPG	<div></div>	
40	26/09/19 16:52	Photographs of Damaged Parts							<div></div> Load JPG	<div></div>	
41	26/09/19 16:52	Photographs of Damaged Parts							<div></div> Load JPG	<div></div>	
42	26/09/19 16:52	Photographs of Damaged Parts							<div></div> Load JPG	<div></div>	
43	26/09/19 16:52	Photographs of Damaged Parts							<div></div> Load JPG	<div></div>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	26/09/19 16:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	26/09/19 16:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	26/09/19 16:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	26/09/19 16:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	26/09/19 16:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	26/09/19 16:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	26/09/19 16:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	26/09/19 16:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	26/09/19 16:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	26/09/19 16:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	26/09/19 16:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	26/09/19 16:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	26/09/19 16:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	26/09/19 16:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	26/09/19 16:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	26/09/19 16:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	10/10/19 12:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
61	10/10/19 12:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
62	10/10/19 12:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
63	10/10/19 12:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
64	10/10/19 12:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
65	10/10/19 12:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
66	10/10/19 12:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
67	10/10/19 12:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
68	10/10/19 12:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
69	10/10/19 12:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
70	10/10/19 12:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
71	10/10/19 12:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
72	10/10/19 12:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
73	10/10/19 12:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
74	10/10/19 12:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
75	10/10/19 12:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
76	10/10/19 12:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
77	10/10/19 12:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
78	10/10/19 12:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
79	10/10/19 12:54	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	10/09/19 16:31	EMAIL TO OI (NR)	 Load PDF	
2	10/09/19 16:33	SURVEY DISAGREE ON SJE - ASSIGN LKK	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/FWD19016003/AVD3E2

Date: 01/11/2019

## REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNMC2019-00002564  
 Claimant: SCH19U Insured Vehicle No: FBJ5744C  
 Vehicle No: SCH19U  
 Date of Loss: 06/09/2019 Nature of Claim: TP Claim No: 1201900026795

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SCH19U  
 Make & Model: MERCEDES-BENZ E220D SE, 2.0 (A) Engine No: 65492080052244  
 Reg. Date: 11/01/2017 (Man. Year: 2016) Chassis No: WDD2130042A120503  
 Colour: Blue Odometer: 92105 km  
 Engine Capacity: 1950 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 275/40 R19 Rear Tyre Size: 275/40 R19  
 Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm  
 Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,181.85	7,474.30	5,707.55	43.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,050.00	1,580.00	1,470.00	48.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>16,231.85</b>	<b>9,054.30</b>	<b>7,177.55</b>	<b>44.22</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>7,200.00</b>		
<b>Nett Amount (S\$)</b>	<b>16,231.85</b>	<b>7,200.00</b>	<b>9,031.85</b>	<b>55.64</b>

## INSPECTION

Date of Assignment: 10/09/2019  
 Date Inspected: 10/09/2019 Inspected At: Eclipse Auto Pte Ltd (HQ)  
 155 Kaki Bukit Avenue 1, Shun Li  
 Industrial Park #01-01  
 Singapore 416012  
 Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 01 Nov 2019)
<b>Parts:</b>	143	MERCEDES-BENZ E220D SE 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SCH19U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Bent	2,293.00 FL	*2,293.00 FL
2	1		*REAR BOOTLID E220D EMBLEM	Necessary	75.00 FL	*75.00 FL
3	1		*REAR BOOTLID LOGO EMBLEM	Necessary	60.00 FL	*60.00 FL
4	2		*REAR BOOTLID HINGES L/R	Repair	290.00 FL	*- FL
5	1		*REAR BOOTLID INNER PULL HANDLE	Repair	262.00 FL	*- FL
6	2		*REAR BOOTLID INNER RUBBER SIDE GUIDE STOPPER L/R	Not Necessary	66.00 FL	*- FL
7	1		*REAR BOOTLID LOCK STRIKER	Not Necessary	88.00 FL	*- FL
8	1		*REAR BOOTLID MECHANISM LOCK	Bent	236.00 FL	*236.00 FL
9	1		*REAR BOOTLID MECHANISM LOCK GARNISH	Cut	107.00 FL	*107.00 FL
10	1		*REAR BOOTLID WEATHERSTRIP	Cut	238.00 FL	*238.00 FL
11	1		*REAR LH TAILLAMP	Reuse	596.00 FL	*- FL
12	1		*REAR RH TAILLAMP	Cracked	596.00 FL	*596.00 FL
13	1		*REAR RH TAILLAMP LOWER BRACKET	Bent	116.00 FL	*116.00 FL
14	1		*REAR BUMPER	Cracked	1,950.00 FL	*1,950.00 FL
15	1		*REAR BUMPER CENTER BRACKET	Bent	258.00 FL	*258.00 FL
16	1		*REAR BUMPER REINFORCEMENT	Bent	670.00 FL	*670.00 FL
17	1		*REAR BUMPER ELECTRICAL SENSOR	Not Necessary	310.00 FL	*- FL
18	1		*REAR BUMPER REFLECTOR L/R	O/S Necessary / N/S Not Necessary	340.00 FL	*170.00 FL
19	1		*REAR BUMPER LOWER DIFFUSER	Cracked	875.00 FL	*720.00 FL
20	1		*REAR BUMPER REVERSE SENSOR (6PCS)	Damaged (1Pc Only)	1,404.00 FL	*234.00 FL
21	6		*REAR BUMPER REVERSE SENSOR O RING	Necessary	108.00 FL	*108.00 FL
22	1		*REAR BUMPER REVERSE SENSOR HOLDER (6PCS)	Damaged (1Pc Only)	150.00 FL	*25.00 FL
23	2		*REAR BUMPER SIDE RETAINER L/R	Bent	62.00 FL	*62.00 FL
24	1		*REAR BUMPER SMART OPENER SENSOR LEAD	Not Necessary	367.50 FL	*- FL
25	1		*REAR BUMPER SMART OPENER SYSTEM MODULES	Not Necessary	958.00 FL	*- FL
26	1		*REAR BUMPER SMART OPENER SYSTEM MODULES GARNISH	Not Necessary	158.00 FL	*- FL
27	1		*REAR BUMPER TOW HOOK COVER	Necessary	79.00 FL	*79.00 FL
28	1		*REAR BUMPER EXHAUST CHROME GARNISH L/R	O/S Damaged	460.00 FL	*230.00 FL
29	1		*REAR END PANEL INNER TOP GARNISH	Not Necessary	156.00 FL	*- FL
30	1		*REAR END PANEL	Repair	768.00 FL	*- FL
31	1		*SET REAR BOOTLID INNER PULL HANDLE CLIPS	Not Necessary	40.00 FS	*- FS
32	1		*REAR BOOTLID MECHANISM LOCK GARNISH CLIPS	Not Necessary	40.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
33	2		*SET REAR TAILLAMP CLIPS L/R	Necessary	40.00 FS	*20.00 FS
34	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*50.00 FS
35	1		*SET REAR BUMPER REVERSE SENSOR WIRE HARNESS	Not Necessary	255.00 FS	*- FS
36	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>14,591.50</b>	<b>8,297.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (S\$)</b>	<b>1,409.65</b>	<b>822.70</b>
<b>Total Parts (S\$)</b>	<b>13,181.85</b>	<b>7,474.30</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	120.00	80.00
2	TO REMOVE, REINSTALL TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET	New	100.00	60.00
3	TO RESET SYSTEM AFTER REPAIR WORKS	New	350.00	150.00
4	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	New	1,200.00	500.00
5	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,200.00	750.00
6	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	80.00	40.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,050.00</b>	<b>1,580.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >