

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 02/09/2019
TP Veh Reg No: SMN210H

Estimate No: EST1900290
Date: 09 Sep 2019
Veh Reg No: SLZ7201L
Make/Model: HONDA FIT 1.3GF CVT
Chasis No: GK31316503
Reg. Date: 16/05/2018
Your Ref No: SMN210H

Estimate Repair Cost to Vehicle No :SLZ7201L

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	List Price		
1	1 PC FRT BUMPER <i>del</i>	1337.10	781.60 ✓
2	1 PC FRT BUMPER RETAINER LH <i>re</i>	1069.68	34.60 ✓
3	1 PC HEADLAMP LH <i>then included</i>		762.50 ✓
		1,578.70	
	Less 20%	315.74	1,262.96
	Special Net		
4	1 SET FRT BUMPER CLIPS <i>re</i>	40	40.00 ✓
		40.00	40.00
	Labour		
5	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.		650.00 <i>200</i>
6	1 TO SPRAY PAINTING		650.00 <i>200</i>
7	1 TO SPRAY UNDERSEAL	630	80.00 ✓
8	1 TO CHECK WIRING		50.00 <i>30</i>
		1,430.00	1,430.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 1735.68
H/s I-HK
03 Sep
1-HK

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 **FAX:** 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 02/09/2019
TP Veh Reg No: SMN210H

Estimate No: EST1900290
Date: 09 Sep 2019
Veh Reg No: SLZ7201L
Make/Model: HONDA FIT 1.3GF CVT
Chasis No: GK31316503
Reg. Date: 16/05/2018
Your Ref No: SMN210H

Estimate Repair Cost to Vehicle No :SLZ7201L

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	Total		S\$ 2,732.96
	Add GST @ 7%		191.31
	Total Amount Payable		<u>S\$ 2,924.27</u>

TOTAL: SINGAPORE DOLLAR TWO THOUSAND NINE HUNDRED TWENTY FOUR AND CENTS
TWENTY SEVEN ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time
which may be required after work has begun.

AT

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE

Adrian King
w/s 09/09/19.
03 days.