

ASS. REC. BY:

REF: CS/FCI19016017/ VS d3 ^{m2}

Special Instruction:

Envelope: Marcus

CWS

ASSIGNMENT (Office)

From (Person): Mengira chian

of FCI

Date/Time: 12.16pm @ 10/9/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: QBE 6225D

Insured: SHC 0746X

at Workshop m/s ZOOM Auto Services

Tel: 94507920

of 130 Bedok Reservoir Road # 05-1339

Policy No:

Claim No: D19005788 MFST

Sum Insured:

Excess:

Make of Veh: (Client's Record)

D.O.A. 4/09/2019

CA / REV / REP. / REV 24 HRS (DS)

H.O.D. Endorsement:

Date/Time: 12.57pm @ 10/9/19

Person Contacted:

Eline ... Vehicle IN / OUT

Date/Time	Action/Instruction	Estimated	Insp: 15 Kaki Bukit Road 4 #01-53
	QBE 6225D-X		
	SHC 0746X - NS/11NC18019171/1clghn2		SOA: 19/10/2018
12/9/19	Informed FCI pending workshop est by email		

ASS. REC. BY:

REF: FCI

ASSIGNMENT

From: _____ Date: 11/09/2019

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: GBE 622SD
at Workshop m/s Zoom Autowerks
of 15 Telci Bulkit Road 4 #01-53

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: After 11am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 42

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (DS) 2150
Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: GBE 622SD Yr Regn: 1 / 16

Type: M.Car / M.Cycle / Bus / Van / Loary / Taxi / Prime Mover /

Truck / Trailer or (M)

Make: Toyota Dyna C.C. 2982

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 182232 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFAT35 Y80K205623

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195 R15 OHTSU

R: 155 R12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front

Rear

R/Bal: 6 mm R/Bal: 6/6 mm

L/Bal: 6 mm L/Bal: 6/6 mm

D.O.A: 4/9/19 D.O.I: 11/9/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MA 12762 bys 4hrs.

1/10/19 Confirmed 2/5 @ 3600 w.l. Slin
(@ 4,453.75 Red - 55%)

RECEIVED 02 OCT 2019

Date/Time, File Pass to?

02/10/19
Typist

: Prel. Report

: Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Date/Time, File Return to?

2)

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech. Invs (\$)

: Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photo

Other

TOTAL

160

50

50

62

322

Report Format :

Temp Est. H.P.R. @ \$3,600/- H/S

MOTOR SURVEY ASSIGNMENT

Date 06-09-2019 **Our Ref No.** D19005788MFSH
Accident Date 04-09-2019 **Claim Type.** Third Party
Insured Vehicle SHC0746X **Third Party Vehicle.** GBE6225D
Survey Location 130 BEDOK RESERVOIR ROAD#08-1339
Contact Person. ELIN CAI
Contact No. 0/ 94507920 **Fax No.** 0
Survey Type WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:
Appointed Surveyor LKK AUTO CONSULTANTS PTE LTD
Contact Person NA **Fax No.** 68416315
Contact Number. NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop ZOOM AUTOWERKS PTE LTD **Attention.** NIL
LTD
Cc : TP Solicitor NA **TP Solicitor Fax No.** NA
Officer Incharge MERINA CHIA SAN SAN

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 12 September 2019 8:51 AM
To: 'CWS Motor Claims'
Cc: 'Merina Chia'; SUR
Subject: RE: SURVEY ASSESSMENT - D19005788MFSH/1-GBE 6225D

Dear Sir/Madam,

Please be informed that we have inspected the vehicle GBE 6225D on 11/9/2019.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler **on behalf of Shirley**

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Tuesday, 10 September 2019 1:00 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Merina Chia' <MerinaChia@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19005788MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer arrange on 11/09/2019.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 10 September 2019 12:16 PM
To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Merina Chia <MerinaChia@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19005788MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

UOB VISA INFINITE METAL CARD
 Enjoy 25,000 welcome miles and up to 2 miles per S\$1 spend
[FIND OUT MORE](#)
 T&Cs apply

Post an Advertisement
 Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

2010 Nissan Teana 2.5 New 5 Years Coe At \$39500.



Only 2-Owners, Original Black Paintwork With 18 Inch Rims, Good Condition, Direct Owner - See Ad

Aut
 An Inspiration!
[click here to view our PRISTINE at](#)

Post an Ad

Advertiser Login

Ways of Selling

Browse by Category

Sort by Date Posted

17 vehicles

DYNA

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage
Search Selection	DYNA	Any	Any	2016	Any	Any
	Toyota Dyna 150 3.0M	\$48,800	\$7,020 /yr	30-Aug-2016	2,982 cc	74,000 km
Fuel Type: Diesel						
1 Owner Only! Low Mileage. Smooth Yet Powerful Engine And Gearbox. Original Upholstery From Borneo Means Under Utilised. One Of The Best And Durable 10ft Truck Worldwide. This Robust Truck Is Ready To Be On The Road, Arrange For Viewing And Test Drive This..						
Car (S) Pte Ltd						
Posted: 16-Sep-2019 Tags: 2016 Toyota Dyna, 2016 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota						
	Toyota Dyna 150 3.0M	\$45,800	\$6,890 /yr	11-May-2016	2,982 cc	24,787 km
Fuel Type: Diesel						
Low Mileage, 1 Owner, Accident Free, Owner Never Ferry Goods Or Pax At Back Before, Well-Maintained. High Trade In And High Loan Available. Call For Viewing Appointment.						
Posted: 16-Sep-2019 Tags: 2016 Toyota Dyna, 2016 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota						
	Toyota Dyna 150 3.0M	\$45,800	\$7,020 /yr	30-Mar-2016	2,982 cc	-
Fuel Type: Diesel						
View At Our Showroom Now! Cheapest In Market, 1 Owner Full Agent Serviced Unit! Reliable Manual Gear Train, Call Us Now!						
Yes Motoring						
Posted: 16-Sep-2019 Tags: 2016 Toyota Dyna, 2016 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota						
	Toyota Dyna 150 3.0M	\$47,800	\$7,540 /yr	20-Jan-2016	2,982 cc	-
Fuel Type: Diesel						
1 Owner Only! Accident Free, Immaculate Condition, No Repairs Needed, New Paintwork, New Servicing Done. Various Bank And In House Loan With Competitive Rate Available. Trade In Are Welcome. Call Us Now For Appointment.						
Skylink Auto Pte Ltd						
Posted: 15-Sep-2019 Tags: 2016 Toyota Dyna, 2016 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota						

Hyundai's new i10 gets a dynamic design

Hyundai Motor has unveiled the all new i10, featuring a new dynamic design that illustrates its agile and active nature.

Read this article

ta Dyna 150 3.0M	\$44,800	\$6,780 /yr	27-Apr-2016	2,982 cc	98,000 km
e: Diesel					

Compare

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	215C
Vehicle Details	
Vehicle No.:	GBE6225D
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Sep 2019
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA DYNA 150 MANUAL
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	1KD2575102
Chassis No.:	JTFAT35Y80K205623
Maximum Power Output:	-
Open Market Value:	\$24,944.00
Original Registration Date:	29 Jan 2016
First Registration Date:	29 Jan 2016
Transfer Count:	0
Actual ARF Paid:	\$1,248.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	28 Jan 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$20,015.00
COE Rebate Amount:	\$12,762.00
Total Rebate Amount:	\$12,762.00

The information contained herein is correct as at 12 Sep 2019

OK

LETTER OF UNDERTAKING

I/We, K. P. CHOW CONSTRUCTION, the owner of vehicle no. BR262ED

My/Our Insurance is under M/s AXA Insurance Pte Ltd, I/we shall decide whether to claim under my/our Policy or against the Third Party and if the former shall submit such a claim to M/s AXA Insurance Pte Ltd with all relevant facts and documents **within 14(fourteen) days of occurrence or discovery of damage.**

My/Our Third Party claim is handle by my/our preferred workshop, _____

Signed and Acknowledge by:

.....
Nric no. & signature of policyholder



.....
Company stamp

05/09/2017
.....
Date



redefining / insurance

AXA Insurance Pte Ltd
 1800 880 4808 (Within Singapore)
 (65) 6880 4888 (International)
 (65) 6880 4740
 customer.care@axa.com.sg
 www.axa.com.sg

date
 03/01/2019

policy number
 CV1 / CA152125

Certificate of Insurance

Commercial Vehicle (Third Party Risk and Compensation) Act (Chapter 103) - Commercial Vehicle (Third Party Risk and Compensation) Rules, 1997 (Road Transport Act, 1987 (Malaysia) - Commercial Vehicle (Third Party Risk) Rules, 1991 (Malaysia)

Policy details

Policyholder name	K.T. CHOW CONSTRUCTION	Certificate number	GA152125 / 1
Class	Cocapreinsure	KCD	20%
Expiry number	1KJ25731C2	Chassis number	ITP4TSVW001005635
Vehicle Registration number	GBE622SD		
Period of Insurance	from 29/01/2019 to 28/01/2020 (with dates included)		
Sum Insured	Market Value at Time of Loss		
Finance/Len Company	HONG LEONG FINANCE LIMITED		

Persons or classes of persons entitled to drive

Any person who is driving on the Policyholder's order or with their permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of law or by reason of any enactment or regulation in that behalf providing the Motor Vehicle.

Limitations as to use*

- (a) Use in connection with the Policyholder's business.
- (b) Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business.
- (c) Use for social, domestic and pleasure purposes.

The Policy does not cover:

- (a) Use for the hire or reward or for racing, performance, reliability trial or speed testing.
- (b) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

* Limitations include (dependent by Section 8 of the Commercial Vehicle (Third Party Risk and Compensation) Act, (Chapter 103) and Section 83 of the Road Transport Act, 1987 (Malaysia), and not to be included under these headings.

Excess

Section 1	SGD700.00
Windscreen	SGD140.00

An additional excess in application as follows:

Additional Own Damage Excess of SGD1,000 is applicable for any insured/uninsured drivers who:

- a) is 22 years old to 24 years old and/or
- b) is 65 years old to 70 years old and/or
- c) with driving experience of 1 year to less than 2 years on the relevant classes of driving license

Additional All Claims excess of \$2,000.00 is applicable for any insured/uninsured drivers who:

- a) is 18 years old to 24 years old and/or
- b) is 71 years old and above and/or
- c) with driving experience of less than 1 year on the relevant classes of driving license

Additional clauses & endorsements to your policy

Nil



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring
 #08-1339 Singapore 470130
 Tel: 9450 7920
 zoomautowerks@gmail.com

Vehicle Number : GBE6225D
 Model : Toyota Dyna

Date: 30/09/2019

Damaged Area: (Rear Portion Damaged)

Repairer Estimation Cost of Repair :
 Supplementary may be included during the cost of repair :

*Not Authorized
 LKR
 1/3 \$3600
 SDP*

Parts / Material :

Quantity				
1	Rear Tailgate	1262.60	00/Seat	\$ 1,850.00
2	Rear Tailgate Lock		o/s seat	\$ 270.00
3	Rear Tailgate Hinges		11	\$ 168.00
4	Rear Tailgate lower Side Bracket		o/s seat	\$ 396.00
5	Rear Tailgate Lower Side Bracket Mounting		o/s 70.11	\$ 152.00
6	Taillamps		o/s seat	\$ 550.00
7	Taillamps Bracket		o/s seat	\$ 150.00
8	Rear Number Plate Bracket		seat	\$ 185.00
9	Rear Number Plate Lamp		11	\$ 96.00
10	Rear End Panel	623.10	00/Seat	\$ 1,123.00
11	Rear Tyre Carrier		11	\$ 385.00
12	Rear Exhaust End Pipe		seat	\$ 565.00
13	Rear Tailgate Sticker (TOYOTA)		new	\$ 175.00
Parts :				\$ 6,065.00
Less Parts 25% :				\$ 1,516.25
Total Parts :				\$ 4,548.75

Special Net Items :

set
 Reverse Sensor
 70 KM/H Sticker
 Dyna Sticker
 13 Pax Sticker
 Rear Number Plate

short	\$ 320.00	200
new	\$ 35.00	10
new	\$ 75.00	45
new	\$ 35.00	10
seat	\$ 40.00	15
Total S/N Parts :	\$ 505.00	

Labour :

To Remove, Repair & Renew Rear Affected Accident Areas
 To Putty, Spray Paint on Affected Accident Areas
 To Check & Re-Connect all electrical wiring
 To Remove & Renew Rear Exhaust
 To Rust Proof Affected Areas

	\$ 1,500.00	800
	\$ 1,200.00	600
	\$ 50.00	20
	\$ 150.00	60
	\$ 100.00	80
Total Labour :	\$ 3,000.00	

TOTAL PARTS : \$ 4,548.75
TOTAL SPECIAL NET ITEM : \$ 505.00
TOTAL LABOUR : \$ 3,000.00
TOTAL REPAIR COST : \$ 8,053.75

DATE OF SURVEY / INSPECTED:
 RECOMMENDED PART BY PART / LUMP SUM :
 RECOMMENDED NUMBER OF DAYS :
 SURVEY BY / SURVEYOR FIRM :
 RE-SURVEY DISMANTLE PARTS / BEFORE PAINT / AFTER PAINT :
 FINALISED AMOUNT :

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

*7-3586.70
 257
 2675.02
 45/502
 3612*



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19016017/Usd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 07-10-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 746X	Veh. Inspected	GBE 6225D
Policy No.		Coverage (\$)	0.00
Claim No.	D19005788MFSH	Excess (\$)	0.00
Assign From	MERINA CHIA	Assign Date	10/09/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA DYNA (M)	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JTFAT35Y80K205623	Colour	SILVER
Odometer	182232	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15	OHTSU	6 mm
L/H Front Tyre	195 R15	OHTSU	6 mm
R/H Rear Tyre	155 R12 (D)	FALKEN	6/6 mm
L/H Rear Tyre	155 R12 (D)	FALKEN	6/6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	04/09/2019	Inspection Date	11/09/2019
Survey held at	15 KAKI BUKIT RD 4 #01-53		
Repairer	ZOOM AUTOWERKS PTE LTD		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 6225D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR TAILGATE	DENTED / BENT	1,850.00	1,265.60
2	REAR TAILGATE LOCK @\$135.00	O/S BENT	270.00	135.00
4	REAR TAILGATE HINGES @\$42.00	NOT NECESSARY	168.00	-
2	REAR TAILGATE LOWER SIDE BRACKET @\$198.00	O/S BENT	396.00	198.00
4	REAR TAILGATE LOWER SIDE BRACKET MOUNTING @\$38.00	O/S TORN (1 PC ONLY)	152.00	38.00
2	TAILLAMPS @\$275.00	O/S CRACKED	550.00	275.00
2	TAILLAMPS BRACKET @\$75.00	O/S BENT	150.00	75.00
1	REAR NUMBER PLATE BRACKET	BENT	185.00	185.00
2	REAR NUMBER PLATE LAMP @\$48.00	NOT NECESSARY	96.00	-
1	REAR END PANEL	DENTED / BENT	1,123.00	655.10
1	REAR TYRE CARRIER	NOT NECESSARY	385.00	-
1	REAR EXHAUST END PIPE	BENT	565.00	565.00
1	REAR TAILGATE STICKER (TOYOTA)	NECESSARY	175.00	175.00
	LESS 25% DISCOUNT		-1,516.25	-891.68
			4,548.75	2,675.02
SPECIAL NETT ITEMS				
1	SET REVERSE SENSOR (SN)	SHORTED	320.00	200.00
1	70 KM/H STICKER (SN)	NECESSARY	35.00	10.00
1	DYNA STICKER (SN)	NECESSARY	75.00	45.00
1	13 PAX STICKER (SN)	NECESSARY	35.00	10.00
1	REAR NUMBER PLATE (SN)	BENT	40.00	15.00
			505.00	280.00
LABOUR				
	TO REMOVE,REPAIR & RENEW REAR AFFECTED ACCIDENT AREAS.		1,500.00	800.00
	TO PUTTY,SPRAY PAINT ON AFFECTED ACCIDENT AREAS.		1,200.00	600.00
	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING.		50.00	20.00
	TO REMOVE & RENEW REAR EXHAUST.		150.00	60.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RUST PROOF AFFECTED AREAS.		100.00	80.00
			3,000.00	1,560.00
GRAND TOTAL			8,053.75	4,515.02
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,600.00

Report Ref No. CS/FCI19016017/Usd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.