

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 6061S (Supplementary)

DATE : 17/09/2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Door (LH) <i>Done 1st</i>			\$ 2,201.10 ✓
	Rear Door Lock Assy <i>Done</i>			\$ 240.00 ✓
	SUB TOTAL			\$ 2,441.10
	LESS 20%			\$ 488.22
	DISCOUNTED TOTAL			\$ 1,952.88
			<i>2441.10</i>	
			<i>1952.88</i>	
	Rear Door Advertisement Logo (LH) <i>N/A NF</i>			\$ 100.00 <i>Nett</i> ✗
	ESTIMATE TOTAL			\$ 2,052.88
				<i>35538.02</i>

Done
2 KE Ando
17/09/2019

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.