

INS. CASE OWNER:

JIMMY FOO

CC6/AIG19016020/Uda3

LKK:

IDAC:

ASSIGNMENT

Surveyor:

MARCUS

DOI: 10/09/2019

Date / Time: 10/09/2019

Registered in Merimen: 10/09/2019

Pre-assign / CCU / FTE



Insured Vehicle No.:

SGZ 308T

Claim No.:

2977280027SG

Name of Insured:

Lim Han Leong

Policy No.:

Insured Tel No.:

HP:

Make / Model:

East Coast Rd Near

Excess Sec II : \$5

D.O.A: 08/09/2019

Place of Accident:

Siglap Centre

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability:

% Final ? Yes / No

SGZ 308T



INSRS:

WSP: NPH AUTO

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	☐ ☐
	After call ltr to OI:	☐ ☐
	Authorisation To Act:	☐ ☐
	Release Voucher:	☐ ☐
	Final Repair Bill:	☐ ☐
	Car Rental Invoice:	☐ ☐
	Towing Invoice:	☐ ☐
	LTA / GIA:	☐ ☐
	Medical Bill:	☐ ☐
	PIR:	☐ ☐
	Mandate/Reject Instruction:	☐ ☐
	LOD	☐ ☐
	Payment Breakdown Form:	☐ ☐
	Post-Repair Photos:	☐ ☐
	Others:	☐ ☐

PRELIMINARY ADVICE Date/Time:		Sent By:	
FINALIZATION Date/Time:		Confirm with:	
Repair Cost:	\$5	(days) Reduction:	%
FINAL SETTLEMENT Date/Time: 30/12/19		Confirm with: Peggy	
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.:	29
Repair Cost: (w/hst)	\$5 3531.80		
Loss of Rental (LOR): (w/hst)	\$5 299.60	(2 days) x \$140	
Loss of Use (LOU):	\$5 -	(\$ x days)	
Loss of Income (LOI):	\$5 -	(\$ x days)	
LOR only ☒ LOU only ☐	LOR + LOU ☐	LOR + LOI ☐	(Tick only one)
GIA/LTA Search	\$5 -		
Medical:	\$5 -		
Disbursement:	\$5 -	(e.g. Tow/ Independent)	
Legal Cost	\$5 -		
Total:	\$5 3831.40	Global Sum \$5:	
FINAL PAYMENT Date/Time:		Confirm with:	
Payee 1:	\$5 3831.40	Name 1:	NPH Auto Service
Payee 2: (Strike if N.A.)	\$5	Name 2:	
Payee 3: (Strike if N.A.)	\$5	Name 3:	

COPY SENT

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: \$320

08/11/13) wcl
ASS. REC. BY: *Marcus*

REF:

A16/

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: *SG2308T*
at Workshop m/s *MPV*
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: *881.*

IDAC Accident Report: _____

GL / PR Seen *8*

Est. Repairs: *3* days

Res.: Yes or No

Lum Sum: _____

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

L1A53934

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: *SG2308T* Yr Regn: *6, 16*
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or *CA*
Make: *Toyota* harrier C.C. *1986*
Colour: *white* A/C: Insured / Std / NI / NA
Sp. Reading: *83234* T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: *25460 0078802*
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: *225/65 R17*
R: _____

BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. *6* mm

L/Bal. *6* mm

D.O.A. *8/9/19*

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision. *Acc*

Date / Time Action / Instruction

P/P - \$3300.75 (Red \$2270.45 / 417.)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐

Site Insp (\$ _____)

Interview (\$ _____)

Tech. Invs (\$ _____)

Weekend (\$ _____)

Photos

Others

Report Format: _____

Lump Sum / I.B.I. (\$) _____

TOTAL



QA International
ISO 9001:2000

UKAS
Quality Management
9001

$$\begin{array}{r}
 1665.75 \\
 1635.00 \\
 \hline
 3000.75
 \end{array}$$



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
E-mail: nphauto@pacific.net.sg



Your Ref : Page : 2/2
Our Ref : TP0066/09/19 Date : 10/09/2019

THIRD PARTY CLAIM

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost	U/Price	Total
		\$	\$	\$
Total Labour				\$1,925.00
Nett Total Before Gst				\$5,571.20

Your faithfully

NPH AUTO SERVICE
(Manager)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 573I

Vehicle Details

Vehicle No.: SGZ308T

Vehicle to be Exported: No

Intended Deregistration Date: 10 Sep 2019

Vehicle Make: TOYOTA

Vehicle Model: HARRIER ELEGANCE 2.0 A

Primary Colour: White

Manufacturing Year: 2016

Engine No.: 3ZRB786826

Chassis No.: ZSU600078802

Maximum Power Output: 111.0 kW (148 bhp)

Open Market Value: \$29,060.00

Original Registration Date: 10 Jun 2016

First Registration Date: 10 Jun 2016

Transfer Count: 0

Actual ARF Paid: \$27,684.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 09 Jun 2026

PARF Rebate Amount: \$20,763.00

Intended COE Rebate Details

COE Expiry Date: 09 Jun 2026

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$49,700.00

COE Rebate Amount: \$33,171.00

Total Rebate Amount: \$53,934.00

The information contained herein is correct as at 10 Sep 2019

OK

SGCARMART.COM

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

Get More Cash for Your Car, Post an Ad Today

Receive a higher selling price by selling your car yourself.
Advertise it for sale at just \$58, list till sold.

Post an Advertisement

Sell it yourself! Advertise it at just \$58 until it's SOLD!

Subaru Forester 2.0i-L Sunroof



Accident Free, Pristine Cond,
Fully Serviced By Motor Image,
Very Low Mileage
Direct Owner StarA2

Auto Inn

As Inspiration For Car Buyers

click here to view
our PRISTINE USED CARS
at GREAT PRICES

Browse by Category

Back (1 2 3) Next >

Sort by Date Posted

20 results/page

46 vehicles

Harrier

Advanced Search

Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Harrier		Any	Any	2016	Any	Any	Any	Available
	Toyota	Harrier 2.0A Elegance	\$90,800	\$11,190 /yr	20-Jul-2016	1,986 cc	100,000 km	SUV	Available
Well Maintained. Loans Available, With Lowest Interest Rates. High Trade In Welcome. Call Now To Book An Appointment To View This...									
Car Search									
Posted: 09-Sep-2019 Tags: 2016 Toyota Harrier, 2016 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota									
	Toyota	Harrier 2.0A Premium Panoramic	\$93,000	\$12,260 /yr	07-Jan-2016	1,986 cc	51,000 km	SUV	Available
Well Maintained Unit In Tip Top Condition Both Interior And Exterior! View To Believe. 1 Owner With Low Mileage Done. Trade In Welco...									
Posted: 09-Sep-2019 Tags: 2016 Toyota Harrier, 2016 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota									
	Toyota	Harrier 2.0A Premium Panoramic	\$88,800	\$11,820 /yr	29-Jan-2016	1,986 cc	82,000 km	SUV	Available
Toyota Harrier 2.0A Premium Panoramic, Buy With Peace Of Mind, Immediate Registration. Flexible Loan Available. Kindly Call Us To Dis...									
Shuang Hup Credit									
Posted: 09-Sep-2019 Tags: 2016 Toyota Harrier, 2016 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota									
	Toyota	Harrier 2.0A Premium Panoramic	\$92,500	\$12,090 /yr	23-Feb-2016	1,986 cc	52,538 km	SUV	Available
Premium Model! Popular Luxury Full-Size SUV That Has Both Style And Comfort! Car As Good As New! Drop By To See It With Your Own...									
Posted: 09-Sep-2019 Tags: 2016 Toyota Harrier, 2016 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota									
Car Buying									
Car Selling									
Car Ownership									
Car Aftermarket									
On The Move									
Lifestyle									
Buy Tyres Online									
Latest Special Offers from Tyrespac									
	Toyota	Harrier 2.0A Premium Panoramic	\$96,999	\$12,150 /yr	26-May-2016	1,986 cc	58,195 km	SUV	Available
Premium Model. 100% Accident-Free. One Owner. Alpine X009E Stereo For Harrier. V-kool For Whole Car Including Sunroof.									
Posted: 09-Sep-2019 Tags: 2016 Toyota Harrier, 2016 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota									
	Toyota	Harrier 2.0A Premium Panoramic	\$102,800	\$12,420 /yr	28-Sep-2016	1,986 cc	49,000 km	SUV	Available
12 Months Warranty And Attractive Financing Available With Free Titan X! Beautiful Black Premium Model With Panoramic Glass Roof! Fle...									
Supreme Cars Pte Ltd									
Posted: 08-Sep-2019 Tags: 2016 Toyota Harrier, 2016 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota									
Compare			\$92,188	\$12,320 /yr	06-Jan-2016	1,986 cc	-	SUV	Available

View Received Message

This mail is associated with :

***SGZ308T (6124521857SG)**
[SGD2115K]

TP
CHUA CHYE THIAM
Sep 8 2019 12:00AM
[LIM HUAT LEONG]
NPH Auto Service

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 27/12/2019 17:23 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$3831.40) - SGZ308T - Claim Handler: Foo, Chit Yan

Approved:3831.40;Cost of repair: \$3,531.80 (Subject to final repair bill) Rental: \$256.80 - \$299.60 (\$128.40 - \$149.80 x 2 days)

DOCUMENTS SUMMARY

There are no documents.

Jia Le (LKK Auto)

From: peggy <nphauto@pacific.net.sg>
Sent: Monday, 30 December 2019 10:26 AM
To: Jia Le (LKK Auto)
Subject: RE: Your ref: SGZ308T [ACCIDENT INVOLVING VEHICLES SGD2115K AND SGZ308T ON 08/09/2019]

Dear Jia Le

We prepare to accept your offer \$3831.40.

Please let us have the payment soon.

REGARDS

PEGGY FOO
NPH AUTO SERVICE
Email : peggy@nphauto.com
TEL: 67840663
FAX: 67840692

From: Jia Le (LKK Auto) [mailto:JiaLe@lkkauto.com]
Sent: Monday, 30 December 2019 9:17 AM
To: nphauto@pacific.net.sg
Subject: Your ref: SGZ308T [ACCIDENT INVOLVING VEHICLES SGD2115K AND SGZ308T ON 08/09/2019]

WITHOUT PREJUDICE

Dear Sir/Mdm.

We refer to the above matter.

We propose settlement as follows:-

1. Cost of Repair (w/GST)	\$ 3,531.80
2. Loss of Rental (2days x \$140)(w/GST)	\$ 299.60
TOTAL	\$ 3,831.40

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

"Best Wishes for Merry Christmas & Happy New Year 2020"

Best Regards,

Chan Jia Le | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Sep 2019 Edit Reg		10 Sep 2019 00:00 Edit Adj Rpt	S\$3,300.75 Edit Estimates	S\$3,300.75 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: LIM HUAT LEONG , ID: S0161337E, Tel: +6599999999									
Main Claimant: CHUA CHYE THIAM , ID: S0024573I									
Vehicle Reg. No.:	SGZ308T	Date of Loss:	08/09/2019 00:00 - :59 [38 Months and 28 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 6124521857SG	Policy/Cover Note No.:	2100471913 (Comprehensive)						
Vehicle Reg. No. (Insured):	SG02115K	Policy No. (Claimant):	D300132456QMY						
		Excess:							
Repairer: NPH Auto Service (HQ) Blk 9005 Tampines Steet 93, #01-246/254, 528839 Tampines - Tel: 6784 0663									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com									
Claimant's Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 19/09/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG_EXPRESS (27/12/2019): Alert - Adj Mandate Approved (S\$3831.40) - SGZ308T - Claim Handler: Foo, Chit Ya...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGZ308T (6124521857SG)
[SGD2115K]
TP
CHUA CHYE THIAM
Sep 8 2019 12:00AM
[LIM HUAT LEONG]
NPH Auto Service

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
Letters/Correspondences										1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	(Draft)	Third Party Express Settlement – Payment Breakdown							Edit		
Assessment Reports										1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	25/10/19 10:18	Adjuster Immediate Advice							Load HTM		
Photos/Images										3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	10/09/19 16:30	Odometer Reading							Load JPG ☒		
2	10/09/19 16:30	Chassis Number							Load JPG ☒		
3	10/09/19 16:31	General View							Load JPG ☒		
4	10/09/19 16:31	General View							Load JPG ☒		
5	10/09/19 16:31	General View							Load JPG ☒		
6	10/09/19 16:31	General View							Load JPG ☒		
7	10/09/19 16:31	General View							Load JPG ☒		
8	10/09/19 16:31	General View							Load JPG ☒		
9	10/09/19 16:31	General View							Load JPG ☒		
10	10/09/19 16:31	General View							Load JPG ☒		
11	10/09/19 16:31	General View							Load JPG ☒		
12	10/09/19 16:31	General View							Load JPG ☒		
13	10/09/19 16:31	General View							Load JPG ☒		
14	10/09/19 16:31	General View							Load JPG ☒		
15	10/09/19 16:31	General View							Load JPG ☒		
16	10/09/19 16:31	General View							Load JPG ☒		
17	10/09/19 16:31	General View							Load JPG ☒		
18	10/09/19 16:31	General View							Load JPG ☒		
19	10/09/19 16:31	General View							Load JPG ☒		
20	10/09/19 16:31	General View							Load JPG ☒		
21	10/09/19 16:31	General View							Load JPG ☒		
22	10/09/19 16:31	General View							Load JPG ☒		
23	10/09/19 16:31	General View							Load JPG ☒		
24	10/09/19 16:31	General View							Load JPG ☒		
25	10/09/19 16:31	General View							Load JPG ☒		
26	10/09/19 16:31	General View							Load JPG ☒		
27	10/09/19 16:31	General View							Load JPG ☒		
28	10/09/19 16:31	General View							Load JPG ☒		
29	10/09/19 16:31	General View							Load JPG ☒		
30	10/09/19 16:31	General View							Load JPG ☒		
31	16/09/19 18:53	Reinspection Photo							Load JPG ☒		
32	16/09/19 18:53	Reinspection Photo							Load JPG ☒		
33	16/09/19 18:53	Reinspection Photo							Load JPG ☒		
34	16/09/19 18:53	Reinspection Photo							Load JPG ☒		
35	16/09/19 18:53	Reinspection Photo							Load JPG ☒		
36	16/09/19 18:53	Reinspection Photo							Load JPG ☒		

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
37	16/09/19 18:53	Reinspection Photo	1	Load JPG	☒
38	16/09/19 18:53	Reinspection Photo	1	Load JPG	☒
39	16/09/19 18:53	Reinspection Photo	1	Load JPG	☒
40	16/09/19 18:53	Reinspection Photo	1	Load JPG	☒
41	16/09/19 18:53	Reinspection Photo	1	Load JPG	☒
42	16/09/19 18:53	Reinspection Photo	1	Load JPG	☒
43	16/09/19 18:53	Reinspection Photo	1	Load JPG	☒
44	16/09/19 18:53	Reinspection Photo	1	Load JPG	☒
45	16/09/19 18:53	Reinspection Photo	1	Load JPG	☒
46	16/09/19 18:53	Reinspection Photo	1	Load JPG	☒
47	16/09/19 18:53	Reinspection Photo	1	Load JPG	☒
48	16/09/19 18:53	Reinspection Photo	1	Load JPG	☒
49	16/09/19 18:53	Reinspection Photo	1	Load JPG	☒
50	16/09/19 18:53	Reinspection Photo	1	Load JPG	☒
51	16/09/19 18:53	Reinspection Photo	1	Load JPG	☒
52	16/09/19 18:53	Reinspection Photo	1	Load JPG	☒
53	16/09/19 18:54	Reinspection Photo	1	Load JPG	☒
54	16/09/19 18:54	Reinspection Photo	1	Load JPG	☒
55	16/09/19 18:54	Reinspection Photo	1	Load JPG	☒
Documentation				1 per page	☒
No	Refabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	11/09/19 18:04	TP GIA REPORT	1	Load PDF	
2	25/10/19 10:01	TP_ESTIMATE-MARKED-FINAL	1	Load PDF	
3	25/10/19 10:04	RENTAL RECEIPT	1	Load PDF	
4	08/01/20 08:37	WORKSHOP INVOICE	1	Load PDF	
5	08/01/20 08:37	AUTHORISATION TO ACT FORM	1	Load PDF	
6	08/01/20 08:37	Release Voucher	1	Load PDF	
7	08/01/20 08:37	LOD	1	Load PDF	
8	08/01/20 08:37	LETTER TO OI	1	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	18/09/19 14:45	OI GIA REPORT	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SGD2115K (Insd veh)	Model:	TOYOTA HARRIER 2.0
	SGZ308T (TP veh)		ELEGANCE (A)
Date of Accident:	08/09/2019		

Global Sum Settlement	☐ Yes	☒ No
Repair Estimate	\$	6,127.03
Final Repair Cost	\$	3,531.80
Loss of Use	\$	days at \$0.00 per day
Rental (if any)	\$	299.60 2 days
LTA / GIA Search Fee	\$	0.00
Others:	\$	0.00
	\$	
Final Settlement Sum	\$	3,831.40

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown		
1)	NPH Auto Service	\$ 3,831.40
2)		\$

JOANNE LEE KHANG MIN

08 Jan
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19016020/UDA3Q2

Date: 08/01/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100471913
 Claimant: SGZ308T Insured Vehicle No: SGD2115K
 Vehicle No: Date of Loss: 08/09/2019 Nature of Claim: TP Claim No: 6124521857SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGZ308T Engine No: 3ZRB786826
 Make & Model: TOYOTA HARRIER, 2.0 Elegance (A) Chassis No: ZSU600078802
 Reg. Date: 11/06/2016 (Man. Year: 2016) Odometer: 83234 km
 Colour: White
 Engine Capacity: 1986 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/65 R17 Rear Tyre Size: 225/65 R17
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,801.20	1,865.75	1,935.45	50.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,925.00	1,435.00	490.00	25.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,726.20	3,300.75	2,425.45	42.36
+ GST 7.00/7.00% (S\$)	400.83	231.05	169.78	42.36
Nett Amount (S\$)	6,127.03	3,531.80	2,595.23	42.36
+ Car Rental (2.0 x S\$140.00/day + 7.00% GST) (S\$)		299.60		
	Nett Liability (S\$)	3,831.40		

INSPECTION

Date of Assignment: 10/09/2019
 Date Inspected: 10/09/2019 Inspected At: NPH Auto Service (HQ)
 Blk 9005 Tampines Steet 93, #01-246/254
 Singapore 528839
 Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT HARRIER EMBLEM	Necessary	73.00 F	*73.00 FL
2	1		*REAR BUMPER	Dented / Deformed	1,400.00 F	*1,400.00 FL
3	1		*REAR BUMPER LOWER BLACK GARNISH	Cut	435.00 F	*435.00 FL
4	2		*REAR BUMPER SIDE RETAINER L&R	Not Necessary	170.00 F	*- FL
5	2		*REAR BUMPER REFLECTOR LAMP L&R	Not Necessary	115.20 F	*- FL
6	1		*REAR BUMPER SPONGE	Torn	125.00 F	*125.00 FL
7	6		*REAR BUMPER CLIPS	Necessary	33.00 F	*33.00 FL
8	1		*REAR LAMP CENTER PANEL LOCK PANEL	Repair	795.00 F	*- FL
9	2		*REAR BUMPER BRACKET L&R	Not Necessary	300.00 F	*- FL
10	1		*REAR BOOT KEYLESS SENSOR	Shorted	155.00 F	*155.00 FL
11	1		*REAR BUMPER PARKING SENSOR	Shorted	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,801.20	2,421.00
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	555.25
Total Parts (\$\$)	3,801.20	1,865.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & INSTALL R/LAMP ,R/BUMPER ,CUT OUT & RENEW R/LAMP CENTER PANEL ,KNOCK R/BOOT,R/SPARE TYRE PANEL AND RESTRIAGHTEN BODY & CHASSIS	New	850.00	600.00
2	SPRAY PAINTING FOR PEARL WHITE	New	850.00	700.00
3	CHECK WIRING SYSTEM	New	25.00	25.00
4	RENEW PARKING SENSOR AND RESET	New	100.00	50.00
5	REMOVE & INSTALL REAR BOOT CARPET	New	100.00	60.00
Gross Labour Cost (S\$)			1,925.00	1,435.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >