

Kd
Arthur Kenneth

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SDZ 6779 M1

TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department

Estimate No: ES1992025/YISHUN
Date: 11 Sep 2019
Policy No: 5093372881-02
Veh Reg No: SDZ6779M
Make/Model: TOYOTA COROLLA
AXIO 1.5G MT ABS
D/AIRBAG 2WD

WS Ref: TP/AIG/YS
Claim Type: Third Party
Accident Date: 07/09/2019
TP Veh Reg No: SMC7119B

Chassis No: NZE1617124378
Engine No: 1NZE8217377
Reg. Date: 17/08/2017

Not Authorized

Resurvey 134 points

82756.42 6 days

b4p

Estimate Repair Cost to Vehicle No :SDZ6779M

PAGE:1/1

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 REAR BUMPER	684.80	1 PC	684.80	✓
2 REAR BUMPER RH SIDE RETAINER	92.33	1 PC	92.33	✓
3 REAR BUMPER CLIPS	3.50	6 PCS	21.00	✓
4 REAR BUMPER RH REFLECTOR	56.90	1 PC	56.90	✓
5 RH TAILLAMP	548.10	1 PC	548.10	✓
6 RH TAILLAMP PANEL	133.90	1 PC	133.90	✗
7 RH TAILLAMP LOWER RETAINER	89.90	1 PC	89.90	✗
8 REAR RH FENDER	989.20	1 PC	989.20	✗
9 REAR RH FENDER INNER AIR SCROP GRILLE	49.40	1 PC	49.40	✓
10 REAR RH FENDER INNER GARNISH	292.80	1 PC	292.80	✓
11 REAR BOOT RUBBER	187.10	1 PC	187.10	✗
12 REAR WINDSCREEN GLASS MOULDING	97.80	1 PC	97.80	✗
			3,243.23	
		Less 25%	810.81	2,432.42
Special Net				
13 REAR WINDSCREEN GLASS GUM	40.00	1 PC	40.00	✗
			40.00	40.00
Labour				
14 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✗
15 REMOVE & REFIX REAR SEAT,CARPET,GARNISH, TOP ROOF LININ,ETC	120.00	1 LA	120.00	100 50 ✓
16 REMOVE & REFIX REAR BUMPER ASSY,RH TAILLAMP,CUT,WELD & RENEW REAR RH FENDER,RH TAILLAMP PANEL & REALIGN THE SAME	800.00	1 LA	800.00	700 ✓
17 PUTTY & RESPRAY ON REAR RH FENDER,RH TAILLAMP PANEL,REAR BUMPER	700.00	1 LA	700.00	600 ✓
18 RUSTPROOFING	30.00	1 LA	30.00	✓
			1,770.00	1,770.00

Total SS 4,242.42

Add GST @ 7% 296.97

Total Amount Payable SS 4,539.39

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

#1835.23

458.30

#1376.42

1380

#2756.42 ✓