

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SFV 3249T

TP/India

M/S : INDIA INT'L INSURANCE PTE LTD

64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63476100

FAX: 62247743

ATTN: Motor Claim Department

WS Ref: TP/INDIA

Claim Type: Third Party

Accident Date: 08/09/2019

TP Veh Reg No: SHB4492G

Estimate No: ES1992052/YISHUN

Date: 20 Sep 2019

Policy No: 5105378699

Veh Reg No: SFV3249T *Subaru Forester*

Make/Model: ~~TOYOTA PICNIC AUTO~~

Chassis No: ~~JTEGH23B700017390~~

Engine No: 1A21785487

Reg. Date: ~~01/06/2005~~ 21/11/2018

Estimate Repair Cost to Vehicle No :SFV3249T

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 REAR BUMPER	600.30	1 PC	600.30	✓
2 REAR BUMPER LH SIDE RETAINER	29.80	1 PC	29.80	X
3 REAR BUMPER CLIPS	3.90	6 PCS	23.40	✓
4 REAR LH WHEEL ARP GARNISH	170.90	1 PC	170.90	✓
5 REAR LH DOOR	790.60	1 PC	790.60	X
6 REAR LH DOOR LOWER MOULDING	190.90	1 PC	190.90	X
7 REAR LH DOOR FRAME STICKER - FRT VERTICAL	24.50	1 PC	24.50	X
8 REAR LH DOOR FRAME STICKER - REAR VERICAL	19.10	1 PC	19.10	X
9 REAR LH DOOR FRAME STICKER - TOP	13.90	1 PC	13.90	X
10 FRONT LH DOOR LOWER MOULDING	190.80	1 PC	190.80	X
11 REAR LH SPORT RIM	750.00	1 PC	750.00	✓
			2,804.20	
		Less 20%	560.84	2,243.36
Labour				
12 REMOVE & REFIX REAR BUMPER ASSY, REAR LH DOOR & ATTACHMENT, KNOCK & REPAIR FRT LH DOOR & REALIGN THE SAME	600.00	1 LA	600.00	480/
13 PUTTY & RESPRAY ON REAR BUMPER, FRT & REAR LH DOOR & ALL AFFECTED AREAS	800.00	1 LA	800.00	600/
14 TO CHECK REAR LH UNDERCARRIAGE & COMPUTERIZED WHEEL ALIGNMENT	60.00	1 LA	60.00	✓
15 REMOVE & REFIX REAR LH SPORT RIM	40.00	1 LA	40.00	20/
16 RUSTPROOFING	30.00	1 LA	30.00	X
			1,530.00	1,530.00
		Total	S\$ 3,773.36	

Add GST @ 7%

264.14

Total Amount Payable

S\$ 4,037.50

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal repair work(s) involved
- Supplier's liability is not covered and is subject to the supplier's policy

Acknowledged by:

Signature:

Date: