

# MG SOLUTION PTE LTD LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03B Vicom Inspection Centre Singapore

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

|                                           |                                  |                |              |
|-------------------------------------------|----------------------------------|----------------|--------------|
| TO                                        | : CHINA TAIPING                  | DATE           | : 09/09/2019 |
| ATTENTION                                 | : MOTOR CLAIMS DEPT              | JOB TYPE       | : T/P CLAIM  |
| ESTIMATE REPORT :                         |                                  |                |              |
| <u>VEHICLE DETAILS</u>                    |                                  |                |              |
| VEHICLE NO                                | : GBE2476Y                       | <i>1chenda</i> |              |
| MODEL                                     | : TOYOTA DYNA 150 MANUAL 3SEATER |                |              |
| CHASSIS NO                                |                                  |                |              |
| <u>ACCIDENT DETAILS</u>                   |                                  | DATE           | : 8-Sep-19   |
|                                           |                                  | TIME           | : 08:45HRS   |
| THIRD PARTY REQUESTOR / CONTACT : JACK LI |                                  |                |              |

## CLAIM DETAIL : PARTS

| S/N | DESCRIPTION                                  | QTY | UNIT LIST PRICE | TOTAL LIST PRICE |   |
|-----|----------------------------------------------|-----|-----------------|------------------|---|
| 1   | FRONT WIPER PANEL <i>the new</i>             | 1   | \$ 830.00       | \$ 830.00        | + |
| 2   | FRONT WIPER SIDE PANEL <i>the new</i>        | 1   | \$ 280.00       | \$ 280.00        | + |
| 3   | FRONT SIDE MIRROR <i>the new</i>             | 1   | \$ 455.30       | \$ 455.30        | ✓ |
| 4   | FRONT CENTRE PANEL <i>the new</i>            | 1   | \$ 920.00       | \$ 920.00        | + |
| 5   | FRONT CENTRE PANEL DYNA <i>the new</i>       | 1   | \$ 80.00        | \$ 80.00         | ✓ |
| 6   | FRONT CENTRE PROTECTOR <i>the new</i>        | 1   | \$ 280.00       | \$ 280.00        | + |
| 7   | FRONT CONCERT PANEL LH <i>the new</i>        | 1   | \$ 356.00       | \$ 356.00        | + |
| 8   | FRONT SIDE PANEL PROTECTOR LH <i>the new</i> | 1   | \$ 180.00       | \$ 180.00        | ✓ |
| 9   | FRONT BUMPER <i>the new</i>                  | 1   | \$ 530.00       | \$ 530.00        | + |
| 10  | FRONT RADIATOR GRILLE <i>the new</i>         | 1   | \$ 415.00       | \$ 415.00        | ✓ |
| 11  | FRONT RADIATOR GRILLE LOGO <i>the new</i>    | 1   | \$ 69.50        | \$ 69.50         | ✓ |
| 12  | HEAD LAMP LH <i>the new</i>                  | 1   | \$ 598.00       | \$ 598.00        | ✓ |

2077.80

1558.35

TOTAL PRICE \$ 4,993.80

MINUS 25% \$ 1,248.45

SUB TOTAL PRICE \$ 3,745.35

| S/N | DESCRIPTION                       | QTY | UNIT S/NETT | TOTAL S/NETT |   |
|-----|-----------------------------------|-----|-------------|--------------|---|
| 1   | FRONT NUMBER PLATE <i>the new</i> | 1   | \$ 50.00    | \$ 50.00     | + |

|   |                                  |   |          |          |   |
|---|----------------------------------|---|----------|----------|---|
| 2 | FRONT GRILLE CLIP(SET) <i>NA</i> | 1 | \$ 22.00 | \$ 22.00 | ✓ |
| 3 | HEADLAMP CLIP(SET) <i>NA</i>     | 1 | \$ 22.00 | \$ 22.00 | ✓ |

44

TOTAL \$ 94.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (F)

| S/N | JOB DESCRIPTION                         | PRICE                  | ADJUSTED COST | APPROVED |
|-----|-----------------------------------------|------------------------|---------------|----------|
| 1   | TO PANEL BEAT, WELD, CUT, ADJUST, KNOCK | \$ <del>1,400.00</del> | 400           |          |
| 2   | TO PUTTY, SPRAY PAINT, POLISH WAX       | \$ <del>1,400.00</del> | 600           |          |
| 3   | TO SPRAY TUFF COAT                      | \$ 250.00              | X             |          |
| 4   | WIRING, BULB CHECKING                   | \$ <del>60.00</del>    | 30            |          |
| 5   | TO REMOVE AND REFIX FRONT DASHBOARD     | \$ 450.00              | X             |          |
| 6   | REMOVE AND REFIX FRONT WINDSCREEN       | \$ 120.00              | X             |          |

1030

TOTAL \$ 3,680.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 3,839.35  
TOTAL LABOUR COST : \$ 3,680.00  
TOTAL REPAIR COST : \$ 7,519.35  
EXCESS :  
NO. OF DAYS :  
RE-SURVEY :  
PART BY PART OR LUMP SUM :  
DATE & TIME OF SURVEY :  
SURVEYED BY :  
CONTACT NUMBER :  
FAX NUMBER :

Adrian Lij  
H/S 09/09/19.

03 Days.

Total: 2632.35

H/S: 2.11.19.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: