

MG SOLUTION PT

23 Kaki Bukit Avenue 4 (South)

Tel: (+65) 6243 1373 | Fax

Reg. No: 201427944

TO	: AIG
ATTENTION	: MOTOR CLAIMS DEPT
ESTIMATE REPORT	:
<u>VEHICLE DETAILS</u>	
VEHICLE NO	: SJQ526S
MODEL	: SUZUKI SX4 1.6HB AT
CHASSIS NO	
<u>ACCIDENT DETAILS</u>	
DATE	: 5-Sep-19
TIME	: 08:50HRS
THIRD PARTY REQUESTOR / CONTACT	: JACK LI

CLAIM DETAIL : PARTS

1	FRONT BUMPER	Rehnd
2	FRONT BUMPER SIDE RETAINER	neu
3	FRONT BUMPER LOWER GRILLE	neu
4	CENTRE GRILLE	crackd
5	CENTRE GRILLE LOGO	neu
6	HEADLAMP RH	crackd
7	BOOTLID	Repis
8	BOOTLID LOGO	neu
9	BOOTLID SX4	
10	REAR BUMPER	Rehnd
11	REAR BUMPER SIDE RETAINER	neu
12	REAR BUMPER REFLECTOR	LH crackd
13	REAR BUMPER REINFORCEMENT	Best
14	REAR END PANEL	Repis
15	REAR END PANEL TOP GARNISH	Not crackd
16	TAILLAMP	LH crackd.

Front bumper reinforcement bar

283460

240941

TC
LE
SL

688.3+

64.+

196.+

45.+

422.3+

40.+

42.+

530.+

55.+

80.+

257.+

160.+

255.=

2,834.6*

2,834.6*

85.%

2,409.41*

0.C

1,000.+

1,200.+

30.+

50.+

=

2,280.*

0.C

20.+

600.+

20.+

600.+

10.+

200.=

1,450.*

0.C

2,409.41+

2,280.+

1,450.+

=

6,139.41*

6,139.41*

80.%

4,911.528*

0.C

4st 4,900.◇
◇

0.255