

ASSIGNMENT

Surveyor:

ADRIAN

DOI: 09/09/2019

Date / Time: 09/09/2019

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. : SKU 5256E

Name of Insured :

JHUM CHOW WATA

Insured Tel No. :

HP:

Excess Sec II :S\$

D.O.A : 07/09/2019 14:45

Is driver the owner?

(YES / NO)

Nature of Accident :

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES/ NO)

Claim No. :

Policy No. :

Make / Model :

Place of Accident : CTE TWDS SLE B4 BRADDELL RD

OI GIA REPORT: YES/ NO ; TP GIA REPORT: YES/ NO

Insured Liability : % Final ? Yes/ No

SKU 5256E

SMD 8692A

SKB 5169Z



INSRS:

WSP:

Tel :

Liability :

RMKS: OI



INSRS:

WSP: SM

Tel : AUTOMOTIVE

Liability :

RMKS: TP



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/ Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	20/09/19- vic
	Documentation Check List: Handler Typist	
	Notification ltr (if non-pickup)	
	After call ltr to OI:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
	LTA / GIA :	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	
20/09/19	MUR EQUIPMENT. OI INVOLVED IN A 3 VEH. C.C. 4 WAS THE LAST CAR IN REAR BUNDED TP. SHAW LETTER TO OI TO NOTIFY TP CLAIM AND NO ISSUES.	
	OI VIDEO FOOTAGE IN (After Accident)	
	TP LOD IN BY EMAIL	
21/10/19	MUR PDS TO REPORT TEAM TO TYPE REPORT FOR WANDER APPROVAL	
	HARVEST DONE	
26/11/19	900K WANDER APPROVAL TO GBE	
27/11/19	GBE APPROVED WANDER.	
	SEND 1st OFFER TO TP.	
	TP ACCEPTED OFFER.	
02/12/19	ALL DONE IN CLIMATE.	
PRELIMINARY ADVICE Date/Time: 21/10/19 Sent By: UC		
FINALIZATION Date/Time: Confirm with: Confirm by:		
Repair Cost: LG S\$ 18,900.00 (15 days) Reduction: 67 %	Email ☐ Call ☐	
FINAL SETTLEMENT Date/Time: 02/12/19 Confirm with: 02/12/19	Email ☐ Call ☐	
Final Liability: % 100 (A free) / Assessed) BOLA S/N No. : 28	If NO or B 28, Ass. Lia : 100%	
Repair Cost: S\$ 18,900.00	C.B. VEH. C.C.; OI User center)	
Loss of Rental (LOR): S\$ 900.00 (9 days) x \$100		
Loss of Use (LOU): S\$ - (\$ x days)		
Loss of Income (LOI): S\$ - (\$ x days)		
LOR only ☒ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ (Tick only one)		
GIA/LTA Search S\$ 7.45		
Medical: S\$ -		
Disbursement: S\$ - (e.g. Tow/ Independent)		
Legal Cost S\$ -		
Total: S\$ 19,807.45 Global Sum S\$: 19,800.00		
FINAL PAYMENT Date/Time: Confirm with: Confirm by:	Email ☐ Call ☐	
Payee 1: S\$ 19,800.00 Name 1: SM AUTOMOTIVE		
Payee 2: (Strike if N.A.) S\$ - Name 2: -		
Payee 3: (Strike if N.A.) S\$ - Name 3: -		

COPY 7/19

Adrian

ADJUSTMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 15 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMD8692A Yr Regn: 2013 / Sept.

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Note cc 1198

Colour: Gold A/C: Insured / Std / Nil / NA

Sp. Reading: 136/2 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: JN1TAAE12Z0982083

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/65 R15

R: 185/65 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 09/09/19

Sunray held at 3M

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP QBE.

Lg \$18,900.00

CRB: \$20,840.30 (57%)

MV: 63K.

PV: 31K

Nett: 32K

Date/Time, File Pass to?

Date/Time, File Return to?

- 1)
- 2)
- 3)
- 4)
- 5)
- 6)

Print Report

Final Report

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

ANG AI NGOH

10/09/2019

Blk C 1 Kaki Bukit Ave 6

TPOBE

JN1TAAE12Z0982083.

01-43

Vic

Singapore 417883

Accident date: 07/09/2019

Estimated repair cost for vehicle no: SMD8692A NISSAN NOTE 1.2 A '18

CHASSIS: JN1TAAE12Z0982083

S/n	Qty	Items / Nett	U/price	Amount
1	1	Front Bonnet <i>not new</i>		\$847.80 <i>x</i>
2	2	Front Headlamp <i>cracked</i>	\$1,614.60	\$3,229.20 <i>✓</i>
3	2	Front Headlamp Lower Bracket <i>not new</i>	\$28.10	\$56.20 <i>x</i>
4	1	Front Grille <i>cracked</i>		\$276.70 <i>✓</i>
5	1	Front Grille Emblem Logo <i>new</i>		\$19.90 <i>✓</i>
6	1	Front Grille Top Cover <i>cracked</i>		\$194.40 <i>✓</i>
7	1	Front Bumper <i>deformed</i>		\$354.90 <i>✓</i>
8	2	Front Bumper Side Retainer <i>new</i>	\$27.50	\$55.00 <i>✓</i>
9	2	Front Bumper Fog Lamp Cover <i>3M</i>	\$130.20	\$260.40 <i>x</i>
10	1	Front Bumper Towing Cover <i>3M</i>		\$38.10 <i>x</i>
11	1	Front Bumper Inner Foam <i>cracked</i>		\$218.60 <i>✓</i>
12	1	Front Bumper Reinforcement <i>Bent</i>		\$341.60 <i>✓</i>
13	1	Front Bumper Reinforcement Bracket <i>Bent</i>		\$549.80 <i>185</i>
14	1	Front Support Panel <i>Repair</i>		\$318.50 <i>x</i>
15	1	Rear Boot Lid <i>Distorted</i>		\$1,018.20 <i>✓</i>
16	2	Rear Boot Lid Hinge <i>not new</i>	\$46.50	\$93.00 <i>+</i>
17	2	Rear Boot Lid Shock Absorber <i>not new</i>	\$138.40	\$276.80 <i>+</i>
18	1	Rear Boot Lid Emblem Logo <i>3M</i>		\$64.60 <i>✓</i>
19	1	Rear Boot Lid Note Logo <i>3M</i>		\$94.90 <i>✓</i>
20	2	Rear Boot Lid Number Plate Lamp <i>not new</i>	\$88.20	\$176.40 <i>x</i>
21	1	Rear Boot Lid Center Moulding <i>cracked</i>		\$255.60 <i>✓</i>
22	1	Rear Boot Lid Inner Lock <i>Damaged</i>		\$173.20 <i>✓</i>
23	1	Rear Boot Lid Inner Rubber <i>cut</i>		\$68.20 <i>✓</i>
24	1	Rear Boot Lid Inner Trim Board <i>cracked</i>		\$162.00 <i>✓</i>
25	1	Rear Boot Lid Windscreen Moulding <i>new</i>		\$76.50 <i>✓</i>
26	2	Rear Taillamp <i>cracked</i>	\$435.80	\$871.60 <i>✓</i>
27	1	Rear R/H Taillamp Panel <i>Distorted</i>		\$185.20 <i>✓</i>

28	1	Rear Bumper Distorted		\$460.00 ✓
29	10	Rear Bumper Clip new	\$6.50	\$65.00 30
30	2	Rear Bumper Side Retainer new	\$35.00	\$70.00 ✓
31	2	Rear Bumper Side Reflector RH cracked.	\$66.60	\$133.20 66.60
32	2	Rear Bumper Bracket RH Bent	\$96.90	\$193.80 96.90
33	1	Rear Bumper Inner Foam cracked.		\$111.90 ✓
34	1	Rear End Panel Distorted		\$552.80 ✓
35	1	Rear End Panel Top Garnish Deland		\$85.00 ✓
36	1	Rear R/H Fender Reps		\$909.00 x
37	1	Rear R/H Fender Closing New		\$55.10 x
38	1	Rear R/H Fender Inner Trim Board cracked.		\$378.40 ✓
39	1	Rear Spare Tyre Panel Distorted.		\$5,116.00 891
40	1	Rear Spare Tyre Panel Top Cover Deformed		\$433.70 298
41	1	Rear Exhaust Bent.		\$480.00 ✓
42	2	Rear Exhaust Mounting New	\$37.10	\$74.20 x
43	1	Rear Center Exhaust Bent.		\$399.80 ✓
			11765.70	
			10589.13.	
			Subtotal :-	\$19,795.20

S/n	Qty	Items / Special Nett	U/price	Amount
44	1 set	Body Kit Distorted.		\$3,800.00 2000/12
45	8	Front Grille Clip New	\$6.50	\$52.00 30
46	10	Front Bumper Clip	\$6.50	\$65.00 30
47	2	Front Bumper Fog Lamp New	\$323.70	\$647.40 x
48	1	Front Air-Con Condenser Bent		\$658.20 ✓
49	1	Front Radiator Bent.		\$1,585.00 ✓
50	1	Front Radiator Fan Motor Assy Cracked		\$748.60 ✓
51	1	Rear Boot Lid Number Plate New		\$50.00 x
52	8	Rear Boot Lid Inner Trim Board Clip New	\$6.50	\$52.00 30
53	1	Rear Boot Lid Reverse Camera Dazed.		\$1,000.00 x 400 (SN)
54	4	Rear Taillamp Clip New	\$8.00	\$32.00 20
55	1	Rear Bumper Reverse Sensor Damaged		\$294.00 200/50
56	1	Rear Antenna Dazed		\$238.80 29.
57	1	Rear Buzzer Sensor New		\$91.70 x
58	8	Rear R/H Fender Inner Trim Board Clip New	\$8.00	\$64.00 30
59	1	Rear Spare Tyre Panel & End Panel Sealant New		\$155.50 ✓
			3366.30	SN 2600
			3028.67.	
			Subtotal :-	\$9,534.20

Labour charges

To remove & refit cushion & trim board	\$380.00 280
To remove & refit reverse camera	\$180.00 50
To remove & refit reverse sensor	\$100.00 50
To remove & refit rear & centre exhaust	\$380.00 160
To remove & refit rear windscreen	\$120.00 ✓
Gum }	\$50.00 ✓
To remove & refit rear R/H fender glass	\$100.00 X
Gum }	\$50.00 X
Towing fee	\$150.00 120
Tuff kote	\$150.00 120
To check wiring	\$100.00 60.
Panel beating	5010. \$3,000.00 200
Spray painting	\$2,400.00 1800.

Subtotal :- \$7,160.00

39740.30

Total:- \$36,489.40

Supplement, 2423.81

39,740.30

total 23652.61

L/S: 189K.

15 Days.

18.9/K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

ANG AI NGOH

10/09/2019

Blk C 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 07/09/2019

Supplementary repair cost for vehicle no: SMD8692A NISSAN NOTE 1.2 A '18

CHASSIS: JN1TAAE12Z0982083

S/n	Qty	Items / Special Nett	U/price	Amount
1	1	Rear Axle Bent		\$1,519.90 ✓

2		Exhaust Heat Shield. <i>angled</i>	125 ✓	
3		Rear Fender Inner Shield. <i>tom</i>	38 ✓	
Subtotal :-				\$1,519.90

4		Tools Tray Sponge <i>cracked</i>	288. ✓	
				1,970.9
				1,732.81

Labour charges

To remove & refit rear undercarriage

650

~~\$480.00~~ 350

To apply ceramic coating

~~\$800.00~~ 300

Total:- \$1,280.00

Supplementary 2423.81

AuraShine

31 Woodlands Close, #01-17
Woodland Horizon, Singapore 737855
Reg No. 201719543K

Official Receipt

No. 01050

Date: 16.09.18

Vehicle No: SMTA 8692A

Vehicle Model: Nissan note galaxy fold

Name: Ang Ai Ngoh

HP: 9758 6632

Description: AuraShield Ceramic Coating (18 month warranty)

AuraShine

Reg No. 201719543K

Kym Koli
Sales Manager
Hp: 9177 8878

31 Woodlands Close
#01-17 Woodland Horizon
Singapore 737855
www.aurashine.com/AuraShine

Total	\$ 450
Deposit	\$ —
Balance	\$ —

Cash / Note / Cheque

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

Jetstar

Jetstar
Singapore to
Jakarta

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

 Post an Ad  Advertiser Login  Ways of Selling

New 5 Years Renewal Coo Honda Fit 1.3A G



2.88% P.A. \$0 Admin, \$0
Down, Monthly Fm \$438. Sta.
"B" 2 Yr Warranty Engine, gear
120 Credit Pte Ltd StarAd



**VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND**

HOTLINE: 6741 9997

[View Our Cars](#)

Browse by Category

 Save Search

 Print

Sort by Date Posted 20 results/page

9 vehicles

 Search Note

 Advanced Search

 Search

 View All

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

Search Selection	Note	Any	Any	2018	Any	Any	Any	Any	Available
	☐ Nissan Note 1.2A Rare Color: Atomic Gold! Agent Unit W/ Valid Agent Warranty Till 2021, Fully Serviced By Tan Chong! Good & Affordable Proposition For A Stylish & Cheap Little City Cruiser W All Necessary Features! Definitely Enough Space For Any Task & It's Fuel Economy Is Impressive! FL...	\$58,800	\$6,590 /yr	07-Feb-2018	1,198 cc	20,000 km	Hatchback	Available	
	☐ Nissan Note 1.2A One Owner, Car Like New, Responsive Yet Fuel Efficient, High Trade In And In House Loan Available.	\$57,800	\$6,560 /yr	12-Feb-2018	1,198 cc	25,028 km	Hatchback	Available	
	☐ Nissan Note 1.2A Bank Loan Interest Rate Offer From 2.48%! \$3k Drivesway With Our In House Financing! Attractive Trade In Price, All Our Car Go Thought 120 Point Check With Our In- House Workshop Buying With Peace Of Mind. Call Us Now.	\$59,800	\$6,720 /yr	19-Mar-2018	1,198 cc	28,000 km	Hatchback	Available	
	☐ Nissan Note 1.2A 1 Owner, Excellent Almost New Condition. Low Mileage, Fully Agent Serviced With 3 Years Agent Warranty. In House Financing And High Trade In Available! Call Now To View!	\$59,800	\$6,640 /yr	23-Apr-2018	1,198 cc	22,000 km	Hatchback	Available	
	☐ Nissan Note 1.2A 1 Owner Only, Fully Agent Maintained/Warranty, View To Believe, Flexible High Loan Available. Call Or Visit Us Now For Further Details.	\$59,800	\$6,580 /yr	23-May-2018	1,198 cc	18,000 km	Hatchback	Available	
	☐ Nissan Note 1.2A Owned By A Single Car Enthusiastic With Full Tracked Records From Agent Since Day 1. Responsive Yet Fuel Efficient, Irresistible To Its Superb Condition, Perfectly Well Balanced Between Power And Comfort, Super High Paper Value! Zero Mishap! Higher Loan Can Be Ach...	\$59,388	\$6,440 /yr	10-Jul-2018	1,198 cc	26,000 km	Hatchback	Available	
	☐ Nissan Note 1.2A Beautiful White Unit! 1 Owner, Like New Condition, Full Agent Unit, Lowest Mileage Clocked 7565Km, Cheap And Low Depreciation, 3 Years Engine Warranty, Flexible Loan And High Trade In Available, View Now!	\$60,800	\$6,560 /yr	30-Jul-2018	1,198 cc	7,565 km	Hatchback	Available	
	☐ Nissan Note 1.2A Bank Lower Interest Rate Only 2.28% And Flexible Loan Schemes Available! Full Agent Maintenance With Service Records, Lowest Mileage	\$62,800	\$6,780 /yr	31-Jul-2018	1,198 cc	12,600 km	Hatchback	Available	

View Full Listing View History

 Compare

TYREPAC

Best Tyres Online!
Latest Special Offers from Tyrepac!





Republic Auto

Posted: 27-Aug-2018 Tags: 2018 Nissan Note, 2018 review note, Nissan Note, nissan note, Nissan, Note, nro, Used Nissan

Save this search criteria, to get email alerts whenever a match is found.



[For old advertisements, view Expired ads](#)

20 • results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

Follow sgCarMart.com



[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

DATE: _____ TIME: _____

Compare 

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 4111

Vehicle Details

Vehicle No.: SMD8692A
Vehicle to be Exported: No
Intended Deregistration Date: 07 Sep 2019
Vehicle Make: NISSAN
Vehicle Model: NOTE 1.2 CVT
Primary Colour: Gold
Manufacturing Year: 2018
Engine No.: HR12200669J
Chassis No.: JN1TAAE12Z0982083
Maximum Power Output: 58.0 kW (77 bhp)
Open Market Value: \$13,305.00
Original Registration Date: 08 Sep 2018
First Registration Date: 08 Sep 2018
Transfer Count: 0
Actual ARF Paid: \$5,000.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 07 Sep 2028
PARF Rebate Amount: \$3,750.00

Intended COE Rebate Details

COE Expiry Date: 07 Sep 2028
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$30,209.00
COE Rebate Amount: \$27,188.00
Total Rebate Amount: \$30,938.00

The information contained herein is correct as at 07 Sep 2019

OK

Mei Kwan (LKKAUTO)

From: Jenny Toh <jenny.toh@qbe.com>
Sent: Monday, 16 September, 2019 3:10 PM
To: Mei Kwan (LKKAUTO)
Subject: Direct Settlement - Accident Involving SKU5256E (OI : QBE - TBA) AND SMD8692A (TP : LKK REF - CC6/QBE19016036/Aha3) on 07/09/2019
Attachments: TP GIA REPORT.PDF; SKU5256E - VC012962.pdf
Categories: HMK

Our ref: VC012962

Hi Mei Kwan

Please find attached as per requested.

regards

Jenny Toh

Senior Assistant

Claims / Asia

1 Raffles Quay, #29-10 South Tower, Singapore 048583

+65 6224 6633 | +65 6477 1225

[Website](#) [LinkedIn](#) [Twitter](#)



From: Mei Kwan (LKKAUTO) <Meikwan@lkkauto.com>
Sent: Monday, 16 September 2019 2:56 PM
To: Jenny Toh <jenny.toh@qbe.com>; Janice Goh Siew Geok <janice.goh@qbe.com>
Cc: Vic (LKKAUTO) <vicalpeh@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: Direct Settlement - Accident Involving SKU5256E (OI : QBE - TBA) AND SMD8692A (TP : LKK REF - CC6/QBE19016036/Aha3) on 07/09/2019

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle SMD 8692A at M/s SM Automotive - Kaki Bukit on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:
- TP GIA report

Please be informed that the estimated cost of repair and preliminary advice is not ready yet.

We will revert to you on preliminary advice in due course.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
QBE INSURANCE (SINGAPORE) PTE LTD			Ref : CC6/QBE19016036/Aha3q2	
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583			Date : 09-12-2019	
			Code : QBE	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKU 5256E	Veh. Inspected	SMD 8692A	
Policy No.	8-V0022906-MVA	Coverage (\$)	0.00	
Claim No.	VC012962	Excess (\$)	0.00	
Assign From		Assign Date	09/09/2019	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN NOTE	c.c	1198	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JN1TAAE12Z0982083	Colour	GOLD	
Odometer	13612	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/65 R15	CONTINENTAL	6 mm	
L/H Front Tyre	185/65 R15	CONTINENTAL	6 mm	
R/H Rear Tyre	185/65 R15	CONTINENTAL	6 mm	
L/H Rear Tyre	185/65 R15	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/09/2019	Inspection Date	09/09/2019	
Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		15 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMD 8692A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BONNET	NOT NECESSARY	847.80	-
2	FRONT HEADLAMP @\$1614.60	CRACKED	3,229.20	3,229.20
2	FRONT HEADLAMP LOWER BRACKET @\$28.10	NOT NECESSARY	56.20	-
1	FRONT GRILLE	CRACKED	276.70	276.70
1	FRONT GRILLE EMBLEM LOGO	NECESSARY	19.90	19.90
1	FRONT GRILLE TOP COVER	CRACKED	194.40	194.40
1	FRONT BUMPER	DEFORMED	354.90	354.90
2	FRONT BUMPER SIDE RETAINER @\$27.50	NECESSARY	55.00	55.00
2	FRONT BUMPER FOG LAMP COVER @\$130.20	NOT NECESSARY	260.40	-
1	FRONT BUMPER TOWING COVER	NOT NECESSARY	38.10	-
1	FRONT BUMPER INNER FOAM	CRACKED	218.60	218.60
1	FRONT BUMPER REINFORCEMENT	BENT	341.60	341.60
2	FRONT BUMPER REINFORCEMENT BRACKET	BENT	549.80	185.00
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	318.50	-
1	REAR BOOT LID	DISTORTED	1,018.20	1,018.20
2	REAR BOOT LID HINGE @\$46.50	NOT NECESSARY	93.00	-
2	REAR BOOT LID SHOCK ABSORBER @\$138.40	NOT NECESSARY	276.80	-
1	REAR BOOT LID EMBLEM LOGO	NECESSARY	64.60	64.60
1	REAR BOOT LID NOTE LOGO	NECESSARY	94.90	94.90
2	REAR BOOT LID NUMBER PLATE LAMP @\$88.20	NOT NECESSARY	176.40	-
1	REAR BOOT LID CENTER MOULDING	CRACKED	255.60	255.60
1	REAR BOOT LID INNER LOCK	DAMAGED	173.20	173.20
1	REAR BOOT LID INNER RUBBER	CUT	68.20	68.20
1	REAR BOOT LID INNER TRIM BOARD	CRACKED	162.00	162.00
1	REAR BOOT LID WINDSCREEN MOULDING	NECESSARY	76.50	76.50
2	REAR TAILLAMP @\$435.80	CRACKED	871.60	871.60
1	REAR R/H TAILLAMP PANEL	DENTED	185.20	185.20
1	REAR BUMPER	DISTORTED	460.00	460.00
10	REAR BUMPER CLIP @\$6.50	NECESSARY	65.00	30.00
2	REAR BUMPER SIDE RETAINER @\$35.00	NECESSARY	70.00	70.00

Report Ref No. CC6/QBE19016036/Aha3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR BUMPER SIDE REFLECTOR @\$66.60	O/S CRACKED	133.20	66.60
2	REAR BUMPER BRACKET @\$96.90	O/S DENTED	193.80	96.90
1	REAR BUMPER INNER FOAM	CRACKED	111.90	111.90
1	REAR END PANEL	DISTORTED	552.80	552.80
1	REAR END PANEL TOP GARNISH	DEFORMED	85.00	85.00
1	REAR R/H FENDER	TO REPAIR SEE LABOUR	909.00	-
1	REAR R/H FENDER CLOSING	NOT NECESSARY	55.10	-
1	REAR R/H FENDER INNER TRIM BOARD	CRACKED	378.40	378.40
1	REAR SPARE TYRE PANEL	DISTORTED	5,116.00	891.00
1	REAR SPARE TYRE PANEL TOP COVER	DEFORMED	433.70	298.00
1	REAR EXHAUST	BENT	480.00	480.00
2	REAR EXHAUST MOUNTING @\$37.10	NOT NECESSARY	74.20	-
1	REAR CENTER EXHAUST	BENT	399.80	399.80
1	REAR AXLE (ADDITIONAL)	BENT	1,519.90	1,519.90
1	EXHAUST HEAT SHIELD (ADDITIONAL)	CRUMPLED	125.00	125.00
1	REAR FENDER INNER SHIELD (ADDITIONAL)	TORN	38.00	38.00
1	TOOLS TRAY SPONGE (ADDITIONAL)	CRACKED	288.00	288.00
8	FRONT GRILLE CLIP @\$6.50	NECESSARY	52.00	20.00
10	FRONT BUMPER CLIP @\$6.50	NECESSARY	65.00	30.00
2	FRONT BUMPER FOG LAMP @\$323.70	NOT NECESSARY	647.40	-
1	FRONT AIR-CON CONDENSER	BENT	658.20	658.20
1	FRONT RADIATOR	BENT	1,585.00	1,585.00
1	FRONT RADIATOR FAN MOTOR ASSY	CRACKED	748.60	748.60
1	REAR BOOT LID NUMBER PLATE	NOT NECESSARY	50.00	-
8	REAR BOOT LID INNER TRIM BOARD CLIP @\$6.50	NECESSARY	52.00	30.00
4	REAR TAILLAMP CLIP @\$8.00	NECESSARY	32.00	20.00
1	REAR ANTENNA	DAMAGED	238.80	89.00
1	REAR BUZZER SENSOR	NOT NECESSARY	91.70	-
8	REAR R/H FENDER INNER TRIM BOARD CLIP @\$8.00	NECESSARY	64.00	30.00
1	REAR SPARE TYRE PANEL & END PANEL SEALANT	NECESSARY	155.50	155.50
	LESS 10% DISCOUNT		-	-1,710.29
			26,206.30	15,392.61

Report Ref No. CC6/QBE19016036/Aha3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	SET BODY KIT (SN)	DISTORTED	3,800.00	2,000.00
1	REAR BOOT LID REVERSE CAMERA (SN)	DAMAGED	1,000.00	400.00
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	294.00	200.00
1	GUM (SN)	NECESSARY	100.00	50.00
			5,194.00	2,650.00
	<u>LABOUR</u>			
	TO REMOVE & REFIT CUSHION & TRIM BOARD.		380.00	280.00
	TO REMOVE & REFIT REVERSE CAMERA.		180.00	50.00
	TO REMOVE & REFIT REVERSE SENSOR.		100.00	50.00
	TO REMOVE & REFIT REAR & CENTRE EXHAUST.		380.00	160.00
	TO REMOVE & REFIT REAR WINDSCREEN.		120.00	120.00
	TO REMOVE & REFIT REAR R/H FENDER GLASS.	NOT NECESSARY	100.00	-
	TOWING FEE.		150.00	120.00
	TUFF KOTE.		150.00	120.00
	TO CHECK WIRING.		100.00	60.00
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL AND REAR R/H FENDER.		3,000.00	2,200.00
	SPRAY PAINTING.		2,400.00	1,800.00
	TO REMOVE & REFIT REAR UNDERCARRIAGE (ADDITIONAL).		480.00	350.00
	TO APPLY CERAMIC COATING(ADDITIONAL).		800.00	300.00
			8,340.00	5,610.00
	GRAND TOTAL		39,740.30	23,652.61
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			18,900.00

Report Ref No. CC6/QBE19016036/Aha3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.