

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

ANG AI NGOH

10/09/2019

Blk C 1 Kaki Bukit Ave 6

TPQBE

JN1TAAE12Z0982083.

01-43

Vic

Singapore 417883

Accident date: 07/09/2019

Estimated repair cost for vehicle no: SMD8692A NISSAN NOTE 1.2 A '18

CHASSIS: JN1TAAE12Z0982083

S/n	Qty	Items / Nett	U/price	Amount
1	1	Front Bonnet <i>Not Rec</i>		\$847.80 X
2	2	Front Headlamp <i>cracked.</i>	\$1,614.60	\$3,229.20 ✓
3	2	Front Headlamp Lower Bracket <i>Not Rec</i>	\$28.10	\$56.20 X
4	1	Front Grille <i>cracked</i>		\$276.70 ✓
5	1	Front Grille Emblem Logo <i>Not Rec</i>		\$19.90 ✓
6	1	Front Grille Top Cover <i>cracked.</i>		\$194.40 ✓
7	1	Front Bumper <i>Deformed</i>		\$354.90 ✓
8	2	Front Bumper Side Retainer <i>Not Rec</i>	\$27.50	\$55.00 ✓
9	2	Front Bumper Fog Lamp Cover <i>Not Rec</i>	\$130.20	\$260.40 X
10	1	Front Bumper Towing Cover <i>Not Rec</i>		\$38.10 X
11	1	Front Bumper Inner Foam <i>cracked</i>		\$218.60 ✓
12	1	Front Bumper Reinforcement <i>Bent.</i>		\$341.60 ✓
13	2	Front Bumper Reinforcement Bracket <i>Bent</i>		<u>\$549.80</u> 185
14	1	Front Support Panel <i>Repair</i>		\$318.50 X
15	1	Rear Boot Lid <i>Distorted.</i>		\$1,018.20 ✓
16	2	Rear Boot Lid Hinge <i>Not Rec</i>	\$46.50	\$93.00 +
17	2	Rear Boot Lid Shock Absorber <i>Not Rec</i>	\$138.40	\$276.80 +
18	1	Rear Boot Lid Emblem Logo <i>Not Rec</i>		\$64.60 ✓
19	1	Rear Boot Lid Note Logo <i>Not Rec</i>		\$94.90 ✓
20	2	Rear Boot Lid Number Plate Lamp <i>Not Rec</i>	\$88.20	\$176.40 X
21	1	Rear Boot Lid Center Moulding <i>cracked.</i>		\$255.60 ✓
22	1	Rear Boot Lid Inner Lock <i>Damaged.</i>		\$173.20 ✓
23	1	Rear Boot Lid Inner Rubber <i>cut</i>		\$68.20 ✓
24	1	Rear Boot Lid Inner Trim Board <i>cracked.</i>		\$162.00 ✓
25	1	Rear Boot Lid Windscreen Moulding <i>Not Rec</i>		\$76.50 ✓
26	2	Rear Taillamp <i>cracked</i>	\$435.80	\$871.60 ✓
27	1	Rear R/H Taillamp Panel <i>Deformed</i>		\$185.20 ✓

28	1	Rear Bumper Distorted		\$460.00 ✓
29	10	Rear Bumper Clip <i>new</i>	\$6.50	\$65.00 30
30	2	Rear Bumper Side Retainer <i>new</i>	\$35.00	\$70.00 ✓
31	2	Rear Bumper Side Reflector RH cracked.	\$66.60	\$133.20 66.60
32	2	Rear Bumper Bracket RH dented	\$96.90	\$193.80 96.90
33	1	Rear Bumper Inner Foam cracked.		\$111.90 ✓
34	1	Rear End Panel Distorted		\$552.80 ✓
35	1	Rear End Panel Top Garnish <i>Del</i>		\$85.00 ✓
36	1	Rear R/H Fender <i>Repis</i>		\$909.00 X
37	1	Rear R/H Fender Closing <i>HE new</i>		\$55.10 X
38	1	Rear R/H Fender Inner Trim Board cracked.		\$378.40 ✓
39	1	Rear Spare Tyre Panel Distorted.		\$5,116.00 891
40	1	Rear Spare Tyre Panel Top Cover Deformed		\$433.70 288
41	1	Rear Exhaust Bent.		\$480.00 ✓
42	2	Rear Exhaust Mounting <i>Not new</i>	\$37.10	\$74.20 X
43	1	Rear Center Exhaust Bent.		\$399.80 ✓

11765.70
10589.13.

Subtotal :- \$19,795.20

S/n	Qty	Items / Special Nett	U/price	Amount
44	1 set	Body Kit Distorted.		\$3,800.00 2000 (sn)
45	8	Front Grille Clip <i>3 new</i>	\$6.50	\$52.00 30
46	10	Front Bumper Clip	\$6.50	\$65.00 30
47	2	Front Bumper Fog Lamp <i>HE new</i>	\$323.70	\$647.40 X
48	1	Front Air-Con Condenser Bent.		\$658.20 ✓
49	1	Front Radiator Bent.		\$1,585.00 ✓
50	1	Front Radiator Fan Motor Assy cracked.		\$748.60 ✓
51	1	Rear Boot Lid Number Plate <i>HE new</i>		\$50.00 X
52	8	Rear Boot Lid Inner Trim Board Clip <i>new</i>	\$6.50	\$52.00 30
53	1	Rear Boot Lid Reverse Camera <i>Damaged</i>		\$1,000.00 X 400 (sn)
54	4	Rear Taillamp Clip <i>new</i>	\$8.00	\$32.00 20
55	1	Rear Bumper Reverse Sensor <i>Damaged</i>		\$294.00 200 (sn)
56	1	Rear Antenna <i>Damaged</i>		\$238.80 89.
57	1	Rear Buzzer Sensor <i>HE new</i>		\$91.70 X
58	8	Rear R/H Fender Inner Trim Board Clip <i>new</i>	\$8.00	\$64.00 30
59	1	Rear Spare Tyre Panel & End Panel Sealant <i>new</i>		\$155.50 ✓

3366.30 SN: 2600.
3029.67.

Subtotal :- \$9,534.20

Labour charges

To remove & refit cushion & trim board	\$380.00 280.
To remove & refit reverse camera	\$180.00 50
To remove & refit reverse sensor	\$100.00 50
To remove & refit rear & centre exhaust	\$380.00 160.
To remove & refit rear windscreen	\$120.00 ✓
Gum	\$50.00 ✓
To remove & refit rear R/H fender glass	\$100.00 X
Gum	\$50.00 X
Towing fee	\$150.00 120.
Tuff kote	\$150.00 120.
To check wiring	\$100.00 60.
Panel beating	5010. \$3,000.00 2200
Spray painting	\$2,400.00 1800.

Subtotal :- \$7,160.00

Total:- \$36,489.40

Supplementary 2423.81

total: 23852.61

H/S: 189K.

15 Pays.

18.9/K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

ANG AI NGOH

10/09/2019

Blk C 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 07/09/2019

Supplementary repair cost for vehicle no: SMD8692A NISSAN NOTE 1.2 A '18

CHASSIS: JN1TAAE12Z0982083

S/n	Qty	Items / Special Nett	U/price	Amount
1	1	Rear Axle Bent		\$1,519.90 ✓

2		Exhaust Heat Shield. crimped	125 ✓	
3		Rear Fender Inner Shield. torn	38 ✓	
4		Tools Tray Sponge crimped	288 ✓	
<u>Labour charges</u>				

Subtotal :- \$1,519.90

1970.9
1773.81

650

To remove & refit rear undercarriage

~~\$480.00~~ 350

To apply ceramic coating

~~\$800.00~~ 300

Total:- \$1,280.00

Supplementary 2423.81

AuraShine

31 Woodlands Close, #01-17
Woodland Horizon, Singapore 737855
Reg No. 201719543K

Date: 16.09.18

Vehicle No: SMD 8692A

Name: Ang Ai Ngoh

Description: AuraShield Ceramic Coating (18 month warranty)

Official Receipt

No. 01050

Vehicle Model: Nissan Note Galaxy fold

HP: 9758 6630

AuraShine

Reg No 201719543K

Kym Koh
Sales Manager
Hp: 9177 8878

31 Woodland Close
#01-17 Woodland Horizon
Singapore 737855
www.facebook.com/AuraShine

Total	\$ 450
Deposit	\$ —
Balance	\$ —

Cash / Note / Cheque