

CC6/CTI19016038/Abb3

SJES611J.

TP Chinn
Vic

Toyota Altis 1598CC

MR053ZEE106107081

Front Number Plate	Bent	30(SN) ✓
Front Number Plate Holder	Deformed	30(SN) ✓
Front Bumper	Distorted	563.80 ✓
Front Bumper Clips.	Neu	30 ✓
Front Bumper Reinforcement	Best	339.70 ✓
Front Bumper Side Holder x02	Neu	$60.7 \times 2 = 121.40$ ✓
Front Bumper Lower Grille	Deformed	106.50 ✓
Front Bumper Fog Lamp Cover x02	RH Missing	$96.3 \times 2 = 192.60$ 96.30 ✓
Front Bumper Logo	Missing	32.80 ✓
Front Grille	Crushed	298.80 ✓
Headlamp x02	RH smashed	$635 \times 2 = 1270$ 635 ✓
Front Support Panel	Buckled	699.90 ✓
Bonnet	Distorted	894.50 ✓
Bonnet Lock	Damaged	98.20 ✓
Bonnet Hinge x02	Best	$48.9 \times 2 = 97.80$ ✓
Front RH Fender	Distorted	585 ✓

SJES611J.

Front RH Fender Inner Shield	torn	169.30 ✓
Front RH Fender Inner Shield Clips.	Ner	30 ✓
VVTi Emblem.	Ner	34.10 ✓
Engine Undercover	torn	193.10 ✓
Engine Undercover Clips.	Ner	30 ✓
Air Con Condenser	} RH Ner	1299.40 +
Radiator		1681.90 +
Radiator Top Cover		193.40 +
Radiator Spare Tank.	cracked	139.70 ✓
Wiper Panel Garnish.	cut	354 ✓
Wiper Panel Garnish Clips.	Ner	30 ✓
Steering Air Bag	} Activated	2821.10 ✓
Steering Air Bag Sensor		298.30 ✓
Steering Wheel Anti Clock Spring.	Activated	274.50 ✓
Dashboard	torn	897.70 ✓
Dashboard Air Bag	} Activated	2721.80 ✓
Dashboard Air Bag Sensor		298.30 ✓
Air Bag ECU.		985 ✓
Seat Belt x02		599.8 x 2 = 1199.60 ✓

SJES611J.

Front RH Wheel Rim. 4t

Front RH Tyre.

Front RH Lower Arm.

Front RH Knuckle Arm.

Front RH Shock Absorber

Front RH Wheel Hub c/w Bearing

~~600 (SN)~~ 400(SN)

250(SN) x

371.80 x

562.70 x

335.20 x

216.50 x

Net

Net

List: 15076.20

Len 25%: 11307.15

SIN: 460

Labour: 3340

total: 15107.15

L/S: 9K (Nett Value) Wiring.

11 Days. To undersent

To remove condenser, radiator

To remove air bag and seat belt

To remove dashboard

To remove undercarriage

To perform wheel alignment

Towing Charges.

~~1800~~ 1200

~~1600~~ 1200

~~50~~ 30

~~150~~ 80

~~180~~ 120

~~480~~ 350

~~380~~ 220

380 x

~~150~~ 80

60 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: