





SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 13/09/2019

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SG5802H
Case Reference Number	BUS/09/19/7004
Registration Date	7/3/2017
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN A95
Name of Driver	TAN PENG KWEE
Type of Accident	Side Swipe
Accident Date and Time	4/9/2019 7:25 AM
Accident Reported Date and Time	4/9/2019 11:15 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24103286
Special Instruction to ARC, if any	SG5802H-RIGHT REAR PORTION SDG2121L (TP) INSURED WITH AIG
Prepared Date and Time	8/9/2019 2:57 PM
Chassis Number	WMAA95ZZ9G7003444
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,325.00	\$795.00
Total Spray Cost	\$602.00	\$446.00
Total Spare Part Cost	\$537.90	\$235.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$2,464.90	\$1,476.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	3.0	2.0
Prepared / Adjusted By	Kok Khoo Goh	STEVE CHEN
ARC / Surveyor Sign Off Date	08/09/2019 3:04 PM	09/09/2019 11:04 AM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 13/09/2019

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	\$1,325.00	\$795.00
Total Labour	\$1,325.00	\$795.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$602.00	\$446.00
Total Spray Painting & Panel Beating	\$602.00	\$446.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6012636	VE		REVERSE LAMP BULB (A95 MAN)	1.00	\$235.00	0.00	\$235.00	Replace	Replace
6012635	VE		REAR LAMP BULB (A95 MAN)	0.00	\$245.00	0.00	\$0.00	Replace	Not Given
6013425	Body	155-2-2-009009	O/S FRP REAR LAMP COVER	1.00	\$975.00	100.00	\$0.00	Repair	Repair
	Body	81910-02170	REFLECTOR ASSY, REFLEX, RH	0.00	\$57.90	0.00	\$0.00	Replace	Check
Total					\$1,512.90		\$235.00		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

785
446
235
P/P - 1476