

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

VEHICLE NO : SH 8455B

DATE 9/9/2019 10:22

MAKE :

Like

CHINA

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper			\$ 553.00
	Rear Bumper Clip 10 pcs			\$ 22.00
	Rear Bumper Bracket, LH			\$ 35.60
	Front Door Mirror Assy (LH)			\$ 670.00
	Rear Wheel Hup-Cap (LH)			\$ 107.10
	<i>Front Door (LH) x repair</i>			
	<i>Rear Door (LH) x repair</i>			
	<i>Rocker Panel Assembly (LH) x repair</i>			
	<i>Rear Fender (LH) x repair</i>			
	SUB TOTAL			\$ 1,387.70
	LESS 20%			\$ 277.54
	DISCOUNTED TOTAL			\$ 1,110.16
	Rear Bumper Rubber Mat			\$ 50.00 Nett
	Rear Door Comfortdelgro & Apps Sticker (LH)			\$ 80.00 Nett
	Front Door Coloured Comfort Logo (LH)			\$ 75.00 Nett
				\$ 205.00
	Labour Charge			
	Panel Beating			\$ 800.00 <i>400</i>
	Spray Painting Charge			\$ 900.00 <i>850</i>
	Wiring Charge			\$ 30.00 <i>x</i>
	Tuff Kote			\$ 50.00 <i>x</i>
	Rear Wheel Alignment			\$ 80.00 <i>x</i>
	TOTAL LABOUR			\$ 1,860.00
	ESTIMATE TOTAL			\$ 3,175.16

(Kahr) (1ck)
M 9/9/19 1045h
3 Rep
45
After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before any repair
- To disclose any defects before survey
- Rep's prices are subject to confirmation
- The repair work is done with "justice" parts
- No illegal money transfer is allowed
- Subject to the terms of the repair and is subject to the additional terms of the insurance company.

Acknowledged by Repairer
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.