

COMFORTDELGRO ENGINEERING

Our Job Ref No 305331449

Date : 14/09/19

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr KALVIN ANG

Vehicle Reg No. SH8455B CTPL

09/07/19

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA --- SJX6470S
2. The finalized amount shall be:
 - (a) Spare Parts after List discount
 - (b) Labour Charges
 - Total for Part-By-Part Repair Cost**
 - (c) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:	<u>20%</u>	<u>\$1,600.00</u>
Final Lumpsum Repair cost		<u>\$1,600.00</u>

3. Estimated normal period for repairs: 3 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : LIM KWOK ENG

Tel : 62148316

Fax : 65468156

Signature : 

Name : Calvin

Date : 16/9/19

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	<u>\$7.49</u>			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 8455B

DATE 9/9/2019 10:22

MAKE :

Like

CHINA

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>cut</i>			\$ 553.00
	Rear Bumper Clip 10 pcs <i>✗ - m</i>			\$ 22.00
	Rear Bumper Bracket, LH <i>x m</i>			\$ 35.60
	Front Door Mirror Assy (LH) <i>x repair</i>			\$ 670.00
	Rear Wheel Hup-Cap (LH) <i>— head</i>			\$ 107.10
	<i>Front Door (LH) x repair</i>			
	<i>Rear Door (LH) x repair</i>			
	<i>Roof Panel Grime (LH) x repair</i>			
	<i>Rear Fender (LH) x repair</i>			
	SUB TOTAL			\$ 1,387.70
	LESS 20% DISCOUNTED TOTAL			\$ 277.54
				\$ 1,110.16
	Rear Bumper Rubber Mat <i>— m</i>			\$ 50.00 Nett
	Rear Door Comfortdelgro & Apps Sticker (LH) <i>— m</i>			\$ 80.00 Nett
	Front Door Coloured Comfort Logo (LH) <i>— m</i>			\$ 75.00 Nett
				\$ 205.00
	Labour Charge			<i>400</i>
	Panel Beating			\$ 800.00
	Spray Painting Charge			\$ 900.00 <i>850</i>
	Wiring Charge			\$ 30.00 <i>x 2</i>
	Tuff Kote			\$ 50.00 <i>x 2</i>
	Rear Wheel Alignment			\$ 80.00 <i>x 2</i>
	TOTAL LABOUR			\$ 1,860.00
	ESTIMATE TOTAL			\$ 3,175.16

Lkk Alliance
 The Repairer must be approved by the insurance company.
 • To be approved, the repairer must be a member of the Motor Vehicle Repairers Association of Singapore (MVRAS).
 • Third party liability insurance must be in place.
 • The repairer must be insured by a member of the Motor Vehicle Repairers Association of Singapore (MVRAS).
 • The repairer must be insured by a member of the Motor Vehicle Repairers Association of Singapore (MVRAS).
 Signature: _____
 Date: _____

Kahr (LKK)
9/9/19 10:45h
3 Rep
45
After Repair photo

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.