

2/03/2007

ASS. REC. BY:

REF:

CS/FCI 19016043 / U4f3n2

Special Instruction:

Survey: Marcus

ASSIGNMENT (Office)

From (Person): Karen Tan

of FCI

Date/Time: 2:30pm @ 10/9/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SDR 131M

Insured: SHA 1326D

at Workshop m/s: Zoom Autoworks

Tel: 9450 7420

of 130 Bedok Reservoir Road #08-1339

Policy No:

Claim No: D19005577MFSH

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 24/08/2019

CA / REV / REP. / REV 24 HRS

11/9/19

H.O.D. Endorsement:

Date/Time: 3:39pm @ 10/9/19

Person Contacted:

Cin

Vehicle IN/OUT

Date/Time	Action/Instruction
	Insp: 15 Kaki Bukit Road 4 #01-53
	SHA 1326D CC3/E62/17001539/H1hg3q2 D.O.A. 21/01/2017
	SDR 131M CC6/A2G1/2015276/T2pt2w2 D.O.A. 24/01/2013
13/9 @ 8:42am	Sent email pending estimate.

ASSIGNMENT

From: Date: 11/9/19

Estimated Cost:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SDR 131M
at Workshop m/s ZOOM Autowerkes
of 15 Kelki Bukit Road 4 #01-53

Insured:

Policy No.


Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 65

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (DS)

Date: Person Contacted: Vehicle: IN / OUT

Veh No: SDR 131M Yr Regn: 7 00

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAI

Make: Porsche boxster C.C. 3179

Colour: not black A/C: Insured / Std / NI / NA

Sp. Reading: 132902 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WP022298245643360

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/352219

R: 265/352219

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 mm Rear 6 mm

R/Bal. 8 mm L/Bal. 6 mm

D.O.A. D.O.I. 11/9/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Cor 28-2-2019 LTA31348

1/10/19 L/S ← 2400 confirmed with SLI (Red: 16494.69; 8790)
EST

MV: \$65,000

LTA: \$31,348

Nett: \$33,652.

RECEIVED 04 OCT 2019

Date/Time, File Pass to?

☐ : Preli. Report

3/10 Typist.

☒ : Final Report

Date/Time, File Return to?

By

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Wheel end (\$)

Survey Fee:

Transportation:

3 + RS: \$1

Finance

Others:

TOTAL

8X15-120

1704 120

50

50

51

441

Report Format:

Lump ☒ in / LBR: 2400

MOTOR SURVEY ASSIGNMENT

Date	28-08-2019	Our Ref No. D19005577MFSH
Accident Date	24-08-2019	Claim Type. Third Party
Insured Vehicle	SHA1326D	Third Party Vehicle. SDR131M
Survey Location	130 BEDOK RESERVOIR ROAD#08-1339	
Contact Person.	ELIN CAI	
Contact No.	0/ 94507920	Fax No. 0
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ZOOM AUTOWERKS PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Friday, 13 September 2019 8:42 AM
To: Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments
Cc: 'Karen Tan'; SUR
Subject: RE: SURVEY ASSESSMENT - D19005577MFSH/1

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SDR 131M on 11/9/2019
We are pending estimate from repairer.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Tuesday, 10 September 2019 3:42 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19005577MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that repairer agreed survey on 11/09/2019.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 10 September 2019 2:30 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19005577MFSH/1

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F



Loaded with delectably Sweetdeals!

Porsche Boxster

Price Range ▼

Depreciation ▼

> 10 year(s) ▼

Vehicle Type ▼

Home » Used Cars » Igua Motoring » Porsche Boxster S 3.2A Tip (COE till 04/2029)

Porsche Boxster S 3.2A Tip (COE till 04/2029)

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price \$73,800

Depreciation ⓘ \$7,700 /yr

Reg Date 02-Mar-2001
(9yrs 6mths 29days COE left)

Mileage 124,000 km (6.7k /yr)

Manufactured ⓘ 2000

Road Tax ⓘ \$3,999 /yr

Transmission Auto

Dereg Value ⓘ \$33,946 as of today (change)

OMV ⓘ \$73,384

COE ⓘ \$35,411

ARF ⓘ \$102,738

Engine Cap 3,179 cc

No. of Owners ⓘ More than 6

Curb Weight ⓘ N.A.

Type of Vehicle Sports Car

Features

Porsche Flat 6 Multi Point Injection Engine, 5 Speed Tiptronic Auto, Perfect Weight Distribution, Porsche Soft Top Roadster, ABS, SRS Airbags.

Accessories

19" Sports Rims, Beautifully Restored Interior, No Flaky/Sticky Interior. Retractable Soft Top Cabriolet. Climatic Aircon, Tiptronic Steering Shifter.

Description

STA Certified, Accident Free Quality Pre-Owned With Low Mileage Done! Here's Your Chance To Own This Gorgeous Soft Top Porsche At A Very Affordable Depreciation. Pristine Low Mileage Done! Well Kept And Maintained By Previous Owner, Original Paintwork With Clean And Neat Interior! 100% Loan Approval With Our Flexible In House Financing, All Enquiries Are Welcome Thru Call Or WhatsApp!

Category

COE Car, Low Mileage Car

Status

Avr ⓘ
Compare



Location Map

Shortlist

Com

Report Error

M

Seller Information

Company	Igua » dec » 22
Address	210 1 Search
Location	Car M
Office No	6383
Contact Person(s)	Mix L

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	007D
Vehicle Details	
Vehicle No.:	SDR131M
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Oct 2019
Vehicle Make:	PORSCHE
Vehicle Model:	BOXSTER S TP
Primary Colour:	Black
Manufacturing Year:	2000
Engine No.:	67Y09192
Chassis No.:	WPOZZZ98ZYS643360
Maximum Power Output:	-
Open Market Value:	\$72,193.00
Original Registration Date:	28 Jul 2000
First Registration Date:	28 Jul 2000
Transfer Count:	11
Actual ARF Paid:	\$101,071.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	28 Feb 2029
COE Category:	E - Open Category
COE Period(Years):	10
PQP Paid:	\$31,933.00
COE Rebate Amount:	\$31,348.00
Total Rebate Amount:	\$31,348.00

The information contained herein is correct as at 01 Oct 2019

OK

**ZOOM AUTOWERKS PTE LTD**

130 Bedok Reservoir Road, Eunus Spring

#08-1339 Singapore 470130

Tel: 9450 7920

zoomautowerks@gmail.com

Car Number: SDR131M

Date: 04/09/2019

Model: Porsche Boxster 'S'

Damaged Area: (Front Portion Damaged)

Supplementary may be included during the cost of repair:

Parts / Material:

1	Front Bumper (Accessories)	2400
2	Front Bumper Top Rubber	
3	Front Bumper Side Retainer	
4	Front bumper Reinforcement	
5	Front Bumper Centre Air Mesh	
6	Front Bumper Side Air Mesh	
7	Front Bumper Lower Spoiler	
8	Front Bumper Clips	60.00
9	Front Support Panel	
10	Front Centre Brace Panel	
11	Front Headlamp Assy	
12	Front Headlamp Bracket	
13	Front Headlamp Apron Garnish	
14	Front Headlamp Apron Quarter Garnish	

Quantity			
De/CNE	\$	4,790.50	✓
11	\$	220.00	X
\$294.80 X 2pcs	11	\$	589.60 X
11	\$	985.00	X
11	\$	668.00	X
11	\$	368.00	X
CNE	\$	968.00	X
\$10.00 X 10pcs	11	\$	100.00 ✓
11	\$	1,251.00	X
11	\$	228.00	X
\$1,650.00 X 2pcs	11	\$	3,300.00 X
\$175.00 X 2pcs	11	\$	350.00 ✓
\$458.00 X 2pcs	11	\$	916.00 X
\$155.00 X 2pcs	11	\$	310.00 X

Parts:	\$	15,044.10
Less Parts 10%:	\$	1,504.41
Total Parts:	\$	13,539.69

Special Net Items:

Front Number Plate With Garnish
Accessories Front Wrapping on Affected Areas

S/N	\$	55.00	15
NF	\$	2,200.00	X
Total S/N Parts:	\$	2,255.00	

Labour:

To Remove & Renew Front Affected Accident Areas
To Putty, Spray Paint on Front Affected Accident Areas
To Check & Re-Connect all electrical wiring
To Re-Programme & Reset Diagnostic
To Rust Proof Affected Areas

	\$	1,400.00	380
	\$	1,200.00	400
11	\$	50.00	X
11	\$	250.00	X
11	\$	200.00	X
Total Labour:	\$	3,100.00	

TOTAL PARTS:	\$	13,539.69
TOTAL SPECIAL NET ITEM:	\$	2,255.00
TOTAL LABOUR:	\$	3,100.00
TOTAL REPAIR COST:	\$	18,894.69

DATE OF SURVEY / INSPECTED:

RECOMMENDED PART BY PART / LUMP SUM:

RECOMMENDED NUMBER OF DAYS:

SURVEY BY / SURVEYOR FIRM:

RE-SURVEY DISMANTLE PARTS / BEFORE PAINT / AFTER PAINT:

FINALISED AMOUNT:

LKK Auto Consultants hence notify
the Repairer of the following:

- To be done before/after spray painting
- To inspect damaged part(s) during resurvey
- Parts change are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

not Authorized
LKK
11/9/19
2400/
1/5 3 day
Whisper Affected

18894.69

P-2460

102
2214
3009

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI19016043/Utf3n2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 09-10-2019



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 1326D	Veh. Inspected	SDR 131M
Policy No.		Coverage (\$)	0.00
Claim No.	D19005577MFSH	Excess (\$)	0.00
Assign From	KARENT	Assign Date	10/09/2019

2. Vehicle Particulars & Condition

Make & Model	PORSCHE BOXSTER (A)	c.c	3179
Engine No.	HIDDEN	Year of Reg.	2000
Chassis No.	WPOZZZ98ZYS643360	Colour	MATT BLACK
Odometer	132902	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/35 ZR19	MICHELIN	6 mm
L/H Front Tyre	235/35 ZR19	MICHELIN	6 mm
R/H Rear Tyre	265/35 ZR19	MICHELIN	6 mm
L/H Rear Tyre	265/35 ZR19	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	24/08/2019	Inspection Date	11/09/2019
Survey held at	15 KAKI BUKIT ROAD 4 #01-53		
Repairer	ZOOM AUTOWERKS PTE LTD		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDR 131M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER (ACCESSORIES)	DEFORMED / CRACKED	4,790.50	2,400.00
1	FRONT BUMPER TOP RUBBER	NOT NECESSARY	220.00	-
2	FRONT BUMPER SIDE RETAINER @\$294.80	NOT NECESSARY	589.60	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	985.00	-
1	FRONT BUMPER CENTRE AIR MESH	NOT NECESSARY	668.00	-
1	FRONT BUMPER SIDE AIR MESH	NOT NECESSARY	368.00	-
1	FRONT BUMPER LOWER SPOILER (CRACKED)	NOT CONSISTENT WITH THE IMPACT	968.00	-
10	FRONT BUMPER CLIPS @\$10.00	NECESSARY	100.00	60.00
1	FRONT SUPPORT PANEL	NOT NECESSARY	1,251.00	-
1	FRONT CENTRE BRACE PANEL	NOT NECESSARY	228.00	-
2	FRONT HEADLAMP ASSY @\$1650.00	NOT NECESSARY	3,300.00	-
2	FRONT HEADLAMP BRACKET @\$175.00	NOT NECESSARY	350.00	-
2	FRONT HEADLAMP APRON GARNISH @\$458.00	NOT NECESSARY	916.00	-
2	FRONT HEADLAMP APRON QUARTER GARNISH @\$155.00	NOT NECESSARY	310.00	-
	LESS 10% DISCOUNT		-1,504.41	-246.00
			13,539.69	2,214.00
SPECIAL NETT ITEMS				
1	FRONT NUMBER PLATE WITH GARNISH (SN)	SCRATCHED	55.00	15.00
1	ACCESSORIES FRONT WRAPPING ON AFFECTED AREAS (SN)	NOT FITTED	2,200.00	-
			2,255.00	15.00
LABOUR				
	TO REMOVE & RENEW FRONT AFFECTED ACCIDENT AREAS.		1,400.00	380.00
	TO PUTTY, SPRAY PAINT ON FRONT AFFECTED ACCIDENT AREAS.		1,200.00	400.00
	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING.	NOT NECESSARY	50.00	-
	TO RE-PROGRAMME & RESET DIAGNOSTIC.	NOT NECESSARY	250.00	-

Report Ref No. CS/FCI19016043/Utf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RUST PROOF AFFECTED AREAS.	NOT NECESSARY	200.00	-
			3,100.00	780.00
GRAND TOTAL			18,894.69	3,009.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,400.00

Report Ref No. CS/FCI19016043/Utf3n2

MARKET VALUE: \$65,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$31,348.00=NETT VALUE: \$33,652.00

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.