

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

6-Sep-19

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1379 K

1 pc	Emblem I30	- <i>acc</i>	\$	27.80
1 pc	Emblem CRDI	- <i>acc</i>	\$	29.40
1 pc	Emblem Hyundai	- <i>acc</i>	\$	29.40
1 pc	Rear bumper	- <i>Repl</i>	\$	811.11
1 pc	Rear bumper sponge	X <i>acc</i>	\$	79.20
1 pc	Rear bumper reinforcement	X <i>acc</i>	\$	815.64
1 pc	Rear bumper reinforcement centre	X <i>acc</i>	\$	79.20
2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20	X <i>acc</i>	\$	104.40
1 pc	Tailgate lower garnish	- <i>acc</i>	\$	362.61
1 pc	Tailgate	- <i>Repl</i>	\$	2,292.30
1 pc	Rear windscreen moulding	- <i>acc</i>	\$	64.10
2 pcs	Tailgate license lamp @ \$18.60	X <i>acc</i>	\$	37.20
1 pc	Handle Assy- Twin swing	X <i>acc</i>	\$	36.80
			\$	4,732.36
			Less 20%	\$ 946.47
			\$	3,785.89

S/NETT

1 set	Rear bumper clips	- <i>acc</i>	\$	48.00
1 set	Reverse sensor	- <i>shld</i>	\$	280.00 200
1 pc	Rear no. plate	X <i>acc</i>	\$	50.00
1 set	Tailgate stickers	- <i>acc</i>	\$	100.00
1 set	Tailgate lower garnish clips	- <i>acc</i>	\$	28.00
To replace the rear windscreen into new shd tailgate			\$	120.00 100
To dismantle and refit the inner component into new tailgate, test wiper motor and water etc			\$	80.00 50
Sundry			\$	50.00 20
To dismantle and replace reverse sensor and test system			\$	80.00 30
To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the tailgate, end panel, etc			\$	600.00 400
To putty and spray painting on the rear bumper, tailgate, tailgate lower garnish, end panel			\$	800.00 540

LKK Auto Consultant's hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Accepted by Repairer

Signature:

Date:

To apply rustproofing on the repaired and replaced panels

	²⁰
	\$ 120.00
Total	\$ 6,141.89

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

1/26/19 11/10/19

9/9/19 1025L

3 by,

P'P

Before Part photo

18/10/19

colored 45 \$3550 / 3 by,

1/