

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

6-Sep-19

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1379 K

1 pc	Emblem I30		\$	27.80
1 pc	Emblem CRDI		\$	29.40
1 pc	Emblem Hyundai		\$	29.40
1 pc	Rear bumper		\$	811.11
1 pc	Rear bumper sponge	X	\$	79.20
1 pc	Rear bumper reinforcement	X	\$	815.64
1 pc	Rear bumper reinforcement centre	X	\$	79.20
2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20	X	\$	104.40
1 pc	Tailgate lower garnish		\$	362.61
1 pc	Tailgate		\$	2,292.30
1 pc	Rear windscreen moulding		\$	64.10
2 pcs	Tailgate license lamp @ \$18.60	X	\$	37.20
1 pc	Handle Assy- Twin swing	X	\$	36.80
				\$ 4,732.36
Less 20%				\$ 946.47
				\$ 3,785.89

S/NETT

1 set	Rear bumper clips		\$	48.00
1 set	Reverse sensor		\$	280.00 200
1 pc	Rear no. plate	X	\$	50.00
1 set	Tailgate stickers		\$	100.00
1 set	Tailgate lower garnish clips		\$	28.00
To replace the rear windscreen into new shell tailgate				\$ 120.00 100
To dismantle and refit the inner component into new tailgate, test wiper motor and water etc				\$ 80.00 50
Sundry				\$ 50.00 20
To dismantle and replace reverse sensor and test system				\$ 80.00 30
To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the tailgate, end panel, etc				\$ 600.00 400
To putty and spray painting on the rear bumper, tailgate, tailgate lower garnish, end panel				\$ 800.00 540

LWK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

To apply rustproofing on the repaired and replaced panels

20

	\$	120.00
Total	\$	<u>6,141.89</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.**

Ka hū 11/1/19

9/9/19 1025h

3 Aug,

P/P

Before Port photo