

TTS EUROCARS PTE LTD

383 Sin Ming drive Singapore 575717

Date : 23.09.2019

RE: VEHICLE REPAIR QUOTATION

| | | |
|-------------------|---|------------------------------------|
| Insurance Company | : | AIG Asia Pacific Insurance Pte Ltd |
| Vehicle Reg No | : | SKN3090R |
| Name of Insured | : | |
| Policy Number | : | |
| Date of Accident | : | 31.08.2019 |
| Tyre of Claim | : | Third Party Claim |
| Model | : | MAZDA CX 5 5 DOOR WAGOB |
| Chassis No | : | JM6KE1071E0251256 |

We are please to submit our estimate of repairs to the above mention vehicle.

| | | Parts | Labour |
|----|--|-------------|--------|
| 1 | REAR BOOT <i>bt</i> / | \$ 1,637.40 | |
| 2 | REAR WINDSCREEN <i>?? (photo)</i> | \$ 1,020.00 | |
| 3 | REAR BOOT EMBLEM <i>rec</i> / | \$ 54.30 | |
| 4 | REAR BOOT LOGO "CX-5" <i>rec</i> / | \$ 47.60 | |
| 5 | REAR BOOT LOGO "SKY ACTIV" <i>rec</i> / | \$ 75.20 | |
| 6 | REAR BOOT LOCK <i>bt</i> / | \$ 269.30 | |
| 7 | REAR BOOT INNER TRIM BOARD <i>?</i> | \$ 313.40 | |
| 8 | REAR NUMBER PLATE LAMP <i>X</i> | \$ 47.60 | |
| 9 | REAR BOOT INNER TRIM CLIPS <i>rec</i> / | \$ 45.00 | |
| 10 | REAR BUMPER <i>de</i> / | \$ 1,278.90 | |
| 11 | REAR BUMPER SIDE RETAINER <i>rec</i> / | \$ 34.16 | |
| 12 | REAR BUMPER BRACKET <i>rec</i> / | \$ 17.30 | |
| 13 | REAR BUMPER REINFORCEMENT <i>bt</i> / | \$ 614.10 | |
| 14 | REAR BUMPER CENTRE BRACEKET <i>rec</i> / | \$ 6.00 | |
| 15 | REAR END PANL <i>repair</i> | \$ 476.10 | |
| 16 | REAR END PANEL TOP GARNISH <i>?</i> | \$ 78.20 | |
| 17 | REAR BUMPER CLIPS <i>rec</i> / | \$ 40.00 | |
| 18 | REAR WEATHERSTRIP <i>rec</i> / | \$ 183.30 | |
| 19 | END PANEL TOP GARNISH CLIPS <i>rec</i> / | \$ 16.00 | |
| 20 | REAR FENDER AIR VENT <i>?</i> | \$ 74.90 | |
| 21 | REAR BUMPER REFLECTOR RH <i>X</i> | \$ 106.30 | |
| 22 | REAR BUMPER REFLECTOR LH <i>X</i> | \$ 106.30 | |
| 23 | REAR EXHAUST TAIL PIPE <i>X</i> | \$ 1,754.00 | |
| 24 | REAR SPARE TYRE BOARD <i>X</i> | \$ 763.40 | |
| | REAR REAR FENDER INNER TRIM BOARD <i>X</i> | | |
| 25 | RH | \$ 458.30 | |
| 26 | REAR FENDER INNER TRIM BOARD LH <i>X</i> | \$ 354.20 | |
| 27 | REAR TOWING COVER <i>mis</i> / | \$ 15.00 | |
| 28 | TAIL LAMP RH <i>X</i> | \$ 588.00 | |
| 29 | TAIL LAMP LH <i>X</i> | \$ 588.00 | |
| 30 | REAR BOOT LAMP RH <i>X</i> | \$ 378.90 | |
| 31 | REAR BOOT LAMP LH <i>X</i> | \$ 378.90 | |

| | |
|-----------------|-------------|
| Sub Total Parts | \$11,820.06 |
| Less 10% | \$ 1,182.01 |

Total Parts \$10,638.05

| | | | |
|----------------|---|----|------------------------------------|
| 1 | Sundries | \$ | 30 150.00 |
| 2 | To conduct electrical wiring check for proper functioning | \$ | 150.00 X |
| 3 | Tuff kote - body cavity preservation | \$ | 150.00 40 |
| 4 | Sealant for body panel | \$ | 150.00 X |
| 5 | To remove and refix/ replace rear bumper reverse sensors/ conduct distance setting | \$ | 150.00 60 |
| 6 | To remove and refix/ replace rear reverse camera, calibrate and adjust distance angle | \$ | 150.00 60 |
| 7 | To remove and refix rear windscreen, conduct water leak test | \$ | 150.00 120 |
| 8 | Sealant for rear windscreen | \$ | 60.00 40 60 |
| 9 | Inner seal for rear windscreen | \$ | 50.00 } 60 |
| 10 | To supply and install solar film for rear windscreen | \$ | 350.00 ? 200 |
| 11 | To transfer rear tail gate mechanisms, components, trims, scuff plates, and all other affected components and parts | \$ | 450.00 80 |
| 12 | To remove and refix rear spare tyre board, compartment, trims, carpets, seats, seat belts, buckles, to facilitate repair | \$ | 550.00 80 |
| 13 | To repair, replace rear boot, rear bumper rear end panel, rear spare tyre panel rear fender rh and lh and all other affected parts and areas | \$ | 2,000.00 500 |
| 14 | To putty, sand, spray paint, polish and wax rear boot, rear bumper, rear end panel, spare tyre panel, rear fender rh, rear fender lh, boot outer trim, and all other affected areas | \$ | 2,000.00 600 |
| 15 | To conduct ECU programming, check and clear fault codes, restore programme modules | \$ | 550.00 100 |
| Total (Labour) | | \$ | <u>7,060.00</u> |
| Sub Total : | | \$ | \$10,638.05 + \$7,060.00 17,698.05 |
| GST 7% | | \$ | 1,238.86 |
| Grand Total : | | \$ | <u>18,936.92</u> |

Rasul
Hp 90010068

5 days

45

24/09/19 @ 1510

Resurvey after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.