

Agher

TTS EUROCARS PTE LTD

383 Sin Ming drive Singapore 575717

Date : 23.09.2019

RE: VEHICLE REPAIR QUOTATION

Insurance Company	:	AIG Asia Pacific Insurance Pte Ltd
Vehicle Reg No	:	SKN3090R
Name of Insured	:	
Policy Number	:	
Date of Accident	:	31.08.2019
Tyre of Claim	:	Third Party Claim
Model	:	MAZDA CX 5 5 DOOR WAGOB
Chassis No	:	JM6KE1071E0251256

We are please to submit our estimate of repairs to the above mention vehicle.

		Parts	Labour
1	REAR BOOT <i>bt</i>	\$ 1,637.40 ✓	
2	REAR WINDSCREEN <i>photo</i> <i>x sue</i>	\$ 1,020.00	
3	REAR BOOT EMBLEM <i>new</i>	\$ 54.30 ✓	
4	REAR BOOT LOGO "CX-5" <i>new</i>	\$ 47.60 ✓	
5	REAR BOOT LOGO "SKY ACTIV" <i>new</i>	\$ 75.20 ✓	
6	REAR BOOT LOCK <i>bt</i>	\$ 269.30 ✓	
7	REAR BOOT INNER TRIM BOARD <i>x sue</i>	\$ 313.40	
8	REAR NUMBER PLATE LAMP <i>x sue</i>	\$ 47.60	
9	REAR BOOT INNER TRIM CLIPS <i>new</i>	\$ 45.00 ✓	
10	REAR BUMPER <i>bt</i>	\$ 1,278.90 ✓	
11	REAR BUMPER SIDE RETAINER <i>new</i>	\$ 34.16 ✓	
12	REAR BUMPER BRACKET <i>new</i>	\$ 17.30 ✓	
13	REAR BUMPER REINFORCEMENT <i>bt</i>	\$ 614.10 ✓	
14	REAR BUMPER CENTRE BRACEKET <i>new</i>	\$ 6.00 ✓	
15	REAR END PANL <i>repair</i>	\$ 476.10	
16	REAR END PANEL TOP GARNISH <i>x sue</i>	\$ 78.20	
17	REAR BUMPER CLIPS <i>new</i>	\$ 40.00 ✓	
18	REAR WEATHERSTRIP <i>new</i>	\$ 183.30 ✓	
19	END PANEL TOP GARNISH CLIPS <i>new</i>	\$ 16.00 ✓	
20	REAR FENDER AIR VENT <i>x sue</i>	\$ 74.90	
21	REAR BUMPER REFLECTOR RH <i>x sue</i>	\$ 106.30	
22	REAR BUMPER REFLECTOR LH <i>x sue</i>	\$ 106.30	
23	REAR EXHAUST TAIL PIPE <i>x sue</i>	\$ 1,754.00	
24	REAR SPARE TYRE BOARD <i>x sue</i>	\$ 763.40	
	REAR REAR FENDER INNER TRIM BOARD <i>x sue</i>		
25	RH	\$ 458.30	
26	REAR FENDER INNER TRIM BOARD LH <i>x sue</i>	\$ 354.20	
27	REAR TOWING COVER <i>mis</i>	\$ 15.00 ✓	
28	TAIL LAMP RH <i>x sue</i>	\$ 588.00	
29	TAIL LAMP LH <i>x sue</i>	\$ 588.00	
30	REAR BOOT LAMP RH <i>x sue</i>	\$ 378.90	
31	REAR BOOT LAMP LH <i>x sue</i>	\$ 378.90	

Sub Total Parts \$11,820.06

Less 10% \$ 1,182.01

Total Parts \$10,638.05

1	Sundries	\$	30 150.00
2	To conduct electrical wiring check for proper functioning	\$	150.00 X ⁿⁿ
3	Tuff kote - body cavity preservation	\$	150.00 60 ⁴⁰
4	Sealant for body panel	\$	150.00 X ⁿⁿ
5	To remove and refix/ replace rear bumper reverse sensors/ conduct distance setting	\$	150.00 60
6	To remove and refix/ replace rear reverse camera, calibrate and adjust distance angle	\$	150.00 60
7	To remove and refix rear windscreen, conduct water leak test	\$	150.00 120
8	Sealant for rear windscreen	\$	60.00 20 ⁶⁰
9	Inner seal for rear windscreen	\$	50.00 ⁶⁰
10	To supply and install solar film for rear windscreen	\$	350.00 ? ^X ⁿⁿ 200 X
11	To transfer rear tail gate mechanisms, components, trims, scuff plates, and all other affected components and parts	\$	450.00 80
12	To remove and refix rear spare tyre board, compartment, trims, carpets, seats, seat belts, buckles, to facilitate repair	\$	550.00 80
13	To repair, replace rear boot, rear bumper rear end panel, rear spare tyre panel rear fender rh and lh and all other affected parts and areas	\$	2,000.00 500
14	To putty, sand, spray paint, polish and wax rear boot, rear bumper, rear end panel, spare tyre panel, rear fender rh, rear fender lh, boot outer trim, and all other affected areas	\$	2,000.00 600
15	To conduct ECU programming, check and clear fault codes, restore programme modules	\$	550.00 100
Total (Labour)		\$	<u>7,060.00</u>
Sub Total :		\$	\$10,638.05 + \$7,060.00 17,698.05
GST 7%		\$	1,238.86
Grand Total :		\$	<u>18,936.92</u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.

PRE INVOICE

AIG INSURANCE
78 SHENTON WAY
#08-16
SINGAPORE 079120

DOCUMENT NO : IN19-000045
DATE : 07/10/2019

Vehicle No: SKN3090R
MAZDA CX5
Mileage: 0

Staff ID : KAVIDHA
Account No : AIG INSUR
JOB NO : TN19-000045

No	Description	quantity U	List Price	Amount
1	Rear Boot	1		\$1,637.40 ✓
2	Rear boot Emblem	1		\$54.30 ✓
3	Rear Boot Logo "CX-5"	1		\$47.60 ✓
4	Rear boot logo "SKY ACTIV"	1		\$75.20 ✓
5	Rear Boot Lock	1		\$269.30 ✓
6	Rear boot inner trim clips	1		\$45.00 ✓
7	Rear Bumper	1		\$1,278.90 ✓
8	Rear bumper side retainer	1		\$34.16 ✓
9	Rear bumper bracket	1		\$17.30 ✓
10	Rear bumper reinforcement	1		\$614.10 ✓
11	Rear bumper centre bracket	1		\$6.00 ✓
12	Rear bumper clips	1		\$40.00 ✓
13	Rear weather strip	1		\$183.30 ✓
14	End panel top garnish clips	1		\$16.00 ✓
15	Rear towing cover	1		\$15.00 ✓
Parts Total				\$4,333.56
Less 20%				\$866.71
				<u>\$3,466.85</u> ✓

Labour

1	Sundries	1		\$30.00 ✓
2	Tuff kote body cavity preservation	1		\$40.00 ✓
3	Remove/refix/replace rear bumper reverse sensors/conduct distance setting	1		\$60.00 ✓
4	Remove/refix/replace rear reverse camera calibrate and adjust distance angle	1		\$60.00 ✓
5	Remove/refix rear windscreen conduct water leak test	1		\$120.00 ✓
6	sealant and inner seal for windscreen	1		\$60.00 ✓
7	supply/install solar film for rear windscreen	1		\$200.00 ✗
8	Trasfer rear tailgate mechanism component trims,scuff plates and all other affected parts	1		\$80.00 ✓
9	Remove/refix rear spare tyre board compartment,trims,carpets,seats,seat beltbuckle for repair	1		\$80.00 ✓
10	Repair/replace rear boot rear bumper rear end panel rear spare tyre panel rear fender RH LH and other affected parts /areas	1		\$500.00 ✓
11	Putty,sand,spray paint polish and wax rear boot,rear bumper rear end panel spare tyre	1		\$600.00 ✓

- panel rear fender RH, rear fender LH boot
outer trim and all other affected areas
- 12 Conduct ECU programming check and clear
fault codes restore programme modules

1

\$100.00 /

Labour	\$1,930.00 1730
Subtotal	\$5,396.85
Less 15%	\$809.53
Total	\$4,587.32
add GST 7%	\$321.11
	\$4,908.43

* Acknowledgement by Customer *

I confirm that the goods stated in this invoice have
been received by me in good working order and condition.

I further confirm that all services and /or repair jobs

Stated in this invoice are completed and done to my Satisfaction. TTS EUROCARS PTE LTD

Name/Signature/NRIC No/Co Stamp (where applicable)

Authorised Signature



TTS EUROCARS pte ltd

Company Reg. No: 200413930H

383 Sin Ming Drive, TTS Centre, Singapore 575717 Ssles: +65 6842 2222 Admin: +65 6757 0122 Aftersal
Branch : No.15, Commonwealth Lane, Lot A1, Commonwealth Car Mall, Singapore 149554 Tel : +65 6462
For corporate, fleet & leasing enquiries, please contact +65 6462 1111 24-Hour Emergency Assistance: +6

3466.84
1730.00

5196.84
15%
4417.31

4/s - 4400