

1/1/2011

INS. CASE OWNER:

Janet

CC4/EQ1901 6057, R19630

LKK
IDAC

Surveyor:

RASHI

DOI:

ASSIGNMENT

2/1/19

Date / Time:

9/9/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLD 76187

Name of Insured:

LEE GUE NGOR SHARON

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

20/8/19

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

DM19H00508/JT

Policy No.:

DMPDH19-004079

Make / Model:

Honda

Place of Accident:

COMMONWEALTH HW

If NO, Driver Name / Age:

Driver Tel No.:

(VA: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SMA 984D



INSRS:

WSP:

Tel:

Liability:

RMKS:

MOVA



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time		STAGE	DATE / PIC
	2019-08-20 - 8	Non-Reporting 1st (1st):	
	2019-08-20 - 8	Non-Reporting 1st (2nd):	
		Non-Reporting 1st (Final):	
		Notification 1st (if non-pickup):	
		Call OI:	
		After call 1st to OI:	
		Documentation Check List:	Handler Typist
		Notification 1st (if non-pickup):	☒
		After call 1st to OI:	☒
		Authorisation To Act:	☒
		Release Voucher:	☒
		Final Repair Bill:	☒
		Car Rental Invoice:	☒
		Towing Invoice:	☒
		LTA / GIA:	☒
		Medical Bill:	☒
		PIR:	☒
		Mandate/Reject Instruction:	☒
		LOD:	☒
		Payment Breakdown Form:	☐
		Post-Repair Photos:	☐
		Others:	☐

PRELIMINARY ADVICE	Date/Time:	Sent By:
--------------------	------------	----------

PRELIMINARY ADVICE		Date/Time:	Sent By:	Confirm with:	Confirm by:
Repair Cost:	PIP	SS 5360.80	(5 days) Reduction:	51674.00 x 24	Email ☐ Call ☐
FINAL SETTLEMENT		Date/Time:	Confirm with:	Confirm by:	
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.:	27		
Repair Cost:	(W/EST)	SS 5360.80			
Loss of Rental (LOR):	SS	(5 days)			
Loss of Use (LOU):	SS 600.00	(5 days)			
Loss of Income (LOI):	SS	(5 days)			
LOR only ☐ LOU only ☒	LOR + LOU ☐ LOR + LOI ☐	[Tick only one]			
GIA/LTA Search	SS 2.00				
Medical:	SS				
Disbursement:	SS	(e.g. Tow/Independent)			
Legal Cost:	SS				
Total:	SS 6370.80	Global Sum SS:			
FINAL PAYMENT		Date/Time:	Confirm with:	Confirm by:	
Payee 1:	SS 6370.80	Name 1:	MOVA Automotive Pte Ltd		
Payee 2: (Strike if N.A.)	SS	Name 2:			
Payee 3: (Strike if N.A.)	SS	Name 3:			

06
22/11
2w



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/EQ119016057/R1gb3

Date: 24.09.2019

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SMA9821D

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 23.09.2019 at the premises of M/s Mova Automotive Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	6,935.26
Revised Estimate Amount	: S\$	4,421.63
"Check" Items Amount	: S\$	621.58
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5 days

Yours faithfully,

MOHD. RASUL
Licensed Appraiser

Location

Estimate

09/09/2019

EQ INSURANCE CO LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK MND COMPLEX
SINGAPORE 069110

Attention :- XA039

Page # :- 1

Veh # :- SMA9821D

Veh Model :- TOYOTA VOXY

Estimate# :- CK419667

Claim # :-

ACC. Date :- 30/08/19

Terms :- C.O.D Days

Remarks :-

Main Office:
Move Building
No. 22, Jalan Klang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.move.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/04
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088964-2

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	REAR BOOT	1 PC	1,980.50	1,980.50
2.	REAR BOOT LOGO (HYBRID)	1 PC	105.20	105.20
3.	REAR WINDSCREEN MOULDING	4 PC	89.20	356.80
4.	REAR BOOT LOCK	1 PC	585.31	585.31
5.	REAR BOOT CATCH	1 PC	42.10	42.10
6.	REAR BUMPER	1 PC	1,025.00	1,025.00
7.	BUMPER CLIPS	10 PC	5.80	58.00
8.	REAR BUMPER RETAINER L+R	2 PC	255.80	511.60
9.	REAR BUMPER REFLECTOR LIGHT L+R	2 PC	65.20	130.40
10.	END PANEL - REPAIR	1 PC		
11.	END PANEL TOP GARNISH	1 PC	362.10	362.10
12.	WETHERSTRIP	1 PC	390.00	390.00
LIST TOTAL S\$				5,547.01
25% DISCOUNT S\$				-1,386.75
Parts \$450081 -25%				\$3375.60
Sn \$445				4,160.26
SPECIAL NET ITEMS :				
1.	REAR WINDSCREEN SEALANT	1 PC	45.00	45.00
2.	REAR PARKING SENSOR CENTRE	2 PC	250.00	500.00
3.	REAR BOOT COMPANY DECAL	1 PC	400.00	400.00
SPECIAL NET TOTAL S\$				945.00
LABOUR :				
TO REPAIR REAR END PANEL, TO STRAIGHTEN & REALIGN ON ACCIDENT AFFECTED AREAS				500 600.00
TO SPRAY PAINT ON ACCIDENT AFFECTED AREAS				600 200.00
TO REMOVE REAR WINDSCREEN GLASS				120 150.00
TO REMOVE & REFIX REAR BOOT LOCK & OTHER ATTACHMENT PARTS				60 80.00
TO REMOVE & REFIX REAR SIDE TRIM BOARD L+R, SPARE TYRE & OTHER ATTACHMENT PARTS				60 120.00
TO REMOVE & REFIX REAR PARKING SENSOR				60 80.00
TO RUST PROOF ON ACCIDENT AFFECTED AREAS				40 80.00
TO INSPECT REAR TAILLAMP WATER LEAKAGE TEST				10 X 40.00
LABOUR TOTAL S\$				1,830.00

Parts \$450081 -25%

\$3375.60

Sn \$445

Labour \$1440

Total PIP \$5260.60

200 180 400.00

500 600.00

600 200.00

120 150.00

60 80.00

60 120.00

60 80.00

40 80.00

10 X 40.00

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6478 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/08/09/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

09/09/2019

EQ INSURANCE CO LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK MND COMPLEX
SINGAPORE 069110

Attention :- XA039

Page # :- 1 136095

Veh # :- SMA9821D

Veh Model :- TOYOTA VOXY

Estimate# :- CK419667

Claim # :-

ACC. Date :- 30/08/19

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 6,935.26

GST @ 7 % 485.47

AMOUNT DUE S\$ 7,420.73

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

Issue
Hp 90010068
5 days
4/5 P/P
23/09/19 @ 1350
Recovery after repair

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

09/09/2019

EQ INSURANCE CO LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK MND COMPLEX
SINGAPORE 069110

Attention :- XA039

Page # :- 1

Veh # :- SMA9821D

Veh Model :- TOYOTA VOXY

Estimate# :- CK419667

Claim # :-

ACC. Date :- 30/08/19

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	REAR BOOT <i>df /</i>	1 PC	1,980.50	1,980.50
2.	REAR BOOT LOGO (HYBRID) <i>ren /</i>	1 PC	105.20	105.20
3.	REAR WINDSCREEN MOULDING <i>ren /</i>	4 PC	89.20	356.80
4.	REAR BOOT LOCK <i>X</i>	1 PC	585.31	585.31
5.	REAR BOOT CATCH <i>X</i>	1 PC	42.10	42.10
6.	REAR BUMPER <i>de -</i>	1 PC	1,025.00	1,025.00
7.	BUMPER CLIPS <i>ra -</i>	10 PC	5.80	58.00
8.	REAR BUMPER RETAINER L+R <i>X</i>	2 PC	255.80	511.60
9.	REAR BUMPER REFLECTOR LIGHT L+R <i>X</i>	2 PC	65.20	130.40
10.	END PANEL - REPAIR	1 PC		
11.	END PANEL TOP GARNISH <i>?</i>	1 PC	362.10	362.10
12.	WETHERSTRIP <i>ren /</i>	1 PC	390.00	390.00
LIST TOTAL S\$				5,547.01
25% DISCOUNT S\$				-1,386.75
				4,160.26
SPECIAL NET ITEMS :				
1.	REAR WINDSCREEN SEALANT <i>ren /</i>	1 PC	45.00	45.00
2.	REAR PARKING SENSOR CENTRE <i>?</i>	2 PC	250.00 200	500.00
3.	REAR BOOT COMPANY DECAL	1 PC	400.00 150	400.00
SPECIAL NET TOTAL S\$				945.00
LABOUR :				
TO REPAIR REAR END PANEL, TO STRAIGHTEN & REALIGN ON ACCIDENT AFFECTED AREAS				500 600.00
TO SPRAY PAINT ON ACCIDENT AFFECTED AREAS				600 700.00
TO REMOVE REAR WINDSCREEN GLASS				120 150.00
TO REMOVE & REFIX REAR BOOT LOCK & OTHER ATTACHMENT PARTS				60 80.00
TO REMOVE & REFIX REAR SIDE TRIM BOARD L+R, SPARE TYRE & OTHER ATTACHMENT PARTS				60 120.00
TO REMOVE & REFIX REAR PARKING SENSOR				60 80.00
TO RUST PROOF ON ACCIDENT AFFECTED AREAS				40 60.00
TO INSPECT REAR TAILLAMP WATER LEAKAGE TEST				X 40.00
LABOUR TOTAL S\$				1,830.00

Estimate

09/09/2019

EQ INSURANCE CO LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK MND COMPLEX
SINGAPORE 069110

Attention :- **XA039**

Page # :- 1 136095

Veh # :- SMA9821D

Veh Model :- TOYOTA VOXY

Estimate# :- CK419667

Claim # :-

ACC. Date :- 30/08/19

Terms :- C.O.D Days

Remarks :-

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel : **(65) 6476 3333**
Fax : (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 100B
Bukit Merah Lane 3,
#01-04/06/08/04
Singapore 159722

Tel : **(65) 6272 3892**
Fax : 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$

6,935.26

GST @ 7 %

485.47

AMOUNT DUE S\$

7,420.73

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

Repair

Hp 90010068

5 days

H/S

23/09/19 @ 1350

Recovery after repair

LKK Auto Consultants hereby notify the Repairer of the following:

- To repair/replacement/repair painting
- To display damaged parts during repairing
- Parts prices are subject to cost-plus
- Third party survey is on a "Without Prejudice" basis
- No legal involvement is involved
- Supplementary items must be provided and is subject to final approval from the insurance company.

Acknowledged by Repairer:

Signature:

Date:

Nivitha (LKK Auto)

From: Janet Tan <janet.tan@eqinsurance.com.sg>
Sent: Monday, 9 September 2019 3:30 PM
To: assignments
Cc: Admin A
Subject: FW: DM19HO02508/JT: TP CLAIMS - SMA9821D AGAINST SLD7618J DOA 30/08/2019 AT ALONG COMMONWEALTH AVE TOWARDS GIM MOH
Attachments: RPT.PDF; EST.PDF

4:24pm 9/9/19
while not in
person @ RTH

Dear all,

Please arrange to attend to the PRS.

Meanwhile, we are following up on non reporting.

Regards,

Janet Tan
Senior Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Nitha [mailto:nitha@nova.com.sg]
Sent: Monday, September 9, 2019 12:16 PM
To: Janet Tan <janet.tan@eqinsurance.com.sg>
Cc: tanyw@nova.com.sg
Subject: RE: DM19HO02508/JT: TP CLAIMS - SMA9821D AGAINST SLD7618J DOA 30/08/2019 AT ALONG COMMONWEALTH AVE TOWARDS GIM MOH

Dear Janet,

Please assign LKK.

Thank you.

Best Regards,

Nitha

Claims Officer
Nova Automotive Pte Ltd
Tel: 6272 3892 Fax: 6270 8314

From: Janet Tan [mailto:janet.tan@eqinsurance.com.sg]
Sent: Monday, 9 September 2019 11:49 AM
To: nitha@nova.com.sg
Cc: tanyw@nova.com.sg
Subject: DM19HO02508/JT: TP CLAIMS - SMA9821D AGAINST SLD7618J DOA 30/08/2019 AT ALONG COMMONWEALTH AVE TOWARDS GIM MOH

Without Prejudice
Save As To Costs

Dear Nitha

Accident not reported. We are unable to comment on liability as yet.

We shall be appointing our surveyor to attend to the pre-repair survey of your client's vehicle.

Below is a list of motor surveyors in our panel. Please revert within 2 working days if you agree or have any objections to the appointment of any of the motor surveyors. If we do not hear from you, you are deemed to have agreed to the appointment of any of the motor surveyors listed by us. Alternatively, please specify one or more of our proposed motor surveyors to the said assignment.

1) AJAX Inspection Services Pte Ltd Tel: 6255 0808 Fax: 6849 9155	2) Automobile Inspection Services Pte Ltd Tel: 6286 0155 Fax: 6284 1539 Contact Person: Sophia
3) LBS Automotive Appraisal Pte Ltd L.B.S. Auto Consultants Pte Ltd Tel: 6281 6690 / 62832866 Fax: 6281 8748 Contact Person: Amy/ Grace	4) Priority Services Tel: 62934822 Fax: 62963283 Contact Person: Sharon
5) RT Appraisal Pte Ltd Tel: 67486076 Fax: 67480361 Contact Person: Elson/Elgene	6) LKK Auto Consultants Pte Ltd Tel: 6256-3561 Fax: 6741-4108
7) Kelvin Automotive Appraising Services Tel: 81825263 Fax: 67461148 Contact Person: Kelvin	8) Automotive Appraiser & Surveying Services Tel: 96623655 Fax: 67655662 Contact Person: Mr Chee
9) JP Knights Pte Ltd Tel: 63450068	10) Appraisals Associates Pte Ltd Tel : 67472822

Fax: 63445328	Fax: 67470070
11) Infiniti Appraisal Service Tel : 96684818/90099001 Fax: 64587432	12) Formteam Adjusters Pte Ltd Tel: 65091788 Fax: 65096221

If you object to all the motor surveyors as proposed by us, please provide a list of at least 10 motor surveyors whom you consider as suitable to appoint for our consideration. We shall revert to you within 2 working days.

Meanwhile, we reserve our rights on Post-Repair Inspection, kindly contact us or our appointed surveyor before you return your client's vehicle to him/her.

Thank you.

Regards,

Janet Tan
Senior Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqinsurance.com.sg

A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Nitha [<mailto:nitha@nova.com.sg>]
Sent: Monday, September 9, 2019 10:51 AM
To: EQI PRS <EQIPRS@eqinsurance.com.sg>
Cc: 'Tan Yoong Wei' <tanyw@nova.com.sg>
Subject: TP CLAIMS - SMA9821D AGAINST SLD7618J DOA 30/08/2019 AT ALONG COMMONWEALTH AVE TOWARDS GIM MOH

Dear Sir/Mdm,

Kindly assist to advise on the officer-in-charge and revert on the liability of accident.

Thank you.

Best Regards,
Nitha
Claims Officer

Mova Automotive Pte Ltd
Tel: 6272 3892 Fax: 6270 8314



Cecilia Chong (LKK Auto)

From: Cecilia Chong (LKK Auto)
Sent: Wednesday, 20 November 2019 12:02 PM
To: Suann
Subject: RE: SMA9821D & SLD7618J on 30/8/19

WITHOUT PREJUDICE

Dear Suann,

We are pleased to accept the proposed amount of \$6230.85.

Please note that no DV is required for this case.

We shall proceed to submit and close off the case at our end.

Thanks

"Please note that our above settlement is made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our insured/driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Settlement and payment are subject to production of original documents on demand at any time and execution of Discharge Voucher (for settlement sum above \$20,000/-) by the Plaintiff/Claimant. Further all original documents shall be retained by us after we have made payment on the settlement sum."

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Suann [mailto:suann@nova.com.sg]
Sent: Wednesday, 20 November 2019 11:55 AM
To: Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com>
Subject: RE: SMA9821D & SLD7618J on 30/8/19

Dear Cecilia

My client does not accept your offer.

Please compromise loss of use \$600.00 total sum all in \$6230.85.

Thank you.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD			Ref : CC4/EQ19016057/R1gb3q2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date : 11-12-2019	
			Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLD 7618J	Veh. Inspected	SMA 9821D	
Policy No.	DMPPHQ19-004079	Coverage (\$)	0.00	
Claim No.	DM19HO02508/JT	Excess (\$)	0.00	
Assign From	JANET	Assign Date	09/09/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VOXY HYBRID 1.8	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	ZWR800318892	Colour	WHITE	
Odometer	69010	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	BRIDGESTONE	6 mm	
L/H Front Tyre	195/65 R15	BRIDGESTONE	6 mm	
R/H Rear Tyre	195/65 R15	BRIDGESTONE	6 mm	
L/H Rear Tyre	195/65 R15	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/08/2019	Inspection Date	23/09/2019	
Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMA 9821D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT	BENT	1,980.50	1,980.50
1	REAR BOOT LOGO (HYBRID)	NECESSARY	105.20	105.20
4	REAR WINDSCREEN MOULDING @\$89.20	NECESSARY	356.80	356.80
1	REAR BOOT LOCK	CRACKED	585.31	585.31
1	REAR BOOT CATCH	SERVICEABLE	42.10	-
1	REAR BUMPER	DEFORMED	1,025.00	1,025.00
10	BUMPER CLIPS @\$5.80	NECESSARY	58.00	58.00
2	REAR BUMPER RETAINER L+R @\$255.80	SERVICEABLE	511.60	-
2	REAR BUMPER REFLECTOR LIGHT L+R @\$65.20	SERVICEABLE	130.40	-
1	END PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
1	END PANEL TOP GARNISH	SERVICEABLE	362.10	-
1	WEATHERSTRIP	NECESSARY	390.00	390.00
	LESS 25% DISCOUNT		-1,386.75	-1,125.20
			4,160.28	3,375.61
SPECIAL NETT ITEMS				
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	45.00	45.00
2	REAR PARKING SENSOR CENTRE @\$250.00 (SN)	NOT WORKING	500.00	200.00
1	REAR BOOT COMPANY DECAL (SN)	NECESSARY	400.00	200.00
			945.00	445.00
LABOUR				
	TO REPAIR REAR END PANEL ,TO STRAIGHTEN & REALIGN ON ACCIDENT AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF END PANEL .		600.00	500.00
	TO SPRAY PAINT ON ACCIDENT AFFECTED AREAS.		700.00	600.00
	TO REMOVE REAR WINDSCREEN GLASS.		150.00	120.00
	TO REMOVE & REFIX REAR BOOT LOCK & OTHER ATTACHMENT PARTS.		80.00	60.00
	TO REMOVE & REFIX REAR SIDE TRIM BOARD L+R,SPARE TYRE & OTHER ATTACHMENT PARTS.		120.00	60.00
	TO REMOVE & REFIX REAR PARKING SENSOR.		80.00	60.00
	TO RUST PROOF ON ACCIDENT AFFECTED AREAS.		60.00	40.00

Report Ref No. CC4/EQI19016057/R1gb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO INSPECT REAR TAILLAMP WATER LEAKAGE TEST.	NOT NECESSARY	40.00	-
			1,830.00	1,440.00
GRAND TOTAL			6,935.26	5,260.61
RECOMMENDED COST OF REPAIRS				5,260.61

Report Ref No. CC4/EQ19016057/R1gb3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.