

NTUC INCOME INSURANCE CO-OP LTD			NAME : Ms YY Siau		WIP : 30347	
1 MARITIME SQUARE			ADDRESS : Apt Blk 58 Jalan Ma'Mor		EXCESS :	
#10-01 HARBOUR FRONT CENTRE			#01-45		DATE: 09.09.2019	
SINGAPORE 099253			Singapore 320058			
ATTN. : MOTOR CLAIMS			TEL : 84183638			
FAX :						
VEH NO :	SKT3638E		DATE IN :		CONTACT PERSON :	JOBI THOMAS 63310682
CHASSIS NO :	WMWSU32020T316071		MILEAGE :		TYPE OF CLAIM :	TP
MODEL :	R56		DATE REG.:	13.09.2012	POLICY NO. :	
NATURE OF WORKS						
S/NO	Parts Description					
	QTY				REVISED	PRICES
1	RH REAR FENDER R56		1	M41.00.7.230.554	\$850.00	\$ 1,116.24
2	BLINDNIET N3		8	M83.19.0.301.421	\$3.50	\$ 5.76
3	ADHESIVE K5B		1	B83.19.2.157.298	\$300.00	\$ 424.84
4	CLEANER R1		1	M83.19.2.211.217	\$25.00	\$ 33.99
5	PUNCH RIVET		29	B83.19.2.457.307	\$15.00	\$ 20.88
6	RH REAR LIGHT,		1	M63.21.7.255.912	\$320.00	\$ 424.39
7	NUT		2	M63.21.2.756.354	\$8.00	\$ 9.62
8	RH TAIL LIGHT CHROME FRAME		1	M51.13.2.752.244	\$80.00	\$ 96.46
9	RH REAR FENDER MOULDING		1	M51.37.2.756.102	\$80.00	\$ 93.08
10	RH REAR FENDER MOULDING INSERT		1	M51.37.2.754.857	\$35.00	\$ 41.66
11	RH REAR COLUMN C BRACKET		1	M51.37.2.754.776	\$30.00	\$ 34.26
12	CLIP		2	M51.37.2.756.103	\$25.00	\$ 29.26
13	CLIP W/WASHER WHITE		6	B51.41.8.224.768	\$8.00	\$ 10.14
14	REAR BUMPER W/CHROME LCI COOPER		1	M51.12.7.264.356	\$700.00	\$ 873.54
15	CTR SPOILER W/PDC LCI COOPER		1	M51.12.7.265.087	\$250.00	\$ 260.07
16	REAR BUMPER SUPPORT RH		1	M51.12.2.751.304	\$20.00	\$ 25.35
17	EXPANDING NUT		8	M63.25.2.758.031	\$16.00	\$ 17.20
18	CLIP		12	M51.47.2.754.477	\$25.00	\$ 30.48
19	RIVET		12	M07.13.0.702.966	\$15.00	\$ 18.00
20	EXPANDING RIVET		10	M51.48.1.915.964	\$5.00	\$ 6.50
21	SENSOR PARKASSIST		1	M66.20.9.196.705	\$250.00	\$ 307.90
22	GASKET		1	M66.20.6.923.000	\$5.00	\$ 6.57
23	RH REAR WHEEL ARCH		1	M51.77.7.157.106	\$160.00	\$ 168.93
24	RH SIDE SKIRT R56		1	M51.77.7.147.916	\$ -	\$ 239.27
25	JACK POINT		2	M51.71.7.039.760	\$80.00	\$ 92.56
26	CLIP BLACK		9	M07.13.1.480.419	\$22.00	\$ 25.20
27	CLIP		1	M07.13.7.073.915	\$1.80	\$ 2.21
28	CLIP		4	M51.71.1.496.621	\$4.50	\$ 5.72
29	RHR FENDER INNER SHIELD		1	M51.71.7.136.168	\$130.00	\$ 143.26
30	DOOR ENTRANCE "BAKER STREET"		1	M51.47.7.310.501	\$125.00	\$ 133.51
31	LABEL "RESET		1	M71.24.6.763.822	\$25.00	\$ 31.72
32	LABEL "TIRE		1	M71.24.6.851.461	\$25.00	\$ 31.72
				TOTAL PARTS	\$ 3,638.80	\$ 4,760.29

		\$ -	\$ -
	TOTAL PARTS COST	\$ 3,638.80	\$ 4,760.29
	<u>Labour Description</u>		
1	TO REPLACE RH REAR FENDER AND REAR BUMPER. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 2,000.00	\$ 5,040.00
2	TO RESPRAY RH REAR FENDER AND REAR BUMPER.	\$ 1,000.00	\$ 2,000.00
3	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS.	\$ -	\$ 200.00
4	TO CARRY-OUT BODY CAVITY PRESERVATION.	\$ -	\$ 200.00
5	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	\$ 200.00	\$ 1,680.00
6	TO REMOVE & REFIT THE RH REAR QUARTER GLASS.	\$ 400.00	\$ 560.00
7	TO SUPPLY SEALER ON THE RH REAR QUARTER GLASS.	\$ 80.00	\$ 195.00
8	TO TRANSFER THE REVERSE SENSORS.	\$ 60.00	\$ 250.00
9	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 60.00	\$ 150.00
10	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 60.00	\$ 250.00
11	SUNDRIES.	\$ 1.20	\$ 50.00
		TOTAL LABOUR	\$ 3,861.20 \$ 10,575.00
		TOTAL PARTS	\$ 3,638.80 \$ 4,760.29
		TOTAL	\$ 7,500.00 \$ 15,335.29
		LESS EXCESS	\$ - \$ -
		TOTAL AFTER EXCESS	\$ 7,500.00
		GST 7%	\$ 525.00 \$ -
		GRAND TOTAL	\$ 8,025.00 \$ -

NUMBER OF DAYS: 8 WORKING DAYS(EXCLUDE WAITING FOR SURVEY,AUTHORIZATION,PARTS,SAT,SUN & PH)