

ASS. REC. BY:

REF:

03/INC19016061/R1vd3n4

Special Instruction:

Assigner: Rasul

ASSIGNMENT (Office)

From (Person): Annie Koh of INC Date/Time: 12:24pm @ 10/9/19
 Estimated Cost: Bill to:

OD: ☒ WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No: SKT 3638E Insured: SHB 8048E

at Workshop m/s Trans Eurocars Tel: 633 10682 / 0686

of 27A Tanjong Penjun

Policy No: Claim No: MT/1060994-002

Sum Insured: Excess:

Make of Veh: D.O.A. 4/09/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 12:57pm @ 10/9/19 Person Contacted: Jobi Vehicle ☒ IN / OUT


Date/Time	Action/Instruction
	Estimate ✓
	SKT 3638E-X
	SHB 8048E-003 / III/8003082/K1hb392 JWA: 13/2/2018
24/9/19	Confirmed RS \$7500 by email (Ref 7835.29, 519)

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SKT 3638E
 at Workshop m/s TRANSWORKERS
 of _____
 Insured: NTUC
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: 42500
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKT 3638E Yr Regn: 2012 / SEP
 Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: MINI COOPER F6 A c.c. 1598
 Colour: WHITE A/C: Insured / Std / NI / NA
 Sp. Reading: 070944 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WMW5U32020T316 071
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 195/55R16
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front: _____ Rear: _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 04/09/19 D.O.I. 10/09/19
 Survey held at TRANSWORKERS 3.43
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Left O/S
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	From to Transworkers for the repair limit 7k

RECEIVED 24 SEP 2019

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 8Resurvey No. of Trip: 1

Date/Time, File Return to?

2) 24/9 - typist

Report Format: TP
 Lump Sum / R.R. / RS \$75000

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

250

Nivitha (LKK Auto)

From: Annie Koh <annie.koh@income.com.sg>
Sent: Tuesday, 10 September 2019 12:24 PM
To: 'assignments@lkkauto.com'; Admin-D (LKKAuto)
Subject: RE: TP CASES FARMED OUT TO LKK ON 10/09/2019

From: Annie Koh
Sent: Tuesday, 10 September 2019 11:58 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>; 'Admin-D (LKKAuto)' <admin-d@lkkauto.com>
Subject: RE: TP CASES FARMED OUT TO LKK ON 10/09/2019

Re-send

Warmest Regards

Annie Koh
Senior Admin,
Motor Insurance
T +65 64307899
www.income.com.sg

 **income**
mode different



From: Annie Koh
Sent: Tuesday, 10 September 2019 9:24 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>; 'Admin-D (LKKAuto)' <admin-d@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Teng Ken Leong <kenleong.teng@income.com.sg>
Subject: RE: TP CASES FARMED OUT TO LKK ON 10/09/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	Charlotte Chew	MT/1060673-002	SGJ6583J	ACCORD AUTO SERVICES PTE LTD	BLK 1009 BUKIT MERAH LANE 3 #01-80	celia lai / 92740999		SJT2613U	31/8/19	
2	Juliana Lee	MT/1061610-001	SGR3518B	ACCORD AUTO SERVICES PTE LTD	BLK 1009 BUKIT MERAH LANE 3 #01-80	celia lai / 92740999		SJM2951E	7/9/19	
3	Charlotte Chew	MT/1060994-002	SKT3638E	EUROKARS HABITAT PTE LTD	NO.27A TANJONG PENJURU SINGAPORE 609042	JOB THOMAS / 63310682	14-00-16:00	SHB8048E	4/9/19	
4	Serene Lim	MT/1061249-002	SLE1509A	HITACHI CAPITAL (S) PTE LTD	8 FOURTH LOK YANG ROAD SINGAPORE 629705	ng jiong how / 68336282	14-00-16:00	GBE3833T	5/9/19	
5	Helena Tan	MT/1059976-001	SMD2338M	KAH MOTOR CO SDN BHD	255 ALEXANDRA ROAD BODY REPAIR & PAINT CENTRE SINGAPORE 159937	jack ng / 82886309	10-00-12:00	FBE481U	28/8/19	
6	Azhari	MT/1053928-001	SMD5182	PERFORMANCE MOTORS LTD	303 ALEXANDRA ROAD SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941	caroline / 63190174	10-00-12:00	SMH5415H	17/7/19	
7	Alice Low	MT/1061272-002	SLW9079B	PREMIUM AUTOMOBILES PTE LTD	281 ALEXANDRA ROAD SINGAPORE 159938	GEORGE WONG / 63662323	10-00-12:00	SLM6686X	5/9/19	

8	Jared Liu	MT/1061679-001	PA9876K	SERVE YOU MOTOR SERVICE	8 # JALAN PAPAN SINGAPORE 619418	ELAINE CHIA / 92393188	XE4372P	6/9/19	
9		To be advise	XD8408A	VFIX AUTO PTE LTD	26 CHIA PING ROAD SINGAPORE 619977	weng sheng / 64552957			

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Annie Koh

Senior Admin Assistant, Motor Insurance

T +65 6430 7899

www.income.com.sg



Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 24 September 2019 9:44 AM
To: 'stephanie.loke@eurokars.com.sg'; rickteo@eurokars.com.sg; Rasul (LKKAUTO)
Cc: jobithomas@eurokars.com.sg; SUR
Subject: RE: SKT3638E DOA : 04/09/19

Dear Stephanie,

Noted with thanks

Kindly send Final invoice and all supporting documents directly to NTUC INCOME

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: stephanie.loke@eurokars.com.sg <stephanie.loke@eurokars.com.sg>
Sent: Tuesday, 24 September 2019 9:41 AM
To: rickteo@eurokars.com.sg; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; Rasul (LKKAUTO) <Rasul@lkkauto.com>
Cc: jobithomas@eurokars.com.sg
Subject: RE: SKT3638E DOA : 04/09/19

Dear Veron

Thanks for your call. Yes we accepted the repair limit of S\$7.5K

Regards
Stephanie

From: Rick Teo <rickteo@eurokars.com.sg>
Sent: 23 September 2019 PM 4:28
To: Stephanie Loke <stephanie.loke@eurokars.com.sg>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; Rasul (LKKAUTO) <Rasul@lkkauto.com>
Cc: Jobi Thomas <jobithomas@eurokars.com.sg>
Subject: RE: SKT3638E DOA : 04/09/19

Hi Veron,

Herewith attached photos.

Thank you.
Best Regards.



Rick Teo
Insurance Claims Executive
EUROKARS SERVICES
27A Tanjong Perjuru
Singapore 609042
DID : (+65) 63310697
Email : rickteo@eurokars.com.sg

From: Rick Teo
Sent: 13 September 2019 2:13 PM
To: Stephanie Loke <stephanie.loke@eurokars.com.sg>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; Rasul (LKKAUTO) <Rasul@lkkauto.com>
Cc: Jobi Thomas <jobithomas@eurokars.com.sg>
Subject: RE: SKT3638E DOA : 04/09/19

Dear Stephanie,

Noted.

Thank you.
Best Regards.



Rick Teo
Insurance Claims Executive
EUROKARS SERVICES
27A Tanjong Perjuru
Singapore 609042
DID : (+65) 63310697
Email : rickteo@eurokars.com.sg

From: Stephanie Loke <stephanie.loke@eurokars.com.sg>
Sent: 13 September 2019 12:12 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; Rasul (LKKAUTO) <Rasul@lkkauto.com>
Cc: Jobi Thomas <jobithomas@eurokars.com.sg>; Rick Teo <rickteo@eurokars.com.sg>
Subject: RE: SKT3638E DOA : 04/09/19

Dear Veron

Thanks for the email.

Aside to Rick, please assist Veron's requests.

Much appreciated

Best Regards
Stephanie

From: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Sent: 13 September 2019 PM 12:10

To: Stephanie Loke <stephanie.loke@eurokars.com.sg>; Rasul (LKKAuto) <Rasul@lkkauto.com>
Cc: Jobi Thomas <jobithomas@eurokars.com.sg>; Rick Teo <rickteo@eurokars.com.sg>
Subject: RE: SKT3638E DOA : 04/09/19

Dear Stephine,

Please forward resurvey photos.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: stephanie.loke@eurokars.com.sg <stephanie.loke@eurokars.com.sg>
Sent: Friday, 13 September 2019 12:08 PM
To: Rasul (LKKAuto) <Rasul@lkkauto.com>
Cc: jobithomas@eurokars.com.sg; rickteo@eurokars.com.sg; Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: RE: SKT3638E DOA : 04/09/19

Dear Rasul

We will accept \$7.5K repair limit.

Thank you.

Best Regards
Stephanie

From: Rasul (LKKAuto) <Rasul@lkkauto.com>
Sent: 13 September 2019 AM 9:12
To: Stephanie Loke <stephanie.loke@eurokars.com.sg>
Cc: Jobi Thomas <jobithomas@eurokars.com.sg>; Rick Teo <rickteo@eurokars.com.sg>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: RE: SKT3638E DOA : 04/09/19

Hi Stephanie,

I did spoken to Jobi that limit max is 7500
More than that is unacceptable
Kindly confirm amount of 7500

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: stephanie.loke@eurokars.com.sg [<mailto:stephanie.loke@eurokars.com.sg>]
Sent: Thursday, 12 September, 2019 5:40 PM
To: Rasul (LKKAuto)
Cc: jobithomas@eurokars.com.sg; rickteo@eurokars.com.sg
Subject: FW: SKT3638E DOA : 04/09/19

Dear Rasul

Hope this email finds you well.

Any chance for us to increase the repair limit to 10K?

Please advise

Thank you.

Regards
Stephanie

From: Jobi Thomas <jobithomas@eurokars.com.sg>
Sent: 12 September 2019 PM 2:42
To: Stephanie Loke <stephanie.loke@eurokars.com.sg>
Subject: FW: SKT3638E DOA : 04/09/19

Dear Stephanie,

As spoken,

Kindly refer to the email below and assist, thanks.

Best Regards.



Jobi Thomas
Senior Insurance Claims Executive
27A Tanjong Penjuru, Singapore 609042
T: (65) 6331 0680 D: (65) 6331 0682 F: (65) 6331 0690
E: jobithomas@eurokars.com.sg W: www.eurokarsgroup.com

From: Rasul (LKKAuto) <Rasul@lkkauto.com>
Sent: 12 September 2019 9:00 AM
To: Rick Teo <rickteo@eurokars.com.sg>; Jobi Thomas <jobithomas@eurokars.com.sg>
Subject: SKT 3638e DOA : 04/09/19

Hi Rick,

As spoken to Jobi,

This vehicle reg. is 2012, I've checked that the repair limit for this case is 7K only.


Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

Veron Chen (LKKAUTO)

From: stephanie.loke@eurokars.com.sg
Sent: Tuesday, 24 September 2019 9:41 AM
To: rickteo@eurokars.com.sg; Veron Chen (LKKAUTO); Rasul (LKKAUTO)
Cc: jobithomas@eurokars.com.sg
Subject: RE: SKT3638E DOA : 04/09/19

Dear Veron

Thanks for your call. Yes we accepted the repair limit of S\$7.5K

Regards
Stephanie

From: Rick Teo <rickteo@eurokars.com.sg>
Sent: 23 September 2019 PM 4:28
To: Stephanie Loke <stephanie.loke@eurokars.com.sg>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; Rasul (LKKAUTO) <Rasul@lkkauto.com>
Cc: Jobi Thomas <jobithomas@eurokars.com.sg>
Subject: RE: SKT3638E DOA : 04/09/19

Hi Veron,

Herewith attached photos.

Thank you.
Best Regards.



Rick Teo
Insurance Claims Executive
EUROKARS SERVICES
27A Tanjong Perjuru
Singapore 609042
DID : (+65) 63310697
Email : rickteo@eurokars.com.sg

From: Rick Teo
Sent: 13 September 2019 2:13 PM
To: Stephanie Loke <stephanie.loke@eurokars.com.sg>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; Rasul (LKKAUTO) <Rasul@lkkauto.com>
Cc: Jobi Thomas <jobithomas@eurokars.com.sg>
Subject: RE: SKT3638E DOA : 04/09/19

Dear Stephanie,

Noted.

Thank you.
Best Regards.

Rick Teo
Insurance Claims Executive
EUROKARS SERVICES
27A Tanjong Perjuru
Singapore 609042
DID : (+65) 63310697
Email : rickteo@eurokars.com.sg

From: Stephanie Loke <stephanie.loke@eurokars.com.sg>
Sent: 13 September 2019 12:12 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Rasul (LKKAuto) <Rasul@lkkauto.com>
Cc: Jobi Thomas <jobithomas@eurokars.com.sg>; Rick Teo <rickteo@eurokars.com.sg>
Subject: RE: SKT3638E DOA : 04/09/19

Dear Veron

Thanks for the email.

Aside to Rick, please assist Veron's requests.

Much appreciated

Best Regards
Stephanie

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: 13 September 2019 PM 12:10
To: Stephanie Loke <stephanie.loke@eurokars.com.sg>; Rasul (LKKAuto) <Rasul@lkkauto.com>
Cc: Jobi Thomas <jobithomas@eurokars.com.sg>; Rick Teo <rickteo@eurokars.com.sg>
Subject: RE: SKT3638E DOA : 04/09/19

Dear Stephine,

Please forward resurvey photos.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: stephanie.loke@eurokars.com.sg <stephanie.loke@eurokars.com.sg>
Sent: Friday, 13 September 2019 12:08 PM
To: Rasul (LKKAuto) <Rasul@lkkauto.com>
Cc: jobithomas@eurokars.com.sg; rickteo@eurokars.com.sg; Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: RE: SKT3638E DOA : 04/09/19

Dear Rasul

We will accept \$7.5K repair limit.

Thank you.

Best Regards
Stephanie

From: Rasul (LKKAUTO) <Rasul@lkkauto.com>
Sent: 13 September 2019 AM 9:12
To: Stephanie Loke <stephanie.loke@eurokars.com.sg>
Cc: Jobi Thomas <jobithomas@eurokars.com.sg>; Rick Teo <rickteo@eurokars.com.sg>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: RE: SKT3638E DOA : 04/09/19

Hi Stephanie,

I did spoken to Jobi that limit max is 7500
More than that is unacceptable
Kindly confirm amount of 7500

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: stephanie.loke@eurokars.com.sg [mailto:stephanie.loke@eurokars.com.sg]
Sent: Thursday, 12 September, 2019 5:40 PM
To: Rasul (LKKAUTO)
Cc: jobithomas@eurokars.com.sg; rickteo@eurokars.com.sg
Subject: FW: SKT3638E DOA : 04/09/19

Dear Rasul

Hope this email finds you well.

Any chance for us to increase the repair limit to 10K?

Please advise

Thank you.

Regards
Stephanie

From: Jobi Thomas <jobithomas@eurokars.com.sg>
Sent: 12 September 2019 PM 2:42
To: Stephanie Loke <stephanie.loke@eurokars.com.sg>
Subject: FW: SKT3638E DOA : 04/09/19

Dear Stephanie,

As spoken,

Kindly refer to the email below and assist, thanks.

Best Regards,



Jobi Thomas

Senior Insurance Claims Executive

27A Tanjong Penjuru, Singapore 609042

T: (65) 6331 0680 D: (65) 6331 0682 F: (65) 6331 0690

E: jobithomas@eurokars.com.sg W: www.eurokarsgroup.com

From: Rasul (LKKAuto) <Rasul@lkkauto.com>

Sent: 12 September 2019 9:00 AM

To: Rick Teo <rickteo@eurokars.com.sg>; Jobi Thomas <jobithomas@eurokars.com.sg>

Subject: SKT 3638e DOA : 04/09/19

Hi Rick,

As spoken to Jobi,

This vehicle reg. is 2012, I've checked that the repair limit for this case is 7K only.


Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

Rasul (LKKAUTO)

From: Rasul (LKKAUTO)
Sent: Thursday, 12 September, 2019 9:00 AM
To: rickteo@eurokars.com.sg; jobithomas@eurokars.com.sg
Subject: SKT 3638e DOA : 04/09/19

Hi Rick,

As spoken to Jobi,

This vehicle reg. is 2012, I've checked that the repair limit for this case is 7K only.


Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK
Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

[➤ Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	056Z
Vehicle Details	
Vehicle No.:	SKT3638E
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Sep 2019
Vehicle Make:	MINI
Vehicle Model:	COOPER HATCHBACK 1.6 ABS D/AB 2WD HID
Primary Colour:	White
Manufacturing Year:	2012
Engine No.:	B286J197N16B16A
Chassis No.:	WMWSU32020T316071
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$22,113.00
Original Registration Date:	13 Sep 2012
First Registration Date:	13 Sep 2012
Transfer Count:	3
Actual ARF Paid:	\$22,113.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Sep 2022
PARF Rebate Amount:	\$14,373.00
Intended COE Rebate Details	
COE Expiry Date:	12 Sep 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$68,000.00
COE Rebate Amount:	\$20,400.00
Total Rebate Amount:	\$34,773.00

The information contained herein is correct as at 12 Sep 2019

OK

42,500
34,773
7,727

repair limit 7500



CERTIFICATE OF INSURANCE

AUTOPLUS PRIVATE VEHICLE

Name of Policyholder : Heng Cher Lik Daniel
Period of Insurance : 13 Mar 2019 To 12 Mar 2020
Engine No. : B286J197N16B16A
Chassis No. : WMWSU32020T316071

Vehicle No. : SKT3638E
Policy No. : 2100503466-02
Endorsement No. :
Issued Date : 21 Feb 2019

ABOUT THE COVER

Make/Model : MINI COOPER 1.6
Engine Capacity/Tonnage : 1,598.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2017
Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Heng Cher Lik Daniel - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

Approved Reporting Centres/ AIG Authorised Repairers (For claims related repairs)

Any accident repairs to the Vehicle must be carried out by one of our Authorised Repairers. Within the first 3 years of the first registration of the Vehicle in Singapore, You have the option of having the accident repairs carried out at the Sole Agent's workshop.

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, You may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: NA

[We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).]

0000064000

DIRECT CLIENTS 01.4.95

AIG BUILDING 78 SHENTON WAY #07-16

SINGAPORE 079120

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

SSPOCC

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: S8018056Z

Name: HENG CHER LIK, DANIEL

Birth Date: 19 Jun 1980

Issue Date: 14 Oct 2003

1000921925J



REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S8018056Z



Name: HENG CHER LIK, DANIEL

Race: CHINESE

Date of birth: 19-06-1980

Country of birth: SINGAPORE

Sex: M

S8018056Z




YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE: 25 Oct 2002

Licence No: S8018056Z



NP 428A

4755273



NRIC No: S8018056Z



Date of issue: 03-08-2011

80 HOLLAND ROAD #03-09
SINGAPORE 278535

NRIC No: S8018056Z

Date: 09/07/2017

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/09/2019 09:43
Date Of Accident	04/09/2019 14:45
Exact Location Of Accident	MACKENZIE RD TO BUKIT TIMAH RH
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKT3638E
Insured/Policyholder	
Name Of Registered Owner	HENG CHER LIK DANIEL
NRIC No	S8018056Z
Email Address	MANINABOX@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97403346
Alternative Phone No	OFFICE-97403346

Vehicle Particulars

Manufacturer	MINI
Model	COOPER S-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	HENG CHER LIK DANIEL
NRIC No	S8018056Z
Date Of Birth	19/06/1980
Occupation	INDOOR
Date Of Driving Pass	25/10/2002
Driving Experience	16 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97403346
Fax Number	
Contact Number	OFFICE-97403346
EMail Address	MANINABOX@GMAIL.COM

Address	90 HOLLAND ROAD #03-09
Postcode	278535
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

KINDLY REFER TO THE ATTACHED SKETCH PLAN.


Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHB8048E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	GOH HOCK HIN
NRIC/Passport Number	S0118529B
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

LICENSE PLATE NO: SUT 3638E

ACCIDENT DATE: 04/09/19	CONTACT NUMBER: 97403346
ACCIDENT TIME: 14:44	EMAIL: MANNA80X@GMAIL.COM
LOCATION: MACKENZIE ROAD.	

I WAS AT MACKENZIE ROAD, TURNING OUT TO
 BUKIT TIMAH. I STOPPED AT THE GIVE WAY
 LINE AND THE SILVER CAB TAXI SHB 8048E
 HIT MY CAR FROM THE REAR.


NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIMS UNDER YOUR OWN POLICY.

PLEASE CHECK YOUR POLICY FOR MORE INFORMATION

PLEASE STATE: ☐ CLAIM OWN POLICY ☒ CLAIM THIRD PARTY ☐ REPORTING ONLY

DECLARATION

I/We declare the foregoing particulars are true in every respect.

 X
 Policyholder's Signature

Date & Time: 05/09/19

 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

09:17.

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

05/09/19

09:13

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



EUROKARS HABITAT PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS



NTUC INCOME INSURANCE CO-OP LTD		NAME : Mr. Domrel	WIP : 30347
1 MARITIME SQUARE		ADDRESS : 97403346	EXCESS :
#10-01 HARBOUR FRONT CENTRE			DATE: 09.09.2019
SINGAPORE 099253			
ATTN. : MOTOR CLAIMS	TEL :		
FAX :			

VEH NO :	SKT3638E	DATE IN :		CONTACT PERSON :	JOBI THOMAS 63310682
CHASSIS NO :	WMWSU32020T316071	MILEAGE :		TYPE OF CLAIM :	TP
MODEL :	R56	DATE REG.:	13.09.2012	POLICY NO. :	

NATURE OF WORKS

S/NO	Parts Description	QTY	REVISED	PRICES
1	RH REAR FENDER R56 <i>st</i> ✓	1		\$ 1,116.24
2	BLINDNIET N3 <i>ne</i> ✓	8		\$ 5.76
3	ADHESIVE K5B <i>ne</i> ✓	1		\$ 424.84
4	CLEANER R1 <i>ne</i> ✓	1		\$ 33.99
5	PUNCH RIVET <i>ne</i> ✓	29		\$ 20.88
6	RH REAR LIGHT, <i>con</i> ✓	1		\$ 424.39
7	NUT <i>ne</i> ✓	2		\$ 9.62
8	RH TAIL LIGHT CHROME FRAME <i>cut</i> ✓	1		\$ 96.46
9	RH REAR FENDER MOULDING <i>ne</i> ✓	1		\$ 93.08
10	RH REAR FENDER MOULDING INSERT <i>ne</i> ✓	1		\$ 41.66
11	RH REAR COLUMN C BRACKET <i>ne</i> ✓	1		\$ 34.26
12	CLIP <i>ne</i> ✓	2		\$ 29.26
13	CLIP W/WASHER WHITE <i>ne</i> ✓	6		\$ 10.14
14	REAR BUMPER W/CHROME LCI COOPER <i>sea</i> ✓	1		\$ 873.54
15	CTR SPOILER W/PDC LCI COOPER <i>sea</i> ✓	1		\$ 260.07
16	REAR BUMPER SUPPORT RH <i>ne</i> ✓	1		\$ 25.35
17	EXPANDING NUT <i>ne</i> ✓	8		\$ 17.20
18	CLIP <i>ne</i> ✓	12		\$ 30.48
19	RIVET <i>ne</i> ✓	12		\$ 18.00
20	EXPANDING RIVET <i>ne</i> ✓	10		\$ 6.50
21	SENSOR PARKASSIST <i>cut</i> ✓	1		\$ 307.90
22	GASKET <i>ne</i> ✓	1		\$ 6.57
23	RH REAR WHEEL ARCH <i>sea</i> ✓	1		\$ 168.93
24	RH SIDE SKIRT R56 <i>X SVC</i>	1		\$ 239.27
25	JACK POINT <i>ne</i> ✓	2		\$ 92.56
26	CLIP BLACK <i>ne</i> ✓	9		\$ 25.20
27	CLIP <i>ne</i> ✓	1		\$ 2.21
28	CLIP <i>ne</i> ✓	4		\$ 5.72
29	RHR FENDER INNER SHIELD <i>? X SVC</i>	1		\$ 143.26
30	DOOR ENTRANCE "BAKER STREET" <i>ne</i> ✓	1		\$ 133.51
31	LABEL "RESET" <i>ne</i> ✓	1		\$ 31.72
32	LABEL "TIRE" <i>ne</i> ✓	1		\$ 31.72
TOTAL PARTS				\$ 4,760.29

			\$ -
	TOTAL PARTS COST		\$ 4,760.29
	Labour Description		
1	TO REPLACE RH REAR FENDER AND REAR BUMPER. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	✓ 4200	\$ 5,040.00
2	TO RESPRAY RH REAR FENDER AND REAR BUMPER.	✓ 1600	\$ 2,000.00
3	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS.	✓ 100	\$ 200.00
4	TO CARRY-OUT BODY CAVITY PRESERVATION.	✓ 100	\$ 200.00
5	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	✓ 840	\$ 1,580.00
6	TO REMOVE & REFIT THE RH REAR QUARTER GLASS.	✓ NETT	\$ 560.00
7	TO SUPPLY SEALER ON THE RH REAR QUARTER GLASS.	✓ NETT	\$ 195.00
8	TO TRANSFER THE REVERSE SENSORS.	✓ 100	\$ 250.00
9	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	✓ NETT	\$ 150.00
10	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	✓ NETT	\$ 250.00
11	SUNDRIES. <i>nee</i>	✓ NETT	\$ 30 50.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

***DISCLAIMER**

- 1 THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.
- 2 TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.
- 3 THIS IS ONLY AN ESTIMATE BASED ON PARTS AVAILABILITIES AT CURRENT LOCAL SINGAPORE

TOTAL LABOUR	\$ -	\$ 10,575.00
TOTAL PARTS	\$ -	\$ 4,760.29
TOTAL	\$ -	\$ 15,335.29
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

Rasul
12/9/19
4p 90010068
8 days
10/09/19 @ 1550
Resy before paint



EUROKARS HABITAT PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS



NTUC INCOME INSURANCE CO-OP LTD		NAME :	Ms YY Siau	WIP :	30347
1 MARITIME SQUARE		ADDRESS :	Apt Blk 58 Jalan Ma'Mor	EXCESS :	
#10-01 HARBOUR FRONT CENTRE			#01-45	DATE:	09.09.2019
SINGAPORE 099253			Singapore 320058		
ATTN. :	MOTOR CLAIMS	TEL :	84183638		
FAX :					
VEH NO :	SKT3638E	DATE IN :		CONTACT PERSON :	JOBI THOMAS 63310682
CHASSIS NO :	WMWSU32020T316071	MILEAGE :		TYPE OF CLAIM :	TP
MODEL :	R56	DATE REG.:	13.09.2012	POLICY NO. :	

NATURE OF WORKS

S/NO	Parts Description		QTY	REVISED	PRICES
1	RH REAR FENDER R56		1	\$1,116.24	\$ 1,116.24
2	BLINDNIET N3		8	\$5.76	\$ 5.76
3	ADHESIVE K5B		1	\$424.84	\$ 424.84
4	CLEANER R1		1	\$33.99	\$ 33.99
5	PUNCH RIVET		29	\$20.88	\$ 20.88
6	RH REAR LIGHT,		1	\$424.39	\$ 424.39
7	NUT		2	\$9.62	\$ 9.62
8	RH TAIL LIGHT CHROME FRAME		1	\$96.46	\$ 96.46
9	RH REAR FENDER MOULDING		1	\$93.08	\$ 93.08
10	RH REAR FENDER MOULDING INSERT		1	\$41.66	\$ 41.66
11	RH REAR COLUMN C BRACKET		1	\$34.26	\$ 34.26
12	CLIP		2	\$29.26	\$ 29.26
13	CLIP W/WASHER WHITE		6	\$10.14	\$ 10.14
14	REAR BUMPER W/CHROME LCI COOPER		1	\$873.54	\$ 873.54
15	CTR SPOILER W/PDC LCI COOPER		1	\$260.07	\$ 260.07
16	REAR BUMPER SUPPORT RH		1	\$25.35	\$ 25.35
17	EXPANDING NUT		8	\$17.20	\$ 17.20
18	CLIP		12	\$30.48	\$ 30.48
19	RIVET		12	\$18.00	\$ 18.00
20	EXPANDING RIVET		10	\$6.50	\$ 6.50
21	SENSOR PARKASSIST		1	\$307.90	\$ 307.90
22	GASKET		1	\$6.57	\$ 6.57
23	RH REAR WHEEL ARCH		1	\$168.93	\$ 168.93
24	RH SIDE SKIRT R56		1	-	\$ 239.27
25	JACK POINT		2	\$92.56	\$ 92.56
26	CLIP BLACK		9	\$25.20	\$ 25.20
27	CLIP		1	\$2.21	\$ 2.21
28	CLIP		4	\$5.72	\$ 5.72
29	RHR FENDER INNER SHIELD		1	-	\$ 143.26
30	DOOR ENTRANCE "BAKER STREET"		1	\$133.51	\$ 133.51
31	LABEL "RESET		1	\$31.72	\$ 31.72
32	LABEL "TIRE		1	\$31.72	\$ 31.72
TOTAL PARTS				\$ 4,377.76	\$ 4,760.29

			\$ -
	TOTAL PARTS COST	\$ 4,377.76	\$ 4,760.29
	Labour Description		
1	TO REPLACE RH REAR FENDER AND REAR BUMPER. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 4,200.00	\$ 5,040.00
2	TO RESPRAY RH REAR FENDER AND REAR BUMPER.	\$ 1,600.00	\$ 2,000.00
3	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS.	\$ 100.00	\$ 200.00
4	TO CARRY-OUT BODY CAVITY PRESERVATION.	\$ 100.00	\$ 200.00
5	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	\$ 840.00	\$ 1,680.00
6	TO REMOVE & REFIT THE RH REAR QUARTER GLASS.	\$ 560.00	\$ 560.00
7	TO SUPPLY SEALER ON THE RH REAR QUARTER GLASS.	\$ 195.00	\$ 195.00
8	TO TRANSFER THE REVERSE SENSORS.	\$ 100.00	\$ 250.00
9	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 150.00	\$ 150.00
10	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 250.00	\$ 250.00
11	SUNDRIES.	\$ 30.00	\$ 50.00
	TOTAL LABOUR	\$ 8,125.00	\$ 10,575.00
	TOTAL PARTS	\$ 4,377.76	\$ 4,760.29
	TOTAL	\$ 12,502.76	\$ 15,335.29
	LESS EXCESS	\$ -	\$ -
	TOTAL AFTER EXCESS	\$ 12,502.76	
	GST 7%	\$ 875.19	\$ -
	GRAND TOTAL	\$ 13,377.95	\$ -

***DISCLAIMER**

- 1 THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.
- 2 TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.
- 3 THIS IS ONLY AN ESTIMATE BASED ON PARTS AVAILABILITIES AT CURRENT LOCAL SINGAPORE



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19016061/R1vd3n2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 26-09-2019



ATTN: CHARLOTTE CHEW

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 8048E	Veh. Inspected	SKT 3638E
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1060994-002	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	10/09/2019

2. Vehicle Particulars & Condition

Make & Model	MINI COOPER 1.6A	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	WMWSU32020T316071	Colour	WHITE
Odometer	70944 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/55 R16	GOODYEAR	6 mm
L/H Front Tyre	195/55 R16	GOODYEAR	6 mm
R/H Rear Tyre	195/55 R16	GOODYEAR	6 mm
L/H Rear Tyre	195/55 R16	GOODYEAR	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	04/09/2019	Inspect Date / Time	10/09/2019 (03:43 PM)
Survey held at	27A TANJONG PENJURI		
Repairer	TRANS EUROKARS PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKT 3638E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	RH REAR FENDER R56 (SN)	BENT	1,116.24	1,116.24
8	BLINDNIET N3 (SN)	NECESSARY	5.76	5.76
1	ADHESIVE K5B (SN)	NECESSARY	424.84	424.84
1	CLEANER R1 (SN)	NECESSARY	33.99	33.99
29	PUNCH RIVET (SN)	NECESSARY	20.88	20.88
1	RH REAR LIGHT (SN)	CRACKED	424.39	424.39
2	NUT (SN)	NECESSARY	9.62	9.62
1	RH TAIL LIGHT CHROME FRAME (SN)	CUT	96.46	96.46
1	RH REAR FENDER MOULDING (SN)	NECESSARY	93.08	93.08
1	RH REAR FENDER MOULDING INSERT (SN)	NECESSARY	41.66	41.66
1	RH REAR COLUMN C BRACKET (SN)	NECESSARY	34.26	34.26
2	CLIP (SN)	NECESSARY	29.26	29.26
6	CLIP W/WASHER WHITE (SN)	NECESSARY	10.14	10.14
1	REAR BUMPER (SN)	SCRATCHED	873.54	873.54
1	CTR SPOILER W/PDC LCI COOPER (SN)	SCRATCHED	260.07	260.07
1	REAR BUMPER SUPPORT RH (SN)	NECESSARY	25.35	25.35
8	EXPANDING NUT (SN)	NECESSARY	17.20	17.20
12	CLIP (SN)	NECESSARY	30.48	30.48
12	RIVET (SN)	NECESSARY	18.00	18.00
10	EXPANDING NUT (SN)	NECESSARY	6.50	6.50
1	SENSOR PARKASSIST (SN)	CUT	307.90	307.90
1	GASKET (SN)	NECESSARY	6.57	6.57
1	RH REAR WHEEL ARCH (SN)	SCRATCHED	168.93	168.93
1	RH SIDE SKIRT R56 (SN)	SERVICEABLE	239.27	-
2	JACK POINT (SN)	NECESSARY	92.56	92.56
9	CLIP BLACK (SN)	NECESSARY	25.20	25.20
1	CLIP (SN)	NECESSARY	2.21	2.21
4	CLIP (SN)	NECESSARY	5.72	5.72
1	RHR FENDER INNER SHIELD (SN)	SERVICEABLE	143.26	-
1	DOOR ENTRANCE "BAKER STREET" (SN)	NECESSARY	133.51	133.51
1	LABEL "RESET (SN)	NECESSARY	31.72	31.72

Report Ref No. CS/INC19016061/R1vd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	LABEL "TIRE (SN)	NECESSARY	31.72	31.72
1	SUNDRIES (SN)	NECESSARY	50.00	30.00
			4,810.29	4,407.76
	LABOUR			
	TO REPLACE RH REAR FENDER AND REAR BUMPER.TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.		5,040.00	4,200.00
	TO RESPRAY RH REAR FENDER AND REAR BUMPER.		2,000.00	1,600.00
	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS.		200.00	100.00
	TO CARRY-OUT BODY CAVITY PRESERVATION.		200.00	100.00
	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.		1,680.00	840.00
	TO REMOVE & REFIT THE RH REAR QUARTER GLASS.		560.00	560.00
	TO SUPPLY SEALER ON THE RH REAR QUARTER GLASS.		195.00	195.00
	TO TRANSFER THE REVERSE SENSORS.		250.00	100.00
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		150.00	150.00
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		250.00	250.00
			10,525.00	8,095.00
	GRAND TOTAL		15,335.29	12,502.76
	RECOMMENDED COST OF REPAIR SUM (CONFIRMED)			7,500.00

Report Ref No. CS/INC19016061/R1vd3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.