

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III19016080/UGA3Q2**Date:** 11/05/2020REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
Claimant
Vehicle No : GBC7743D **Insured Vehicle No :** SHD4855H
Date of Loss: 09/09/2019 Nature of Claim: TP Claim No: MCT19090172

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBC7743D**
Make & Model: MITSUBISHI CANTER, 3.0 D FEA01BR2SDEB (CBU) (M) Engine No: 4P10A85070
Reg. Date: 28/10/2013 (Man. Year: 2013) Chassis No: FEA01BA00025
Colour: White Odometer: 180652 km
Engine Capacity: 2998 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/70R15 Rear Tyre Size: 195/70R15(D)
Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6/6 mm
Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,410.70	600.50	7,810.20	92.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,575.00	1,120.00	455.00	28.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,985.70	1,720.50	8,265.20	82.77
Approved Total (Overridden) (S\$)		1,350.00		
(S\$)	9,985.70	1,350.00	8,635.70	86.48
+ GST 7.00/7.00% (S\$)	699.00	94.50	604.50	86.48
Nett Amount (S\$)	10,684.70	1,444.50	9,240.20	86.48
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
Nett Liability (S\$)		1,684.50		
Global Sum Settlement (S\$)		1,680.00		

INSPECTION

Date of Assignment: 10/09/2019
Date Inspected: 10/09/2019 Inspected At: Jin Auto Services Pte Ltd (Defu)
Blk 14 Defu Lane 10, #01-410/412
Singapore 539195
Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 05 Dec 2019)	
Parts:	N/A	mitsubishi canter 3.0 D FEA01BR2SDEB (CBU) (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC7743D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR TAIL LAMP LH	Cracked	264.00 FL	*264.00 FL	
2	1		*REAR TAIL LAMP BRACKET LH	Bent	201.00 FL	*201.00 FL	
3	1		*REAR TAIL LAMP BRACKET RUBBER STOPPER	Torn	48.00 FL	*48.00 FL	
4	1		*REAR TAILGATE	Repair	2,899.00 FL	*- FL	
5	2		*REAR TAILGATE LOCK LH	Bent	261.00 FL	*261.00 FL	
6	1		*TIPPER LOWER MEMBER	Repair	699.00 FL	*- FL	
7	1		*TIPPER LH SIDE GATE	Repair	4,951.00 FL	*- FL	
8	1		*REAR TAILGATE 60KM/H	Necessary	10.00 FS	*10.00 FS	
9	1		*REAR TAILGATE 13PAX	Necessary	10.00 FS	*10.00 FS	
					Sub Total (\$\$)	9,343.00	794.00
					- List Item Discount on L Items 10.00/25.00% (\$\$)	932.30	193.50
					Total Parts (\$\$)	8,410.70	600.50

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINTING	New	780.00	600.00
2	LABOUR CHARGE	New	680.00	500.00
3	WIRING	New	35.00	20.00
4	TUFF COATING	New	80.00	0.00
Gross Labour Cost (\$\$)			1,575.00	1,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >