

# Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412  
Singapore 539195  
Tel:62898126 Fax :62870590  
Company Reg No:200704370C GST Reg No ::200704370C

*not allocated  
near  
2/5 = 1350  
3 days  
Wright. Attention*

Your ref :  
Date: 12/9/2019

DEAR SIR / MADAM  
ESTIMATE REPAIR COST FOR GBC7743D ( MITSUBISHI FUSO)  
DATE OF ACCIDENT : 9/9/19  
TO SUPPLY :

<u>LIST ITEMS</u>			
01)	1 PC REAR TAIL LAMP LH	<i>CR2</i>	\$ 264.00 ✓
02)	1 PC REAR TAIL LAMP BRACKET LH	<i>best</i>	\$ 201.00 ✓
03)	1 PC REAR TAIL LAMP BRACKET RUBBER STOPPER	<i>To. n</i>	\$ 48.00 ✓
04)	1 PC REAR TAILGATE	<i>n</i>	\$ 2,899.00 X
05)	2 PC REAR TAILGATE LOCK LH	<i>best</i>	\$ 261.00 ✓
06)	1 PC TIPPER LOWER MEMBER	<i>n</i>	\$ 699.00 X
07)	1 PC TIPPER LH SIDE GATE	<i>n</i>	\$ 4,951.00 X
			<u>\$ 9,323.00</u>
		<i>25%</i> LESS 10%	\$ (932.30)
			\$ 8,390.70
08)	1 PC REAR TAILGATE "60 km/h"	<i>nu</i>	\$ 10.00 ✓ <i>S. 2</i>
09)	1 PC REAR TAILGATE "13 pax"	<i>nu</i>	\$ 10.00 ✓ <i>S. 2</i>
10)	SPRAY PAINTING		\$ 780.00 - 600
11)	LABOUR CHARGE		\$ 680.00 - 500
12)	WIRING		\$ 35.00 - 20
13)	TUFF COATING	<i>^^</i>	\$ 80.00 - X
		<b>TOTAL</b>	<u><u>\$ 9,373.70</u></u>

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

*P-774  
1705*