From (Personal Estimated C	h chin lee ying	of AIG	Date/Time: 10/a/193 3.20pm
OD (TP)	WS/TP RES/OD RES/EV	Bill to:	*
TO TIEDCOL	venucle No:	SKR 18454	Insured: SDG 8889R
at Worksho	m/s Tampin	100 thin Contra	(726)
	B1K 9002 To	mpines steel 93 to	1-36
		Claim No:	889431419356
Sum Insured		Excess:	
Make of Vel (Client's Reco			D.O.A. 31108/2019
	T. Control of the con		
CA / REV	/ REP. / REV 24 HDG		,
CA / REV	/ REP. / REV 24 HDG		,
CA / REV	/ REP. / REV 24 HRS	erson Contacted: Linda	,
CA / REV	/ REP. / REV 24 HRS 10.37 Action/Instruction	erson Contacted: Linda	,
CA / REV	Action/Instruction SKR 1845Y-X	erson Contacted: Linda	,
CA / REV	Action/Instruction SKR 1845Y-X SDG 8889 R-X	Profit (X)	,
CA / REV	Action/Instruction SKR 1845Y-X	erson Contacted: Linda	,

ipes		ASSI	GNMENT	Y		
From	Date: )!	19/19	Veh No:	SKR 1845	Y Yr Regn: MA	R/2006
Estimated Cost:			Type M.Car		Lorry / Taxi / Prime Mov	
	OD RES / EVA / INV / MV		Truck	Trailer or		
To Inspect Vehicle No:	SKR 1845		Make:	Toyota how	mer 2.4 c.c	2362
	tempines Auto	•	Colour	Black.	A/G: Insured / S	Std / NI / NA
	ampines of . 93		Sp.Reading	306697	T/Radio: Insured /	Std / NI / NA
Insured.	arripinos 81 -13	7 01 30	Eng/No:	-		
Policy No.			C/No:	AC U30-004	14428	
Claims No.			Gen. Cond: G	ood (Fair) Poor / Bur		
Sum Insured:	Excess:		Steering: Inor	Jammed / Leake	d/Burnt or	
(Client's Record)			Brake: Inor	rder / Jammed / Leake	d/Burnt or	
Make of Veh:			Modi: Nil/	S/Rim STD A/Rim	or	
			Tyre Size:	F: 225/65	RIT	
(Policy Condition)			1,000	R: 225/65		
Remark: The veh had co	ommenced its	N/S O/S	BS (DUN)E	XNOVA / GY / FS / LIZ	A / MIC / OHTSU / PIR /	SUMI/
	me of inspection.		TOYO / YO			
Bai, பா Market Value:			Front		Rear	
IDAC Accident Rport:	Consistent?: Ye	s or No	R/Bal.	4 mm	R/Bal. 4	mm
GIA / PR Seen:	Consistent? : Ye	s or No	L/Bal.	4 mm	L/Bal. 4	mm
Est. Repairs:	days Res.: Ye		D.O.A. 31	08/2019	D.O.I. 1//09/	19
Lum Sum:	% 3 Val.: Ye	s or No	Survey held			
	(up)		2		S I(N/S) U/C / Roofte	
CA / REV / REP.	1 24 HRS	Vehicle: IN / OUT	1	N/s rear		
Date:	Person Contacted:				ody Structure affected d	lue to collision.
	n / Instruction	-1				
	our days: Ada	JS mm	oft.			
Rone	ge: 3 kto AK	1 1	/			
		1 13	19/20	119		
		()	( )	, ,		
MV:	\$58000					
PV:	\$ 30859	RECE	IVED 2.0	SEP 2019		
WV;	\$27000			011 2010		
Date/Time, File Pass to7	: Preli. Report		Days Of Re	pair: 4		
1)	: Final Report		Resurvey N	o. of Trip: 🗳	Survey Fee:	(80
Date/Time, File Return to?	Name of the last o		-		Transportation:	
2)		Add Fee	: Site	Insp (\$	)S+RS,SI	
			: Inter	view (\$	) Tholos	
Report Formst:	DAR		Tech	Linvs (3	) Others	11
Lump Som / LB.E.	3		: Mee	Lend (\$		
					757741	191

Your password will expire in 5 days. Click here to change it. RE! PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SDG8889R AND SKR... From: Chin, Lee-Ying To: assignments, Admin A Cc: Fong, Andy-SY 9/10/2019 3:20:06 PM Sent: Attachments: GIA REPORT SKR1845Y.PDF LETTER TO 3P AND AIG.PDF Hi LKK, Kindly assist to survey. Thanks. Best Regards Lee Ying, Chin AIG Claims | AIG Asia Pacific Insurance Pte. Ltd. 78 Shenton Way #08-16 Singapore 079120 Tel +(65) 6419 1947 Lee-Ying, Chin@aig.com | www.aig.sg From: sengtat@aplp.com.sg [mailto:sengtat@aplp.com.sg] Sent: Tuesday, September 10, 2019 12:26 PM To: Hor, Yinrul Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divyashni; sengtat@aplp.com.sg Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SDG8889R AND SKR1845Y ON 31/08/2019 Dear Sir/Madam We refer to your email of even date.

Our clients do not agree to your list of surveyors.

We are instructed to propose the use of one of the motor surveyors named below to conduct the joint pre-repair survey as a single joint expert:

- Alan Cheong
- TT Rajan b.
- Oh Han Cheong
- Andrew How
- Dave Ho Joo Koong
- Sincere Appraiser
- g. Seah Kwang Boon
- L H Teo
- Mr Willy Goh
- Nicky Seah
- k. Jayson Liaw

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors.

In the event you are not agreeable to our list of surveyor, please note that our client's vehicle can be inspected at:

#### Repairer Office

M/s. Tampines Auto Services

Contact Person: Ms Linda @ 6786 2884 / 9793 3147 / (Fax: 6786 2926)

Email: tas0136@hotmail.com

Address: Blk 9002, Tampines Street 93, #01-36, Singapore 528836.

Please note that our clients' vehicle will only be available for pre-repair survey within the next two (2) working days. Our clients shall proceed to repair their vehicle thereafter without further notice or reference to you.

All our clients' rights are reserved.

Please note our new office address as of 1st June 2019.

151 Chin Swee Road, #10-03/05 Manhattan House,

Singapore 169876

Tel no.: 6955 8899

Office mobile no.: 9171 4767

Fax no.: 6900 9899

## TAT

A P Law Practice

50 Chin Swee Road #07-01 Thong Chai Building, Singapore 169874

T: 6955 8899 F: 6900 9899 E: sengtat@aplp.com.sg

Singapore UEN No.: 53380739E

This email transmission is confidential and intended only for the addresses(s). It may contain information which is privileged as between solicitor and client or protected by litigation privilege. If you are not the intended receipient, please delete this message and all attachments and inform us by return email. No part of this message should be disclosed to any party, copied or used for any purpose. Thank you for your co-operation.

#### IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information, if you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

## > Back to OneMotoring

Enquire	PARF/CO	E Rebate for	Registered	Vehicle
---------	---------	--------------	------------	---------


Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	919H
Vehicle No.:	SKR1845Y
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Sep 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HARRIER 2.4A
Primary Colour:	Black
Manufacturing Year:	2005
Engine No.:	2AZ2053818
Chassis No.:	ACU300044438
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$31,883.00
Original Registration Date:	26 May 2006
First Registration Date:	26 May 2006
Transfer Count:	1
Actual ARF Paid: Intended PARF Rebate Details	\$35,072.00
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	
PARF Rebate Amount: Intended COE Rebate Details	\$0.00
COE Expiry Date:	25 May 2026
COE Category:	E - Open Category
COE Period(Years):	10
PQP Paid:	\$46,048.00
COE Rebate Amount:	\$30,859.00
Total Rebate Amount:	\$30,859.00

The information contained herein is correct as at 12 Sep 2019

Remaining: 6 years 8 months 25 days (80.8) OK Depri: \$8650/yearly (\$720.83/monthly) 80.8 x \$720.83 = \$58000 Overview

Research

**Photos** 



No cashback cap No minimum spend



Toyota Harrier

**Financial** 

Price Range

Accessories

▼ Depreciation

Similar

▼ > 10 year(: ▼ Vehicle Type

Advanced Search

Home » Used Cars » Takashima Auto Enterprise » Toyota Harrier 2.4A (COE till 05/2026)

Insurance

## Toyota Harrier 2.4A (COE till 05/2026)

Price	\$58,000		
Depreciation (1)	\$8,650 /yr	Reg Date	25-May-2006 (6yrs 8mths 12days COE left)
Mileage	150,000 km (11.3k /yr)	Manufactured 🕖	2006
Road Tax 🕖	\$2,129 /yr	Transmission	Auto
Dereg Value ②	\$30,858 as of today (change)	ому 🗇	\$33,369
COE 💮	\$46,048	ARF ⑦	\$36,706
Engine Cap	2,362 cc	Power	118.0 kW (158 bhp)
Curb Weight	1,600 kg	No. of Owners	4

## Type of Vehicle

View specs of the Toyota Harrier (2004-2012)

SUV

## Description

Features

Like New, 100% Accident Free, Roadtax Due May 2020, Full Accessories, Loan Available, Low Installment, Trade In Welcome.

#### Category

COE Car, Premium Ad Car

## Status

Available

## Resources



Car Valuation - Free

Find out the market value of your existing car for free. Get started



**Vehicle Evaluation** 

Afraid of lemons? Request to have this car evaluated professionally. Find out more

sted on: 04-Sep-2019 | Last Updated on: 11-Sep-2019

#### **Upfront Payment**

Transfer Fee

Insurance

\$25

Down Payment

\$17,400 (change) Maximum 70% Loan

1st Instalment

\$634

\$1,041 onwards Not at fault? No upfront payment required! (Get a quote) Ouote assumes a standard profile. "Get a quote" for exact figure.

Based on 3.75% interest rate

Powered by AVIVA

- more Einancial into

Мар



















Shortlist

Compare

Add note

Report Error

More Actions

#### Seller Information

Company

Takashima Auto Enterprise

» dealer's pricelist

» 8 vehs sold | 4 vehs available

Address

210 Turf Club Road Lot B61 Search cars nearby this location

Location

Car Mall @ The Grandstand

Office No

64658772

Contact Person(s)

Johnny

8113828!

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT
personal december of the second control of

Date Of Report 02/09/2019 09:49
Date Of Accident 31/08/2019 13:20

Exact Location Of Accident ANG MO KIO STREET 12

Country/State of Loss SINGAPORE

### **DETAILS OF OWN VEHICLE**

Vehicle Registration Number SKR1845Y

Insured/Policyholder

Name Of Registered Owner TAN CHERK CHIANG

NRIC No S7563919H

Email Address ALEXTAN182000@GMAIL.COM

Mobile Phone No (LOCAL) +65-90258613
Alternative Phone No OTHERS-90258613

Vehicle Particulars

Manufacturer TOYOTA

Model HARRIER-2.4 (A)

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR

**Insurance Company** 

Name of Insurance Company AXA INSURANCE PTE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number GA351553

Cover Note Number

Driver

Name of Driver TAN CHERK CHIANG

 NRIC No
 S7563919H

 Date Of Birth
 26/02/1975

 Occupation
 INDOOR

 Date Of Driving Pass
 05/07/2007

Driving Experience 12 YEARS AND 1 MONTH

Gender MALE

Mobile Number (LOCAL) +65-90258613

Fax Number

Contact Number OTHERS-90258613

EMail Address ALEXTAN182000@GMAIL.COM

BLK 215 SERANGOON AVENUE 4 #05-114 · Address

SINGAPORE

Postcode 550215

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured **OWNER** 

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident SIDE SWIPE

Weather Conditions CLEAR Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

YES

Was any other material or property damaged?

I have been approached by unknown person(s)

NO

soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

1

**Details of Police Action** 

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO THE ATTACH STATEMENT RECORDED BY PEI WEN - PROGRESSIVE CAR CARE PTE LTD TEL 6741 5336

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

**DETAILS OF OTHER VEHICLE PROPERTY 1** 

Vehicle Registration Number

SDG8889R

Vehicle Make/Model/Colour

**Details Of Properties** 

Vehicle Category

PRIVATE CAR

Name of Driver

QUEK SEOW BOON

NRIC/Passport Number

S6835531A

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### Sketch Plan

#### SKETCH PLAN

#### **IMPORTANT NOTICE**

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
  Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
  interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) Investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (Iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could invoive disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholders Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

TCH PLAN			Vehicle
			A-9KR1145
Ang mo	kno st	12.	B-SDG 888
$\rightarrow$	$\rightarrow$		
	MAI	e .	Legend A
L 1	L	- 1, thoray Lot.	Vehide Motorcycle
SCRIBE CIRCUMSTANCES OF THE	ACCIDENT		
On 318 201	9 , Around	1-20pm. 1	was driving
along ang mo	\$70 st 12	. Suddenly	1 fett an
mpact from m	y Car lef-	rear port	un. I come
out from my	car and rea	lise there w	as a car
B (SDG 8889R')	hit my co	r rear le	Alt portion
	J		
DECLARATION  /We declare the foregoing particulars a  Meass be advised that your insurer may have a  ingin the tay of vacuing lice. Kingly check your p	burteen (14) days clause wherein	y the claim against own policy must be	e made within the stigulated timeframe
1 Inc	Driver's Signature	Reporting	Sentre Personnel's Signature
Policyholder's Signature	(If driver is not the policyho		NO.: PLANER

2/9/19

and facts which will speed up the settlement of ci	summary of Identities ligitation of accident	To be signed by BOTH driver
31819 1320	AMK St (2	3 Injuries even if slight No Yes .
Material damage To vehicles other than vehicles A and B   To of No Yes No	bjects other than vehicles Yes  S  Witness' name, address a is passenger in vehicle A or	and tot no. (to be underlined if he/she   Veticle Video   Camera Available   Ves
Registration No. SKR 1845  (VEHICLE A): SKR 1845  Insured / policyholder (see pisurance cert.)  are Tan (her k.  aptal letters) (hi ang.  diress  RIC / Passport no. \$756391944  Hi no. (from Sem till 5pm)  Vehicle Toyuta Hamer  Insurance company	Discrete Property Colleges - Coll	Registration No. SDG 8886  (VEHICLE B)  [6] Insured / policyholder (see insurance cert  B Name (capital letters)  Address  NRIC / Passport no.  Tel no. (from 9am till 5pm)  100  110  Make, type  [7] Vehicle  [8] Insurance company
AXA C TPFT TPO  as the policy cover damage to vehicle A?  b	C313 Cullision - Boundabout C314 Collision - Union C315 Drink Driving / Drug teffuence C316 Five Explosion or Uphraine C317 Five Explosion or Uphraine C317 Hot and Rus / Vandalism / Damaged white Parked C319 Hot by Fallon Time / Other Objects C320 No Collision C321 Side Seige C322 Theft	Does the policy cover damage to vehicle 87  No Yes Policy No. (if assilable)  180 (if different from insueed 8 above)  Name YUA SOOW (capital letters)  NRIC / Pessport no. SOR 3 5 5 3
Indicate the point	State TOTAL number of boxes marked with a cross  13 Sketch of accident when impact occurred 33 indicates: I layout of the road - 2 the direction of vehicles A and positions at the time of impact - 4 the road signs - 5, names of the	Gender Male Fernale  B with arrows of initial impact with an arrow(-)  IIIVisible damage to vehicle B
	Ay, please make set-reace to one of the shetches on page 4	14 My remarks

## Individual Statement

	AL STATEMENT ( submitted within 24 hours to you		pointed works		rate shee	t of paper				
Insured	1 Occupation (if more than one, st	ate all)				extav	118700	oagi	nail-(	
	2 Vehicle registration no.	cc.		If commercial permissible of				_		
Of which vehicle are	3 is driver the owner? Yes		Awationship of with owner			number and own vehicle	name of t (where applica	bin)		
you the owner?	4 Exact purpose for which vehicle was being used at time of accident Private use Commercial use Hire & reward Private Hire									
Z .	Others - please specify									
	5 Is the vehicle still in use? Yes	No Ifr	no, state where i	t is at present		/	Te	i no.		
□ B	6 Are you claiming under your ow	insurance policy for repai	ir to your vehicle	Yes	No /					
	If no, state action to be taken	☐ Third Party ☐	Reporting Or	nly Thir	d Party	Own W	orkshop)			
	7 Date of birth Occupation		Date of licens			e driven w I's permiss	of th	driver an e e insured's pany?		
Oriver or person in	26/2/75 Indoor	Outdoor	5/7	7	- 1 -	- No	Yes	Π.	u .	
charge of vehicle at the time of accident	16 1 LP Ingoor	Outdoor	214	2004	1 m	NG :	165		NO	
(Including insured)	8 Give details of any pre-existing impairment of sight or hearing and of any other disability									
	9 Full details of all driving convicti	ons including pending pror	ecutions in the I	ast 36 months						
	Date	or	Tence				Репа	By		
					-				-	
	10 Name(s), address(es) and approximate age(s)	Injuries sustained		e occupants, which vehicle	Were seat belts being worn?		tot	to hospital by ambulance?		
Injured persons					Yes :	No	Yes	1	No :	
		1			Yes	No	Yes		No :	
					Yes	No	Yes		No :	
					Yes	No	Yes		No :	
Damage to property 8 vehicles (other than vehicles A and B)	11 Name(s) and address(es) of owner(s)	Wehicle registration in or details of property		d damage			Insurer's (if known)		address	
							-			
	12 Was the accident reported to 1 If yes, please state which Police		No	7						
Police action	13 Was notice of intended prosec	ution given? Yes	No	7						
	If yes, against whom?									
	14 Weather conditions C	cer	Raining		Ot	hers				
		Net	Dry		[~	bers .				
	15 Road surface	1		_		7				
	16 Speed of vehicles A	km/tvr	8	1	km/hr					
Accident	17 What warnings were given by	driver or other party?								
details	18 Were street lights (luminated)	Yes	io							
_	19 What lights were displayed or		hicle(s)?							
	20 If your vehicle is commercial,			dent						
	21 State how accident happened									
	22 State number of Passengers									
Declaration	I/We declare the foregoing participation of the control of the con	ulars are true in every resp	and T	Mb.	D	ate				
				/						
	Driver's signature (if driver is	not the policyholder)_			D	ate				

### **DRIVER NRIC & LICENSE**



REPUBLIC OF SINGAPORE IDENTITY CARD NO. \$7563919H





TAN CHERK CHIANG 陈 志 张



CHINESE
Data of North
26-02-1975
Country/Place of birth
MALAYSIA





Dut of line 16-08-2015

APT BLK 215 SERANGOON AVENUE 4 905-114 SINGAPORE 550215 Condition (CON)

[01] Total (2] Dented, (3) Distorted (4) Cracked (5) Cut (6) Scratched (6) Performed (08) Shifted (40) Broken (11) Nocessary (12) Missing (13) Torn (14) Unconformed (15) Not Working

[15] Not Working

ACTION (AC) (1)Replace (√) (2)Repair (X) (3)Check (?) (4)Not Consistent (NC)

Valida No. SND 10-15 V

-	-			

--11

	ortion			_	-
NAC	INC	Item	CON	AC	Qty
1255	995326	Frt LH Door			
1250	995140	Frt LH Door Protector			
1257		Frt LH Door Hinge			
	995142				
		Frt LH Door Garnish			
-	991593	The state of the s			
1261	991588	Frt LH Door Glass Inner Moulding			
1262	995103				
1263	991595	Frt LH Door Glass Regulator			
1264	991596	Frt LH Door Glass Regulator Motor			
1265		Frt LH Door Rubber			
1266		Frt LH Door Outer Handle			
1267	991607	Frt LH Door Inner Handle			
	991625	Frt LH Door Lock w/Key			
		Frt LH Door Lock			
		Frt LH Door Central Lock			
1271		Frt LH Door Switch			
1272	991617	Frt LH Door Inner Trim Board	1		
1273		Frt LH Door Checker			
1274		Frt LH Door Felt			
1275					
1276	991683	Frt LH Door Window Glass Pillar			
1277		Frt LH Door Outer Pillar			
1278	991613	Frt LH Door Inner Pillar			
1279	991646	Frt LH Door Pillar Inner Garnish			
	990554				
	990542			-	
1282	990517	Centre Pillar Upper Garnish LH			
	990564	Centre Pillar Lower Garnish LH			
	991670	Frt LH Door Step Garnish			
	994052	Rocker Panel LH			
		Rocker Panel Inner Panel LH	00	R	
	994046	Rocker Panel Garnish LH			-
	994055	Rocker Panel Outer Side Skirt LH	300	/	
1,004	991300	Frt Bumper			
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
TOTO	991408	Frt Bumper Sponge			
	991427	Frt Bumper Protector			
	991301	Frt Bumpet Moulding			
	991407	Frt Bumper Lower Spoiler			
	995153	Frt LH Headlamp Assy			
	995088	Frt LH Side Lamp			
	995070	Frt LH Fender			
	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			

Name to Trans		Vehicle No: SKR 1845Y	/		
NλC	INC	Liem	CON	AC	Qty
1289	995156	Rear LH Door	PD	R	
1290		Rear LH Door Protector	1200		
1291		Rear LH Door Hinge			
1292	993228	Rear LH'Door Garnish			
1293	993278	Rear LH Door Glass Outer Moulding		7	
1294	993231	Rear LH Door Glass Inner Moulding			-
1295	-	Rear LH Door Glass			
1296		Rear LH Door Glass Regulator	_	-	
1297		Rear LH Door Glass Regulator Motor			
1298	THE RESERVE AND ADDRESS OF THE PARTY.	Rear LH Door Rubber			
1299		Rear LH Door Outer Handle			
1300	993250	Rear LH Door Inner Handle		-	
1301	993261	Rear LH Door Lock		-	7.55
1302	993256	Rear LH Door Inner Trim Board		7	
1303		Rear LH Door Checker	-	-	-
1304		Rear LH Door Glass Channel	-		
1305		Rear LH Door Glass Triangle Garnish		-	
1306		Rear LH Door 1/4 Glass		-	
1307		Rear LH Door 1/4 Glass Rubber	200000		
1308		Rear LH Door 1/4 Glass Rubber			
1309					-
1310		Rear LH Door Step Garnish	-		
1311		Rear LH Door Switch			
		Roof Top Panel			
	994098	Roof Top Moulding			
	994083	Roof Top Air-bag			
	994084	Roof Top Air-bag Sensor			
Diam.		Roof Top Air-bag Control Unit			_
1107		Rear Bumper CA	=	_	
STATE OF	992976	Rear Bumper Bracket			_
1118	993068	Rear Bumper Side Retainer	nec		
may		Rear Bumper Reinforcement			
11/15/11		Rear Bumper Sponge CIPS	nec		
11156	993040	Rear Bumper Protector			
PLANTER!	993026 993023	Rear Bumper Moulding	o ev		-
41116314	993023	Rear Bumper Lower Spoiler	4		
112018	993436	Rear LH Taillamp . ** Rear LH Fender			
MATERIAL STREET	993436		-		
1136	000247	Rear LH Fender Protector			
60169'O	990247	Sticker	-		
		LH REAR RIM OK	-		-
		LH REAR BLACE arc	CUT		
		HREAR KNUCKLEARM BORNING	BY		_
		LH REN SETEMBER LOWER Arm	128		
		" " Knaile Are	12	/	
		-1.			
		O Virginia de la companya della companya della companya de la companya della comp			
		Miss			
		1 1 -1 -	210	1	
		1 13912	~	V	
		10/1			

No of Items:	Assessor:

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

LAIM SUBF	OLDER TRA	CKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj	Submitted	Ins Auth'ed	Status	
Main	11 Sep 2019 Edit Reg		10 Sep 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0	.00 ew Rpt		Pending for Report Cancel Case	7
	1ain	R	teference	Claim I	etails		Documents		Show All
CLAIM SU	SFOLDER DE	TAILS				[Created	by adjuster]		
Insured:	-, Co. Re	g. No.: -							
Main Claimant:	TAN CHE	TAN CHERK CHIANG, ID: S7563919H							
Vehicle Reg. No.:	SKR184	SKR1845Y			of Loss:	31/08/2019 13:00 - :59 [159 Months and 5 Days From LTA Reg Date (Man Yr)]			
Claim Type:	<b>TP</b> / 8894314193SG				/Cover No.:				
Vehicle Reg. No. (Insured):	SDG8889	R		Policy (Clair	No. nant):				
				Exces	s:				
Repairer:	Tampines	Auto Services	(HQ) BLK 9002 TAMP	INES ST 93, #01	-34/36 1	NDUSTRIAL	PARK A, 528836 Tam	pines - Tel: 6	7862884
Handling Insurer:	AIG Asia	Pacific Insuranc	ce Pte. Ltd. (Expres	s) - Tel: 65-6419	-3000	. [Handled b	y <b>Lee, Ming-Yao</b> ] M	ingYao.Lee@a	g.com
Adjuster:	20/09/20		e Ltd (HQ) - Tel: 625	66-3561 [Hand	led by P	ARASURAM	SHANMUGAM] [	Final Rpt d	ue
ASSOCIAT	ED MAIL RE	CEIVED					View A	II Compos	e Case Mai
		: Conflicting DO : TP GIA REPOR							
ALL ASSO	CIATED TAS	sks⊟			8	View All	Search Tasks Crea	te New Task	Complet
Due Date	Priority	Type Task	k Group Subject	t Handler	Assign	ned By	Completed On	Created Or	Done

### Claim Documents

\*SKR1845Y (8894314193SG) [SDG889R] TP
TAN CHERK CHIANG
Aug 31 2019 1:00PM [-]
Tampines Auto Services

Pho	tos/Images		3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnai	
1	17/09/19 12:13	General View	6 Load JPG	V
2	17/09/19 12:13	General View	Load JPG	V
3	17/09/19 12:13	General View	Load JPG	V
4	17/09/19 12:13	General View	■ Load JPG	V
5	17/09/19 12:13	General View	Load JPG	V
6	17/09/19 12:13	General View	1 Load JPG	V
7	17/09/19 12:13	General View	Load JPG	V
8	17/09/19 12:13	General View	Load JPG	V
9	17/09/19 12:13	General View	Load JPG	V
10	17/09/19 12:13	General View	Load JPG	V
11	17/09/19 12:13	General View	■ Load JPG	V
12	17/09/19 12:13	General View	Load JPG	V
13	17/09/19 12:13	General View	Load JPG	V
14	17/09/19 12:13	General View	Load JPG	4000
15	17/09/19 12:13	General View	Load JPG	V
16	17/09/19 12:13	General View	Load JPG	-
17	17/09/19 12:13	General View	■ Load JPG	
18	17/09/19 12:13	General View	Load JPG	
19	17/09/19 12:13	General View	Load JPG	
20	17/09/19 12:13	General View	■ Load JPG	-
21	17/09/19 12:13	General View	■ Load JPG	-
22	17/09/19 12:13	General View	€3 Load JPG	1 -
23	17/09/19 12:13	General View	Load JPG	
24	17/09/19 12:13	General View	1 Load JPG	V
25	17/09/19 12:13	General View	1 Load JPG	-
26	17/09/19 12:13	General View	■ Load JPG	-
27	17/09/19 12:13	General View	■ Load JPG	_
28	17/09/19 12:13	General View	Load JPG	-
29	17/09/19 12:13	General View	■ Load JPG	-
30	17/09/19 12:13	General View	Load JPG	_
31	17/09/19 12:13	General View	■ Load JPG	100
32	17/09/19 12:13	General View	Load JPG	
33	17/09/19 12:13	General View	1 Load JPG	V
34	17/09/19 12:13	General View	■ Load JPG	
35	17/09/19 12:13	General View	Load JPG	-
36	17/09/19 12:13	General View	Load JPG	-
37	17/09/19 12:13	General View	1 Load JPG	-
38	17/09/19 12:13	General View	1 Load JPG	-
39	17/09/19 12:13	General View	1 Load JPG	-
40	17/09/19 12:13	General View	■ Load JPG	-
41	17/09/19 12:13	General View	1 Load JPG	-
42	17/09/19 12:13	General View	1 Load JPG	-
43	17/09/19 12:13	General View	1 Load JPG	

Photos/Images		3 per	3 per page 🔍		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	- Contraction	Thumbnail	Prin
14	17/09/19 12:13	General View	0	Load JPG	V
15	17/09/19 12:13	General View	0	Load JPG	V
16	17/09/19 12:13	General View	0	Load JPG	V
7	17/09/19 12:13	General View	6	Load JPG	V
8	17/09/19 12:14	Photographs of Damaged Parts	0	Load JPG	V
19	17/09/19 12:14	Photographs of Damaged Parts	0	Load JPG	V
0	17/09/19 12:14	Photographs of Damaged Parts	0	Load JPG	V
1	17/09/19 12:14	Photographs of Damaged Parts	0	Load JPG	2
2	17/09/19 12:14	Photographs of Damaged Parts	0	Load JPG	V
3	17/09/19 12:14	Photographs of Damaged Parts	0	Load JPG	2
4	17/09/19 12:14	Photographs of Damaged Parts	0	Load JPG	V
55	17/09/19 12:14	Photographs of Damaged Parts	0	Load JPG	V
6	17/09/19 12:14	Photographs of Damaged Parts	0	Load JPG	V
57	17/09/19 12:14	Photographs of Damaged Parts	0	Load JPG	V
8	17/09/19 12:14	Photographs of Damaged Parts	0	Load JPG	2
59	17/09/19 12:14	Photographs of Damaged Parts	0	Load JPG	V
50	17/09/19 12:14	Photographs of Damaged Parts	0	Load JPG	2
51	17/09/19 12:14	Photographs of Damaged Parts	0	Load JPG	2
2	17/09/19 12:14	Photographs of Damaged Parts	0	Load JPG	2
3	17/09/19 12:14	Photographs of Damaged Parts	0	Load JPG	2
4	17/09/19 12:14	Photographs of Damaged Parts	0	Load JPG	2
55	17/09/19 12:14	Photographs of Damaged Parts	0	Load JPG	2
6	17/09/19 12:14	Photographs of Damaged Parts	0	Load JPG	2
7	17/09/19 12:14	Photographs of Damaged Parts	0	Load JPG	2
58	17/09/19 12:14	Photographs of Damaged Parts	0	Load JPG	<u> </u>
9	17/09/19 12:14	Photographs of Damaged Parts	0	Load JPG	<u> </u>
70	17/09/19 12:14		0	Load JPG	2
71	17/09/19 12:14	Photographs of Damaged Parts  Photographs of Damaged Parts	0	Load JPG	2
72			0	Load JPG	A
	17/09/19 12:14	Photographs of Damaged Parts		LITTLE COLUMN TO	-
73	17/09/19 12:14	Photographs of Damaged Parts	0	Load JPG	2
4	17/09/19 12:14	After Repair Photo	0	Load JPG	2
75	17/09/19 12:14	After Repair Photo	0	Load JPG	2
76	17/09/19 12:14	After Repair Photo	0	Load JPG	2
7	17/09/19 12:14	After Repair Photo	6	Load JPG	2
8	17/09/19 12:14	After Repair Photo	0	Load JPG	2
9	17/09/19 12:14	After Repair Photo	0	Load JPG	2
30	17/09/19 12:14	After Repair Photo	0	Load JPG	N.
31	17/09/19 12:14	After Repair Photo	0	Load JPG	V
32	17/09/19 12:14	After Repair Photo	0	Load JPG	V
200	umentation		1 per	page V	V
lo	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	1 per	Thumbnail	-
1	12/09/19 11:11	OI GIA REPORT	0	Load PDF	

## **Documents Checklist**

There are no document checklists configured.		
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)		
		^
		~

## LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/AIG19016096/FCD3E2

Date:

23/09/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Claimant Vehicle No:

SKR1845Y

Insured Vehicle No: SDG8889R

Date of Loss:

31/08/2019

Nature of Claim:

TP

Claim No: 8894314193SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No:

**SKR1845Y** 

Make & Model:

TOYOTA HARRIER, 2.4 (A) 26/05/2006 (Man. Year: 2005) Engine No:

2AZ2053818

Reg. Date: Colour:

Black

Chassis No: Odometer:

ACU300044438 300697 km

**Engine Capacity:** 

2362 cc

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Market Value/New Car Price: N/A

Yes Engine Modification:

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

225/65 R17

Rear Tyre Size:

225/65 R17

Front Left Side:

Dunlop 4 mm

Rear Left Side: Rear Right Side: Dunlop 4 mm Dunlop 4 mm

Front Right Side: Dunlop 4 mm The above values represent the remaining tyre treads depth

<b>COST OF CLAIMS</b>		Repairer's	Adjuster's	Difference	Diff %
Parts		0.00	0.00	0.00	
Miscellaneous Items		0.00	0.00	0.00	
Labour		0.00	0.00	0.00	
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:

10/09/2019

Date Inspected:

11/09/2019 Inspected At:

Tampines Auto Services (HQ)

BLK 9002 TAMPINES ST 93, #01-34/36 INDUSTRIAL PARK A

Singapore 528836

Estimated Period of Repair:

4.0 days

Adjuster: PARASURAM SHANMUGAM

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## **REPAIR DETAILS**

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*ROCKER PANEL INNER PANEL LH	Repair	0.00 F	*- F
2	1		*ROCKER PANEL OUTER SIDE SKIRT LH	Cut	0.00 F	*- F
3	1		*REAR LH DOOR	Repair	0.00 F	*- F
4	1		*REAR BUMPER	Cut	0.00 F	*- F
5	1		*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*-F
6	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
7	1		*REAR BUMPER LOWER SPOILER	Cut	0.00 F	*- F
8	1		*LH REAR RIM	Cut	0.00 F	*- F
9	1		*LH REAR WHEELARC	Cut	0.00 F	*- F
10	1		*LH REAR KNUCKLE ARM BEARING	Bent	0.00 F	*- F
11	1		*LH REAR LOWER ARM	Bent	0.00 F	*- F
12	1		*LH REAR KNUCKLE ARM	Bent	0.00 F	*-F
F=Fra	inchise	part.		Total Parts (S\$)	0.00	0.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >