

(08/11/13)

Surveyor: Kalvin

REF:

CC3/TM1 19016098 / KH f302

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. MK 000264Claims No. M1907062

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHA 8310 C Yr Regn: 28 Sep, 2012

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Santa Fe C.C. 1994Colour: Yellow A/C: Insured / Std / NI / NASp. Reading: 39 0582 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHET41VACA830386Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD / Rim orTyre Size: F: 215/60 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Ha / Kook

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 9/9/9 D.O.I. 10/9/9Survey held at C/DHE (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SHA 8310 C - CC3/TM116015406/H1 + b2 DOA - 16/03/2016 To 140
	SLV 222E - X 4s
11/9 @ 2:24pm	Reuse via email preli advise.
16/9/19	Send 4s \$3000 / 3 Pgs. (Red: 373.62 / 51%)
RECEIVED 16 SEP 2019	

Date/Time, File Pass to?

☐ : Preli. Report1) 16/9 Typist☒ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 3Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)Survey Fee: 250

Transportation: _____

S + RS: _____

Photos _____

11

261

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 11 September 2019 2:06 PM
To: 'Motor Claims'
Cc: SUR
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - COMFORTDELGRO ENGINEERING PTE LTD , DOA: 09/09/2019, SHA 8310C (TP VEHICLE), SLV 2222E (OI VEHICLE)
Attachments: PRELI ADVISED OF SHA 8310C.pdf; ESTIMATE.pdf; POLICE REPORT.pdf; GIA REPORT.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHA 8310C at M/s: COMFORTDEGLRO ENGINEERING PTE LTD, 59 LOYANG DRIVE SINGAPORE 508969 on 10/09/2019

Enclosed herewith a copy of TP's GIA report and estimated cost of repair .

Kindly create claim in merimen for our necessary action.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Need Taxi Replacement

**COMFORTDELGRO
ENGINEERING****ComfortDelGro Engineering Pte Ltd**

205 Braddell Road Singapore 579701

Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

59 Loyang Drive Singapore 508869

383 Sin Ming Drive Singapore 575717

45 Pandan Road Singapore 609268

320 Ubi Road 3 Singapore 408648

24 Senoko Loop Singapore 758156

7 Sungai Kadut Way Singapore 728791

501 Yishun Industrial Park A Singapore 758733

Date/Time: 10.09.2019 11:20

Page : 1

Member of COMFORTDELGRO

Repair TP(CFS0)1

JOB CARD

Sales Order:

JC NO.: 305332035

MER

CITYCAB PTE LTD

7010070

383 SIN MING DRIVE

Singapore SINGAPORE 575717

65551188

(O)

MS
TOMER NO.
RESS

(R)

(P)

COUNT CARD NO.

Merimen

REGN NO.:

SHA8310C

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

SONATA

DATE/TIME IN

09.09.2019 17:40

YR OF MANU

28.09.2012

TARGET DATE

CHASSIS CODE

KMHET41VMCA830386

COMPLETION DATE/TIME:

JOB DESCRIPTION

LKS

LKK-Kalvin.

Tokio - SLV2222E


Accident Date: 09.09.2019

NATURE: 3P 09.09.19

S/NO

LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

No.:

SHA8310C

LIMITS

Vehicle No.:

SHA8310C

Service Advisor

Signature/Date

Name of Service Advisor

Date



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: -

Date: 11/9/2019

Our Ref: CC3/TMI19016098/K1tf3

The Motor Claims Department
TOKIO MARINE INSURANCE SINGAPORE LTD

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. SHA 8310C

Please be informed that we had conducted the inspection of the above-mentioned vehicle on 10/09/2019 at the premises of M/s COMFORT ENGINEERING PTE LTD and have the following to report: -

Workshop Estimate Amount	: S\$ 6,173.62
Revised Estimate Amount	: S\$ 3,124.08
"Check" Items Amount	: S\$ 496.56
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ -
Nett Value	: S\$ -

Description of Damage:

The vehicle sustained damages at the n/s front portion.



Repair days: 3

Comments/ Present Status:

Damages Consistent.

Yours faithfully

Kalvin Ang

Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/09/2019 09:25
Date Of Accident	09/09/2019 13:40
Exact Location Of Accident	ALONG PANDAN LOOP
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA8310C
Insured/Policyholder	
Name Of Registered Owner	CITYCAB PTE LTD (COMPANY)
Co Reg No	199502839G
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	SONATA
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088937MFSH
Cover Note Number	

Driver

Name of Driver	TAY KIM TECK
NRIC No	S2187869C
Date Of Birth	24/10/1957
Occupation	OUTDOOR
Date Of Driving Pass	31/01/1979
Driving Experience	40 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93734505
Fax Number	
Contact Number	
EMail Address	TAYKIMTECK@YMAIL.COM

Address	921 10-23 HOUGANG STREET 91
Postcode	530921
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	PASIR RIS NPC
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE POLICE REPORT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLV2222E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage FRT & REAR
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SJR7824E
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage FRT
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name TAY KIM TECK
Approximate Age 62
Injuries Sustain BACK
Injured person in which vehicle? SHA8310C
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

DETAILS OF INJURED PERSON 2

Name DRIVER
Approximate Age
Injuries Sustain NOT SURE
Injured person in which vehicle? SLV2222E
Were seat belts worn?
Was this injured conveyed to hospital by ambulance? YES
Address
Postcode



**SINGAPORE
POLICE FORCE**



T/20190909/2137

Police Station Of Origin:
Pasir Ris N.P.C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1800-5852999

1 of 3

Report No. T/20190909/2137

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 09/09/2019 17:17	Vide Report No.: D/20190909/0058	Station Diary No.: 87
--	-------------------------------------	--------------------------

Informant's Particulars

Name of Informant: TAY KIM TECK			Address: APT BLK 921 HOUGANG STREET 91 #10-23 SINGAPORE 530921		
ID Type / ID No.: NRIC NO / S2187869C			Contact No.: Home/Office: Mobile: 93734505		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 61	Date of Birth: 24/10/1957	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 09/09/2019 13:40	Type of Location: Straight Road
Location: Along Road 1 PANDAN LOOP in front of no 192				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHA8310C	Car A				Slightly Damaged	1
SJR7824E	Car C	Mercedes				0
SLV2222E	Car D	Toyota			Slightly Damaged	0



**SINGAPORE
POLICE FORCE**



T/20190909/2137

2 of 3

Police Station Of Origin:
Pasir Ris N.P.C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1800-5852999

Report No. T/20190909/2137

CONTINUATION OF REPORT

Brief Details.

On 09/09/2019 @ 1340hrs, I was driving my taxi SHA8310C along Pandan Loop I front of no 192, when car in front of me braked. I then applied my brake and stopped gradually. I came to a complete stop when suddenly a car SLV2222E was unable to stop in time and collided onto my taxi. I came out to make a check and discovered that there was another car which collided onto SLV2222E.

The rear bumper of my taxi was dented. Both me and passenger were not injured. The SD card of my dash cam was seized by the traffic Police officer.
The driver of SLV2222E was conveyed to hospital by ambulance.



**SINGAPORE
POLICE FORCE**



T/20190909/2137

3 of 3

Police Station Of Origin:
Pasir Ris N.P.C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1800-5852999

Report No. T/20190909/2137

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

G /

SI MOHAMAD FAIZAL BIN ALIA MARIKAN

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

09/09/2019 17:17

Officer In Charge Of Case:

TP / GIT /

Sr Staff Sgt SHAHRUL NIZAM BIN SAMARRI

Contact No.: 65476904

Classification Of Case:

Authentication Stamp

NP168



SINGAPORE
POLICE FORCE

SIGNATURE

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)
59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
CCPL

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	09/09/2019
Vehicle Reg. No.:	SHA8310C	Driveable?	NO
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI SONATA, 2.0 D CRDI TURBO (NF) (A)	Vehicle Reg. Date:	28/09/2012
Vehicle Colour:	YELLOW	Gen Condition:	GOOD
Engine No:	D4EAC196463	Chassis No:	KMHET41VMCA830386
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	4,373.62
Miscellaneous Items	11.00
Labour	1,900.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	6,284.62
+ GST 7.00% (S\$)	439.92
Nett Amount (S\$)	6,724.54

This claim is handled by: LIM TIEN SIONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 Sep 2019)

Parts: 143 HYUNDAI SONATA 2.0 D CRDi Turbo (NF) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHA8310C/10/09/2019 18:05

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*BOOTLID	20.00	0.00	*1,349.50 FL	BUL /
2	1		*BOOTLID UPR LOCK	20.00	0.00	*132.10 FL	SVC X
3	1		*BOOTLID LWR LOCK	20.00	0.00	*30.30 FL	SVC X
4	1		*BOOTLID SONATA EMBLEM	20.00	0.00	*43.60 FL	NN X
5	1		*BOOTLID HYUNDAI EMBLEM	20.00	0.00	*24.20 FL	NN X
6	1		*BOOTLID H EMBLEM	20.00	0.00	*26.10 FL	NN /
7	1		*BOOTLID CRDI EMBLEM	20.00	0.00	*22.70 FL	NN /
8	2		*BOOTLID LAMP RH/LH LH / CRA RH X SVL	20.00	0.00	*460.40 FL	NN X
9	1		*REAR BUMPER	20.00	0.00	*578.40 FL	DE /
10	1		*REAR BUMPER REINFORCEMENT	20.00	0.00	*483.30 FL	CRA /
11	10		*REAR BUMPER CLIPS	20.00	0.00	*22.00 FL	NN /
12	1		*REAR BUMPER SPONGE	20.00	0.00	*137.40 FL	NN /
13	1		*REAR BUMPER UNDER COVER	20.00	0.00	*185.80 FL	SVC X
14	2		*REAR BUMPER PROTECTOR RH/LH	20.00	0.00	*76.00 FL	R X
15	2		*TAILLAMP RH/LH	20.00	0.00	*688.00 FL	SVC X
16	1		*REAR PANEL	20.00	0.00	*391.80 FL	R X
17	1		*REAR PANEL GARNISH	20.00	0.00	*95.80 FL	SVC X
18	1		*BOOTLID COMFORT / 65521111 STICKERS	0.00	0.00	*30.00 F	NN /
19	1		*BOOTLID COMFORT LOGO STICKER	0.00	0.00	*10.00 F	NN /
20	1		*BOOTLID ADVERTISEMENT STICKER	0.00	0.00	*100.00 F	NN /
21	1		*REVERSE SENSOR	0.00	0.00	*135.70 F	NN X
22	1		*REAR BUMPER ADVERTISEMENT STICKER	0.00	0.00	*50.00 F	NN /
23	1		*REAR BUMPER MAT	0.00	0.00	*50.00 F	NN /
24	2		*REAR FENDER ADVERTISEMENT STICKER RH/LH	0.00	0.00	*200.00 F	NN X

F=Franchise part. L=ListItemDisc.

Sub Total (S\$) 5,323.10

- List Item Discount on L Items (S\$) 949.48

Total Parts (S\$) 4,373.62

ComfortDelGro Engineering Pte Ltd/SHA8310C/10/09/2019 18:05. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00 ✓
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	800.00 600
2	SPRAY PAINTING	New	900.00 600
3	WIRING CHECK	New	30.00 20
4	TUFF KOTE	New	50.00 20
5	R/I REVERSE SENSOR	New	120.00 200
Gross Labour Cost (S\$)			1,900.00

ComfortDelGro Engineering Pte Ltd/SHA8310C/10/09/2019 18:05. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

COMFORTDELGRO ENGINEERING PTE LTD

VEHICLE NO : SHA 8310C (CC)

MAKE :

MODEL : HYUNDAI SONATA

Tokio Marine - 4S

DATE 10/9/2019

Tyre: Hankook 215/60 R16

LKK - Katrin

IS

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid / <i>Repl</i>			\$ 1,349.50
	Boot Lid Lock Upper <i>X sue</i>			\$ 132.10
	Boot Lid Lock Lower <i>X sue</i>			\$ 30.30
	Boot Lid Sonata Plate <i>X sue</i>			\$ 43.60
	Boot Lid Hyundai Plate <i>X sue</i>			\$ 24.20
	Boot Lid 'H' Emblem <i>- sue</i>			\$ 26.10
	Boot Lid CRDI Plate <i>- sue</i>			\$ 22.70
	Boot Lid Lamp (LH/RH) <i>LH/RH Repl sue</i>		\$ 230.20	\$ 460.40
	Rear Bumper <i>- Repl sue</i>			\$ 578.40
	Rear Bumper Reinforcement <i>- sue</i>			\$ 483.30
	Rear Bumper Clip <i>- sue</i>			\$ 22.00
	Rear Bumper Sponge <i>- sue</i>			\$ 137.40
	Rear Bumper Under Cover <i>X sue</i>			\$ 185.80
	Rear Bumper Protector (LH/RH) <i>X Repl</i>		\$ 38.00	\$ 76.00
	Tail Lamp (LH/RH) <i>X sue</i>		\$ 344.00	\$ 688.00
	Rear Panel <i>X Repl</i>			\$ 391.80
	Rear Panel Garnish <i>X sue</i>			\$ 95.80
SUB TOTAL				\$ 4,747.40
LESS 20%				\$ 949.48
DISCOUNTED TOTAL				\$ 3,797.92
	Boot Lid Comfort Logo & Tel No. Sticker <i>- sue</i>			\$ 30.00
	Boot Lid Comfort Logo Sticker <i>- sue</i>			\$ 10.00
	Boot Lid Advertisement Logo <i>- sue</i>			\$ 100.00
	Rear Bumper Reverse Sensor <i>X sue</i>			\$ 135.70
	Rear Bumper Advertisement Logo <i>- sue</i>			\$ 50.00
	Rear Bumper Rubber Mat <i>- sue</i>			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH) <i>X sue</i>			\$ 100.00
TOTAL				\$ 475.70
Labour Charge				
	Panel Beating			\$ 800.00 600
	Spray Painting Charge			\$ 900.00 600
	Wiring Charge			\$ 30.00 20
	Tuff Kote			\$ 50.00 20
	Remove/Refix Reverse Sensor			\$ 120.00 X sue
	<i>Merimen Fee</i>			\$ 11
TOTAL LABOUR				\$ 1,900.00
ESTIMATE TOTAL				\$ 6,173.62

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Our Job Ref No : 305332035

Date : 13/09/19

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN ANG

Vehicle Reg No. : SHA8310C

Date of Accident : 09-Sep-19

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO MARINE --- SLV2222E

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%

\$3,000.00

Final Lumpsum Repair cost**\$3,000.00**

3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and
finalized amount

Signature :

Name : LIM T S

Tel : 62148398

Fax : 65468156

Signature

Name

KALVIN

Date :

16/9/19

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees	-----			
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks: REAR BUMPER SPONGE AND REINFORCEMENT - REPLACED.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Sep 2019 17:52 Sendback Est	10 Sep 2019 18:05 \$6,284.62	11 Sep 2019 13:33 Edit Adj Rpt	\$3,000.00 Edit Estimates	\$3,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: WORK WORK PRIVATE LIMITED , Co. Reg. No.: 201434206M									
Main Claimant: CCPL , Co. Reg. No.: 199502839G									
Vehicle Reg. No.: SHA8310C		Date of Loss: 09/09/2019 13:00 - :59 [83 Months and 12 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / M1907062		Policy/Cover Note No.: MK000264 (Comprehensive) Coverage: 06/03/2019 - 05/03/2020							
Vehicle Reg. No. (Insured): SLV2222E		Policy No. (Claimant):							
		Excess: \$2,500.00							
Repairer: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300									
Handling Insurer: Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Ho Teng Boon Eliza]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 20/09/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SHA8310C (M1907062)
[SLV2222E]
TP
CCPL
Sep 9 2019 1:00PM
[WORK WORK PRIVATE LIMITED]
ComfortDelGro Engineering Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Assessment Reports

1 per page

No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
1	10/09/19 18:05	Repairer Estimates		Load HTM	
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)		Thumbnail	Print
1	11/09/19 09:06	Accident Statement From:SC - Reg. No: SLV2222E, Claimant: WORK WORK PRIVATE LIMITED		Load HTM	
2	11/09/19 13:33	Accident Statement From:SC - Reg. No: SLV2222E, Claimant: WORK WORK PRIVATE LIMITED		Load HTM	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	13/09/19 08:49	General View		Load JPG	
2	13/09/19 08:49	General View		Load JPG	
3	13/09/19 08:49	General View		Load JPG	
4	13/09/19 08:49	General View		Load JPG	
5	13/09/19 08:49	General View		Load JPG	
6	13/09/19 08:49	General View		Load JPG	
7	13/09/19 08:49	General View		Load JPG	
8	13/09/19 08:49	General View		Load JPG	
9	13/09/19 08:49	General View		Load JPG	
10	13/09/19 08:49	General View		Load JPG	
11	13/09/19 08:49	General View		Load JPG	
12	13/09/19 08:49	General View		Load JPG	
13	13/09/19 08:49	General View		Load JPG	
14	13/09/19 08:49	General View		Load JPG	
15	13/09/19 08:49	General View		Load JPG	
16	13/09/19 08:49	General View		Load JPG	
17	13/09/19 08:49	General View		Load JPG	
18	13/09/19 08:49	General View		Load JPG	
19	13/09/19 08:49	General View		Load JPG	
20	13/09/19 08:49	General View		Load JPG	
21	13/09/19 08:49	General View		Load JPG	
22	13/09/19 08:49	General View		Load JPG	
23	13/09/19 08:49	General View		Load JPG	
24	13/09/19 08:49	General View		Load JPG	
25	13/09/19 08:49	General View		Load JPG	
26	13/09/19 08:49	General View		Load JPG	
27	13/09/19 08:49	General View		Load JPG	
28	13/09/19 08:51	Reinspection Photo		Load JPG	
29	13/09/19 08:51	Reinspection Photo		Load JPG	
30	13/09/19 08:51	Reinspection Photo		Load JPG	
31	18/09/19 07:54	Reinspection Photo		Load JPG	
32	18/09/19 07:54	Reinspection Photo		Load JPG	
33	18/09/19 07:54	Reinspection Photo		Load JPG	
34	18/09/19 07:54	Reinspection Photo		Load JPG	

Documentation

1 per page

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
1	10/09/19 18:06	E-filed GIA report	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI19016098/K1TF3E2

Date: 18/09/2019

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MK000264

Claimant Vehicle No : SHA8310C

Insured Vehicle No : SLV2222E

Date of Loss: 09/09/2019

Nature of Claim: TP Claim No: M1907062

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHA8310C

Make & Model: HYUNDAI SONATA, 2.0 D CRDi Turbo (NF) (A)

Engine No: D4EAA915798

Reg. Date: 28/09/2012 (Man. Year: 2012)

Chassis No: KMHET41VMCA830386

Colour: Yellow

Odometer: 390582 km

Engine Capacity: 1991 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Good

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Hankook 7 mm

Rear Left Side: Hankook 7 mm

Front Right Side: Hankook 7 mm

Rear Right Side: Hankook 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,373.62	2,519.68	1,853.94	42.39
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,900.00	1,240.00	660.00	34.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,284.62	3,770.68	2,513.94	40.00
Approved Total (Overridden) (S\$)		3,000.00		
(S\$)	6,284.62	3,000.00	3,284.62	52.26
+ GST 7.00/7.00% (S\$)	439.92	210.00	229.92	52.26
Nett Amount (S\$)	6,724.54	3,210.00	3,514.54	52.26

INSPECTION

Date of Assignment: 11/09/2019 Present Location:

ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 10/09/2019 Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 3.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Sep 2019)
Parts:	143	HYUNDAI SONATA 2.0 D CRDi Turbo (NF) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA8310C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Buckled	1,349.50 FL	*1,349.50 FL
2	1		*BOOTLID UPR LOCK	Serviceable	132.10 FL	*- FL
3	1		*BOOTLID LWR LOCK	Serviceable	30.30 FL	*- FL
4	1		*BOOTLID SONATA EMBLEM	Not Necessary	43.60 FL	*- FL
5	1		*BOOTLID HYUNDAI EMBLEM	Not Necessary	24.20 FL	*- FL
6	1		*BOOTLID H EMBLEM	Necessary	26.10 FL	*26.10 FL
7	1		*BOOTLID CRDI EMBLEM	Necessary	22.70 FL	*22.70 FL
8	1		*BOOTLID LAMP RH/LH	N/S Cracked / O/S Serviceable	460.40 FL	*230.20 FL
9	1		*REAR BUMPER	Deformed	578.40 FL	*578.40 FL
10	1		*REAR BUMPER REINFORCEMENT	Cracked	483.30 FL	*483.30 FL
11	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
12	1		*REAR BUMPER SPONGE	Torn	137.40 FL	*137.40 FL
13	1		*REAR BUMPER UNDER COVER	Serviceable	185.80 FL	*- FL
14	2		*REAR BUMPER PROTECTOR RH/LH	Repair	76.00 FL	*- FL
15	2		*TAILLAMP RH/LH	Serviceable	688.00 FL	*- FL
16	1		*REAR PANEL	Repair	391.80 FL	*- FL
17	1		*REAR PANEL GARNISH	Serviceable	95.80 FL	*- FL
18	1		*BOOTLID COMFORT / 65521111 STICKERS	Necessary	30.00 F	*30.00 FS
19	1		*BOOTLID COMFORT LOGO STICKER	Necessary	10.00 F	*10.00 FS
20	1		*BOOTLID ADVERTISEMENT STICKER	Necessary	100.00 F	*100.00 FS
21	1		*REVERSE SENSOR	Not Necessary	135.70 F	*- FS
22	1		*REAR BUMPER ADVERTISEMENT STICKER	Necessary	50.00 F	*50.00 FS
23	1		*REAR BUMPER MAT	Necessary	50.00 F	*50.00 FS
24	2		*REAR FENDER ADVERTISEMENT STICKER RH/LH	Not Necessary	200.00 F	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,323.10	3,089.60
- List Item Discount on L Items 20.00/20.00% (S\$)	949.48	569.92
Total Parts (S\$)	4,373.62	2,519.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (S\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	800.00	600.00
2	SPRAY PAINTING	New	900.00	600.00
3	WIRING CHECK	New	30.00	20.00
4	TUFF KOTE	New	50.00	20.00
5	R/I REVERSE SENSOR	New	120.00	0.00
Gross Labour Cost (S\$)			1,900.00	1,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >