

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5013U**AAD1909-080***Not Available
L1 Reg & 1750h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

10 SEP 2019

Date of Accident :

Third Party Insurer :

Date of Registration :

SHC 5013U

VF1ABL15AUC275173

RENAULT

LATITUDE

7.9.19

TOKIO MARINE

30/10/2013

PART

1	1	BUMPER COVER REAR
2	1	BUMPER LOWER REAR
3	1	BUMPER BRACKET CTR REAR
4	1	BUMPER BRACKET SIDE RH REAR
5	1	BUMPER RETAINER RH REAR
6	1	BUMPER REFLECTOR RH
7	1	BUMPER BRACKET SIDE LH REAR
8	1	BUMPER RETAINER LH REAR
9	1	BUMPER REFLECTOR LH
10	1	BUMPER BEAM REAR
11	1	BUMPER BEAM BRACKET LH REAR
12	1	BUMPER BEAM BRACKET RH REAR
13	1	OUTER PANEL REAR (End Panel)
14	1	OUTER PANEL REAR (End Panel) TRIM
15	1	TAILLAMP RH
16	1	TAILLAMP PANEL RH
17	1	TAILLAMP LH
18	1	TAILLAMP PANEL LH
19	1	BOOT REAR
20	1	BOOT FINISHER
21	1	BOOT WHEATERSTRIP
22	1	BOOT REFLECTOR LAMP LH
23	1	BOOT REFLECTOR LAMP RH
24	1	BOOT BADGE 'RENAULT'
25	1	BOOT BADGE
26	1	BOOT STRUT LH
27	1	BOOT STRUT RH
28	1	BOOT HINGE LH

LIST

\$	<i>As</i>	561.70	—
\$	<i>nd 10/11</i>	411.90	—
\$	<i>SL</i>	98.10	X
\$	<i>SL</i>	82.10	X
\$	<i>SL</i>	59.80	X
\$	<i>SL</i>	16.60	X
\$	<i>SL</i>	80.80	X
\$	<i>SL</i>	54.20	X
\$	<i>SL</i>	16.60	X
\$	<i>B</i>	547.80	—
\$	<i>B</i>	114.50	—
\$	<i>n</i>	100.90	X
\$	<i>n</i>	745.80	} X
\$	<i>SL</i>	404.56	
\$	<i>SL</i>	313.10	
\$	<i>n</i>	401.40	
\$	<i>SL</i>	401.40	
\$	<i>n</i>	401.40	
\$	<i>n</i>	1,677.20	
\$	<i>SL</i>	344.70	
\$	<i>SL</i>	178.20	
\$	<i>SL</i>	277.70	
\$	<i>SL</i>	277.70	
\$	<i>nn</i>	82.40	}
\$	<i>nn</i>	95.80	
\$	<i>SL</i>	145.10	
\$	<i>SL</i>	145.10	}
\$	<i>n</i>	254.20	

Trans-cab Auto Services Pte Ltd**AAD1909-080**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5013U

29	1	BOOT HINGE RH	\$	<i>n</i>	253.80	X
30	1	BOOT INNER TRIM BOARD	\$	<i>sh</i>	611.00	X
31	1	BOOT SWITCH	\$	<i>n</i>	113.00	X
32	1	BOOT LOCK	\$	<i>n</i>	246.60	X
33	1	BOOT LOCK CATCH	\$	<i>n</i>	41.70	X
TOTAL			\$		9,556.86	
10%			\$		955.69	
			\$		8,601.17	

Special Nett

1	1SET	PARKING AID	\$	<i>sh</i>	700.00	X
2	1SET	REAR BUMPER CLIP	\$	<i>n</i>	66.00	—
3	1SET	BUMPER BRACKET CTR CLIP	\$	<i>n</i>	33.00	✓
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	<i>n</i>	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	<i>n</i>	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	<i>n</i>	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	<i>n</i>	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	<i>n</i>	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	<i>n</i>	66.00	✓
10	1	BOOT STICKER "Trans-cab"	\$	<i>n</i>	30.00	} X
11	1	BOOT STICKER "6555-3333"	\$	<i>n</i>	30.00	
12	2	REAR WINDSCREEN SEALANT	\$	<i>n</i>	80.00	
13	1	WINDSCREEN MOULDING	\$	<i>n</i>	100.00	
14	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>n</i>	100.00	
15	1	BOOT INNER TRIM CLIP	\$	<i>n</i>	45.00	
16	1SET	BOOT FINISHER CLIP	\$	<i>n</i>	24.20	
17	1	TAILLAMP CLIP LH	\$	<i>n</i>	5.00	} X
18	1	TAILLAMP CLIP RH	\$	<i>n</i>	5.00	
19	1	Rear Bumper Protector	\$	<i>n</i>	100.00	401n
TOTAL			\$		1,466.20	

TOTAL PARTS \$ 10,067.37**LABOUR**

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of Parts,
Adjust And Realign The Same

\$

200h
4,500.00

Trans-cab Auto Services Pte Ltd**AAD1909-080**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5013U

To Rust-Proofing Of The Affected Areas.	\$	<i>nn</i> 170.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>101</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00	<i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	<i>X</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>601</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>L</i> 170.00	<i>X</i>
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	<i>L</i> 170.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>L</i> 220.00	<i>X</i>
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>L</i> 380.00	<i>X</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>L</i> 380.00	<i>X</i>
Putty and spray painting of the affected portion.	\$	4,500.00	<i>2201</i>

TOTAL \$ 11,550.00**Over All Total \$ 21,617.37**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Warranty Basis"
- No illegal modifications to be allowed
- Supplementary (extra) work resurveyed and is subject to the insurance company

LUMP SUM (REPAIR DAY)**15 DAYS***2 days*

Acknowledgement by:

Signature:

Date: