

ASS. REC. BY:

REF: CS/MSG/K016/13/GSF302

Special Instruction:

Survivor: GQ

ASSIGNMENT (Office)

From (Person): Christina Wong

of MSG

Date/Time: 10.9.19 19.00pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJN 3963J

Insured: SLN 39174

at Workshop m/s Vin's motor

Tel: 6453221

of 160 San Ming Dam #103-03

Policy No: 29093079QMY

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A. 8.9.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 11.9.19 10:13am

Person Contacted:

Raymond

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate Inspection: 160 San Ming Dam #109-09
	SJN 3963J - CS/MSG/K016/13/GSF302 D.O.A. - 09/03/2019
	SLN 39174 - VA/MSG/K016/13/GSF302 D.O.A. - 05/09/2019
13/09/19	@ 17:13 pm revised PA to Christina Wong via merimen.

ASSIGNMENT

From: 11.10.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SSN 3963J

at Workshop m/s Vin's motor
of 160 Sun my Drive #08-09

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

\$70k.

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. repairs:

7

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

up"

Date:

Person Contacted

Vehicle: IN / OUT

Veh No: SSN3963J

Yt Regn: 21 Jul 2015

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A3 1.4 c.c. 1395

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

95617

T/Radio: Insured / Std / NI / NA

Eng/No:

WAUZZZ8V3F1142733

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size

F: 225/45 R17

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / HIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

11-09-19

Survey held at

w/s

4pm

Des. of Damages: Fit / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

COE: 49877

P/P \$ 17,385.22 @ 7 days
(\$ 3,631.44 Rd. 17 %)

THO Qiang,

RECEIVED 27 DEC 2019

PLS SEE MP.

20/12/2019

20/12

Date/Time, File Pass to?

27/12/19

Date/Time, File Return to?

☐

Preli. Report

☒

Final Report

Days Of Repair:

7

Resurvey No. of Trip:

2

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

200

Transportation:

\$ + RD \$

Photos

Others

TOTAL

11

211

Report Format:

Lump Sum / I.B. (\$ 17,385.22 P/P)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Sep 2019 10:28 Sendback Est	10 Sep 2019 10:40 S\$19,198.68	10 Sep 2019 19:00 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	YEO BOON LEE, ID: S1663979F, Tel: +6596493372		
Main Claimant:	BEK AIK CHIANG ALVIN, ID: S7423466F		
Vehicle Reg. No.:	SJN3963J	Date of Loss:	08/09/2019 17:00 - :59 [49 Months and 18 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	29093079QMY (Comprehensive) Coverage: 24/08/2018 - 15/12/2109
Vehicle Reg. No. (Insured):	SLD3917Y	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Vin's Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive, #03-03, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64532121		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Claimant's Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 11/09/2019]		
Driver/Custodian (Insured):	YEO BOON LEE (55 / Male), NRIC: S1663979F, Tel: +6596493372 Email:		
Adj Asg. Remarks:	on WP. Manual assigned to LKK via email on 10/09/19. Please contact us ASAP if you cannot attend this assignment. (Manual Assign). Liab: NA. Assign: LKK Auto Consultants Pte Ltd. Contact: 6453 2121 / 6458 1111		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Crystal Lee <crystal_lee@sg.msig-asia.com>
Sent: Tuesday, 10 September 2019 5:32 PM
To: Admin-D (LKKAuto); assignments
Cc: Ong Zi Hui; Helene Phua
Subject: Survey Request - Manual Assigned

Importance: High

Request For TP Survey SJN3963J ; Your Insured SLD3917Y DOA: 08/09/2019

Manual Assigned

Dear LKK,

Refer to the email, please arrange survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment

Thank you & Best regards,
Crystal Lee
Admin Officer, Claims Services (In-House Survey)
D: +65 6594 2535 | F: +65 6643 1349 | crystal_lee@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Motor Survey
Sent: Tuesday, 10 September, 2019 1:43 PM
To: Crystal Lee <crystal_lee@sg.msig-asia.com>; Helene Phua <helene_phua@sg.msig-asia.com>; Eileen Ang <eileen_ang@sg.msig-asia.com>
Subject: FW: Request For TP Survey SJN3963J ; Your Insured SLD3917Y DOA: 08/09/2019

Have a nice day

Jason Sim
Manager, Claims Services (Motor)
D: +65 6643 1325 | F: +65 6225 7402 | jason_sim@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Admin @ VAuG [<mailto:admin@vinsautogroup.com.sg>]
Sent: Tuesday, 10 September, 2019 10:43 AM
To: Motor Survey <motorsurvey@sg.msig-asia.com>
Cc: Crystal Lee <crystal_lee@sg.msig-asia.com>; Winnie Chua <pingping_chua@sg.msig-asia.com>
Subject: Request For TP Survey SJN3963J ; Your Insured SLD3917Y DOA: 08/09/2019

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Good morning,

We have submitted the Audatex and Merimen.

Please arrange for the survey

Thanks!
Best Regards
Raymond Teo



Sin Ming AutoCity
160 Sin Ming Drive
Singapore 575722
Showroom/Office: #03-03
Workshops: #08-08/09/10
Tel: 64532121 (4 lines)
Fax: 64599795
Website: www.vinsautogroup.com.sg
Email: admin@vinsautogroup.com.sg

Follow us on :



** w.e.f 15th May 2017, we have shifted location! **

** w.e.f 20th November 2017, we have changed our email address! **

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	466F

Vehicle Details

Vehicle No.:	SJN3963J
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Sep 2019
Vehicle Make:	AUDI
Vehicle Model:	A3 SEDAN 1.4 TFSI AMBIENTE MY 15
Primary Colour:	Grey
Manufacturing Year:	2015
Engine No.:	CZC263331
Chassis No.:	WAUZZZ8V3F1142733
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$27,583.00
Original Registration Date:	21 Jul 2015
First Registration Date:	21 Jul 2015
Transfer Count:	0
Actual ARF Paid:	\$20,617.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Jul 2025
PARF Rebate Amount:	\$15,462.00

Intended COE Rebate Details

COE Expiry Date:	20 Jul 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$58,700.00
COE Rebate Amount:	\$34,415.00
Total Rebate Amount:	\$49,877.00

The information contained herein is correct as at 09 Sep 2019

OK

► Audi A3 Used Vehicle List (12 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availabi
Audi A3 Sedan 1.4A TFSI Ambiente	\$72,800	\$11,950 /yr	27-Feb-2015	1,395 cc	78,000 km	CSH Motors (S) Pte Ltd	Availal
1 Owner, Well Maintained, Excellent Condition, Well Taken Care Of By Previous Owner. Trade In/Loan Available! Hurry Call Or Visit Us Now I Further Details.							
Office No. - 64620662							
Henry Tng - 90262998 Marcus Seah - 91117072 Kelvin Lin - 97605374							
Audi A3 Sedan 1.4A TFSI Ambiente	\$68,800	\$11,120 /yr	16-Mar-2015	1,395 cc	37,100 km	Faster Auto Trading	Availal
1 Owner, Low Mileage Done Only 37,000Km, Full Agent Serviced, 100% Loan Available, Ex-Bankruptcy And Bad Credit Welcome, High Trade In.							
Office No. - 64761970							
Yi De - 97480900 Jimmy - 91010213 Thomas - 96645002							
Audi A3 Sedan 1.4A TFSI Ambiente	\$66,800	\$10,700 /yr	26-Mar-2015	1,395 cc	78,500 km	Euro Performance Asia Pte Ltd	Availal
Enjoy Low-Interest Rates Of Only 1.98%! High Trade-In! Full Agent Serviced By Premium Auto. Flexible Loan Packages With Low Interest Ar Monthly Installments! Comes With Original S3 18" Rims Worth \$2K...							
Office No. - 65330588 / 85009000							
Braden - 81501500 Joseth - 90901043 Shawn - 97252591 Sindy - 90602839							
Audi A3 Sedan 1.4A TFSI Ambiente	\$65,800	\$10,520 /yr	26-Mar-2015	1,395 cc	75,000 km	Autolink Holdings Pte Ltd	Availal
Excellent Condition! Buy With A Peace Of Mind From Award Accredited Company! Attractive Loan Package Interest Rate And Competitive Tra In Price! Call Now To Find Out More! GST Included In Price!							
Office No. - 63463383							
Erik Tan - 94500673 Lee - 98468156							
Audi A3 Sedan 1.4A TFSI S-tronic Ambiente	\$76,800	\$12,480 /yr	31-Mar-2015	1,395 cc	-	Autotek Pte Ltd	Availal
Enjoy Low Interest Rate Available. Well Maintained By Previous Owner. 1 Owner Only. Trade In Welcome. Call Us Now For A Non Obligatory Discussion.							
Office No. - 69043368							
Frankie Lee - 97575401							
Audi A3 Sedan 1.4A TFSI Ambiente	\$68,800	\$10,910 /yr	23-Apr-2015	1,395 cc	63,000 km	Car41 Pte Ltd	Availal
Just Arrived! Well Taken Care By Ex Owner, High Loan With High Trade In Available. Price Nego. Call Now Or Drop By Our Showroom Today							
Office No. - 67022141							
Kelvin - 92788889 Jack - 86566662							
Audi A3 Sportback 1.4A TFSI S-tronic Ambiente	\$69,999	\$11,150 /yr	24-Apr-2015	1,395 cc	49,786 km	Carland Automobile	Availal
100% Loan Approval, 1 Owner, New Paintwork, New Rims, Low Mileage, Low Depreciation, Excellent Maintained Condition, No Repairs Need And Comes With 6 Months Warranty.							
Office No. - 62912129							
Lee - 90044780 Ken Liu - 90775885							
Audi A3 Sportback 1.4A TFSI S-tronic Ambiente	\$72,500	\$10,520 /yr	27-Aug-2015	1,395 cc	56,500 km	Munich Alpina Pte Ltd	Availal
Loan Interest At 2.28%, Extremely Well Maintained And Fully Agent Maintained. This Beast Does Not Just Look Beautiful, It's 100% Accident Free. View To Believe! Up To 70% Financing Possible! Trade In ...							
Office No. - -							
Zen - 90234262 Ben - 91849182							
Audi A3 Sedan 1.4A TFSI Ambiente	\$76,000	\$10,720 /yr	27-Oct-2015	1,395 cc	75,000 km	Otua Auto Pte Ltd	Availal

Consignment Code: A317. Flexible And Attractive Loan Packages Available To Choose From. Trade-Ins Available For Your Car! No Hidden Co For Further Information Or If You Have Any Questions Please D...

Office No. - -

Stedson Koh - 97869900 | Francis Chen - 87539539

Audi A3 Sportback 1.4A TFSI \$73,000 \$10,060 /yr 21-Dec-2015 1,395 cc 46,000 km Carport Enterprise Availal
S-tronic Ambiente

Latest Arrival! Most Valued Buy! Beautiful Blue Unit With Pristine Condition! Peace Of Mind! Fully Serviced By Agent And Warranty Until Marc 2021! 100% Accident Free! Lowest Genuine Mileage At Only 4...

Office No. - 68481307

Celine Ng - 81184814

Audi A3 Sportback 1.4A TFSI \$74,800 \$10,350 /yr 22-Dec-2015 1,395 cc 66,500 km Autolink Holdings Pte Availal
S-tronic Ambiente
 Ltd

Excellent Condition! Low Mileage, Buy With A Peace Of Mind From Award Accredited Company! Attractive Loan Package Interest Rate And Competitive Trade In Price! Call Now To Find Out More! GST Included ...

Office No. - 63463383

Erik Tan - 94500673 | Lee - 98468156

Audi A3 Sedan 1.4A TFSI \$76,800 \$10,550 /yr 30-Dec-2015 1,395 cc 57,000 km Quality Motor Trading Availal
Ambiente
 Enterprise

1 Owner, Full Agent Serviced. 100% Financing And Trade In Are Available! Perfect Condition Audi A3 Sedan. Low Mileage Done At 57000KM. Lightly Driven And Parked Under Shade Most Of The Time. Accident Fr...

Office No. - 64738668

Sharon - 97882224 | Dominic - 86685757

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorized car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2019 sgCarMart. All rights reserved.

Shirley Hiew (LKK Auto)

From: Admin @ VAuG <admin@vinsautogroup.com.sg>
Sent: Thursday, 26 December 2019 5:04 pm
To: Shirley Hiew (LKK Auto)
Cc: SUR
Subject: Re: SJN3963J - MSIG TP - DOA: 08/09/2019 - Finalization

Hi,

Yes confirm. Please proceed.

Thank you.

Best regards,
Yin Lei

On Fri, Dec 20, 2019 at 5:07 PM Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com> wrote:

Dear Raymond,

Please confirm P/P \$ 17,385.22/7 days before GST.

"Best Wishes for Merry Christmas & Happy New Year 2020"

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 13 Sep 2019

Preliminary Advice

Insured Vehicle No	: SLD3917Y	Accident Date	: 08/09/2019
TP Vehicle No	: SJN3963J	Assignment Date	: 10/09/2019
Make	: AUDI A3	Est. Duration of Repair	: 7 days
Date of Inspection	: 11/09/2019		
Inspection At	: Vin's Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive, #03-03, Sin Ming AutoCity Singapore 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front & rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,198.68
Revised Amount	:S\$	9,009.68
Check Items (Estimated)	:S\$	8,353.60
Total	:S\$	17,363.28

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis. Some parts items still pending parts prices.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/09/2019 09:16
Date Of Accident	08/09/2019 17:40
Exact Location Of Accident	ALONG JALAN BOON LAY WAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJN3963J
Insured/Policyholder	
Name Of Registered Owner	BEK AIK CHIANG ALVIN
NRIC No	S7423466F
Email Address	ALVINBEK@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90114325
Alternative Phone No	OFFICE-90114325

Vehicle Particulars

Manufacturer	AUDI
Model	A3 SEDAN 1.4 TFSI AMBIENTE MY 15
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	BEK AIK CHIANG ALVIN
NRIC No	S7423466F
Date Of Birth	27/07/1974
Occupation	INDOOR
Date Of Driving Pass	17/05/1995
Driving Experience	24 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90114325
Fax Number	
Contact Number	OFFICE-90114325
EMail Address	ALVINBEK@GMAIL.COM

Address	50 LAKESIDE DRIVE #09-01
Postcode	648315
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	4
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : CHAN WAI KIN GENDER: : FEMALE
Passenger 2	NAME: : BEK JOON HAO GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Same as sketch plan

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLD3917Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	YEO BOON LEE
NRIC/Passport Number	S1663979F
Contact Number	96493372
Address	
Postcode	

Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SMH2082D
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver CHUA CHENG WAN ISAAC
NRIC/Passport Number S8405241H
Contact Number 85111321
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number GBH1176D
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver KONG MENG HENG
NRIC/Passport Number S7128216C
Contact Number 91816672
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN



A: SJN 3963J
B: SLD 3917Y
C: GBA 1176D
D: SMH 2082D

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the 8th of September 2019, at about 1740 hrs. I was stationary along Jalan Boon Lay Way at the right most lane due to the red light. All of a sudden, I felt an impact from my rear. The impact caused my vehicle to move forward and hit onto the front vehicle SMH2082D. After I came out from my vehicle, I realized the vehicle SLD3917Y hit onto my vehicle. It was a 4 cars chain collision.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Vin's

AUTOMOTIVE GROUP

Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722
T 6453 2121 (4 lines) / 6458 1111 (24 hrs)
F 6459 9795 / 6459 0433
E admin@vinsautogroup.com.sg
W www.vinsautogroup.com.sg

Our Ref : TP/092019/4040
Accident date: 8/9/2019
Your Ref : SLD3917Y

Tax Invoice:

Date : 9/9/2019

Motor Claim Department
MSIG INSURANCE (SINGAPORE) PTE LTD
No.4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

ESTIMATE COST OF REPAIRS TO

Vehicle No. : SJN3963J
Model : AUDI A3 SEDAN 1.4 TFSI AMBIENTE MY 15

1 pc Front grille / CRA	\$ 300.00
1 pc Front bumper / ee	\$ 900.00
2 pcs Front bumper side retainer @ \$20.00 X NN	\$ 40.00
1 pc Front bumper reinforcement 2 BT	\$ 310.00
2 pcs Front headlamp @ \$920.00 2 CRA	\$ 1,840.00
2 pcs Front headlamp ECU @ \$290.00 X NN	\$ 580.00
2 pcs Front safety belt @ \$550.00 Act	\$ 1,100.00
1 pc Front steering wheel airbag 2	\$ 1,800.00
1 pc Front steering wheel coil spring 2 } Act	\$ 500.00
1 pc Front air bag control unit 2	\$ 850.00
1 pc Rear boot lid X repair 2 BT	\$ 1,200.00
1 pc Rear boot lid emblem /	\$ 50.00
1 pc Rear boot lid "A3" name plate /	\$ 40.00
1 pc Rear boot lid "TFSI" name plate /	\$ 40.00
1 pc Rear boot lid auto lock X NN	\$ 70.00
2 pcs Rear boot lid reflector @ \$310.00 2 CRA	\$ 620.00
1 pc Rear bumper / ee	\$ 900.00
4 pcs Rear bumper parking sensor @ \$120.00 2 pc NW	\$ 480.00
2 pcs Rear bumper reflector @ \$20.00 X NN	\$ 40.00
Bonnet 2 BT	\$ 1,500.00
	\$ 11,660.00

Vin's

AUTOMOTIVE GROUP

A Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722
T 6453 2121 (4 lines) / 6458 1111 (24 hrs)
F 6459 9795 / 6459 0433
E admin@vinsautogroup.com.sg
W www.vinsautogroup.com.sg

Our Ref : TP/092019/4040
Accident date: 8/9/2019
Your Ref : SLD3917Y

Tax Invoice:

Date : 9/9/2019

Balance B/F \$ 11,660.00

1 pc	Rear bumper lower pad	✓ CAA	\$ 140.00
2 pcs	Rear bumper side retainer @ \$30.00	X NN	\$ 60.00
1 pc	Rear bumper reinforcement	✓ AT	\$ 290.00
2 pcs	Rear tail lamp @ \$410.00	✓ CAA	\$ 820.00
1 pc	Rear exhaust silencer	X	\$ 500.00
1 pc	Rear exhaust silencer chrome	X NN	\$ 180.00
1 pc	Rear end panel	X Repair	\$ 380.00

Add 15% \$ 2,104.50
\$ 16,134.50

To reset programme	\$ 150.00	80
To reset air bag system	\$ 180.00	120
To repair rear damages	\$ 1,235.00	800 ?
To spray painting	\$ 1,085.00	1000
Paintwork material	\$ 414.18	
	<u>\$ 19,198.68</u>	

VIN'S MOTOR PTE LTD

[Signature]
Enus Corp.
7 Days.
P/P.
11/9/19.

LINK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vin's

AUTOMOTIVE GROUP

Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722

6453 2121 (4 lines) / 6458 1111 (24 hrs)

6459 7795 / 6459 0433

admin@vinsautogroup.com.sg

www.vinsautogroup.com.sg

Our Ref : TP/092019/4040
Accident date: 8/9/2019
Your Ref : SLD3917Y

Tax Invoice:

Date : 9/9/2019

Motor Claim Department
MSIG INSURANCE (SINGAPORE) PTE LTD
No.4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

ESTIMATE COST OF REPAIRS TO

Vehicle No. : SJN3963J
Model : AUDI A3 SEDAN 1.4 TFSI AMBIENTE MY 15

1 pc	Front grille	/ CRA	\$ / 300.00 ✓
1 pc	Front bumper	/ ee	\$ / 900.00
2 pcs	Front bumper side retainer @ \$20.00	X NN	\$ X 40.00
1 pc	Front bumper reinforcement	✓ BT	\$ / 310.00
2 pcs	Front headlamp @ \$920.00	✓ CRA	\$ / 1,840.00 ✓
2 pcs	Front headlamp ECU @ \$290.00	X NN	\$ X 580.00
2 pcs	Front safety belt @ \$550.00	- Act	\$ / 1,100.00 ✓
1 pc	Front steering wheel airbag	✓	\$ / 1,800.00 ✓
1 pc	Front steering wheel coil spring	✓ Act	\$ / 500.00
1 pc	Front air bag control unit	✓	\$ / 850.00
1 pc	Rear boot lid	X Repair ✓ BT	\$ / 1,200.00 ✓
1 pc	Rear boot lid emblem	/	\$ / 50.00
1 pc	Rear boot lid "A3" name plate	/	\$ / 40.00 ✓
1 pc	Rear boot lid "TFSI" name plate	/	\$ / 40.00 ✓
1 pc	Rear boot lid auto lock	X NN	\$ X 70.00
2 pcs	Rear boot lid reflector @ \$310.00	✓ CRA	\$ / 620.00
1 pc	Rear bumper	/ ee	\$ / 900.00
4 pcs	Rear bumper parking sensor @ \$120.00	? 2pc /	\$ 240 480.00 ✓
2 pcs	Rear bumper reflector @ \$20.00	X NN	\$ X 40.00
Bonnet			\$ 11,660.00

Vin's

AUTOMOTIVE GROUP

Sin Ming AutoCity,
160 Sin Ming Drive #03-03
Singapore 575722

6453 2121 (4 lines) / 6458 1111 (24 hrs)

6459 9795 / 6459 0433

admin@vinsautogroup.com.sg

www.vinsautogroup.com.sg

Our Ref : TP/092019/4040
Accident date: 8/9/2019
Your Ref : SLD3917Y

Tax Invoice:

Date : 9/9/2019

Balance B/F		\$ 11,660.00
1 pc Rear bumper lower pad	✓ CAA	\$ / 140.00
2 pcs Rear bumper side retainer @ \$30.00	X NN	\$ X 60.00
1 pc Rear bumper reinforcement	✓ BT	\$ / 290.00
2 pcs Rear tail lamp @ \$410.00	✓ CAA	\$ / 820.00 ✓
1 pc Rear exhaust silencer	X	\$ X 500.00
1 pc Rear exhaust silencer chrome	X LNN	\$ X 180.00
1 pc Rear end panel	X Repair	\$ X 380.00
		\$ 14,030.00
Add 15%		\$ 2,104.50
		\$ 16,134.50

To reset programme
To reset air bag system
To repair ^{front} rear damages
To spray painting
Paintwork material

\$ 150.00 80
\$ 180.00 120
\$ 1,235.00 800 ?
\$ 1,085.00 1000
\$ 414.18
\$ 19,198.68

Good
03/9/19

VIN'S MOTOR PTE LTD



Eric Ong
7 Days.
P/P.
11/9/19.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vin's Motor Pte Ltd
#03-03, Sin Ming AutoCity, 160 Sin
Ming Drive
575722

Vin's

Insurer Reference:
Repairer Reference: TP/092019/4040
Date calculated: 10/09/2019 10:22 AM
Summary Information

Full Report
Registration: SJN3963J
Printed: 10/09/2019 10:23 AM

Claim			
Location:	Singapore (SG)	Work Provider:	MSIG Insurance (Singapore) Pte Ltd
Printed by:	Khong Keng Leng	Currency:	SGD
Claim Reference:		Date of Incident:	08/09/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	AUDI
Model:	A3 SALOON (8VS)
Sub Model:	AMBIENTE
Model Sheet Number:	00 5A 13
Registration:	SJN3963J
VIN number:	WAUZZZ8V3F1142733
Odometer:	

Model Specs

FROM 05/2015	R/ASPHERIC D/MIRROR	L/MIRROR CONVEX	BRILLIANCE PACKAGE
STOP-START SYSTEM	DEACTIVATED P/AIRBAG	FRONT BRAKE 288 X 25	AUTO AIR CON
FRONT SCREEN W/WEDGE	REAR PARKING SYSTEM	HEATED DOOR MIRRORS	ELEC FOLD DR MIRRORS
AUTO DIPPING MIRROR	8 SPEAKER	MMI RADIO STANDARD	XENON HEADLAMPS
MULTI FUNC S-WHEEL	HEATED WASHER JETS	HEADLAMP WASHERS	LIGHT-/RAIN SENSOR
EQUIP LEATH/IMIT LEA	STORAGE PACKAGE	AUTO DIPPING MIRROR	DRIVER INFO COLOUR
INTERIOR LAMP PACK	FRONT CENTRE ARMREST	EMISSION STD EURO 6+	HD COOLING
S-TRONIC 7-SPEED	INDEPENT RR SUSPENS	CRUISE CONTROL	TYRES 205/55 WR 16
WHEELS 7J X 16 ALLOY	PHONE SYS BLUETOOTH	GLASS OPTICS TRIM	1.4 LTR 92KW
PREPARE OFF VEHICLE	THREE COAT PEARL		

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary dem(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by: _____
Signature: _____
Date: _____

Vin's Motor Pte Ltd
#03-03, Sin Ming AutoCity, 160 Sin
Ming Drive
575722

Vin's

Insurer Reference:
 Repairer Reference: TP/092019/4040
 Date calculated: 10/09/2019 10:22 AM

Full Report
 Registration: SJN3963J
 Printed: 10/09/2019 10:23 AM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
 Date of Inspection:

Damage Areas

All ☐
 Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
44 05 19 00	R + R FRONT WHEEL (WHEELS)		2.0	10.00
44 05 19 00	R + R REAR WHEEL (WHEELS)		2.0	10.00
63 29 19 00	R + R FRONT BUMPER COVER		9.0	45.00
63 29 55 54	RENEW FRONT BUMPER COVER (COVER REMOVED)		12.0	60.00
	INCLUDES: R + R RADIATOR GRILLE, FRONT SPOILER AND WASHER NOZZLES			
63 10 19 50)	R + R FRONT BUMPER (IMPACT CARRIER) (BUMPER COVER REMOVED)		3.0	15.00
63 10 55 50	RENEW FRT BUMPER REINFORCER		2.0	10.00
94 15 20 50	R + R BOTH HEADLAMPS (FRONT BUMPER COVER REMOVED)		4.0	20.00
	DOES NOT INCLUDE: ADJUST HEADLAMPS			
94 15 56 51	RENEW HEADLAMPS (REMOVED)		4.0	20.00
50 38 19 00)	R + R FRONT LOCK CARRIER (BUMPER COVER REMOVED)		16.0	80.00
	INCLUDES: SOUND INSULATION PAN R + R WHEELHOUSE, RADIATOR AND CONDENSER DETACH + REFIT			
55 90 19 00	R + R BOOTLID		9.0	45.00

Vin's Motor Pte Ltd
#03-03, Sin Ming AutoCity, 160 Sin
Ming Drive
575722

Vin's

Insurer Reference:

Repairer Reference: TP/092019/4040

Date calculated: 10/09/2019 10:22 AM

Full Report

Registration: SJN3963J

Printed: 10/09/2019 10:23 AM

Code	Description	WU	Price SGD
55 90 55 50	INCLUDES: R + R BOOTLID TRIM, ADJUST BOOTLID RENEW BOOTLID (BOOTLID REMOVED)	11.0	55.00
63 69 55 52	INCLUDES: R + R ALL PARTS RENEW REAR BUMPER COVER (COVER REMOVED)	5.0	25.00
66 59 55 50	INCLUDES: R + R LOWER SPOILER AND SENSORS RENEW REAR LOWER BUMPER SPOILER	1.0	5.00
66 76 19 50	R + R L/R WHEELHOUSE SHELL (WHEEL REMOVED)	2.0	10.00
66 76 19 50	R + R R/R WHEELHOUSE SHELL (WHEEL REMOVED)	2.0	10.00
53 16 53 01	REMOVE PARTS REAR END CROSSMEMBER INCLUDES: REMOVE TAILLAMPS, BUMPER (IMPACT CARRIER), BUMPER COVER, LOCK CARRIER COVER, BOOT TRIMS, TAILGATE SEAL AND LOWER LOCK	9.0	45.00
53 05 55 50	RENEW REAR END PANEL (COMPOSITE WORK) (REAR END CROSSMEMBER REMOVED)	16.0	80.00
53 16 55 01	RENEW REAR END CROSSMEMBER	19.0	95.00
53 16 59 01	FIT PARTS REAR END CROSSMEMBER INCLUDES: FIT REMOVED PARTS, RENEW IF NECESSARY DOES NOT INCLUDE: RENEW BUMPER COVER	11.0	55.00
70 67 19 30)	R + R LEFT LOWER B-PILLAR TRIM	1.0	5.00
70 67 19 20	R + R LEFT UPPER B-PILLAR TRIM	4.0	20.00
70 67 19 30)	R + R RIGHT LOWER B-PILLAR TRIM	1.0	5.00
70 67 19 20	R + R RIGHT UPPER B-PILLAR TRIM	4.0	20.00
69 11 19 10)	R + R LEFT FRONT THREE POINT SEAT BELT (B-PILLAR TRIM REMOVED)	2.0	10.00
69 11 19 10)	R + R RIGHT FRONT THREE POINT SEAT BELT (B-PILLAR TRIM REMOVED)	2.0	10.00
48 10 19 00	R + R STEERING WHEEL INCLUDES: REMOVE AIRBAG UNIT	4.0	20.00
94 13 19 50	R + R AIRBAG RESET RING (STEERING WHEEL REMOVED)	3.0	15.00
26 33 19 00	R + R REAR MUFFLER	5.0	25.00
94 15 16 00	ADJUST HEADLAMPS	2.0	10.00
0741	L/F WING REPAIR	20.0*	100.00
0742	R/F WING REPAIR	20.0*	100.00
3481	L/R SIDE PANEL REPAIR	20.0*	100.00
3482	R/R SIDE PANEL REPAIR	20.0*	100.00
1008	To Reset Programme Programme		150.00*

Vin's Motor Pte Ltd
#03-03, Sin Ming AutoCity, 160 Sin
Ming Drive
575722

Vin's

Insurer Reference:
 Repairer Reference: TP/092019/4040
 Date calculated: 10/09/2019 10:22 AM

Full Report
 Registration: SJN3963J
 Printed: 10/09/2019 10:23 AM
 WU Price SGD

Code	Description			
1009	To Reset AirBag Air Bag			180.00*
	Labour Cost	Hrs	WU	
	Panel / Mechanical Labour	24.70	247.0	1,235.00
	Alignment			
	Fixed Rate			330.00
	Total of Labour			1,565.00

Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description - THREE COAT PEARL	WU Price SGD
	REAR PANEL NEW PART PAINTING	24.8
	BOOTLID/TAILGATE NEW PART PAINTING	19.6
	FRONT BUMPER COVER NEW PART PAINT K1R	13.5
	REAR COVER BUMPER NEW PART PAINT K1R	17.5
	L/R OUTER SENSOR NEW PART PAINT K1R	4.5
	R/R OUTER SENSOR NEW PART PAINT K1R	4.5
	L/R INNER SENSOR NEW PART PAINT K1R	4.5
	R/R INNER SENSOR NEW PART PAINT K1R	4.5
	L/F WING REPAIR PAINTING <50%	13.6
	R/F WING REPAIR PAINTING <50%	13.6
	L/R SIDE PANEL REPAIR PAINTING <50%	18.3
	R/R SIDE PANEL REPAIR PAINTING <50%	18.3
	BONNET SURFACE PAINT	17.2
	L/R OUTER WHEELHOUSE SURFACE PAINT	4.0
	R/R OUTER WHEELHOUSE SURFACE PAINT	4.0

Paint Material Per Part

Code	Description	Price SGD
2711	REAR PANEL NEW PART PAINTING	30.62
2931	BOOTLID/TAILGATE NEW PART PAINTING	51.94
0281	FRONT BUMPER COVER NEW PART PAINT K1R	54.16
2581	REAR COVER BUMPER NEW PART PAINT K1R	79.06
2781	L/R OUTER SENSOR NEW PART PAINT K1R	0.62
2782	R/R OUTER SENSOR NEW PART PAINT K1R	0.62
2783	L/R INNER SENSOR NEW PART PAINT K1R	0.62
2784	R/R INNER SENSOR NEW PART PAINT K1R	0.62
0741	L/F WING REPAIR PAINTING <50%	15.62
0742	R/F WING REPAIR PAINTING <50%	15.62
3481	L/R SIDE PANEL REPAIR PAINTING <50%	28.77
3482	R/R SIDE PANEL REPAIR PAINTING <50%	28.77
0471	BONNET SURFACE PAINT	54.26

Vin's Motor Pte Ltd
#03-03, Sin Ming AutoCity, 160 Sin
Ming Drive
575722

Vin's

Insurer Reference:
Repairer Reference: TP/092019/4040
Date calculated: 10/09/2019 10:22 AM
Paint Material Per Part

Full Report
Registration: SJN3963J
Printed: 10/09/2019 10:23 AM

Code	Description	Price SGD
4161	L/R OUTER WHEELHOUSE SURFACE PAINT	2.99
4162	R/R OUTER WHEELHOUSE SURFACE PAINT	2.99

Labour Cost - Paint

	Factor	Hrs	WU	Price SGD
	50.00 SGD/h			
	Time Paint		182.0	
	Preparation Main Work Metal	2.50	25.0	125.00
	Preparation Comp. Work Plastic	0.50	5.0	25.00
	Preparation Multi-Coat	0.50	5.0	25.00
Total	10 WU/h	21.70	217.0	1,085.00

Material Cost - Paint

	Price SGD
New Part Painting	82.56
New Part Painting - Plastic K1R	135.70
Repair Painting	88.78
Surface-/Blend Paint	60.24
Material-constant Metal Preparation	28.60
Material-constant Multi-Coat	9.30
Material-constant Plastic	9.00
Total	414.18

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-09-02/23	Price SGD
0281	FRONT BUMPER COVER	8V5 807 065 A			900.00
		GRU			
0340	FRT BUMPER SUPPORT	8V4 807 109 C			310.00
0410	GRILLE	8V5 853 651	1QP		300.00
0561	LEFT HEADLAMP ASSY	8V0 941 043 D			920.00
0562	RIGHT HEADLAMP ASSY	8V0 941 044 D			920.00
2581	REAR COVER BUMPER	8V5 807 067 A			900.00
		GRU			
2605	REAR BUMPER SPOILER	8V5 807 521 B			140.00
2640	REAR BUMPER SUPPORT	8V5 807 309			290.00
2711	REAR PANEL	8V5 813 331 TB			380.00
2719	REAR PANEL C-MEMBER	8V5 813 307			0.00
2781	L/R OUTER SENSOR	5Q0 919 275 B			120.00
		GRU			
2782	R/R OUTER SENSOR	5Q0 919 275 B			120.00
		GRU			

Vin's Motor Pte Ltd
 #03-03, Sin Ming AutoCity, 160 Sin
 Ming Drive
 575722

Vin's

Insurer Reference:

Repairer Reference: TP/092019/4040

Date calculated: 10/09/2019 10:22 AM

Full Report

Registration: SJN3963J

Printed: 10/09/2019 10:23 AM

Code	Description	Part Number	Supplier	Price SGD
2783	L/R INNER SENSOR	5Q0 919 275 B GRU		120.00
2784	R/R INNER SENSOR	5Q0 919 275 B GRU		120.00
2931	BOOTLID/TAILGATE	8V5 827 025 F		1,200.00
2951	BOOT/T.GATE MNTG SET	8V0 098 617 B		0.00
2975	BOOT/TAILGATE LOCK	4H0 827 505 A		70.00
3013	L/R BADGE	8P0 853 741 2ZZ		40.00
3019	R/R BADGE	8X0 853 737 A 2ZZ		40.00
3020	REAR BADGE	8V7 853 742 2ZZ		50.00
3279	L/R INNER LAMP	8V5 945 093 H		310.00
3280	R/R INNER LAMP	8V5 945 094 H		310.00
3281	L/R LAMP	8V5 945 095 A		410.00
3282	R/R LAMP	8V5 945 096 A		410.00
3413	L/R REFLECTOR	8V5 945 105 A		20.00
3414	R/R REFLECTOR	8V5 945 106 A		20.00
4661	L/F SEAT BELT	8V5 857 705 E V04		550.00
4662	R/F SEAT BELT	8V5 857 706 E V04		550.00
7435	COMBI SWITCH MODULE	5Q0 953 549 E		500.00
7445	DRIVER AIRBAG	8V0 880 201 AG 6PS		1,800.00
8833	RR EXHAUST SILENCER	8V5 253 609 F		500.00
1000	F RH Side Retainer	Bumper		20.00
1001	F LH Side Retainer	Bumper		20.00
1002	F RH Headlamp ECU	Headlamp		290.00
1003	F LH Headlamp ECU	Headlamp		290.00
1004	AirBag Control Unit	AirBag		850.00
1005	R RH Side Retainer	Bumper		30.00
1006	R LH Side Retainer	Bumper		30.00
1007	R Exhaust Chrome	ExhaustSilencer		180.00
f: OEM Parts				
n: Non-OEM Parts				
u: Used parts				
Savings				0.00
Subtotal				14,030.00
Addition(+15.00%)				2,104.50
Total				16,134.50

7Days.
 part by part
 before paint photos.

Guo Qiang - 82880282
 11/9/19.

Guo Qiang
 10/9/19.

Vin's Motor Pte Ltd
#03-03, Sin Ming AutoCity, 160 Sin
Ming Drive
575722

Vin's

Insurer Reference:
Repairer Reference: TP/092019/4040
Date calculated: 10/09/2019 10:22 AM

Full Report
Registration: SJN3963J
Printed: 10/09/2019 10:23 AM

Final Calculation

	SGD	SGD
Parts	14,030.00	
Addition(+15.00%)	2,104.50	
Total Parts		16,134.50
Labour Time Base 10 WU/h		
Total 247.0 WU X 50.00 SGD/h	1,235.00	800
Alignment		
Fixed Rate	330.00	
Total of Labour		1,565.00
Paint Work Time Base 10 WU/h		
Labour Cost 217.0 WU X 50.00 SGD/h	1,085.00	1000
Material Cost	414.18	
Total Paint Including Material		1,499.18
Repair Cost Excludes GST		19,198.68
GST (+7.0%)		1,343.91
Repair Cost Included GST		20,542.59

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Vin's Motor Pte Ltd
#03-03, Sin Ming AutoCity, 160 Sin
Ming Drive
575722

Vin's

Insurer Reference:
Repairer Reference: TP/092019/4040
Date calculated: 10/09/2019 10:22 AM
Summary Information

Full Report
Registration: SJN3963J
Printed: 10/09/2019 10:23 AM

Claim

Location:	Singapore (SG)	Work Provider:	MSIG Insurance (Singapore) Pte Ltd
Printed by:	Khong Keng Leng	Currency:	SGD
Claim Reference:		Date of Incident:	08/09/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	


Vehicle Details

Vehicle

Manufacturer:	AUDI
Model:	A3 SALOON (8VS)
Sub Model:	AMBIENTE
Model Sheet Number:	00 5A 13
Registration:	SJN3963J
VIN number:	WAUZZZ8V3F1142733
Odometer:	

Model Specs

FROM 05/2015	R/ASPHERIC D/MIRROR	L/MIRROR CONVEX	BRILLIANCE PACKAGE
STOP-START SYSTEM	DEACTIVATED P/AIRBAG	FRONT BRAKE 288 X 25	AUTO AIR CON
FRONT SCREEN W/WEDGE	REAR PARKING SYSTEM	HEATED DOOR MIRRORS	ELEC FOLD DR MIRRORS
AUTO DIPPING MIRROR	8 SPEAKER	MMI RADIO STANDARD	XENON HEADLAMPS
MULTI FUNC S-WHEEL	HEATED WASHER JETS	HEADLAMP WASHERS	LIGHT-/RAIN SENSOR
EQUIP LEATH/IMIT LEA	STORAGE PACKAGE	AUTO DIPPING MIRROR	DRIVER INFO COLOUR
INTERIOR LAMP PACK	FRONT CENTRE ARMREST	EMISSION STD EURO 6+	HD COOLING
S-TRONIC 7-SPEED	INDEPENT RR SUSPENS	CRUISE CONTROL	TYRES 205/55 WR 16
WHEELS 7J X 16 ALLOY	PHONE SYS BLUETOOTH	GLASS OPTICS TRIM	1.4 LTR 92KW
PREPARE OFF VEHICLE	THREE COAT PEARL		



Vin's Motor Pte Ltd
#03-03, Sin Ming AutoCity, 160 Sin
Ming Drive
575722

Vin's

Insurer Reference:
Repairer Reference: TP/092019/4040
Date calculated: 10/09/2019 10:22 AM

Full Report
Registration: SJN3963J
Printed: 10/09/2019 10:23 AM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
 Date of Inspection:

Damage Areas

All ☐
 Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
44 05 19 00	R + R FRONT WHEEL (WHEELS)	2.0	10.00	✓
44 05 19 00	R + R REAR WHEEL (WHEELS)	2.0	10.00	✓
63 29 19 00	R + R FRONT BUMPER COVER	9.0	45.00	✓
63 29 55 54	RENEW FRONT BUMPER COVER (COVER REMOVED)	12.0	60.00	✓
	INCLUDES: R + R RADIATOR GRILLE, FRONT SPOILER AND WASHER NOZZLES			
63 10 19 50)	R + R FRONT BUMPER (IMPACT CARRIER) (BUMPER COVER REMOVED)	3.0	15.00	✓
63 10 55 50	RENEW FRT BUMPER REINFORCER	2.0	10.00	✓
94 15 20 50	R + R BOTH HEADLAMPS (FRONT BUMPER COVER REMOVED)	4.0	20.00	✓
	DOES NOT INCLUDE: ADJUST HEADLAMPS			
94 15 56 51	RENEW HEADLAMPS (REMOVED)	4.0	20.00	✓
50 38 19 00)	R + R FRONT LOCK CARRIER (BUMPER COVER REMOVED)	16.0	80.00	✓
	INCLUDES: SOUND INSULATION PAN R + R WHEELHOUSE, RADIATOR AND CONDENSER			
	DETACH + REFIT			
55 90 19 00	R + R BOOTLID	9.0	45.00	✓

Vin's Motor Pte Ltd
#03-03, Sin Ming AutoCity, 160 Sin
Ming Drive
575722

Vin's

Insurer Reference:
Repairer Reference: TP/092019/4040
Date calculated: 10/09/2019 10:22 AM

Full Report
Registration: SJN3963J
Printed: 10/09/2019 10:23 AM
WU Price SGD

Code	Description	WU	Price SGD	
55 90 55 50	INCLUDES: R + R BOOTLID TRIM, ADJUST BOOTLID RENEW BOOTLID (BOOTLID REMOVED)	11.0	55.00	✓
63 69 55 52	INCLUDES: R + R ALL PARTS RENEW REAR BUMPER COVER (COVER REMOVED)	5.0	25.00	✓
66 59 55 50	INCLUDES: R + R LOWER SPOILER AND SENSORS RENEW REAR LOWER BUMPER SPOILER	1.0	5.00	✓
66 76 19 50	R + R L/R WHEELHOUSE SHELL (WHEEL REMOVED)	2.0	10.00	✓
66 76 19 50	R + R R/R WHEELHOUSE SHELL (WHEEL REMOVED)	2.0	10.00	✓
53 16 53 01	REMOVE PARTS REAR END CROSSMEMBER INCLUDES: REMOVE TAILLAMPS, BUMPER (IMPACT CARRIER), BUMPER COVER, LOCK CARRIER COVER, BOOT TRIMS, TAILGATE SEAL AND LOWER LOCK	9.0	45.00	✗
53 05 55 50	RENEW REAR END PANEL (COMPOSITE WORK) (REAR END CROSSMEMBER REMOVED)	16.0	80.00	✗
53 16 55 01	RENEW REAR END CROSSMEMBER	19.0	95.00	✓
53 16 59 01	FIT PARTS REAR END CROSSMEMBER INCLUDES: FIT REMOVED PARTS, RENEW IF NECESSARY DOES NOT INCLUDE: RENEW BUMPER COVER	11.0	55.00	✗
70 67 19 30)	R + R LEFT LOWER B-PILLAR TRIM	1.0	5.00	✓
70 67 19 20	R + R LEFT UPPER B-PILLAR TRIM	4.0	20.00	✓
70 67 19 30)	R + R RIGHT LOWER B-PILLAR TRIM	1.0	5.00	✓
70 67 19 20	R + R RIGHT UPPER B-PILLAR TRIM	4.0	20.00	✓
69 11 19 10)	R + R LEFT FRONT THREE POINT SEAT BELT (B-PILLAR TRIM REMOVED)	2.0	10.00	✓
69 11 19 10)	R + R RIGHT FRONT THREE POINT SEAT BELT (B-PILLAR TRIM REMOVED)	2.0	10.00	✓
48 10 19 00	R + R STEERING WHEEL INCLUDES: REMOVE AIRBAG UNIT	4.0	20.00	✓
94 13 19 50	R + R AIRBAG RESET RING (STEERING WHEEL REMOVED)	3.0	15.00	✓
26 33 19 00	R + R REAR MUFFLER	5.0	25.00	✓
94 15 16 00	ADJUST HEADLAMPS	2.0	10.00	✗
0741	L/F WING REPAIR ✗	20.0*	100.00	✗
0742	R/F WING REPAIR ✗	20.0*	100.00	✗
3481	L/R SIDE PANEL REPAIR ✗	20.0*	100.00	✗
3482	R/R SIDE PANEL REPAIR ✗	20.0*	100.00	✗
1008	To Reset Programme Programme		150.00*	✓

Vin's Motor Pte Ltd
#03-03, Sin Ming AutoCity, 160 Sin
Ming Drive
575722

Vin's

Insurer Reference:
 Repairer Reference: TP/092019/4040
 Date calculated: 10/09/2019 10:22 AM

Full Report
 Registration: SJN3963J
 Printed: 10/09/2019 10:23 AM

Code	Description	WU	Price SGD
1009	To Reset AirBag Air Bag		180.00* ✓
Labour Cost			
	Panel / Mechanical Labour	Hrs 24.70 WU 247.0	1,235.00
	Alignment		
	Fixed Rate		330.00
	Total of Labour		1,565.00

Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description - THREE COAT PEARL	WU Price SGD
	REAR PANEL NEW PART PAINTING	24.8 30.20
	BOOTLID/TAILGATE NEW PART PAINTING	19.6 ✓
	FRONT BUMPER COVER NEW PART PAINT K1R	13.5 ✓
	REAR COVER BUMPER NEW PART PAINT K1R	17.5 ✓
	L/R OUTER SENSOR NEW PART PAINT K1R	4.5 ✓
	R/R OUTER SENSOR NEW PART PAINT K1R	4.5 ✓
	L/R INNER SENSOR NEW PART PAINT K1R	4.5 X
	R/R INNER SENSOR NEW PART PAINT K1R	4.5 X
	L/F WING REPAIR PAINTING <50%	13.6 X
	R/F WING REPAIR PAINTING <50%	13.6 X
	L/R SIDE PANEL REPAIR PAINTING <50%	18.3 X
	R/R SIDE PANEL REPAIR PAINTING <50%	18.3 X
	BONNET SURFACE PAINT	17.2 X
	L/R OUTER WHEELHOUSE SURFACE PAINT	4.0 ✓
	R/R OUTER WHEELHOUSE SURFACE PAINT	4.0 ✓

Paint Material Per Part

Code	Description	Price SGD
2711	REAR PANEL NEW PART PAINTING	30.62
2931	BOOTLID/TAILGATE NEW PART PAINTING	51.94 ✓
0281	FRONT BUMPER COVER NEW PART PAINT K1R	54.16 ✓
2581	REAR COVER BUMPER NEW PART PAINT K1R	79.06 ✓
2781	L/R OUTER SENSOR NEW PART PAINT K1R	0.62 ✓
2782	R/R OUTER SENSOR NEW PART PAINT K1R	0.62 ✓
2783	L/R INNER SENSOR NEW PART PAINT K1R	0.62 X
2784	R/R INNER SENSOR NEW PART PAINT K1R	0.62 X
0741	L/F WING REPAIR PAINTING <50%	15.62 X
0742	R/F WING REPAIR PAINTING <50%	15.62 X
3481	L/R SIDE PANEL REPAIR PAINTING <50%	28.77 X
3482	R/R SIDE PANEL REPAIR PAINTING <50%	28.77 X
0471	BONNET SURFACE PAINT	97.24 54.26 ✓

Vin's Motor Pte Ltd
#03-03, Sin Ming AutoCity, 160 Sin
Ming Drive
575722

Vin's

Insurer Reference:
Repairer Reference: TP/092019/4040
Date calculated: 10/09/2019 10:22 AM
Paint Material Per Part

Full Report
Registration: SJN3963J
Printed: 10/09/2019 10:23 AM

Code	Description	Price SGD
4161	L/R OUTER WHEELHOUSE SURFACE PAINT	2.99 ✓
4162	R/R OUTER WHEELHOUSE SURFACE PAINT	2.99 ✓

Labour Cost - Paint

	Factor	50.00 SGD/h	Hrs	WU	Price SGD
	Time Paint			182.0	
	Preparation Main Work Metal		2.50	25.0	125.00
	Preparation Comp. Work Plastic		0.50	5.0	25.00
	Preparation Multi-Coat		0.50	5.0	25.00
Total		10 WU/h	21.70	217.0	1,085.00

Material Cost - Paint

	Price SGD
New Part Painting	82.56
New Part Painting - Plastic K1R	135.70
Repair Painting	88.78
Surface-/Blend Paint	60.24
Material-constant Metal Preparation	28.60
Material-constant Multi-Coat	9.30
Material-constant Plastic	9.00
Total	414.18

Spare Parts

				prices as at 2015-09-02/23
Code	Description	Part Number	Supplier	Price SGD
0281	FRONT BUMPER COVER	8V5 807 065 A	GRU	900.00
0340	FRT BUMPER SUPPORT	8V4 807 109 C	BT.	310.00
0410	GRILLE	8V5 853 651	1QP	300.00
0561	LEFT HEADLAMP ASSY	8V0 941 043 D	CRA	920.00
0562	RIGHT HEADLAMP ASSY	8V0 941 044 D		920.00
2581	REAR COVER BUMPER	8V5 807 067 A	GRU	900.00
2605	REAR BUMPER SPOILER	8V5 807 521 B	BT.	140.00
2640	REAR BUMPER SUPPORT	8V5 807 309		290.00
2711	REAR PANEL	8V5 813 331 TB	NN	380.00
2719	REAR PANEL C-MEMBER	8V5 813 307	NN	0.00
2781	L/R OUTER SENSOR	5Q0 919 275 B	GRU	120.00
2782	R/R OUTER SENSOR	5Q0 919 275 B	NN	120.00

Vin's Motor Pte Ltd
#03-03, Sin Ming AutoCity, 160 Sin
Ming Drive
575722

Vin's

Insurer Reference:

Repairer Reference: TP/092019/4040

Date calculated: 10/09/2019 10:22 AM

Full Report

Registration: SJN3963J

Printed: 10/09/2019 10:23 AM

Code	Description	Part Number	Supplier	Price SGD
2783	L/R INNER SENSOR X	5Q0 919 275 B GRU	NN	120.00
2784	R/R INNER SENSOR X	5Q0 919 275 B GRU	NN	120.00
2931	BOOTLID/TAILGATE ?	8V5 827 025 F	BT	1,200.00
2951	BOOT/T.GATE MNTG SET	8V0 098 617 B	KL	0.00
2975	BOOT/TAILGATE LOCK X	4H0 827 505 A	NN	70.00
3013	L/R BADGE /	8P0 853 741	2ZZ	40.00
3019	R/R BADGE /	8X0 853 737 A	2ZZ	40.00
3020	REAR BADGE /	8V7 853 742	2ZZ	50.00
3279	L/R INNER LAMP	8V5 945 093 H		310.00
3280	R/R INNER LAMP	8V5 945 094 H	BR	310.00
3281	L/R LAMP	8V5 945 095 A		410.00
3282	R/R LAMP	8V5 945 096 A		410.00
3413	L/R REFLECTOR X	8V5 945 105 A	NN	20.00
3414	R/R REFLECTOR X	8V5 945 106 A	NN	20.00
4661	L/F SEAT BELT /	8V5 857 705 E		550.00
4662	R/F SEAT BELT /	V04		550.00
7435	COMBI SWITCH MODULE	5Q0 953 549 E	Act	500.00
7445	DRIVER AIRBAG	8V0 880 201 AG 6PS	Act	1,800.00
8833	RR EXHAUST SILENCER X	8V5 253 609 F	NN	500.00
1000	F RH Side Retainer X	Bumper	NN	20.00
1001	F LH Side Retainer X	Bumper	NN	20.00
1002	F RH Headlamp ECU X	Headlamp	NN	290.00
1003	F LH Headlamp ECU X	Headlamp	NN	290.00
1004	AirBag Control Unit	AirBag	Act	850.00
1005	R RH Side Retainer X	Bumper	NN	30.00
1006	R LH Side Retainer X	Bumper	NN	30.00
1007	R Exhaust Chrome X	ExhaustSilencer	NN	180.00
Savings				0.00
Subtotal				14,030.00
Addition(+15.00%)				2,104.50
Total				16,134.50

f: OEM Parts
n: Non-OEM Parts
u: Used parts

7Days.
part by part
before paint photos.

Guo Qiang - 82880282
11/9/19.

Vin's Motor Pte Ltd
#03-03, Sin Ming AutoCity, 160 Sin
Ming Drive
575722

Vin's

Insurer Reference:
Repairer Reference: TP/092019/4040
Date calculated: 10/09/2019 10:22 AM

Full Report
Registration: SJN3963J
Printed: 10/09/2019 10:23 AM

Final Calculation

	SGD	SGD
Parts		
Addition(+15.00%)	14,030.00	13440
Total Parts	2,104.50	2016
		16,134.50
		15456
Labour Time Base 10 WU/h		
Total 247.0 WU X 50.00 SGD/h	1,235.00	665
Alignment		
Fixed Rate	330.00	200
Total of Labour		1,565.00
Paint Work Time Base 10 WU/h		
Labour Cost 217.0 WU X 50.00 SGD/h	1,085.00	725
Material Cost	414.18	389.22
Total Paint Including Material		1,499.18
Repair Cost Excludes GST	21,016.66	19,198.68
GST (+7.0%)		1,343.91
Repair Cost Included GST		20,542.59

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

LMK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:

Vin's

AUTOMOTIVE GROUP

Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722

6453 2121 (4 lines) / 6458 1111 (24 hrs)

6459 9795 / 6459 0433

admin@vinsautogroup.com.sg

www.vinsautogroup.com.sg

Our Ref : TP/092019/4040

Accident date: 8/9/2019

Your Ref : SLD3917Y

Tax Invoice :

Date : 12/9/2019

Motor Claim Department

MSIG INSURANCE (SINGAPORE) PTE LTD

No.4 Shenton Way

#21-01 SGX Centre 2

Singapore 068807

SUPPLEMENTARY COST OF REPAIRS TO

Vehicle No. : SJN3963J

Model : AUDI A3 SEDAN 1.4 TFSI AMBIENTE MY 15

1 pc Front bonnet

/ 07

\$ 1,500.00

\$ 1,500.00

Add 10%

\$ 150.00

\$ 1,650.00

To replace front bonnet

\$ 60.00

To spray paint front bonnet including material

\$ 107.98

\$ 1,817.98

VIN'S MOTOR PTE LTD



13/9/19

Gue Ap.

Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 120038
Main Telephone 6838 2222
Main Fax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 120038
Main Telephone 6388 2223
Main Fax: 6479 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408600
Main Telephone 6388 2223
Main Fax: 6841 1182

Customer Service
Service Appointment 8506 2323
24-Hour Breakdown Service 9628 1223
Email: customer.care@premiumauto.com.sg



TAX INVOICE

Page 1 09:04

Company Reg. No. 199902271W
GST Reg. No. 199902271W

VIN'S MOTOR PTE LTD 160 SIN MING DRIVE #03-03 SIN MING AUTOCITY SINGAPORE 6453 3121		Invoice No: R2071622	Account: V0914		
		Date: 18/09/2019	VIN'S MOTOR PTE LTD 160 SIN MING DRIVE #03-03 SIN MING AUTOCITY SINGAPORE 575722		
		Order: 33029632			
		Term: 60			
Regn No:	Regn Date:	Mileage:	WIP No.: 12775		
Model:	Chassis:	Engine:	Dept: c		
Operator: 124					
	Details	Qty	Unit Price	Amount	
M	ABV3853451AA7F2	GRILLE	1	300.00	300.00
M	ABV5945091	TAIL LIGHT	1	410.00	410.00
M	ABV5845092	TAIL LIGHT	1	410.00	410.00
M	ABV5945093D	TAIL LIGHT	1	310.00	310.00
M	ABV5945094C	TAIL LIGHT	1	310.00	310.00
M	ABV0941773D	HEADLIGHT	1	920.00	920.00
M	ABV0941774D	HEADLIGHT	1	920.00	920.00
M	ABV5827025F	LID	1	1200.00	1200.00
M	ABV0880201DH4F0	AIRBAG	1	1800.00	1800.00
M	ABV6807109E	SEAM	1	310.00	310.00
M	ABV5807309	SEAM	1	290.00	290.00
M	ABV5823029A	HOOD	1	1500.00	1500.00
M	ABV5807067G GRD	COVER	1	900.00	900.00
M	ABV5807065R GRD	COVER	1	900.00	900.00
M	ABV5807521L 989	SPOILER	1	140.00	140.00
M	ABX0653737A 322	INSCRIPTION "TFSI"	1	40.00	40.00
M	ABP0853741 322	NAME PLATE	1	40.00	40.00
M	ABV7853742 322	AUDI SIGN	1	50.00	50.00
M	ABV5857705E V04	SEAT BELT	1	550.00	550.00
M	ABV5857706E V04	SEAT BELT	1	550.00	550.00
M	ASQ0919275H GRD	Sensor	1	120.00	120.00
M	ASQ0959455BJ	MODULE	1	850.00	850.00
M	ASQ0953549E	ELEC.MODULE	1	500.00	500.00
Sub-Total				13680.00	
7% GST				957.60	
Grand Total				14637.60	

Important Note: The above repair estimate is based on an initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Price quoted subjects to 7% GST charges.

Validity: Quotation shown is only applicable within 1 month from the date of quotation.

Payment: Full payment has to be settled via Visa/ Mastercard/ Net/ Cash, upon collection of vehicle.

Received by

For & on behalf of
Premium Automobiles Pte Ltd

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park, 51
Ubi Avenue 1
408933

Insurer Reference:
Repairer Reference: TP/092019/4040
Date calculated: 20/12/2019 9:23 AM

Full Report
Registration: SJN3963J
Printed: 20/12/2019 9:24 AM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	MSIG Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:		Date of Incident:	08/09/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	AUDI
Model:	A3 SALOON (8VS)
Sub Model:	AMBIENTE
Model Sheet Number:	00 5A 13
Registration:	SJN3963J
VIN number:	WAUZZZ8V3F1142733
Odometer:	

Model Specs

FROM 05/2015	R/ASPHERIC D/MIRROR	L/MIRROR CONVEX	BRILLIANCE PACKAGE
STOP-START SYSTEM	DEACTIVATED P/AIRBAG	FRONT BRAKE 288 X 25	AUTO AIR CON
FRONT SCREEN W/WEDGE	REAR PARKING SYSTEM	HEATED DOOR MIRRORS	ELEC FOLD DR MIRRORS
AUTO DIPPING MIRROR	8 SPEAKER	MMI RADIO STANDARD	XENON HEADLAMPS
MULTI FUNC S-WHEEL	HEATED WASHER JETS	HEADLAMP WASHERS	LIGHT-/RAIN SENSOR
EQUIP LEATH/IMIT LEA	STORAGE PACKAGE	AUTO DIPPING MIRROR	DRIVER INFO COLOUR
INTERIOR LAMP PACK	FRONT CENTRE ARMREST	EMISSION STD EURO 6+	HD COOLING
S-TRONIC 7-SPEED	INDEPENT RR SUSPENS	CRUISE CONTROL	TYRES 205/55 WR 16
WHEELS 7J X 16 ALLOY	PHONE SYS BLUETOOTH	GLASS OPTICS TRIM	1.4 LTR 92KW
PREPARE OFF VEHICLE	THREE COAT PEARL		

Vehicle Condition


Vehicle Status

Pre-Accident Damage:

Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
44 05 19 00	R + R FRONT WHEEL (WHEELS)		2.0	10.00
44 05 19 00	R + R REAR WHEEL (WHEELS)		2.0	10.00
63 29 19 00	R + R FRONT BUMPER COVER		9.0	45.00
63 29 55 54	RENEW FRONT BUMPER COVER (COVER REMOVED)		12.0	60.00
	INCLUDES: R + R RADIATOR GRILLE, FRONT SPOILER AND WASHER NOZZLES			
63 10 19 50)	R + R FRONT BUMPER (IMPACT CARRIER) (BUMPER COVER REMOVED)		3.0	15.00
63 10 55 50	RENEW FRT BUMPER REINFORCER		2.0	10.00
94 15 20 50	R + R BOTH HEADLAMPS (FRONT BUMPER COVER REMOVED)		4.0	20.00
	DOES NOT INCLUDE: ADJUST HEADLAMPS			
94 15 56 51	RENEW HEADLAMPS (REMOVED)		4.0	20.00
55 22 19 00	REMOVE/REFIT BONNET PANEL		5.0	25.00
	INCLUDES: ADJUST BONNET CLEARANCES			
55 22 55 50	REPLACE BONNET (WITH BONNET PANEL REMOVED)		7.0	35.00
	INCLUDES: REMOVE/REFIT ALL COMPONENT PARTS			
50 38 19 00)	R + R FRONT LOCK CARRIER (BUMPER COVER REMOVED)		16.0	80.00
	INCLUDES: SOUND INSULATION PAN R + R WHEELHOUSE, RADIATOR AND CONDENSER DETACH + REFIT			
55 90 19 00	R + R BOOTLID		9.0	45.00
	INCLUDES: R + R BOOTLID TRIM, ADJUST BOOTLID			
55 90 55 50	RENEW BOOTLID		11.0	55.00

Code	Description	WU	Price SGD
	(BOOTLID REMOVED)		
63 69 19 01	INCLUDES: R + R ALL PARTS R + R REAR BUMPER COVER	7.0	35.00
63 69 55 52	INCLUDES: R + R TAILLAMPS RENEW REAR BUMPER COVER	5.0	25.00
	(COVER REMOVED)		
	INCLUDES: R + R LOWER SPOILER AND SENSORS		
66 59 55 50	RENEW REAR LOWER BUMPER SPOILER	1.0	5.00
63 50 19 50	R + R REAR IMPACT SUPPORT	3.0	15.00
	(BUMPER COVER REMOVED)		
66 76 19 50	R + R L/R WHEELHOUSE SHELL	2.0	10.00
	(WHEEL REMOVED)		
66 76 19 50	R + R R/R WHEELHOUSE SHELL	2.0	10.00
	(WHEEL REMOVED)		
70 67 19 30)	R + R LEFT LOWER B-PILLAR TRIM	1.0	5.00
70 67 19 20	R + R LEFT UPPER B-PILLAR TRIM	4.0	20.00
70 67 19 30)	R + R RIGHT LOWER B-PILLAR TRIM	1.0	5.00
70 67 19 20	R + R RIGHT UPPER B-PILLAR TRIM	4.0	20.00
70 06 19 00	R + R LUGGAGE COMPARTMENT COVER	2.0	10.00
70 39 19 00	R + R REAR LOCK CARRIER COVER	2.0	10.00
69 11 19 10)	R + R LEFT FRONT THREE POINT SEAT BELT	2.0	10.00
	(B-PILLAR TRIM REMOVED)		
69 11 19 10)	R + R RIGHT FRONT THREE POINT SEAT BELT	2.0	10.00
	(B-PILLAR TRIM REMOVED)		
48 10 19 00	R + R STEERING WHEEL	4.0	20.00
	INCLUDES: REMOVE AIRBAG UNIT		
94 13 19 50	R + R AIRBAG RESET RING	3.0	15.00
	(STEERING WHEEL REMOVED)		
94 15 16 00	ADJUST HEADLAMPS	2.0	10.00
1008	To Reset Programme Programme		80.00*
1009	To Reset AirBag Air Bag		120.00*
Labour Cost		Hrs	WU
Panel / Mechanical Labour		13.30	133.0
Alignment			
Fixed Rate			200.00
Total of Labour			865.00

Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description - THREE COAT PEARL	WU Price SGD
	BONNET NEW PART PAINTING	30.2
	BOOTLID/TAILGATE NEW PART PAINTING	19.6
	FRONT BUMPER COVER NEW PART PAINT K1R	13.5
	REAR COVER BUMPER NEW PART PAINT K1R	17.5
	L/R OUTER SENSOR NEW PART PAINT K1R	4.5
	R/R OUTER SENSOR NEW PART PAINT K1R	4.5
	L/R REARLAMP SUPP SURFACE PAINT	5.9
	R/R REARLAMP SUPP SURFACE PAINT	5.9
	L/R OUTER WHEELHOUSE SURFACE PAINT	4.0
	R/R OUTER WHEELHOUSE SURFACE PAINT	4.0

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	97.24
2931	BOOTLID/TAILGATE NEW PART PAINTING	51.94
0281	FRONT BUMPER COVER NEW PART PAINT K1R	54.16
2581	REAR COVER BUMPER NEW PART PAINT K1R	79.06
2781	L/R OUTER SENSOR NEW PART PAINT K1R	0.62
2782	R/R OUTER SENSOR NEW PART PAINT K1R	0.62
3571	L/R REARLAMP SUPP SURFACE PAINT	1.35
3572	R/R REARLAMP SUPP SURFACE PAINT	1.35
4161	L/R OUTER WHEELHOUSE SURFACE PAINT	2.99
4162	R/R OUTER WHEELHOUSE SURFACE PAINT	2.99

Labour Cost - Paint

Factor	50.00 SGD/h	Hrs	WU	Price SGD
Time Paint			110.0	
Preparation Main Work Metal		2.50	25.0	125.00
Preparation Comp. Work Plastic		0.50	5.0	25.00
Preparation Multi-Coat		0.50	5.0	25.00
Total	10 WU/h	14.50	145.0	725.00

Material Cost - Paint

	Price SGD
New Part Painting	149.18
New Part Painting - Plastic K1R	134.46
Surface-/Blend Paint	8.68
Material-constant Metal Preparation	28.60
Material-constant Multi-Coat	9.30
Material-constant Plastic	9.00
Total	339.22

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-09-02/23	Price SGD
0281	FRONT BUMPER COVER	8V5 807 065 A			900.00
		GRU			
0340	FRT BUMPER SUPPORT	8V4 807 109 C			310.00
0410	GRILLE	8V5 853 651	1QP		300.00
0471	BONNET	8V5 823 029 A			1,500.00
0477	BONNET MOUNTING KIT	8V0 098 615			0.00
0561	LEFT HEADLAMP ASSY	8V0 941 043 D			920.00
0562	RIGHT HEADLAMP ASSY	8V0 941 044 D			920.00
2581	REAR COVER BUMPER	8V5 807 067 A			900.00
		GRU			
2605	REAR BUMPER SPOILER	8V5 807 521 B			140.00
2640	REAR BUMPER SUPPORT	8V5 807 309			290.00
2781	L/R OUTER SENSOR	5Q0 919 275 B			120.00
		GRU			
2782	R/R OUTER SENSOR	5Q0 919 275 B			120.00
		GRU			
2931	BOOTLID/TAILGATE	8V5 827 025 F			1,200.00
2951	BOOT/T.GATE MNTG SET	8V0 098 617 B			0.00

Code	Description	Part Number	Supplier	Price SGD
3013	L/R BADGE	8P0 853 741	2ZZ	40.00
3019	R/R BADGE	8X0 853 737 A		40.00
		2ZZ		
3020	REAR BADGE	8V7 853 742	2ZZ	50.00
3279	L/R INNER LAMP	8V5 945 093 H		310.00
3280	R/R INNER LAMP	8V5 945 094 H		310.00
3281	L/R LAMP	8V5 945 095 A		410.00
3282	R/R LAMP	8V5 945 096 A		410.00
4661	L/F SEAT BELT	8V5 857 705 E		550.00
		V04		
4662	R/F SEAT BELT	8V5 857 706 E		550.00
		V04		
7435	COMBI SWITCH MODULE	5Q0 953 549 E		500.00
7445	DRIVER AIRBAG	8V0 880 201 AG		1,800.00
		6PS		
1004	AirBag Control Unit	AirBag		850.00
f: OEM Parts				Savings 0.00
n: Non-OEM Parts				Subtotal 13,440.00
u: Used parts				Addition(+15.00%) 2,016.00
Total				15,456.00

Final Calculation

	SGD	SGD
Parts		
Addition(+15.00%)	13,440.00	
Total Parts	2,016.00	15,456.00
Labour Time Base 10 WU/h		
Total 133.0 WU X 50.00 SGD/h	665.00	
Alignment		
Fixed Rate	200.00	
Total of Labour		865.00
Paint Work Time Base 10 WU/h		
Labour Cost 145.0 WU X 50.00 SGD/h	725.00	
Material Cost	339.22	
Total Paint Including Material		1,064.22
Repair Cost Excludes GST		17,385.22
GST (+7.0%)		1,216.97
Repair Cost Included GST		18,602.19

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Sep 2019 10:28	10 Sep 2019 10:40	10 Sep 2019 19:00	S\$17,385.22 Edit Estimates	S\$17,385.22 View Rpt		Pending for Survey Report Cancel Case
	Sendback Est	S\$19,198.68	Edit Adj Rpt				
Supp #1	11 Sep 2019 17:17	12 Sep 2019 08:15 S\$1,892.98	12 Sep 2019 08:15			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	YEO BOON LEE , ID: S1663979F, Tel: +6596493372								
Main Claimant:	BEK AIX CHIANG ALVIN , ID: S7423466F								
Vehicle Reg. No.:	SJN3963J	Date of Loss:	08/09/2019 17:00 - :59 [49 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 605347	Policy/Cover. Note No.:	29093079 (Comprehensive) Coverage: 24/08/2018 - 15/12/2019						
Vehicle Reg. No. (Insured):	SLD3917Y	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	Vin's Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive, #03-03, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64532121								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Claimant's Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 10/10/2019]								
Driver/Custodian (Insured):	YEO BOON LEE (55 / Male) , NRIC: S1663979F, Tel: +6596493372 Email:								
Adj Asg. Remarks:	on WP. Manual assigned to LKK via email on 10/09/19. Please contact us ASAP if you cannot attend this assignment. (Manual Assign). Lab: NA. Assign: LKK Auto Consultants Pte Ltd. Contact: 6453 2121 / 6458 1111.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SJN3963J (605347)
[SLD3917Y]
TP
BEK AIK CHIANG ALVIN
Sep 8 2019 5:00PM
[YEO BOON LEE]
Vin's Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	Vin's Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	10/09/19 10:40	Repairer Estimates	 Load HTM	
2	12/09/19 08:15	Repairer Estimates Suppl. #1	 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/09/19 17:13	Adjuster Immediate Advice	 Load HTM	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/09/19 09:25	General View	 Load JPG	☒
2	12/09/19 09:25	General View	 Load JPG	☒
3	12/09/19 09:25	General View	 Load JPG	☒
4	12/09/19 09:25	General View	 Load JPG	☒
5	12/09/19 09:25	General View	 Load JPG	☒
6	12/09/19 09:25	General View	 Load JPG	☒
7	12/09/19 09:25	General View	 Load JPG	☒
8	12/09/19 09:25	General View	 Load JPG	☒
9	12/09/19 09:25	General View	 Load JPG	☒
10	12/09/19 09:25	General View	 Load JPG	☒
11	12/09/19 09:25	General View	 Load JPG	☒
12	12/09/19 09:25	General View	 Load JPG	☒
13	12/09/19 09:25	General View	 Load JPG	☒
14	12/09/19 09:25	General View	 Load JPG	☒
15	12/09/19 09:25	General View	 Load JPG	☒
16	12/09/19 09:25	General View	 Load JPG	☒
17	12/09/19 09:25	General View	 Load JPG	☒
18	12/09/19 09:25	General View	 Load JPG	☒
19	12/09/19 09:25	General View	 Load JPG	☒
20	12/09/19 09:25	General View	 Load JPG	☒
21	12/09/19 09:25	General View	 Load JPG	☒
22	12/09/19 09:25	General View	 Load JPG	☒
23	12/09/19 09:25	General View	 Load JPG	☒
24	12/09/19 09:25	General View	 Load JPG	☒
25	12/09/19 09:25	General View	 Load JPG	☒
26	12/09/19 09:25	General View	 Load JPG	☒
27	12/09/19 09:25	General View	 Load JPG	☒
28	12/09/19 09:25	General View	 Load JPG	☒
29	12/09/19 09:25	General View	 Load JPG	☒
30	12/09/19 09:25	General View	 Load JPG	☒
31	12/09/19 09:25	General View	 Load JPG	☒
32	12/09/19 09:25	General View	 Load JPG	☒
33	12/09/19 09:25	General View	 Load JPG	☒
34	12/09/19 09:25	General View	 Load JPG	☒
35	12/09/19 09:25	General View	 Load JPG	☒
36	12/09/19 09:25	General View	 Load JPG	☒
37	12/09/19 09:25	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Vin's Motor Pte Ltd (Sin Ming)	Thumbnail	Print
38	12/09/19 09:25	General View	 Load JPG	☒
39	12/09/19 09:25	General View	 Load JPG	☒
40	12/09/19 09:25	General View	 Load JPG	☒
41	12/09/19 09:25	General View	 Load JPG	☒
42	12/09/19 09:25	General View	 Load JPG	☒
43	12/09/19 09:25	General View	 Load JPG	☒
44	12/09/19 09:25	General View	 Load JPG	☒
45	12/09/19 09:25	General View	 Load JPG	☒
46	12/09/19 09:25	General View	 Load JPG	☒
47	12/09/19 09:25	General View	 Load JPG	☒
48	12/09/19 09:25	General View	 Load JPG	☒
49	12/09/19 09:25	General View	 Load JPG	☒
50	12/09/19 09:25	General View	 Load JPG	☒
51	12/09/19 09:25	General View	 Load JPG	☒
52	12/09/19 09:25	General View	 Load JPG	☒
53	12/09/19 09:25	General View	 Load JPG	☒
54	12/09/19 09:25	General View	 Load JPG	☒
55	12/09/19 09:25	General View	 Load JPG	☒
56	12/09/19 09:25	General View	 Load JPG	☒
57	12/09/19 09:25	General View	 Load JPG	☒
58	12/09/19 09:25	General View	 Load JPG	☒
59	12/09/19 09:25	General View	 Load JPG	☒
60	12/09/19 09:25	General View	 Load JPG	☒
61	12/09/19 09:25	General View	 Load JPG	☒
62	12/09/19 09:25	General View	 Load JPG	☒
63	12/09/19 09:25	General View	 Load JPG	☒
64	12/09/19 09:25	General View	 Load JPG	☒
65	12/09/19 09:25	General View	 Load JPG	☒
66	12/09/19 09:25	General View	 Load JPG	☒
67	12/09/19 09:25	General View	 Load JPG	☒
68	12/09/19 09:25	General View	 Load JPG	☒
69	12/09/19 09:25	General View	 Load JPG	☒
70	12/09/19 09:25	General View	 Load JPG	☒
71	12/09/19 09:25	General View	 Load JPG	☒
72	12/09/19 09:25	General View	 Load JPG	☒
73	12/09/19 09:25	General View	 Load JPG	☒
74	12/09/19 09:25	General View	 Load JPG	☒
75	12/09/19 09:25	General View	 Load JPG	☒
76	12/09/19 09:25	General View	 Load JPG	☒
77	12/09/19 09:25	General View	 Load JPG	☒
78	12/09/19 09:25	General View	 Load JPG	☒
79	12/09/19 09:25	General View	 Load JPG	☒
80	12/09/19 09:25	General View	 Load JPG	☒
81	12/09/19 09:25	General View	 Load JPG	☒
82	12/09/19 09:25	General View	 Load JPG	☒
83	12/09/19 09:25	General View	 Load JPG	☒
84	12/09/19 09:25	General View	 Load JPG	☒
85	12/09/19 09:25	General View	 Load JPG	☒
86	12/09/19 09:25	General View	 Load JPG	☒
87	12/09/19 09:25	General View	 Load JPG	☒
88	12/09/19 09:25	General View	 Load JPG	☒
89	12/09/19 09:25	General View	 Load JPG	☒
90	12/09/19 09:25	General View	 Load JPG	☒
91	12/09/19 09:25	General View	 Load JPG	☒
92	12/09/19 09:25	General View	 Load JPG	☒
93	12/09/19 09:25	General View	Load JPG	☒

Assessment Reports				1 per page	☒
No	Finalized On	Vin's Motor Pte Ltd (Sin Ming)	Thumbnail	Print	
94	12/09/19 09:25	General View	 Load JPG	☒	
95	12/09/19 09:25	General View	 Load JPG	☒	
96	12/09/19 09:25	General View	 Load JPG	☒	
97	12/09/19 09:25	General View	 Load JPG	☒	
98	12/09/19 09:25	Odometer Reading	 Load JPG	☒	
99	12/09/19 09:25	Chassis Number	 Load JPG	☒	
100	13/11/19 10:19	Dismantled Parts	 Load JPG	☒	
101	13/11/19 10:19	Dismantled Parts	 Load JPG	☒	
102	13/11/19 10:19	Dismantled Parts	 Load JPG	☒	
103	13/11/19 10:19	Dismantled Parts	 Load JPG	☒	
104	13/11/19 10:19	Dismantled Parts	 Load JPG	☒	
105	13/11/19 10:19	Dismantled Parts	 Load JPG	☒	
106	13/11/19 10:19	Dismantled Parts	 Load JPG	☒	
107	13/11/19 10:19	Dismantled Parts	 Load JPG	☒	
108	13/11/19 10:19	Dismantled Parts	 Load JPG	☒	
109	13/11/19 10:19	Dismantled Parts	 Load JPG	☒	
110	13/11/19 10:19	Dismantled Parts	 Load JPG	☒	
111	13/11/19 10:19	Dismantled Parts	 Load JPG	☒	
112	13/11/19 10:19	Dismantled Parts	 Load JPG	☒	
113	13/11/19 10:19	Dismantled Parts	 Load JPG	☒	
114	13/11/19 10:19	Dismantled Parts	 Load JPG	☒	
115	13/11/19 10:19	Dismantled Parts	 Load JPG	☒	
116	13/11/19 10:19	Dismantled Parts	 Load JPG	☒	
117	13/11/19 10:19	Dismantled Parts	 Load JPG	☒	
118	13/11/19 10:19	Dismantled Parts	 Load JPG	☒	
119	13/11/19 10:19	Dismantled Parts	 Load JPG	☒	
120	13/11/19 10:19	Dismantled Parts	 Load JPG	☒	
121	13/11/19 10:19	Dismantled Parts	 Load JPG	☒	
122	13/11/19 10:19	Dismantled Parts	 Load JPG	☒	
123	13/11/19 10:19	Dismantled Parts	 Load JPG	☒	
124	13/11/19 10:19	Dismantled Parts	 Load JPG	☒	
125	13/11/19 10:19	Dismantled Parts	 Load JPG	☒	
126	13/11/19 10:19	Dismantled Parts	 Load JPG	☒	
127	13/11/19 10:19	Dismantled Parts	 Load JPG	☒	
128	13/11/19 10:20	Reinspection Photo	 Load JPG	☒	
129	13/11/19 10:20	Reinspection Photo	 Load JPG	☒	
130	13/11/19 10:20	Reinspection Photo	 Load JPG	☒	
131	13/11/19 10:20	Reinspection Photo	 Load JPG	☒	
132	13/11/19 10:20	Reinspection Photo	 Load JPG	☒	
133	13/11/19 10:20	Reinspection Photo	 Load JPG	☒	
134	13/11/19 10:20	Reinspection Photo	 Load JPG	☒	
135	13/11/19 10:20	Reinspection Photo	 Load JPG	☒	
136	13/11/19 10:20	Reinspection Photo	 Load JPG	☒	
137	13/11/19 10:20	Reinspection Photo	 Load JPG	☒	
138	13/11/19 10:20	Reinspection Photo	 Load JPG	☒	
139	13/11/19 10:20	Reinspection Photo	 Load JPG	☒	
140	13/11/19 10:20	Reinspection Photo	 Load JPG	☒	
141	13/11/19 10:20	Reinspection Photo	 Load JPG	☒	
142	13/11/19 10:20	Reinspection Photo	 Load JPG	☒	
143	13/11/19 10:20	Reinspection Photo	 Load JPG	☒	
Documentation				1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print	
1	10/09/19 15:39	OI SLD3917Y GIA REPORT	 Load PDF		
2	10/09/19 18:01	Manual Assignment	 Load PDF		
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print	
1	10/09/19 18:57	Survey Request - Manual Assigned	 Load PDF		

Assessment Reports				1 per page	☒
No	Finalized On	Vin's Motor Pte Ltd (Sin Ming)		Thumbnail	Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	27/12/19 17:19	S3N 39633 - AUDATEX.pdf	1	Load PDF	
2	16/01/20 17:32	Supplementary	1	Load PDF	

Linked Accident Report Documents

Assessment Reports				1 per page	☒
No	Finalized On	Vin's Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	06/12/19 18:28	Accident Statement	1	Load HTM	
2	06/12/19 18:29	Accident Statement	1	Load HTM	
3	06/12/19 18:29	Accident Statement	1	Load HTM	
4	06/12/19 18:29	Accident Statement	1	Load HTM	
Photos/Images				3 per page	☒
No	Finalized On	Vin's Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	09/09/19 12:27	Accident Photo	1	Load JPG	☒
2	09/09/19 12:27	Accident Photo	1	Load JPG	☒
3	09/09/19 12:27	Accident Photo	1	Load JPG	☒
4	09/09/19 12:27	Accident Photo	1	Load JPG	☒
5	09/09/19 12:27	Accident Photo	1	Load JPG	☒
6	09/09/19 12:27	Accident Photo	1	Load JPG	☒
7	09/09/19 12:27	Accident Photo	1	Load JPG	☒
8	09/09/19 12:27	Accident Photo	1	Load JPG	☒
9	09/09/19 12:27	Accident Photo	1	Load JPG	☒
10	09/09/19 12:27	Accident Photo	1	Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	Vin's Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	09/09/19 11:57	Sketch Plan	1	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Repairer

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19016113/GSF3E2

Date: 16/01/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29093079

Claimant Vehicle No : SJN3963J

Insured Vehicle No : SLD3917Y

Date of Loss: 08/09/2019

Nature of Claim: TP

Claim No: 605347

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJN3963J

Make & Model: AUDI A3, 1.4 TFSI AMBIENTE MY 15 (A)

Engine No: CZC263331

Reg. Date: 21/07/2015 (Man. Year: 2015)

Chassis No: WAUZZZ8V3F1142733

Colour: Grey

Odometer: 95617 km

Engine Capacity: 1395 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size: 225/45 R17

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,859.50	15,456.00	2,403.50	13.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,625.00	865.00	760.00	46.77
Paintwork Labour	1,607.16	1,064.22	542.94	33.78
Towing	0.00	0.00	0.00	
Gross Total (S\$)	21,091.66	17,385.22	3,706.44	17.57
+ GST 7.00/7.00% (S\$)	1,476.42	1,216.97	259.45	17.57
Nett Amount (S\$)	22,568.08	18,602.19	3,965.89	17.57

INSPECTION

Date of Assignment: 10/09/2019

Date Inspected: 11/09/2019 Inspected At:

160 Sin Ming Drive, #08-09

Repairer : Vin's Motor Pte Ltd (Sin Ming)

Estimated Period of Repair: 7.0 days

Adjuster: XING GUO QIANG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Jan 2020)
Parts:	143	AUDI A3 1.4 TFSI AMBIENTE MY 15 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJN3963J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*AirBag Control Unit (WCP)	Activated	850.00 FL	*850.00 F
2	1	NA	*BOOT/T.GATE MNTG SET (NPA)	Necessary	0.00 FL	*- F
3	1	NA	*BOOT/TAILGATE LOCK (WCP)	Not Necessary	70.00 FL	*- F
4	1	NA	*BOOTLID/TAILGATE (WCP)	Bent	1,200.00 FL	*1,200.00 F
5	1	NA	*COMBI SWITCH MODULE (WCP)	Activated	500.00 FL	*500.00 F
6	1	NA	*DRIVER AIRBAG (WCP)	Activated	1,800.00 FL	*1,800.00 F
7	1	NA	*F LH Headlamp ECU (WCP)	Not Necessary	290.00 FL	*- F
8	1	NA	*F LH Side Retainer (WCP)	Not Necessary	20.00 FL	*- F
9	1	NA	*F RH Headlamp ECU (WCP)	Not Necessary	290.00 FL	*- F
10	1	NA	*F RH Side Retainer (WCP)	Not Necessary	20.00 FL	*- F
11	1	NA	*FRONT BUMPER COVER (WCP)	Deformed	900.00 FL	*900.00 F
12	1	NA	*FRT BUMPER SUPPORT (WCP)	Bent	310.00 FL	*310.00 F
13	1	NA	*GRILLE (WCP)	Cracked	300.00 FL	*300.00 F
14	1	NA	*L/F SEAT BELT (WCP)	Activated	550.00 FL	*550.00 F
15	1	NA	*L/R BADGE (WCP)	Necessary	40.00 FL	*40.00 F
16	1	NA	*L/R INNER LAMP (WCP)	Broken	310.00 FL	*310.00 F
17	1	NA	*L/R INNER SENSOR (WCP)	Not Necessary	120.00 FL	*- F
18	1	NA	*L/R LAMP (WCP)	Broken	410.00 FL	*410.00 F
19	1	NA	*L/R OUTER SENSOR (WCP)	Not Working	120.00 FL	*120.00 F
20	1	NA	*L/R REFLECTOR (WCP)	Not Necessary	20.00 FL	*- F
21	1	NA	*LEFT HEADLAMP ASSY (WCP)	Cracked	920.00 FL	*920.00 F
22	1	NA	*R/F SEAT BELT (WCP)	Activated	550.00 FL	*550.00 F
23	1	NA	*R/R BADGE (WCP)	Necessary	40.00 FL	*40.00 F
24	1	NA	*R/R INNER LAMP (WCP)	Broken	310.00 FL	*310.00 F
25	1	NA	*R/R INNER SENSOR (WCP)	Not Necessary	120.00 FL	*- F
26	1	NA	*R/R LAMP (WCP)	Broken	410.00 FL	*410.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
27	1	NA	*R/R OUTER SENSOR (WCP)	Not Working	120.00 FL	*120.00 F
28	1	NA	*R/R REFLECTOR (WCP)	Not Necessary	20.00 FL	*- F
29	1	NA	*REAR BADGE (WCP)	Necessary	50.00 FL	*50.00 F
30	1	NA	*REAR BUMPER SPOILER (WCP)	Deformed	140.00 FL	*140.00 F
31	1	NA	*REAR BUMPER SUPPORT (WCP)	Bent	290.00 FL	*290.00 F
32	1	NA	*REAR COVER BUMPER (WCP)	Deformed	900.00 FL	*900.00 F
33	1	NA	*REAR PANEL (WCP)	Not Necessary	380.00 FL	*- F
34	1	NA	*REAR PANEL C-MEMBER (NPA)	Not Necessary	0.00 FL	*- F
35	1	NA	*R Exhaust Chrome (WCP)	Not Necessary	180.00 FL	*- F
36	1	NA	*RIGHT HEADLAMP ASSY (WCP)	Cracked	920.00 FL	*920.00 F
37	1	NA	*R LH Side Retainer (WCP)	Not Necessary	30.00 FL	*- F
38	1	NA	*RR EXHAUST SILENCER (WCP)	Not Necessary	500.00 FL	*- F
39	1	NA	*R RH Side Retainer (WCP)	Not Necessary	30.00 FL	*- F
40	1	NA	*SUNDRY PARTS (NPA)	Not Necessary	0.00 FL	*- F
Supplementary #1						
41	1		*Bonnet (WCP)	Bent	1,500.00 FL	*1,500.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	15,530.00	13,440.00
- List Item Discount on L Items -15.00/0.00% (S\$)	-2,329.50	0.00
+ Margin on L,N Items 0.00/15.00% (S\$)	0.00	2,016.00
Total Parts (S\$)	17,859.50	15,456.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Total Paint Labour	New	1,085.00	725.00
2	Total Paint Materials	New	414.18	339.22
<u>Labour Items</u>				
3	Total Panel/Mechanical Labour	New	1,565.00	865.00
<u>Supplementary #1</u>				
<u>Paintwork Labour</u>				
4	BONNET	New	65.00	0.00
5	BONNET (Material)	New	42.98	0.00
<u>Labour Items</u>				
6	REMOVE/REFIT BONNET PANEL	New	25.00	0.00
7	REPLACE BONNET (WITH BONNET PANEL)	New	35.00	0.00
Gross Labour Cost (S\$)			3,232.16	1,929.22

Report was unsubmitted during this print-out.

< END OF ESTIMATES >