

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2960/09/19

Your Ref: _____

Date: 11th SEP 2019

MDM LOO CHWEE KIM
BLK 106, #04-335
TAMPINES STREET 11
SINGAPORE 521106

Not Authorized Like
1/5/19
12/9/19
Hdy.
Take photo. Aff.

Estimate cost of repair to TOYOTA COROLLA ALTIS 1.6 (A) Saloon - SKH 5173 D

1 pc front bumper	<i>o/s/ae</i>		\$ 374.40	<i>==</i>
2 pcs front bumper o/s & n/s side retainer	<i>all</i>	@ \$ 41.70	83.40	<i>==</i>
8 pcs front bumper top clips	<i>all</i>	@ \$ 3.90	31.20	<i>---</i>
1 pc front bumper reinforcement			339.70	<i>?</i>
1 pc front bumper damper	<i>n/s</i>		65.00	<i>X</i>
6 pcs front bumper lower clips	<i>all</i>	@ \$ 3.80	22.80	<i>---</i>
1 pc front grille	<i>all</i>		269.70	<i>---</i>
5 pcs front grille clips	<i>all</i>	@ \$ 3.90	19.50	<i>X</i>
1 pc front grille logo emblem	<i>all</i>		39.20	<i>---</i>
2 pcs o/s & n/s head lamp assy	<i>n/s? o/s/ae</i>	@ \$ 331.70	663.40	<i>1 pc</i>
1 pc front number plate & frame	<i>all</i>		60.00	<i>405.1</i>
			<u>\$ 1,968.30</u>	
		Less 25%	\$ 492.08	
			<u>\$ 1,476.22</u>	

To wiring check up & adjust headlight alignment. 40.00 *20*

To respray Tuff-Kote on all affected accident parts. *11* 90.00 *X*

To remove, refix & top up air cond gas for repair & knocking out front support panel & necessary parts. *11* 150.00 *X*

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out front support panel, front o/s & n/s chassis frame member & necessary parts, to weld, renew & align above parts. 750.00 *480*

To putty & respray painting on all affected accident parts. 950.00 *600*

\$ 3,456.22
=====

Dollars : Three Thousand Four Hundred Fifty Six And Cents Twenty Two Only.

HUP MOTOR TRADING & SERVICE

[Signature]

Accepted by Repairer
Signature: _____