

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2960/09/19

Your Ref:

Date: 11th SEP 2019

MDM LOO CHWEE KIM
BLK 106, #04-335
TAMPINES STREET 11
SINGAPORE 521106

Not Authorized
12/9/19
1/5 \$1700
Hdy
the phot. after

Estimate cost of repair to TOYOTA COROLLA ALTIS 1.6 (A) Saloon - SKH 5173 D

1 pc front bumper	<i>DO/OE</i>		\$ 374.40	
2 pcs front bumper o/s & n/s side retainer	<i>all</i>	\$ 41.70	83.40	
8 pcs front bumper top clips	<i>all</i>	\$ 3.90	31.20	
1 pc front bumper reinforcement	<i>R</i>		339.70	<i>X</i>
1 pc front bumper damper	<i>n/s</i>		65.00	<i>X</i>
6 pcs front bumper lower clips	<i>all</i>	\$ 3.80	22.80	
1 pc front grille	<i>one</i>		269.70	
5 pcs front grille clips	<i>all</i>	\$ 3.90	19.50	<i>X</i>
1 pc front grille logo emblem			39.20	
2 pcs o/s & n/s head lamp assy	<i>all n/s n/s</i>	\$ 331.70	663.40	<i>1 pc</i>
1 pc front number plate & frame	<i>all</i>		60.00	<i>405.00</i>
<i>front brace panel</i>				
	<i>1/5/1 set</i>		\$ 1,968.30	
		Less 25%	\$ 492.08	
			<u>\$ 1,476.22</u>	

To wiring check up & adjust headlight alignment.		40.00	<i>30</i>
To respray Tuff-Kote on all affected accident parts.	<i>11</i>	90.00	<i>X</i>
To remove, refix & top up air cond gas for repair & knocking out front support panel & necessary parts.	<i>11</i>	150.00	<i>X</i>
Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out front support panel, front o/s & n/s chassis frame member & necessary parts, to weld, renew & align above parts.		750.00	<i>480</i>
To putty & respray painting on all affected accident parts.		950.00	<i>600</i>
		<u>\$ 3,456.22</u>	

Dollars : Three Thousand Four Hundred Fifty Six And Cents Twenty Two Only.

HUP MOTOR TRADING & SERVICE
[Signature]

1303.40
257
977.55
2127.58
1701