

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5603L**AAD1909-075***Not Notional**Reserve B4 paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

10 SEP 2019

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 5603L

JTDKB3FU703077154

TOYOTA

PRIUS

8.9.19

AIG

4/12/2018

PART**LIST**

1	1	PANEL SUB-ASSY, FRONT DOOR, RH	\$	B ₁	1,264.00	—
2	1	WEATHERSTRIP, FRONT DOOR OPENING TRIM, RH	\$	S ₂	316.90	} X
3	1	CHECK ASSY, FRONT DOOR	\$	S ₂	156.60	
4	1	RUN, FRONT DOOR GLASS, RH	\$	S ₂	151.20	
5	1	WEATHERSTRIP, FRONT DOOR, RH	\$	S ₂	228.10	
6	1	HANDLE ASSY, FRONT DOOR, OUTSIDE RH	\$	S ₂	385.60	
7	1	FRONT DOOR OUTER MOULDING RH	\$	S ₂	188.60	
8	1	MOULDING, FRONT DOOR WINDOW FRAME, FRONT RH	\$	S ₂	38.10	} X
9	1	HINGE ASSY, FRONT DOOR, LOWER RH	\$	N	94.10	
10	1	HINGE ASSY, FRONT DOOR, UPPER RH	\$	N	83.40	
11	1	MOTOR ASSY, POWER WINDOW REGULATOR, RH	\$		791.50	X } NH
12	1	REGULATOR SUB-ASSY, FRONT DOOR WINDOW, RH	\$		235.10	X
13	1	MOULDING ASSY, BODY ROCKER PANEL, RH	\$	N	583.30	X
14	1	REINFORCE SUB-ASSY, ROCKER, OUTER RH	\$	N	572.10	X
15	1	REINFORCEMENT SUB-ASSY, ROCKER PANEL, RH	\$	N	336.60	X
16	1	RIGHT SIDE VIEW MIRROR	\$	S ₂	1,275.52	X
17	1	WIRE, FRONT DOOR, RH	\$	S ₂	454.10	X
18	1	FRAME SUB-ASSY, FRONT DOOR, FRONT LOWER RH	\$	S ₂	142.90	X
19	1	TAPE, BLACK OUT, NO.1 RH	\$	N	13.10	—
20	1	TAPE, BLACK OUT, NO.2 RH	\$	N	42.90	—
21	1	TAPE, BLACK OUT, NO.3 RH	\$	N	25.90	—
22	1	BOARD SUB-ASSY, FRONT DOOR TRIM, RH	\$	S ₂	737.90	X
23	1	FRONT FENDER RH	\$	B ₁	963.80	—
24	1	EXTENSION, FRONT FENDER, RH	\$	S ₂	48.80	X
25	1	COVER SUB-ASSY, FRONT PILLAR, UPR RH	\$	S ₂	98.30	X
26	1	LINER, FRONT FENDER, RH	\$	S ₂	200.70	X
27	1	FRONT FENDER EMBLEM RH	\$	N	86.50	—
28	1	SEAL, FENDER APRON MUDGUARD, RH	\$	S ₂	50.90	X
29	1	PROTECTOR, FRONT FENDER SIDE PANEL, RH	\$	N	92.30	X
30	1	FRONT LED LAMP (LOWER) RH	\$	S ₂	907.75	X

Trans-cab Auto Services Pte Ltd**AAD1909-075**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5603L

31	1	FRONT HEADLAMP RH	\$	<i>Sn</i>	2,909.04	}	<i>X</i>
32	1	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	\$	<i>Sn</i>	492.30		
33	1	MOTOR, HEADLAMP LEVELING, RH	\$	<i>Sn</i>	413.10		
34	1	FRONT BUMPER	\$	<i>Sn</i>	509.10		
35	1	FRONT BUMPER SIDE RETAINER RH	\$	<i>Sn</i>	112.70		
36	1	FRONT BONNET	\$	<i>n</i>	969.00		
37	1	HINGE ASSY, HOOD, RH	\$	<i>n</i>	58.00		
TOTAL			\$		16,029.81		
25%			\$		4,007.45		
			\$		12,022.36		

Special Nett

1	1	FRONT DOOR STICKER "TRANS-CAB"	\$	<i>Net</i>	80.00	<i>601</i>	
2	1	FRONT WHEEL RIM	\$	<i>Sn</i>	1,570.55	<i>X</i>	
3	1	FRONT WHEEL RIM COVER	\$	<i>Net/Net</i>	175.80		
4	1	CLIP, FRONT FENDER LINER	\$	<i>na</i>	22.00	}	<i>X</i>
5	1	BUMPER CLIP FRT	\$	<i>na</i>	66.00		
6	1	WINDSCREEN SEALANT	\$	<i>na</i>	253.80		
7	1	FRONT WINDSCREEN MOULDING	\$	<i>na</i>	120.00		
8	1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i>	100.00		
9	1	FRONT TYRE 195/65/15	\$	<i>Sn</i>	350.00		
TOTAL			\$		2,738.15		

TOTAL PARTS \$ 14,760.51**LABOUR**

To transfer of front door fittings, attachment and perform water seepage test.

\$ 170.00 *601*

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 6,000.00 *4001* ~~6001~~

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ *na* 380.00 *X*

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ *na* 380.00 *X*

Trans-cab Auto Services Pte Ltd**AAD1909-075**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5603L

To Rust-Proofing Of The Affected Areas.	\$	170.00	601
Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	6601
To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of Fender fittings, attachments and perform water seepage test.	\$	170.00 170.00	X
To transfer of Front Bumper fittings, attachments and perform water seepage test.	\$	170.00 170.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00 170.00	X
To check steering geometry and computer wheel alignment	\$	220.00 220.00	X
To transfer of front windscreen glass to facilitate bodywork repair.	\$	170.00 170.00	X
To check Electrical Lighting concerned.	\$	170.00 170.00	X
TOTAL	\$	14,340.00	
Over All Total	\$	29,100.51	

(PART-BY-PART) Repair Days~~20 days~~

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: