



SMRT Accident Vehicle Repair Estimates

NTUC

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672


Date Generated : 09/09/2019

User ID : BoonChewTay

Section A - Accident Details



Registration Number	SMB3529H
Case Reference Number	BUS/09/19/1020
Registration Date	1/9/2014
Company Type	SMRT Buses Ltd
Make	ALEXANDER DENNIS
Model	ENVIRO 500
Name of Driver	Choo Liang San
Type of Accident	Side Swipe
Accident Date and Time	3/9/2019 4:15 PM
Accident Reported Date and Time	3/9/2019 6:45 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB3529H - RIGHT FRONT PORTION SMC2703Y (TP) - INSURED WITH NTUC
Prepared Date and Time	9/9/2019 11:47 AM
Chassis Number	SFD76CLR5EMTL3458
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,060.00	\$0.00
Total Spray Cost	\$538.00	\$0.00
Total Spare Part Cost	\$850.61	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$2,448.61 <i>2779.40</i>	\$0.00
Lump Sum Total	\$2,450.00	\$0.00
Number of Repair Days	4.0	<i>3.0</i>
Prepared / Adjusted By	ARC Manager Team	
ARC / Surveyor Sign Off Date	09/09/2019 11:52 AM	
Signature		<input checked="" type="checkbox"/>
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



STEW (CLKK)
WZ Pajol
9/9/19, 2-7/14
L/S
Ry AL SP
3 dgs
12/9/19



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 09/09/2019

User ID : BoonChewTay

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,060.00	793
Total Labour	\$1,060.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$538.00	446
Total Spray Painting & Panel Beating	\$538.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6011052	BODY RH	20590172/2	BUMPER CORNER: R/H, FOR ADL E500 DD BUS	1.00	\$1,181.40	10.00	\$1,063.26	Replace	OR
Total					\$1,181.40		\$1,063.26		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

795
446
1063.26
2394.26
L/S - 1843.40
= 1850

2729.49