

Tiong Chun Motor Service

Blk 1 #01-135, Sin Ming Industrial Estate, Sector C

Singapore 575636. Tel: 6453-0895

Reg. No: 52827803K

62247478

TO:

China Taiping Insurance (S) Pte Ltd

19/09/2019

Attn: Mr. Alfred

Estimate cost of repair to Kia Cerato - SJW 7414D

To supply:-

- 1 pce. Frt. Lh headlamp
- 1 pce. Frt. Bumper
- 1 pce. Frt. Bumper lh fog lamp
- 1 pce. Frt. Bumper lh retainer
- 1 pce. Frt. Griller
- 1 pce. Frt. Lh fender
- 1 pce. Frt. Lh fender bottom shield
- 1 pce. Frt. Lh knuckle arm
- 1 pce. Frt. Lh shock absorber
- 1 pce. Frt. Lh lower arm.
- 1 pce. Frt. Lh wheel bearing
- 1 pce. Frt. Cross member
- 1 pce. Frt. Lh drive shaft
- 1 pce. Frt. Tie rod
- 1 pce. Frt. Lh tie rod end
- 1 pce. Frt. Suppor panel
- 2 pcs. Frt. Rh & lh tyre rims
- 1 pce. Frt. Lh tyre
- 1 pce. Steering air-bag
- 2 pcs. Frt. Rh & lh safety belts
- 20 pcs. Clips.

Towing fee

- to dismantle frt. Lh undercarriage, replace and refix same.
- to remove, cut-out damaged parts, panel beating, m straighten , replace & refix body damaged parts.
- to putty and spray painting
- to check wiring & focus headlamp
- to check wheel alignment
- to reset air bag

total repair at lump sum basis amounted \$5,800

