

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 11592

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1098/2019/NS
Date	:	11-Sep-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Ms Siti Anis
Address	:	Blk 317 Ang Mo Kio Street 31 #06-205 Singapore 560317
Telephone	:	(HP) +65 90057534
Type of Claim	:	Own Damage Claims
Policy No.	:	
Vehicle No	:	SLT 7955 B
Model Code	:	Audi A4 Sedan 1.4 TFSI S
Model / Year	:	13/11/2017
Engine No	:	CVN 041484
Chassis No	:	WAUZZZF44HA182509
Mileage	:	
Date In	:	
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	7-Sep-19
Place of Accident	:	The Waterina Lor 40 Geylang

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLT 7955 B

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear parking aid and rear lid kick sensor. Check function.	S/N	\$ 360.00 ✓	
2	To renew rear windscreen and lhs 1/4 glass to facilitate fender renewal.	S/N	\$ 600.00 ✓	
3	To install rear windscreen solar film	S/N	\$ 400.00 ✓	
4	To remove and transfer lhs rear door's multi-lock system and power window devices. Inspect for damages.	S/N	\$ 280.00 ✓	
5	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N	\$ 1,400.00 ✓	
SUB TOTAL LABOUR CHARGES		:	<u>\$ 3,040.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLT 7955 B

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
6	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	S/N \$ 1,400.00 ✓	
7	To dismantle rear bumper, rear lid and lhs rear door. Cut out and weld lhs rear fender. Renew lhs rear door. Re-organise crash management components. Reinstall all parts removed.	\$ 6,300.00 3550	
8	To respray rear bumper, lhs rear fender, lhs rear door, lhs silt panel, (door entrances, roof channel,) door handle, drain panel and end panelling. To carry out stone chip treatment and joint sealer works.	\$ 5,700.00 2575. 4.54 x 550 = 2495 Handle = 100	
9	To carry out diagnostic checks.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: <u>\$ 16,632.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 7955 B

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR FENDER SIDE PANEL - LH <i>Dented</i>	\$ 2,443.00 ✓	1954.40
2	REAR WINDSCREEN	\$ 1,049.00 ✓	839.20
3	PRIMER	\$ 19.00 ✓	14.88
4	SIDE WINDOW - LH	\$ 561.00 ✓	448.40
5	REAR DOOR - LH <i>Dented</i>	\$ 2,152.00 ✓	1721.60
6	OUTER DOOR SEAL <i>Nec</i>	NEC \$ 185.00 ✓	147.60
7	BONDING AGENT <i>Not Nec</i>	NEC \$ 45.00 ? X	
8	CLEANING SOLUTION <i>Not Nec</i>	NEC \$ 65.00 ? X	
9	REAR DOOR SEALING STRIP <i>Not Nec</i>	\$ 15.00 X	
10	REAR DOOR CATCH <i>Nec</i>	\$ 109.00 X	
11	REAR DOOR ATTACHMENT PARTS <i>Not Nec</i>	\$ 515.00 ? X	
12	DOOR HANDLE TRIM PLATE - LH <i>Not Nec</i>	\$ 80.00 X	
13	DOOR HANDLE SENSOR - LH <i>Nec</i>	\$ 208.00 X	
14	REAR PERIPHERAL LIGHT - LH <i>Nec</i>	\$ 66.00 X	
15	EXTERIOR DOOR HANDLE - LH <i>Cut</i>	\$ 35.00 ✓	27.52
16	REAR DOOR MOUNTING BAR - LH <i>Nec</i>	\$ 149.00 X	
17	REAR BUMPER GUIDE SECTION - LH <i>Not Nec</i>	\$ 40.00 X	
18	WHEEL HOUSING LINER - LH <i>Not Nec</i>	\$ 223.00 X	
19	WHEEL HOUSING LINER ATTACHMENT PARTS <i>Not Nec</i>	\$ 82.00 X	
20	ACRYLIC SEALANT	\$ 180.00 ✓	
21	CAVITY WAX	\$ 140.00 ✓	
22	STONE CHIP	\$ 180.00 ✓	
23	METAL FILLER POWDER	\$ 280.00 ✓	
24	REAR WINDSCREEN SEALANT	\$ 200.00 ✓	
25	1/4 GLASS SEALANT	\$ 100.00 ✓	
26	SUNDRIES <i>Nec</i>	\$ 400.00 ?	16.64
TOTAL SPARE PARTS		: \$ 9,521.00	
TOTAL LABOUR CHARGES		: \$ 16,632.00	
GRAND TOTAL		: \$ 26,153.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 12/09/19
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 13 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant