

H/lin Tony



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd	
80 Woodlands Industrial Park E4 Singapore 757706	
FAX Number	63685582
Estimator Telephone Number	68662623
Accident Reporting Number	68662672

Date Generated : 11/08/2019

User ID : GohKK2

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope				Quotation from AR		Adjusted by Surveyor, if applicable			
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS				\$1,060.00		530			
Total Labour				\$1,060.00					
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope				Quotation from ARC		Adjusted by Surveyor, if applicable			
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS				\$432.00		262			
Total Spray Painting & Panel Beating				\$432.00					
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope				Quotation from ARC		Adjusted by Surveyor, if applicable			
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6013598	VE	36-25275-6004	REAR LAMP BULB (A95 MAN)	1.00	\$245.00	10.00	\$220.50	Replace	✓ MT
6013425	Body	155-2-2-006009	O/S FRP REAR LAMP COVER	1.00	\$975.00	100.00	\$0.00	Repair	✓
Total					\$1,220.00		\$220.50		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

LGK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

PIP - 101250

