





SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 11/09/2019

User ID : GohKK2

Section A - Accident Details	
Registration Number	SG5869R
Case Reference Number	BUS/09/19/1028
Registration Date	18/12/2017
Company Type	SMRT Buses Ltd
Make	MAN
Model	A95
Name of Driver	Liu Changyue
Type of Accident	Side Swipe
Accident Date and Time	9/9/2019 10:10 AM
Accident Reported Date and Time	11/9/2019 11:40 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC,if any	SG5869R-RIGHT REAR PORTION SH8943J (TP) INSURED WITH III
Prepared Date and Time	11/9/2019 2:11 PM
Chassis Number	WMAA95ZZXG7003548
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,060.00	\$0.00
Total Spray Cost	\$432.00	\$0.00
Total Spare Part Cost	\$220.50	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$1,712.50	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	3.0	
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	11/09/2019 2:18 PM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 11/09/2019

User ID : GohKK2

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.			\$1,060.00						
Total Labour			\$1,060.00						
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS			\$432.00						
Total Spray Painting & Panel Beating			\$432.00						
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6013598	VE	36-25225-6004	REAR LAMP BULB (A95 MAN)	1.00	\$245.00	10.00	\$220.50	Replace	
6013425	Body	155-2-2-009009	O/S FRP REAR LAMP COVER	1.00	\$975.00	100.00	\$0.00	Repair	
Total					\$1,220.00		\$220.50		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									