

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19016173/KGS3Q2

Date: 29/10/2020

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MPC0000563
Claimant Vehicle No :	GBC7483D	Insured Vehicle No :	SKC1896D
Date of Loss:	19/08/2019	Nature of Claim:	TP
		Claim No:	MPC2019D0000956

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBC7483D		
Make & Model:	TOYOTA HIACE, 2.5 (A)	Engine No:	1KD2324409
Reg. Date:	14/10/2013 (Man. Year: 2013)	Chassis No:	JTFPT22P900011971
Colour:	Beige	Odometer:	116591 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	195 R15X8
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,972.00	1,438.25	1,533.75	51.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,400.00	660.00	740.00	52.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,372.00	2,098.25	2,273.75	52.01
Approved Total (Overridden) (S\$)		1,650.00		
(S\$)	4,372.00	1,650.00	2,722.00	62.26
+ GST 7.00/7.00% (S\$)	306.04	115.50	190.54	62.26
Nett Amount (S\$)	4,678.04	1,765.50	2,912.54	62.26
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,947.50		
Global Sum Settlement (S\$)		1,900.00		

INSPECTION

Date of Assignment: 12/09/2019

Date Inspected: 13/09/2019 Inspected At:

Mega Auto Pte Ltd (Sin Ming)
160 Sin Ming Drive #02-01 Auto City
Singapore 575722

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 01 Apr 2020)	
Parts:	N/A	TOYOTA HIACE 2.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC7483D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP RH	Cut	800.00 FL	*800.00 FL
2	1		*FRONT CORNER PANEL RH	Repair	265.00 FL	*- FL
3	1		*FRONT BUMPER	Dented /Cut	530.00 FL	*530.00 FL
4	10		*FRONT BUMPER CLIPS	Necessary	35.00 FL	*35.00 FL
5	1		*FRONT BUMPER RETAINER RH	Serviceable	155.00 FL	*- FL
6	1		*SIDE MIRROR RH	Dented /Cut	450.00 FL	*450.00 FL
7	1		*FRONT DOOR RH	Repair	1,625.00 FL	*- FL
8	1		*FRONT DOOR STICKER RH 966038	Necessary	15.00 FS	*15.00 FS
9	1		*FRONT DOOR STICKER RH THE WORLD ON TIME	Necessary	40.00 FS	*40.00 FS
10	1		*FRONT DOOR COMPANY STICKER	Necessary	22.00 FS	*22.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,937.00	1,892.00
- List Item Discount on L Items 25.00/25.00% (S\$)	965.00	453.75
Total Parts (S\$)	2,972.00	1,438.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	STRAIGHTEN AND PANEL BEAT ACCIDENT AREA	New	600.00	360.00
2	RESPRAY ACCIDENT AREA	New	800.00	300.00
Gross Labour Cost (\$)			1,400.00	660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >