

ASS. REC. BY:

REF:

23/FCT19016187/Aqd3n2

Special Instruction:

Senior: Achan

## ASSIGNMENT (Office)

From (Person): Karen Tanof FCTDate/Time: 11/09/2019 @ 9.2

Estimated Cost: \_\_\_\_\_

Bill to: \_\_\_\_\_

OD  / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: \_\_\_\_\_

SQL906R

Insured: \_\_\_\_\_

SHA 1886D

at Workshop m/s \_\_\_\_\_

TICK-HUI MOTOR

Tel: \_\_\_\_\_

68429089of 1 Kaki Bukit Ave 6 # 01-SF Autobay

Policy No: \_\_\_\_\_

Claim No: \_\_\_\_\_

D19005859MFSH

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_

(Client's Record)

D.O.A. \_\_\_\_\_

08/09/2019

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 9:26am @ 12/9/19

Person Contacted: \_\_\_\_\_

connieVehicle  IN  OUT

Date/Time	Action/Instruction	Follow up
	SQL906R - NA / INCL 4005573 / 0 / 1	✓
	SHA 1886D - NS / INCL 6007725 / H / qhd 1	
13/9/19 @ 3.36pm	informed Karen Tan, we are pending estimate from repairer.	
02/12/19 @ 11.25am	revised to Karen Tan by email.	
	LS @ 4500, 12 days. (Red @ 13496.09, 76%)	

FCI

ASSIGNMENT

From: \_\_\_\_\_ Date: 12/9/19

Estimated Cost: \_\_\_\_\_

OD  WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SGL 906R

at Workshop no: Pick Hai Motor

of 1 Kaki Bukit Ave 6 # 01-54 Autobuy

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : **Yes or No**

GIA / PR Seem: \_\_\_\_\_ Consistent? : **Yes or No**

Est. Repair: 12 days Res: **Yes or No**

Lum Sum: \_\_\_\_\_ % 3 Val: **Yes or No**

CA / REV / REP. / 24 HRS Cup

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: **IN / OUT**

Veh No: SGL906R Tr Regn: 2006 August

Type:  M.Cab / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda Airwave C.C. 1496

Colour: Black A/C: **Insured / Std / NI / NA**

Sp. Reading: \_\_\_\_\_ T/Radio: **Insured / Std / NI / NA**

EngNo: \_\_\_\_\_

C/No: GJ1106298

Gen. Cond: **Good / Fair / Poor / Burnt**

Steering:  Inorder / Jammed / Leaked / Burnt or

Brake:  Inorder / Jammed / Leaked / Burnt or

Modi: **Nil / S/Rim / STD A/Rim or**

Tyre Size: F: 185/55R16  
R: 185/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO /  YOKO or

Front		Rear	
R/Bal. <u>06</u> mm		R/Bal. <u>06</u> mm	
L/Bal. <u>06</u> mm		L/Bal. <u>06</u> mm	
D.O.A. _____		D.O.I. <u>12/09/19</u>	

Survey held at: Pick Hai

Des. of Damages:  Frt / Rear / O/S / N/S / UIC / Rooftop or

The **UIC / Chassis frame / Body Structure** affected due to collision.

Date / Time	Action / Instruction
	<u>TP 1st Cap.</u>
	<u>CoE Expiry: 30/06/21</u>
<u>12/9</u>	<u>MV: 13:1K (Depreciation @ 6k+)</u>
	<u>LTA: 8.4K 5361</u>
	<u>Net: 4.6K. 4639.</u>
<b>RECEIVED 3 DEC 2019</b>	

Date/Time, File Pass to?  : Prel. Report  : Final Report

12/12 turn in

Date/Time, File Return to? \_\_\_\_\_

Days Of Repair: 12

Resurvey No. of Trip: 2

Survey Fee: 170 + 120

Transportation: 50

S + RS: 30 + 50

Other: 49

Net: 489

Report Format: TP

Emp. Fee: 4500

Add Fee:  Site Insp (\$)  Interview (\$)  Tech. Insp (\$)  Work stud (\$)

Date: 12/12/19



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL.: (065) 62563561 FAX : (065) 62564315

Your Ref: D19005859MFSH

Date: 02 December 2019

Our Ref: CS/FCI19016187/Aqd3

The Motor Claims Department  
MS First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SGL 906R.**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 12/09/2019 at the premises of M/s TICK HAI MOTOR, and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 18,496.05</u>
Revised Estimate Amount	: <u>S\$ 4,500.00 (Lump Sum)</u>
"Check" Items Amount	: <u>S\$ -</u>
Market Value	: <u>S\$ -</u>
LTA Reimbursement Value	: <u>S\$ -</u>
Nett Value	: <u>S\$ -</u>

**Description of Damage:**

The vehicle sustained damages at the front portion.



Yours faithfully

ADRIAN LING WAI PING  
*B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI*  
Licensed Appraiser

**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	10-09-2019	<b>Our Ref No.</b> D19005859MFSH
<b>Accident Date</b>	08-09-2019	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHA1886D	<b>Third Party Vehicle.</b> SGL906R
<b>Survey Location</b>	1 KAKI BUKIT AVENUE 6 #01-54AUTOBAY @ KAKI BUKIT	
<b>Contact Person.</b>	MS CONNIE SEE	
<b>Contact No.</b>	68429089/ 0	<b>Fax No.</b> 0
<b>Survey Type</b>	WITHOUT PREJUDICE:	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

<b>Cc : Workshop</b>	TICK HAI MOTOR & WELDING SERVICES	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	ARIDAS & ASSOCIATES	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	KARENT	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Monday, 2 December 2019 11:25 AM  
**To:** 'CWS Motor Claims'; assignments  
**Cc:** 'Karen Tan'; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D19005859MFSH/1  
**Attachments:** CSFC119016187Aqd3.pdf

Dear Karen,

Enclosed herewith preliminary advice of SGL 906R.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Shiau Chan (LKKAuto) <[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)>  
**Sent:** Friday, 13 September 2019 3:36 PM  
**To:** 'CWS Motor Claims' <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** 'Karen Tan' <[karentan@msfirstcapital.com.sg](mailto:karentan@msfirstcapital.com.sg)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: SURVEY ASSESSMENT - D19005859MFSH/1

Dear Karen,

Please be informed that we have inspected the vehicle SGL 906R on 12/09/2019.

We are pending for estimate from repairer.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Sent:** Thursday, 12 September 2019 9:32 AM  
**To:** 'CWS Motor Claims' <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** 'Karen Tan' <[karentan@msfirstcapital.com.sg](mailto:karentan@msfirstcapital.com.sg)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: SURVEY ASSESSMENT - D19005859MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Friday, 13 September 2019 3:36 PM  
**To:** 'CWS Motor Claims'; assignments  
**Cc:** 'Karen Tan'; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D19005859MFSH/1

Dear Karen,

Please be informed that we have inspected the vehicle SGL 906R on 12/09/2019.

We are pending for estimate from repairer.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [sjewsc@lkkauto.com](mailto:sjewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Sent:** Thursday, 12 September 2019 9:32 AM  
**To:** 'CWS Motor Claims' <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** 'Karen Tan' <[karentan@msfirstcapital.com.sg](mailto:karentan@msfirstcapital.com.sg)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: SURVEY ASSESSMENT - D19005859MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

**G.NIVITHA**

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Wednesday, 11 September 2019 5:32 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** CWS Motor Claims <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; Karen Tan <[karentan@msfirstcapital.com.sg](mailto:karentan@msfirstcapital.com.sg)>  
**Subject:** PRI: SURVEY ASSESSMENT - D19005859MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

**FOR SALE BY OWNER**

Post an Advertisement  
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

**Volkswagen Scirocco 1.4A TSI (New 5-yr COE) At \$39800.**



Extremely Well Maintained And Serviced. Rare Scirocco In This Condition!

[Call For More Info](#) [StarAd](#)

Think One Automobile

**NEW & USED COMMERCIAL VEHICLES**



Browse by Category Save Search Print Sort by Date Posted 20 results/page

16 vehicles  [Advanced Search](#) [Search](#) [View All](#)

Search Selection	Airwave	Any	Any	> 10 year(s) old	Any	Any	Any	Available
------------------	---------	-----	-----	------------------	-----	-----	-----	-----------



**Honda Airwave 1.5A (COE till 05/2026)** **\$37,000** **\$5,530 /yr** **20-May-2006** **1,496 cc** **275,000 km** **Stationwagon** **Available**

Consignment Code: A299. Flexible And Attractive Loan Packages Available To Choose From. Trade-Ins Available For Your Car! No Hidden Costs. For Further Information Or If You Have Any Questions Please Do Not Hesitate To Contact Us.

[Posted: 02-Aug-2019](#) [Tags: 2006 Honda Airwave, 2006 Honda Airwave, Honda Airwave, Honda Airwave, Honda Airwave, Honda Airwave, Honda Airwave, Used Honda](#)

[Consignment](#)



**Honda Airwave 1.5A (COE till 07/2021)** **\$12,000** **\$6,370 /yr** **04-Aug-2006** **1,496 cc** **-** **Stationwagon** **Available**

Consignment Code: A350. Flexible And Attractive Loan Available. Trade-In Available For Your Car! No Hidden Costs. For Further Information Or If You Have Any Questions Please Do Not Hesitate To Contact Us.

[Posted: 06-Sep-2019](#) [Tags: 2006 Honda Airwave, 2006 Honda Airwave, Honda Airwave, Honda Airwave, Honda Airwave, Honda Airwave, Used Honda](#)

[Consignment](#)



**Honda Airwave 1.5A M (COE till 01/2028)** **\$44,800** **\$5,340 /yr** **19-Mar-2008** **1,496 cc** **112,000 km** **Stationwagon** **Available**

Well Maintained With No Expenses Spared, Regular Servicing Done. No Repairs Needed. Good To Go For The Many More Years To Come. Safe Buy. Minimum Value To Lose. Feel Free To WhatsApp Me For Viewing.

[Posted: 08-Sep-2019](#) [Tags: 2008 Honda Airwave, 2008 Honda Airwave, Honda Airwave, Honda Airwave, Honda Airwave, Honda Airwave, Used Honda](#)



**Honda Airwave 1.5A (COE till 05/2023)** **\$23,800** **\$6,440 /yr** **23-May-2008** **1,496 cc** **118,000 km** **Stationwagon** **Available**

Well Maintained By Previous Owner! High Loan With High Trade In Available. Price Negotiable. Call Now Or Visit Our Showroom Today.

[Posted: 10-Aug-2019](#) [Tags: 2008 Honda Airwave, 2008 Honda Airwave, Honda Airwave, Honda Airwave, Honda Airwave, Honda Airwave, Used Honda](#)

**GET YOUR COE RENEWAL LOAN**

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



**Honda Airwave 1.5A M (COE till 05/2028)** **\$42,800** **\$4,910 /yr** **04-Jul-2008** **1,496 cc** **121,343 km** **Stationwagon** **Available**

1 Owner, Tip Top Condition, Low Mileage, Best Unit In The Market, 100% In-house Loan At Low Interest, Call Us Now.

[Posted: 10-Sep-2019](#) [Tags: 2008 Honda Airwave, 2008 Honda Airwave, Honda Airwave, Honda Airwave, Honda Airwave, Honda Airwave, Used Honda](#)

[Pre-owned Ad](#)



**Honda Airwave 1.5A M (COE till 10/2028)** **\$45,500** **\$5,010 /yr** **13-Oct-2008** **1,496 cc** **126,783 km** **Stationwagon** **Available**

New Coat Of Paint, New Headunit, Fog Lights, Fully Serviced. Well Maintained. Great Boot Space For PDVL!

[Posted: 10-Sep-2019](#) [Tags: 2008 Honda Airwave, 2008 Honda Airwave, Honda Airwave, Honda Airwave, Honda Airwave, Honda Airwave, Used Honda](#)



**Honda Airwave 1.5A M (COE till 11/2023)** **\$26,800** **\$6,420 /yr** **14-Nov-2008** **1,496 cc** **77,953 km** **Stationwagon** **Available**

BodyKit With Upgraded Sports Rims! Totally Enhance This Wagon To Look So Much Cooler And Sporty Inside Out! Severely Under priced As Owner 2nd Car To Transport Bicycle For Weekend Family Outing Only! Guaranteed You This The Best Airwave You Can Find!

[Compare \(4\)](#)

[Pre-owned Ad](#)

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Details	
Owner ID Type:	Company
Owner ID:	72BH
Vehicle Details	
Vehicle No.:	SGL906R
Vehicle to be Exported:	Yes
Intended Deregistration Date:	12 Sep 2019
Vehicle Make:	HONDA
Vehicle Model:	AIRWAVE 1.5 A
Primary Colour:	Black
Manufacturing Year:	2006
Engine No.:	L15A5107898
Chassis No.:	GJ11106298
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$15,824.00
Original Registration Date:	31 Aug 2006
First Registration Date:	31 Aug 2006
Transfer Count:	3
Actual ARF Paid:	\$17,407.00
PARF Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Details	
COE Expiry Date:	30 Jun 2021
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$23,227.00
COE Rebate Amount:	\$8,361.00
Total Rebate Amount:	\$8,361.00
Message	

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 12 Sep 2019

OK



**159 TICK HAI MOTOR**  
**1 KAKI BUKIT AVE 6 #01-20 SINGAPORE 417883**  
**TEL: 6842 9089 FAX: 6841 2869**  
**REG NO : 53033608A**

Vehicle Number: SGL906R  
 Vehicle Model : Honda Airwave 1.5 A  
 Manufacturing Year : 2006  
 Chassis : GJ11106298

TP 1st Cap.  
 Xiao Chen.

GJ11106298

S/N.	Item Description	Amount (\$)
1	Front Bumper <i>Distorted</i>	\$ 710.60
2	Front Bumper Lower Grille <i>Missing</i>	\$ 220.00
3	Front Bumper Side Retainer x 2 pcs <i>NCC</i>	\$ 116.40
4	Front Grille <i>crushed</i>	\$ 362.30
5	Front Honda Centre Logo <i>New</i>	\$ 21.30
6	Front Bumper Reinforcement <i>Best</i>	\$ <del>702.20</del> 338
7	Front Bumper Reinforcement Bracket x 2 pcs <i>Not New</i>	\$ 305.20
8	Headlamp x 2 pcs <i>cracked</i>	\$ 1,254.40
9	Front Bonnet <i>Distorted</i>	\$ 975.10
10	Front Bonnet Hinge x 2 pcs <i>Best.</i>	\$ 46.06
11	Front Bonnet Chrome <i>Missing</i>	\$ 128.60
12	Front Bonnet Lock <i>Damaged</i>	\$ 80.25
13	Wiper Garnish (Centre) <i>2nd</i>	\$ 240.75
14	Wiper Garnish (Side) x 2 pcs <i>1st</i>	\$ 128.40
15	Wiper Tank <i>2nd New</i>	\$ 72.23
16	Front Fender x 2 pcs <i>LH Buckled</i>	\$ <del>940.60</del> 7030
17	Front Fender Inner Garnish x 2 pcs <i>Not New</i>	\$ 144.46
18	Front Support <del>Panel</del> <i>Distorted</i>	\$ 628.10
19	Front Support Panel Top Garnish <i>2nd</i>	\$ 95.20
20	Radiator <i>Distorted</i>	\$ 433.35
21	Radiator Fan Cowling Assy <i>Smashed</i>	\$ 717.44
22	Radiator Top Hose <i>twisted</i>	\$ 19.26
23	Radiator Bottom Hose <i>Not New</i>	\$ 24.08
24	Air Con Condenser <i>Distorted</i>	\$ 793.20
25	Air Con Cowling Assy <i>smashed</i>	\$ 678.92
26	Dashboard Airbag	\$ 1,091.40
27	Steering Airbag <i>Activated</i>	\$ 963.00
28	Airbag Control Unit	\$ 738.30
29	Front Windscreen <i>cracked</i>	\$ 856.52
30	Front Windscreen Moulding <i>NCC</i>	\$ 121.20
31	Front Seatbelt x 2 pcs <i>Activated</i>	\$ 642.35

12495.55  
 9996.44

	<b>Total :</b>	<b>\$ 14,251.17</b>
	<b>Less 10% :</b>	<b>\$ 1,425.12</b>
	<b>Amount :</b>	<b>\$ 12,826.05</b>

S/N	Special Nett Item	Amount (\$)
1	Front Number Plate With Casing <i>missing</i>	\$ 60.00 ✓
2	Radiator Coolant <i>gale</i>	\$ 100.00 40
3	Windscreen Sealant	\$ 80.00 60
	<b>Amount :</b>	<b>\$ 240.00</b> 160

Labour	Amount (\$)
To towing	\$ 150.00 60
To check front electrical system, repair wire harness & focus headlamp.	\$ 120.00 30
To remove, replace and reinstall a/c condenser & a/c pipings.	\$ 150.00 60
To remove, replace and reinstall radiator & cooling system.	\$ 120.00 60
To remove, and reinstall undercarriage	\$ 450.00 X
To remove, replace and reinstall front windscreen.	\$ 240.00 120
To remove & reinstall dashboard for necessary repairs.	\$ 400.00 220
To conduct chassis alignment	\$ 300.00 280
To spray anti-rust coating on new and affected panels.	\$ 200.00 100
Labour to remove, cut, change & panel beating	\$ 1,800.00 1200
To putty and respray affected areas	\$ 1,500.00 1200
<b>Labour Total :</b>	<b>\$ 5,430.00</b> 3330
<b>Total (Parts &amp; Labour) :</b>	<b>\$ 18,496.05</b>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Total: 13886.44

w/s: 45K

12 Days.




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19016187/Aqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 02-12-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 1886D	Veh. Inspected	SGL 906R
Policy No.		Coverage (\$)	0.00
Claim No.	D19005859MFSH	Excess (\$)	0.00
Assign From	KARENT	Assign Date	11/09/2019
2. Vehicle Particulars & Condition			
Make & Model	HONDA AIRWAVE	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	GJ11106298	Colour	BLACK
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/55 R16	YOKOHAMA	6 mm
L/H Front Tyre	185/55 R16	YOKOHAMA	6 mm
R/H Rear Tyre	185/55 R16	YOKOHAMA	6 mm
L/H Rear Tyre	185/55 R16	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	08/09/2019	Inspection Date	12/09/2019
Survey held at	TICK HAI MOTOR & WELDING SERVICES BLK 1 KAKI BUKIT AVE 6 #01-54 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>12 Working Days</b>	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGL 906R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER	DISTORTED	710.60	710.60
1	FRONT BUMPER LOWER GRILLE	MISSING	220.00	220.00
2	FRONT BUMPER SIDE RETAINER	NECESSARY	116.40	116.40
1	FRONT GRILLE	SMASHED	362.30	362.30
1	FRONT HONDA CENTRE LOGO	NECESSARY	21.30	21.30
1	FRONT BUMPER REINFORCEMENT	BENT	702.20	338.00
2	FRONT BUMPER REINFORCEMENT BRACKET	NOT NECESSARY	305.20	-
2	HEADLAMP	CRACKED	1,254.40	1,254.40
1	FRONT BONNET	DISTORTED	975.10	975.10
2	FRONT BONNET HINGE	BENT	46.06	46.06
1	FRONT BONNET CHROME	MISSING	128.60	128.60
1	FRONT BONNET LOCK	DAMAGED	80.25	80.25
1	WIPER GARNISH (CENTRE)	NOT NECESSARY	240.75	-
2	WIPER GARNISH (SIDE)	NOT NECESSARY	128.40	-
1	WIPER TANK	NOT NECESSARY	72.23	-
2	FRONT FENDER	N/S BUCKLED	940.60	470.30
2	FRONT FENDER INNER GARNISH	NOT NECESSARY	144.46	-
1	FRONT SUPPORT PANEL	DISTORTED	628.10	628.10
1	FRONT SUPPORT PANEL TOP GARNISH	DEFORMED	95.20	95.20
1	RADIATOR	DISTORTED	433.35	433.35
1	RADIATOR FAN COWLING ASSY	SMASHED	717.44	717.44
1	RADIATOR TOP HOSE	TWISTED	19.26	19.26
1	RADIATOR BOTTOM HOSE	NOT NECESSARY	24.08	-
1	AIR CON CONDENSER	DISTORTED	793.20	793.20
1	AIR CON COWLING ASSY	SMASHED	678.92	678.92
1	DASHBOARD AIRBAG	ACTIVATED	1,091.40	1,091.40
1	STEERING AIRBAG	ACTIVATED	963.00	963.00
1	AIRBAG CONTROL UNIT	ACTIVATED	738.30	738.30
1	FRONT WINDSCREEN	CRACKED	856.52	856.52
1	FRONT WINDSCREEN MOULDING	NECESSARY	121.20	121.20
2	FRONT SEATBELT	ACTIVATED	642.35	642.35

Report Ref No. CS/FCI19016187/Aqd3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-1,425.12	-
	LESS 20% DISCOUNT		-	-2,500.31
			12,826.05	10,001.24
	<b>SPECIAL NETT ITEMS</b>			
1	FRONT NUMBER PLATE WITH CASING (SN)	MISSING	60.00	60.00
1	RADIATOR COOLANT (SN)	NECESSARY	100.00	40.00
1	WINDSCREEN SEALANT (SN)	NECESSARY	80.00	60.00
			240.00	160.00
	<b>LABOUR</b>			
	TO TOWING.		150.00	60.00
	TO CHECK FRONT ELECTRICAL SYSTEM,REPAIR WIRE HARNESS & FOCUS HEADLAMP.		120.00	30.00
	TO REMOVE,REPLACE AND REINSTALL A/C CONDENSER & A/C PIPINGS.		150.00	60.00
	TO REMOVE,REPLACE AND REINSTALL RADIATOR & COOLING SYSTEM.		120.00	60.00
	TO REMOVE AND REINSTALL UNDERCARRIAGE.	NOT NECESSARY	450.00	-
	TO REMOVE,REPLACE AND REINSTALL FRONT WINDSCREEN.		240.00	120.00
	TO REMOVE & REINSTALL DASHBOARD FOR NECESSARY REPAIRS.		400.00	220.00
	TO CONDUCT CHASSIS ALIGNMENT.		300.00	280.00
	TO SPRAY ANTI-RUST COATING ON NEW AND AFFECTED PANELS.		200.00	100.00
	LABOUR TO REMOVE,CUT,CHANGE & PANEL BEATING.		1,800.00	1,200.00
	TO PUTTY AND RESPRAY AFFECTED AREAS.		1,500.00	1,200.00
			5,430.00	3,330.00
	<b>GRAND TOTAL</b>		<b>18,496.05</b>	<b>13,491.24</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>4,500.00</b>

Report Ref No. CS/FCI19016187/Aqd3n2

MARKET VALUE: \$13,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$8,361.00=NETT VALUE: \$4,639.00

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.